

REF:

RC3/ALH18011309/Abcz

REC BY: Adrian King

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No: 1800008731

Claims No:

Sum Insured:

Excess:

300

(Client's Record)

Make of Veh:

Veh No:

SLW2489Y

Yr Regn:

2018, Feb.

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A3 Sedan

CC

999

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading:

3844

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WAUZZZ8V5J1041735

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55R16

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automobile Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES: This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

22/6/18 Revert by merimen
 22/6/18 Rece approved \$14,110 from Victor by merimen
 MV: 120K
 PV: 50K
 Ned: 70K
 22/6/18 Informed Jeffery c/a ex \$300 by email

Date/Time, File Pass 1/2

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return 1/2

13/11- typist

Days Of Repair: 8

Resurvey No. of Trip: 2

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)

Report Format:

merimen

Lump Sum / I.B.I. (\$)

15,931.56

Survey Fee:

200

Transportation:

5 x RS 10

Phone

Other

TOTAL

10

210

INS. REC. BY: Adrian King

REF:

CC3 / ALH18011309 / A/bczASSIGNMENT

From

Date:

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No. 1800008731

Claims No.

Sum Insured:

Excess:

300

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$120K

IDAC Accident Rpt: Consistent? - Yes or No

GIA / PR Seen: Consistent? - Yes or No

Est. Repairs: 8 days 17/8/18 Res. Adrian Yes or NoLum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLV2489YYr Regn: 2018 / FebType M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A3 Sedan c.c. 999

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

3844

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WAUZZ28V5J1041735Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/55R16R: 205/55R16BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

18/6/18

D.O.A.

21/06/18

Survey held at

PremierDes. of Damages: Frnt

Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22/8/18 @ 440pm Carine said additional labour \$1500 - etc15/10/18 Final fig \$15,931.56 confirmed by email (Ref 821144, 3419)

RECEIVED 13 NOV 2018

Camp / Sum / Est /

15,931.56

Worked /

TOTAL

210

View Received Message

This mail is associated with :

***SLW2489Y (6427833006SG)**

OD

Jun 18 2018 10:00AM

[KOH YAU HWEE ALVIN (GAO TAOHUI ALVIN)]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 15/10/2018 12:50 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$15931.56) - SLW2489Y - Claim Handler: Mohd Zawaye, Norsazani

Approved:15931.56.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Mohd Zawaye, Norsazani

Date: 24 Aug 2018

Preliminary Advice

Vehicle No	: SLW2489Y	Accident Date	: 18/06/2018
Make	: AUDI A3	Policy No.	: 1800008731
Assignment Date	: 21/06/2018	Excess	: S\$300.00
Date of Inspection	: 21/06/2018	Est. Duration of Repair	: 8.00
Inspection At	PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,143.00	(incl.supplementary \$4140)
Revised Amount	:S\$	15,931.56	(incl.supplementary \$4140)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	15,931.56	

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	120,000.00
COE / PARF Rebate	:S\$	55,385.00
Salvage Value	:S\$	
Margin for Repair	:S\$	64,615.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 22 June 2018 3:00 PM
To: claims@premiumauto.com.sg
Cc: SUR
Subject: SLW 2489Y-DOA: 18/6/2018 (AIG OD)

Dear Jeffery,

As instructed by our client, please proceed to repair the insured vehicle **SLW 2489Y (Excess S300/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

***SLW2489Y (6427833006SG)**

OD

Jun 18 2018 10:00AM

[KOH YAU HWEE ALVIN (GAO TAOHU ALVIN)]
Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 22/06/2018 14:40 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$14110.00) - SLW2489Y - Claim Handler: Mohd Zawaye, Norsazani

Approved:14110.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 22 Jun 2018

Preliminary Advice

Vehicle No	: SLW2489Y	Accident Date	: 18/06/2018
Make	: AUDI A3	Policy No.	: 1800008731
Assignment Date	: 21/06/2018	Excess	: S\$0.00
Date of Inspection	: 21/06/2018	Est. Duration of Repair	: 5.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,003.00
Revised Amount	:S\$	14,110.00
Check Items (Estimated)	:S\$	1,359.00
Total	:S\$	15,469.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	120,000.00
COE / PARF Rebate	:S\$	55,385.00
Salvage Value	:S\$	
Margin for Repair	:S\$	64,615.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5443F
Vehicle Details	
Vehicle No.:	SLW2489Y
Vehicle to be Exported:	No
Intended De-registration Date:	22 Jun 2018
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.0 TFSI S TRONIC (LED)
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	CHZ638055
Chassis No.:	WAUZZZ8V5J1041735
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$24,698.00
Original Registration Date:	02 Feb 2018
First Registration Date:	02 Feb 2018
Transfer Count:	0
Actual ARF Paid:	\$26,578.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Feb 2028
PARF Rebate Amount:	\$19,933.00
Intended COE Rebate Details	
COE Expiry Date:	01 Feb 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,890.00
COE Rebate Amount:	\$35,452.00
Total Rebate Amount:	\$55,385.00

The information contained herein is correct as at 22 Jun 2018

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5443F
Vehicle Details	
Vehicle No.:	SLW2489Y
Vehicle to be Exported:	Yes
Intended De-registration Date:	21 Jun 2018
Vehicle Make:	AUDI
Vehicle Model:	A3 SEDAN 1.0 TFSI S TRONIC (LED)
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	CHZ638055
Chassis No.:	WAUZZZ8V5J1041735
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$24,698.00
Original Registration Date:	02 Feb 2018
First Registration Date:	02 Feb 2018
Transfer Count:	0
Actual ARF Paid:	\$26,578.00
Vehicle PARF Eligibility Particulars	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	01 Feb 2028
PARF Rebate Amount:	\$19,933.00
Vehicle COE Details	
COE Expiry Date:	01 Feb 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$36,890.00
COE Rebate Amount:	\$29,512.00
Total Rebate Amount:	\$49,445.00

The information contained herein is correct as at 21 Jun 2018

OK

AUDI-AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : KOH YAU HWEE ALVIN
Period of Insurance : 02 Feb 2018 To 01 Feb 2020
Engine No. : CHZ638055
Chassis No. : WAUZZZ8V5J1041735

Vehicle No. : SLW2489Y
Policy No. : 1800008731
Endorsement No. :
Issued Date : 07 Feb 2018

ABOUT THE COVER

Make/Model : AUDI A3 Sedan 1.0 TFSI S tronic
Engine Capacity/Tonnage : 999.00 CC Sum Insured : Market Value First Year of Registration : 2018
Driver Restriction : NA Off Peak Car : No Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.
You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDE") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

KOH YAU HWEE ALVIN - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6335 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125202

PREMIUM LEASING - JT

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.


AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

Chong Dan Yee

License Number: **S7828983Z**

TAN LEE YEW, EDWIN
(CHEN LIYOU, EDWIN)

Birth Date: 02 Oct 1978
Valid Date: 15 Mar 2006

001328559G

KOH YAU HWEE ALVIN
(GAO YAOHUI ALVIN)

高耀輝

Race: CHINESE
Date of Birth: 12-12-1971
Country of Birth: SINGAPORE

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7828983Z

TAN LEE YEW, EDWIN
(CHEN LIYOU)

陈利友

Race: CHINESE
Date of birth: 02-10-1978
Country/Place of birth: SINGAPORE

Sex: M

57828983Z

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES

Class 3 Motor cars $\leq$ 3000 kg with $\leq$ 7 passengers, exclusive of the driver; and motor tractors / vehicles $\leq$ 2500 kg

PASS DATE 15 Mar 2006

NP 428A

License No: S7828983Z

NRIC No. S7145443F

20 HONG SAN WALK #03-07
SINGAPORE 500090

NRIC No. S7145443F **Date: 21-05-2004** **No. 4945018**

20-12-1992

NRIC No. S7828983Z

APT BLK 105 LORONG 7 TDA' PAVOH
#15-211
SINGAPORE 312019

11-02-2013

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/06/2018 17:24
Date Of Accident	18/06/2018 10:15
Exact Location Of Accident	CTE NEAR LAMPOST 401
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW2489Y
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	KOH YAU HWEE ALVIN (GAO TAOHUI ALVIN)
NRIC No	S7145443F
Email Address	AK12121971@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96329969
Alternative Phone No	OFFICE-96329969

Vehicle Particulars

Manufacturer	AUDI
Model	A3 SEDAN 1.0 TFSI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800008731
Cover Note Number	

Driver

Name of Driver	TAN LEE YEW, EDWIN (CHEN LIYOU, EDWIN)
NRIC No	S7828983Z
Date Of Birth	02/10/1978
Occupation	INDOOR
Date Of Driving Pass	15/03/2005
Driving Experience	13 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96609948
Fax Number	
Contact Number	
Email Address	EDWINTTT@SINGNET.COM.SG

Address	APT BLK 16B LORONG 7 TOA PAYOH #16-211
Postcode	312010
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	FRIEND
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG CTE TOWARDS AYE ON 18 JUNE 2018 AT AROUND 10:15AM, NEAR LAMP POST 401, IN LANE 4. I WAS CHANGING LANE TO LANE 3 AND COULD NOT STOP IN TIME, HITTING THE REAR OF LIMOUSINE TAXI SHD 22 X.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD22X
Vehicle Make/Model/Colour	WHITE/MERCEDES E220
Details Of Properties	LIMOUSINE
Vehicle Category	TAXI
Name of Driver	THAN KIM SENG RICHARD
NRIC/Passport Number	S1407499F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: *James E. Smith, Jr.*
NRIC/FIN No: *4227162*



17/6/18
1:40 am




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along CTE towards AYE on 18 June 2018 at around 10:15am, near lamp post 401, in lane 4 going towards AYE.

I was changing lane to lane 3 and could not stop in time, hitting the rear of a limousine tax SHD22X.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 18/6/18
1140 am


Reporting Centre Personnel's Signature
Name: WONG AUNNG SEH, Guy
NRIC/FIN No: 673987142X



Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



Accident Photo



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0704/2018/PH
Date	:	20-Jun-18

VehicleIN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Koh Yau Hwee Alvin
Address	:	Blk 10B Lorong 7 Toa Payoh #16-211 Singapore 312010
Telephone	:	HP +65 90612928
Type of Claim	:	Own Damage claims
Policy No.	:	1800008731
Vehicle No	:	SLW 2489 Y
Model Code	:	Audi A3 Sedan 1.0 TFSI S
Model / Year	:	Feb-18
Engine No	:	CHZ 638055
Chassis No	:	WAUZZZ8V5J1041735
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	18-Jun-18
Place of Accident	:	CTE near lamppost 401

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : *Adrian King*
Surveyed Date : *21/06/18*
Authorised Date :
Excess Cost :
Liability :
Remarks : *not authorised, 05 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLW 2489 Y.

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer Assy.	S/N \$ 360.00 ✓ ✓
2	To dismantle and renew front bumper, lhs front fender, headlight and bonnet. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,700.00 1250 ✓
3	To respray front bumper, lhs front fender and bonnet.	\$ 2,200.00 1650 ✓
4	To carry out diagnostic checks.	S/N \$ 192.00 ✓ ✓
TOTAL LABOUR CHARGES		: \$ <u>5,452.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2489 Y.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	BUMPER COVER <i>Rehd</i>	\$ 1,739.00 ✓	1391.20
2	GUIDE SECTION - LH <i>new</i>	\$ 33.00 X	
3	GRILLE - CENTER <i>new</i>	\$ 140.00 X	
4	CLOSING ELEMENT - LH/RH <i>Not new</i>	2 \$ 508.00 X	
5	COVER TRIM - LH/RH <i>Not new</i>	2 \$ 280.00 X	
6	FRONT BUMPER COVER TRIM-LH/RH <i>new</i>	2 \$ 280.00 X	
7	RADIATOR GRILLE <i>Crushed</i>	\$ 1,239.00 ✓	991.20
8	CLOSING ELEMENT <i>new Dayd</i>	\$ 167.00 ✓	133.30
9	COVER <i>new Dayd</i>	\$ 105.00 ✓	83.60
10	FOAM FILLER PIECE <i>Crushed</i>	\$ 162.00 ?	129.60
11	SIDE REINFORCEMENT <i>Best</i>	\$ 633.00 ?	506
12	CAUTION SIGN STICKER <i>new</i>	\$ 12.00 ✓	9.28
14	FRONT FENDER - LH <i>Regr</i>	\$ 746.00 r	
15	BRACKET FOR FENDER - LH <i>new</i>	\$ 34.00 r	
16	BRACE - LH <i>new</i>	\$ 84.00 r	
17	LED HEADLIGHT - LH <i>Crushed</i>	\$ 4,888.00 ✓	3910.40
18	LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM-LH <i>Not new</i>	\$ 123.00 ? X	
19	BONNET <i>Crushed</i>	\$ 2,755.00 ✓	2204
20	ATTACHMENT PARTS FOR BONNET <i>Not new</i>	\$ 141.00 ? X	
TOTAL SPARE PARTS		\$ 14,069.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2489 Y.

		Damage Parts & Prices	
S/N	Parts Description	S/NETT	REMARKS
21	CATCH HOOK <i>new</i>	\$ 78.00	X
22	EDGE PROTECTOR <i>new</i>	\$ 24.00	X
23	CATCH HOOK <i>new</i>	\$ 55.00	X
24	FRONT NUMBER PLATE <i>Best</i>	S/N \$ 25.00	✓ 25
25	SUNDRIES <i>new</i>	\$ 300.00	14.88
TOTAL SPARE PARTS		:	\$ 14,551.00
TOTAL LABOUR CHARGES		:	\$ 5,452.00
GRAND TOTAL		:	\$ 20,003.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

24, 143

23996.20

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0704/2018/PH

9-Jul-18

Jeffery Tan

1

SLW 2489 Y

Audi A3 Sedan 1.0 TFSI S

Quantity	Description	Unit Price	Amount
Parts			
1	Lock carrier <i>cracked.</i>	\$ 638.00	<i>510</i>
2	Coolant <i>rec</i>	\$ 82.00	<i>65.38</i>
3	Lock carrier air guide - LHS <i>defect</i>	\$ 20.00	<i>15.92</i>
		\$ 740.00	
LABORS			
1	To remove and transfer aircond condenser, radiator additional radiator, electrical fans and control unit. To carry out vacuum/regas and to pressurize cooling system. (Special Nett)	\$ 1,000.00	<i>✓</i>
2	To renew front lock carrier and align to position.	\$ 2,400.00	<i>2000 1500 S/S</i>
TOTAL		\$ 4,140.00	

For Premium Automobiles Pte Ltd

Adrian Ling -
S/S

Authorised Signature

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 10 July 2018 11:17 AM
To: 'Claims Dept'
Cc: SUR
Subject: RE: SLW 2489Y-DOA: 18/6/2018 (AIG OD)
Attachments: MARK EST.pdf

Dear Jeffery,

Please refer attached.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept [mailto:claims@premiumauto.com.sg]
Sent: Tuesday, 10 July 2018 8:18 AM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; 'Claims Dept' <claims@premiumauto.com.sg>
Subject: RE: SLW 2489Y-DOA: 18/6/2018 (AIG OD)

Dear Veron,

Attached the supplementary and photos for your kind reference.

Kindly forward to Adrian for his kind reference.

Many thanks!

Best regards,
Jeffery Tan

Premium Automobiles Pte Ltd (Reg No 149902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]

Sent: Friday, 22 June, 2018 3:00 PM

To: claims@premiumauto.com.sg

Cc: SUR <sur@lkkauto.com>

Subject: SLW 2489Y-DOA: 18/6/2018 (AIG OD)

Dear Jeffery,

As instructed by our client, please proceed to repair the insured vehicle **SLW 2489Y (Excess S300/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0704/2018/PH
Date : 20-Jun-18

Vehicle in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

You recommended 6 days

We took 8 days exclude 1 Sunday

Added repairs - jb - 13 Aug 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Koh Yau Hwee Alvin
Address : Blk 10B Lorong 7 Toa Payoh
#16-211
Singapore 312010
Telephone : HP +65 90612928
Type of Claim : Own Damage claims
Policy No. : 1800008731
Vehicle No : **SLW 2489 Y**
Model Code : Audi A3 Sedan 1.0 TFSI S
Model / Year : Feb-18
Engine No : CHZ 638055
Chassis No : WAUZZZ8V5J1041735
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 18-Jun-18
Place of Accident : CTE near lampost 401

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLW 2489 Y.

S/N	Nature of Jobs	Estimated Charges	
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	\$ 360.00
2	To dismantle and renew front bumper, lhs front fender, headlight and bonnet. Re-organise front crash management components. Reinstall all parts removed.	\$ 2,700.00	\$ 1,250.00
3	To respray front bumper, lhs front fender and bonnet.	\$ 2,200.00	\$ 1,650.00
4	<i>Added labour chrges - see attached</i>	\$ 3,400.00	\$ 3,000.00
5	To carry out diagnostic checks.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 8,852.00	\$ 6,452.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2489 Y.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	BUMPER COVER	\$ 1,739.00	\$ 1,391.20
2	GUIDE SECTION - LH	\$ 33.00	
3	GRILLE - CENTER	\$ 140.00	
4	CLOSING ELEMENT - LH/RH	2 \$ 508.00	
5	COVER TRIM - LH/RH	2 \$ 280.00	
6	FRONT BUMPER COVER TRIM-LH/RH	2 \$ 280.00	
7	RADIATOR GRILLE	\$ 1,239.00	\$ 991.20
8	CLOSING ELEMENT	\$ 167.00	\$ 133.20
9	COVER	\$ 105.00	\$ 83.60
10	FOAM FILLER PIECE	\$ 162.00	\$ 129.60
11	SIDE REINFORCEMENT	\$ 633.00	\$ 506.00
12	CAUTION' SIGN STICKER	\$ 12.00	\$ 9.28
14	FRONT FENDER - LH	\$ 746.00	
15	BRACKET FOR FENDER - LH	\$ 34.00	
16	BRACE - LH	\$ 84.00	
17	LED HEADLIGHT - LH	\$ 4,888.00	\$ 3,910.40
18	LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM-LH	\$ 123.00	
19	BONNET	\$ 2,755.00	\$ 2,204.00
20	ATTACHMENT PARTS FOR BONNET	\$ 141.00	
TOTAL SPARE PARTS		\$ 14,069.00	\$ 9,358.48

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 2489 Y.

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		<i>c/f</i>		\$ 9,358.48
21	CATCH HOOK		\$ 78.00	
22	EDGE PROTECTOR		\$ 24.00	
23	CATCH HOOK		\$ 55.00	
24	FRONT NUMBER PLATE	S/N	\$ 25.00	\$ 25.00
25	ADDED PARTS - SEE ATTACHED		\$ 740.00	\$ 591.20
26	SUNDRIES		\$ 300.00	\$ 4.88
TOTAL SPARE PARTS		:	\$ 15,291.00	\$ 9,979.56
TOTAL LABOUR CHARGES		:	\$ 5,452.00	\$ 6,452.00
GRAND TOTAL		:	\$ 20,743.00	\$ 16,431.56

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0704/2018/PH

9-Jul-18

Jeffery Tan

1

SLW 2489 Y

Audi A3 Sedan 1.0 TFSI S

Quantity	Description	Unit Price	Amount
Parts			
1	Lock carrier <i>crushed</i>	\$ 638.00	\$ 510.00 ✓
2	Coolant <i>in</i>	\$ 82.00	\$ 65.28 ✓
3	Lock carrier air guide - LHS <i>Defend</i>	\$ 20.00	\$ 15.92 ✓
		\$ 740.00	\$ 591.20
LABORS			
1	To remove ad transfer aircond condenser, radiator additional radiator, electrical fans and control unit. To carry out vacuum/regas and to pressurize cooling system. (Special Nett)	\$ 1,000.00	\$ 1,000.00 ✓
2	To renew front lock carrier and align to position.	\$ 2,400.00	\$ 2,000.00
TOTAL		\$ 4,140.00	\$ 3,591.20

For Premium Automobiles Pte Ltd

Authorised Signature



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 15 October 2018 3:24 PM
To: 'Boo seng yak'; Adrian Ling (LKKAUTO); SUR; Carrine Leong;
jiayee.yap@premiumauto.com.sg; Chang Chee Sing
Subject: RE: FIFNAL REVISION - SLW2489Y - OD AIG - SURVEYED 22 JUN 18

Dear Mr Boo,

Repair cost of \$15,931.56 before excess \$300 and GST @ 8 days of repairs.

To renew front lock carrier and align to position revised to \$1500.

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Monday, 13 August 2018 6:22 PM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>
Subject: FIFNAL REVISION - SLW2489Y - OD AIG - SURVEYED 22 JUN 18

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$16,431.56 @ 8 days of repairs exclude 1 Sunday.

Your early closure is well appreciated.

Best regards - jb

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLW 2489 Y

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0704/2018/MAS

13 Nov 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SLW 2489 Y, Audi A3 Sedan 1.0 TFSI

With reference to the above-mentioned vehicle, no **SLW 2489 Y**, claimant, **Mr. Koh Yau Hwee Alvin**, please find the related document per attached.

1. A copy of the Original invoice no. 85013108 – S\$16,725.77
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLW 2489 Y

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6336 2223
Fax: 6471 2123
Page 1 12:00

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6336 2223
Telefax: 6471 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408623
Telephone: 6336 2223
Telefax: 6471 1023

Customer Service
Service Appointment
Hour Breakdown Service
Email: customer.care@premiumauto.com.sg
4366 2223
6471 1233

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013108 Date : 09/11/2018 Order : SLM2489Y Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLM2489Y (V 36792) Regn Date: 02/02/2018 Mileage: 4313 WIP No.: 14244
Model: A3 SEDAN 1.0 TFSI 8VHANG Chassis: WAUZZZ8V5J1041735 Engine: CHZ 630055 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
S	SURLET	N: TO SUPPLY VEHICLE NUMBER PLATE	25.00	1.00	25.00
Q	EXC	N: 8888 Insurance Excess/Liability	-300.00	1.00	-300.00
S	BODYWORK	N: TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	350.00	1.00	350.00
S	BODYWORK	N: TO DISMANTLE AND RENEW FRONT BUMPER, LHS HEADLIGHT AND BONNET, REPAIR LHS FRONT FENDER, REORGANISE FRONT CRASH MANAGEMENT COMPONENTS, REINSTALL ALL PARTS REMOVED	1250.00	1.00	1,250.00
S	BODYWORK	N: TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND BONNET	1650.00	1.00	1,650.00
S	BODYWORK	N: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159538
Main Telephone: 6334 2223
Main Telefax: 6471 2723
Page 2 12:00

Alexandra Service Centre
281 Alexandra Road
Singapore 159538
Telephone: 6334 2223
Telefax: 6471 1033

Ubi Service Centre
55 Ubi Road 1
Singapore 408653
Telephone: 6385 3453
Telefax: 6341 1127

Customer Service
Service Appointment:
4346 2323
9828 1233
Email: customer.care@premiumauto.com.sg

INS TAX INVOICE

Company No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120 079120

Invoice: 85013108
Date : 09/11/2018
Order : SLM2489Y
Term : 30

Account: A0006 (T 0)
AIG ASIA PACIFIC INSURANCE PTE LTD
MOTOR CLAIM DEPT
AIG BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120

Regn No.: SLM2489Y (V 36792) Regn Date: 02/02/2018 Mileage: 4313 WTP No.: 14244
Model: A3 SEDAN 1.0 TFSI 8VHANG Chassis: WAUZZZ8V5J1041735 Engine: CHZ 638055 Dept: U
USB No.:

You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND TRANSFER AIRCON CONDENSER, RADIATOR, ADDITIONAL RADIATOR, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM/REGAS AND TO PRESSURISE COOLING SYSTEM	1000.00	1.00	1,000.00
S	BODYWORK	M: TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION	1500.00	1.00	1,500.00
X	A8V3853651AA3FZ	GRILLE	1.00	1239.00	991.20
X	A8V0941773D	HEADLIGHT(SK)	1.00	4888.00	3,910.40
X	A8V0805588A	CARRIER (SK) (V)	1.00	637.50	510.00
X	A8V0807550A	FOAM INSER	1.00	162.00	129.60
X	A8V4807109E	BEAM	1.00	632.50	506.00
X	AG A13040M2	PREMIX-COOLANT	4.00	20.40	65.28
X	A8V5823829A	HOOD	1.00	2755.00	2,204.00
X	A8V5807065R GRU	COVER(SK)	1.00	1739.00	1,391.20
X	A8V0807217A	COVER	1.00	104.50	83.60
X	A8K0010520A	PLATE	1.00	11.60	9.28
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159558
Main Telephone: 6386 2223
Main Telefax: 6475 3131
Page 3 12:00

Alexandra Service Centre
281 Alexandra Road
Singapore 159558
Telephone: 6386 2223
Telefax: 6475 1033

UBI Service Centre
55 Ubi Road 1
Singapore 408826
Telephone: 6386 2223
Telefax: 6475 1033

Customer Service
Service Appointment
Hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6386 2223
6626 1233

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013108 Date : 09/11/2018 Order : SLM2489Y Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLM2489Y (V 36792) Regn Date: 02/02/2018 Mileage: 4313 WIP No.: 14244
Model: A3 SEDAN 1.0 TFSI 8VWANG Chassis: WAUZZZ8V5J1041735 Engine: CHZ 638055 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details		Qty	Unit Price	Amount
X	ABV0010515A	STICKER	Less 020%	1.00	5.10	4.88
X	ABV0121283X	AIR DUCT (SK) (V)	Less 020%	1.00	19.90	15.92
X	ABV3853949	PLATE	Less 020%	1.00	166.50	133.20

Parts 9,954.56
Labour 0.00
Sublet 5,977.00
Menus 0.00
Lubricant 0.00

Sub-Total 15,631.56
7% GST 1,094.21
Grand Total 16,725.77



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SLW2489Y

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0704/2018/TF
16 July 2018

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

1 total pages

RE : CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model : Audi A3 SEDAN 1.0 TFSI
Vehicle Chassis No. : WAUZZZ8V5J1041735
Vehicle Regn No. : SLW2489Y
Vehicle Mileage : 4398 KM
Vehicle Owner : Mr. Koh Yau Hwee Alvin
Certificate No : 1800008731
Policy Excess : S\$321.00 (inclusive 7% GST)
Accident Date : 18 June 2018
Place : CTE Near Lamp POST 401
Repair Cost : \$ 16,725.77
WIP No. : 14244
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature : 
Time : 1601
Date : 18/07/18

Identity Card No. S7828983Z

TAN LEE YEW, EDWIN
(CHEN LIYOU, EDWIN)

Birth Date: 02 Oct 1978
Valid Until: 15 Mar 2008

001528851G

IDENTITY CARD NO. S7828983Z

KOH YAU HWEE ALVIN
(GAG YAOHUI ALVIN)

高耀輝

Race: CHINESE
Date of Birth: 12-12-1971
Sex: M
Country of Birth: SINGAPORE

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7828983Z

TAN LEE YEW, EDWIN
(CHEN LIYOU)

陈利友

Race: CHINESE
Date of Birth: 02-10-1978
Country/Place of Birth: SINGAPORE

57828983Z

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

Class 3 Motor cars $\leq$ 3000 kg with $\leq$ 7 passengers, exclusive of the driver; and motor tractors / vehicles $\leq$ 2500 kg

Valid Until: 15 Mar 2008

Licence No: S7828983Z

NP 428A

0088810

57145443F

20-12-1992

21-06-2004

No: 4945015

5191955

S7828983Z

15-07-2013

APT BLK 105 LORONG 7 TOW PAKOH
H15-211
SINGAPORE 319015

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : KOH YAU HWEE ALVIN
Period of Insurance : 02 Feb 2018 To 01 Feb 2020
Engine No. : CHZ638055
Chassis No. : WAUZZZ8V5J1041735

Vehicle No. : SLW2489Y
Policy No. : 1800008731
Endorsement No. :
Issued Date : 07 Feb 2018

ABOUT THE COVER

Make/Model : AUDI A3 Sedan 1.0 TFSI S tronic
Engine Capacity/Tonnage : 999.00 CC Sum Insured : Market Value First Year of Registration : 2018
Driver Restriction : NA Off Peak Car : No Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

- a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDER") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 6 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

KOH YAU HWEE ALVIN - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 406009 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download 'AIG SG' from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125202

PREMIUM LEASING - JT

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.



AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

Cheng Guan Yee

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Jun 2018 09:01		21 Jun 2018 18:03 Edit Adj Rpt	S\$15,931.56 Edit Estimates	S\$15,931.56 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	KOH YAU HWEE ALVIN (GAO TAOHUI ALVIN) , ID: S7145443F, Tel: +6596329969								
Vehicle Reg. No.:	SLW2489Y	Date of Loss:	18/06/2018 10:00 - :59 [4 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 6427833006SG	Policy/Cover Note No.:	1800008731 (Comprehensive)						
		Excess:	S\$300.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Mohd Zawaye, Norsazani]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 02/07/2018]								
Driver/Custodian:	TAN LEE YEW, EDWIN (CHEN LIYOU, EDWIN) (39 / Male), NRIC: S7828983Z, Tel: +6596609948								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (15/10/2018): Alert - Adj Mandate Approved (S\$15931.56) - SLW2489Y - Claim Handler: Mohd Zaway... - AIG_SG (22/06/2018): Alert - Adj Mandate Approved (S\$14110.00) - SLW2489Y - Claim Handler: Mohd Zaway... - AIG_SG (22/06/2018): SLW2489Y / OD / 18/06/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLW2489Y (6427833006SG)
 OD
 Jun 18 2018 10:00AM
 [KOH YAU HWEE ALVIN (GAO TAOHUI ALVIN)]
 Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Video															1 per page		v	☒		
No	Finalized On	Premium Autocare Centre (Alexandra)												Thumbnail		Print				
1	18/06/18 17:53	Video - Accident [Linked Accident Report Documents]													Load MP4					
Assessment Reports															1 per page		v	☒		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	22/06/18 09:34	Adjuster Immediate Advice													Load HTM					
2	24/08/18 10:14	Adjuster Immediate Advice													Load HTM					
Photos/Images															3 per page		v	☒		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	22/06/18 09:03	General View													Load JPG	☒				
2	22/06/18 09:03	General View													Load JPG	☒				
3	22/06/18 09:03	General View													Load JPG	☒				
4	22/06/18 09:03	General View													Load JPG	☒				
5	22/06/18 09:03	General View													Load JPG	☒				
6	22/06/18 09:03	General View													Load JPG	☒				
7	22/06/18 09:03	General View													Load JPG	☒				
8	22/06/18 09:03	General View													Load JPG	☒				
9	22/06/18 09:03	General View													Load JPG	☒				
10	22/06/18 09:03	General View													Load JPG	☒				
11	22/06/18 09:03	General View													Load JPG	☒				
12	22/06/18 09:03	General View													Load JPG	☒				
13	22/06/18 09:03	General View													Load JPG	☒				
14	22/06/18 09:03	General View													Load JPG	☒				
15	22/06/18 09:03	General View													Load JPG	☒				
16	22/06/18 09:03	General View													Load JPG	☒				
17	22/06/18 09:03	General View													Load JPG	☒				
18	22/06/18 09:03	General View													Load JPG	☒				
19	22/06/18 09:03	General View													Load JPG	☒				
20	22/06/18 09:03	General View													Load JPG	☒				
21	22/06/18 09:03	General View													Load JPG	☒				
22	22/06/18 09:03	General View													Load JPG	☒				
23	22/06/18 09:03	General View													Load JPG	☒				
24	22/06/18 09:03	General View													Load JPG	☒				
25	22/06/18 09:03	General View													Load JPG	☒				
26	22/06/18 09:03	General View													Load JPG	☒				
27	22/06/18 09:03	General View													Load JPG	☒				
28	22/06/18 09:03	General View													Load JPG	☒				
29	22/06/18 09:03	General View													Load JPG	☒				
30	22/06/18 09:03	General View													Load JPG	☒				

Video			1 per page	☒
No	Finalized On	Premium Autocare Centre (Alexandra)	Thumbnail	Print
31	22/06/18 09:03	General View	 Load JPG	☒
32	22/06/18 09:03	General View	 Load JPG	☒
33	22/06/18 09:03	General View	 Load JPG	☒
34	22/06/18 09:03	General View	 Load JPG	☒
35	22/06/18 09:03	General View	 Load JPG	☒
36	22/06/18 09:03	General View	 Load JPG	☒
37	22/06/18 09:03	General View	 Load JPG	☒
38	17/08/18 16:00	Reinspection Photo	 Load JPG	☒
39	17/08/18 16:00	Reinspection Photo	 Load JPG	☒
40	17/08/18 16:00	Reinspection Photo	 Load JPG	☒
41	17/08/18 16:00	Reinspection Photo	 Load JPG	☒
42	17/08/18 16:00	Reinspection Photo	 Load JPG	☒
43	17/08/18 16:00	Reinspection Photo	 Load JPG	☒
44	17/08/18 16:00	Reinspection Photo	 Load JPG	☒
45	17/08/18 16:00	Reinspection Photo	 Load JPG	☒
46	17/08/18 16:00	Reinspection Photo	 Load JPG	☒
47	17/08/18 16:00	Reinspection Photo	 Load JPG	☒
48	17/08/18 16:01	Reinspection Photo	 Load JPG	☒
49	17/08/18 16:01	Reinspection Photo	 Load JPG	☒
50	17/08/18 16:01	Reinspection Photo	 Load JPG	☒
51	17/08/18 16:01	Reinspection Photo	 Load JPG	☒
52	17/08/18 16:01	Reinspection Photo	 Load JPG	☒
53	17/08/18 16:01	Reinspection Photo	 Load JPG	☒
54	17/08/18 16:01	Reinspection Photo	 Load JPG	☒
55	17/08/18 16:01	Reinspection Photo	 Load JPG	☒
56	17/08/18 16:01	Reinspection Photo	 Load JPG	☒
57	17/08/18 16:01	Reinspection Photo	 Load JPG	☒
58	17/08/18 16:01	Reinspection Photo	 Load JPG	☒
59	17/08/18 16:01	Reinspection Photo	 Load JPG	☒
60	17/08/18 16:01	Reinspection Photo	 Load JPG	☒
61	17/08/18 16:01	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/06/18 09:12	Singapore Accident Statement	 Load PDF	
2	22/06/18 09:12	Certificate of Insurance	 Load PDF	
3	22/06/18 09:12	Driver's Driving License	 Load PDF	
4	22/06/18 09:12	MARK ESTIMATE	 Load PDF	
5	24/08/18 10:15	FINALISE MARK ESTIMATE	 Load PDF	
6	24/08/18 10:15	SUPPLEMENTARY	 Load PDF	
7	04/12/18 14:07	Workshop Invoice	 Load PDF	
8	04/12/18 14:07	Discharge Voucher	 Load PDF	

Linked Accident Report Documents

Video			1 per page	☒
No	Finalized On	Premium Autocare Centre (Alexandra)	Thumbnail	Print
1	18/06/18 17:53	Video - Accident	 Load MP4	
Assessment Reports			1 per page	☒
No	Finalized On	Premium Autocare Centre (Alexandra)	Thumbnail	Print

Video			1 per page	☒
No	Finalized On	Premium Autocare Centre (Alexandra)	Thumbnail	Print
1	19/06/18 09:55	Accident Statement	 Load HTML	☒
Photos/Images			3 per page	☒
No	Finalized On	Premium Autocare Centre (Alexandra)	Thumbnail	Print
1	18/06/18 17:51	Accident Photo	 Load JPG	☒
2	18/06/18 17:51	Accident Photo	 Load JPG	☒
3	18/06/18 17:51	Accident Photo	 Load JPG	☒
4	18/06/18 17:52	Accident Photo	 Load JPG	☒
5	18/06/18 17:52	Accident Photo	 Load JPG	☒
6	18/06/18 17:52	Accident Photo	 Load JPG	☒
7	18/06/18 17:52	Accident Photo	 Load JPG	☒
8	18/06/18 17:52	Accident Photo	 Load JPG	☒
9	18/06/18 17:52	Accident Photo	 Load JPG	☒
10	18/06/18 17:52	Accident Photo	 Load JPG	☒
11	18/06/18 17:52	Accident Photo	 Load JPG	☒
12	18/06/18 17:52	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Premium Autocare Centre (Alexandra)	Thumbnail	Print
1	18/06/18 17:50	Sketch Plan	 Load JPG	☒
2	18/06/18 17:51	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18011309/AVBE2

Date: 04/12/2018

REFERENCE

Insured/Claimant: KOH YAU HWEE ALVIN (GAO TAOHUI ALVIN) Policy No: 1800008731

Date of Loss: 18/06/2018

Nature of Claim: OD

Claim No: 6427833006SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW2489Y	Engine No:	CHZ638055
Make & Model:	AUDI A3, 999cc TFSI (A)	Chassis No:	WAUZZZ8V5J1041735
Reg. Date:	02/02/2018 (Man. Year: 2017)	Odometer:	3844 km
Colour:	Blue		
Engine Capacity:	999 cc		
Market Value/New Car Price:	S\$120,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,142.20	9,979.56	5,162.64	34.09
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,852.00	5,952.00	2,900.00	32.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,994.20	15,931.56	8,062.64	33.60
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	23,694.20	15,631.56	8,062.64	34.03
+ GST 7.00/7.00% (S\$)	1,658.59	1,094.21	564.38	34.03
Nett Amount (S\$)	25,352.79	16,725.77	8,627.02	34.03

INSPECTION

Date of Assignment: 21/06/2018

Date Inspected: 21/06/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BUMPER COVER	Deformed	1,739.00 FS	*1,391.20 FS
2	1	*GUIDE SECTION - LH	Not Necessary	33.00 FS	*- FS
3	1	*GRILLE - CENTER	Not Necessary	140.00 FS	*- FS
4	2	*CLOSING ELEMENT - LH/RH	Not Necessary	508.00 FS	*- FS
5	2	*COVER TRIM - LH/RH	Not Necessary	280.00 FS	*- FS
6	2	*FRONT BUMPER COVER TRIM - LH/RH	Not Necessary	280.00 FS	*- FS
7	1	*RADIATOR GRILLE	Cracked	1,239.00 FS	*991.20 FS
8	1	*CLOSING ELEMENT	Damaged	167.00 FS	*133.20 FS
9	1	*COVER	Damaged	105.00 FS	*83.60 FS
10	1	*FOAM FILLER PIECE	Cracked	162.00 FS	*129.60 FS
11	1	*SIDE REINFORCEMENT	Bent	633.00 FS	*506.00 FS
12	1	*CAUTION SIGN STICKER	Necessary	12.00 FS	*9.28 FS
13	1	*FRONT FENDER - LH	Repair	746.00 FS	*- FS
14	1	*BRACKET FOR FENDER - LH	Not Necessary	34.00 FS	*- FS
15	1	*BRACE - LH	Not Necessary	84.00 FS	*- FS
16	1	*LED HEADLIGHT - LH	Cracked	4,888.00 FS	*3,910.40 FS
17	1	*LIFT CYLINDER FOR HEADLIGHT WASHER SYSTEM - LH	Not Necessary	123.00 FS	*- FS
18	1	*BONNET	Buckled	2,755.00 FS	*2,204.00 FS
19	1	*ATTACHMENT PARTS FOR BONNET	Not Necessary	141.00 FS	*- FS
20	1	*CATCH HOOK	Not Necessary	78.00 FS	*- FS
21	1	*EDGE PROTECTOR	Not Necessary	24.00 FS	*- FS
22	1	*CATCH HOOK	Not Necessary	55.00 FS	*- FS
23	1	*FRONT NUMBER PLATE	Bent	25.00 FS	*25.00 FS
24	1	*SUNDRIES	Necessary	300.00 FS	*4.88 FS
25	1	*LOCK CARRIER	Cracked	510.00 FS	*510.00 FS
26	1	*COOLANT	Necessary	65.28 FS	*65.28 FS
27	1	*LOCK CARRIER AIR GUIDE - LHS	Deformed	15.92 FS	*15.92 FS

F=Franchise part, S=SpcNett

Total Parts (\$\$) 15,142.20 9,979.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, HEADLIGHT AND BONNET. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,700.00	1,250.00
3	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER AND BONNET	New	2,200.00	1,650.00
4	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
5	TO REMOVE AND TRANSFER AIRCOND CONDENSER, RADIATOR ADDITIONAL RADIATOR, ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT VACUUM / REGAS AND TO PRESSURIZE COOLING SYSTEM	New	1,000.00	1,000.00
6	TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION	New	2,400.00	1,500.00
Gross Labour Cost (S\$)			8,852.00	5,952.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >