

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHB 4181D

DATE 21/6/2018 14:37

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			\$ 603.60
	Rear Bumper Reinforcement ?			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket ?			\$ 49.00
	Rear Bumper Clips ✓			\$ 22.00
	Rear Bumper Sponge ?			\$ 143.40
	Rear Bumper Under Cover ✕			\$ 225.00
	<b>SUB TOTAL</b>			<b>\$ 1,907.35</b>
	<b>LESS 20%</b>			<b>\$ 381.47</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 1,525.88</b>
	Rear Bumper Reverse Sensor ✕			\$ 135.70
				<b>\$ 135.70</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ <del>380.00</del> <sup>200</sup>
	Spray Painting Charge			\$ <del>250.00</del> <sup>200</sup>
	Wiring Charge			\$ <del>50.00</del> ✕
	R/Refix Reverse Sensor			\$ <del>120.00</del> <sup>30</sup>
	<b>TOTAL LABOUR</b>			<b>\$ 800.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 2,461.58</b>
<p>1 cal/h (1600)</p> <p>21/6/18 1505hr</p> <p>2 Pys</p> <p>P/P</p> <p>Before Part p/Lh</p>				
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>To resurvey before/after spray painting</li> <li>To display damaged part(s) during resurvey</li> <li>Parts prices are subject to confirmation</li> <li>Third party survey is on a "Without Prejudice" basis</li> <li>No illegal modification(s) is allowed</li> <li>Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p>				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				