



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 12/10/2018

### Survey Details:

Date of loss	19-Jun-18
Date of appointment	21-Jun-18
Date of survey	21-Jun-18
Location of survey	F-1 AUTOCLINIC PTE LTD

### Vehicle Details:

Claim Type:	Third party
Vehicle number	GBG 5781K
Make and Model	TOYOTA HIACE VAN TURBO 5DR MT 2982cc
Date of registration	11/9/2017
Excess	
Market Value (est)	\$70,000.00
Parf Rebate (est)	\$27,000.00
Nett Loss (est)	\$43,000.00

### Repair details:

Initial Estimate	\$ 17,387.93
------------------	--------------

### Proposed/Revised repair cost:

Parts	\$ 4,239.32
Check items (estimate)	\$ -
Labour	\$ 2,090.00
<b>Total</b>	<b>\$ 6,329.32</b>
<b>Lump Sum(if applicable)</b>	<b>\$ 5,000.00</b>

Number of days for repair	<u>7 DAYS</u>
---------------------------	---------------



**Remarks:**

*We have not authorized repairs. We called Insured Driver several times but to no avail. TP provided video footage (uploaded) which shows Insured vehicle had turned too early and TP did not cross the stop line yet when the collision happened. A letter and was sent out to the Insured to notify of TP claim, liability and NCD issue. No feedback from Insured till date. TP LOD IN.*

**Mandate:**

Liability(TP)	100%	
Proposed Repair Cost	\$ 5,000.00	
Loss of Use	\$ -	no. of days
Loss of Rental	\$ 800.00	\$100 x 8 days
Loss of Income	\$ -	no. of days
GIA/LTA search fees (TBC)	\$ -	
Others	\$ -	
<b>Proposed Total</b>	<b>\$ 5,800.00</b>	
***TBC - To Be Confirmed		