

# CRUISE AUTOCARE PTE LTD

## QUOTATION

MS: AIG ASIA PACIFIC INSURANCE PTE. LTD.

TO: CLAIM DEPARTMENT

Fax: 6835 7416

Quotation No: QCA160188

Quote Date: 21-Jun-18

Contact No: 68416760

Fax No: 68413527

Veh No. GBC1783C		Make / Model:	TOYOTA HIACE	
S/N	Description	LIST PRICE	Qty	Amount
<b>PARTS</b>				
1	FRONT HEADLAMP, LH	\$636.00	1	\$636.00 <i>car</i>
2	FRONT BUMPER BRACKET, LH	\$143.20	1	\$143.20 <i>?</i>
3	FRONT BUMPER	\$475.10	1	\$475.10 <i>cut</i>
DISCOUNT GIVEN 25 %				(\$313.58)
<b>SPECIAL NETT ITEM</b>				
1	COMPANY REGISTRATION STICKER	\$20.00	1	\$20.00 <i>am</i>
2	ART WORK ON SLIDING DOOR	\$500.00	1	\$500.00 <i>250</i>
<b>LABOUR</b>				
1	LABOUR TO REMOVE DAMAGED PARTS, ALIGN AND REPLACE PARTS.			<del>\$400.00</del> <i>300</i>
	PANEL BEAT FRONT LH DOOR AND LH SLIDING DOOR			
2	SPRAY PAINTING ON FRONT LH DOOR AND LH SLIDING DOOR			<del>\$600.00</del> <i>500</i>
3	CHECK ELECTRICAL			<del>\$50.00</del> <i>30</i>
LUMP SUM 20% DISCOUNT				(\$502.15)

Sub Total \$2,008.58  
GST @ 7% \$140.60

Total: **\$2,149.18**

Cruise Autocare Pte Ltd.

Signature of Customer



*Rasul*  
*Hp 90010068*

*4 days*  
*4/8*

*22/06/18 @ 1055*

*Resurvey after repair*

*email: rasul@lkkauto.com*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

53 Ubi Avenue 1, Paya Ubi Industrial Park #03-53 Singapore 408934

TEL: 6841 6760 FAX: 6841 3527

Email: cruiseac@singnet.com.sg