

## Vic (LKKAUTO)

---

**From:** Annie Yew <annie.yew@hotmail.com>  
**Sent:** Monday, 16 July, 2018 4:06 PM  
**To:** GERALD POH WEE BIN  
**Cc:** MT\_Claim\_SG; Vic (LKKAUTO)  
**Subject:** Re: ACCIDENT INVOLVING SFA3311G & SHA2506U ALONG MT ELIZABETH LINK ON 21.6.2018 LKK REF CC4/LPC18011384/K1ha3

Gerald,

Can you confirm that my NCD 50% maintain if I renew with Lonpac?

Annie

On 16 Jul 2018, at 15:39, GERALD POH WEE BIN <[geraldpoh@lonpac.com](mailto:geraldpoh@lonpac.com)> wrote:

Hi Annie,

Our surveyor had reverted with their findings (as per email below).

The vehicle was surveyed on 22 June 2018 and we attached the photos (closed up view) taken at the time of the survey for your attention.

The estimate of \$1,234.40 submitted by the workshop had been adjusted to \$100.00 which is recommended by our surveyor for labour only.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** Vic (LKKAUTO) [<mailto:vicalpeh@lkkauto.com>]

**Sent:** Friday, 13 July, 2018 5:05 PM

**To:** GERALD POH WEE BIN

**Cc:** MT\_Claim\_SG; Admin A; Vic (LKKAUTO); Calvin Ang (LKKAUTO)

**Subject:** RE: ACCIDENT INVOLVING SFA3311G & SHA2506U ALONG MT ELIZABETH LINK ON 21.6.2018 LKK REF CC4/LPC18011384/K1ha3

Dear Gerald,

We refer further to our below email.

Please be informed that we confirmed in receipt of the Insured's GIA report and the photos. Insured photos doesn't show any closer view of the TP RH side mirror cover.

Our surveyor after inspection and further review of the damages to TP taxi, is in the view that the damages sustained to the TP vehicle is consistent to the nature of the accident.

Below inspection photos show the damages observed to the TP RH side mirror. A paint chip off with grazing nature damages were observed (circled).

<image002.jpg>

<image004.jpg>

<image008.jpg>

<03072018114519.pdf>

<16072018145634.pdf>