

ASS. SEC. BY:

REF:

CS/EG118011388/U1d322

Special Instruction:

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Yee Pei Li

of

EGI

Date/Time:

22/6/18 @ 2:05pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJZ 1480K

Insured:

SLL 33664

at Workshop m/s

Quande Motor

Tel:

9670 9191

of

1 Kaki Bukit Ave 6 # 01-67

Policy No:

Claim No:

SLL 33664 / SL / p1

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18/06/2018

CA / REV / REP. / REV 24 HRS 'up'

H.O.D. Endorsement:

Date/Time: 2:30pm @ 22/6/18

Person Contacted:

jennifer

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

(✓)

Estimate

SJZ 1480K - X

SLL 33664 - X

26/6

Revert pending estimate.

(08/11/13) wel

ASS RECD BY 170645

REF:

ER11/
ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SJ71Kf06
 at Workshop m/s: Queen St
 of: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Est. or Market Value: 21k.
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: SJ71Kf06 Yr Regn: 5 06
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CA
 Make: Honda Civic or 1799
 Colour: Black A/C: _____ Insured / Std / NI / NA
 Sp. Reading: 154389 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JHMFD16306S 20875-7
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: _____ R: 205/55-R16
 BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal: 5 mm R/Bal: 5 mm
 L/Bal: 5 mm L/Bal: 5 mm
 D.O.A: 8/6/18 D.O.I: 22/6/18
 Survey held at: _____
 Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or
Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction Col 24-5-2021
L7A 13455 2yrs. 11mths. next 7545

21/7/18 2/5 4000 confirmed with Lennor (Red: 7860; 66%)

RECEIVED 24 JUL 2018

Date/Time, File Pass to?

☐ : Preli. Report
☒ : Final Report

1) 23A Typist
 Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

Photos

Others

TOTAL

Report Format: TPLump Sum / I.B.I: (\$ 4000)

350

350

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Friday, 22 June 2018 2:05 PM
To: 'admin-d@lkkauto.com'
Subject: OI : SLL3366U / TP : SJZ1480K/LKK / DOA : 18/06/2018
Attachments: SJZ1480K - PRS FORM.pdf

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **QUANDE MOTOR TRADING**,

ADDRESS : 1 KAKI BUKIT AVENUE 6
#01-67 AUTOBAY
SINGAPORE 417883

PERSON TO CONTACT : MS JENNIFER @ 9670 9191

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on WITHOUT PREJUDICE basis. Obtain estimate and please advise the consistency of damages to third party vehicle and Inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 22.06.2018
 Our Reference: SLL 3366U/SL/pl
 Your Reference: SJZ 1480K
 To: QUAN DE MOTOR TRADING

Sent via Fax

or

Email

quanv3@yahoo.com.sg

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SJZ 1480K
 Insured's Vehicle: SLL 3366U
 Date Of Accident: 18.06.2018


We acknowledge receipt of your request for PRS on: 21.06.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LBS Auto Consultants Pte Ltd

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
IPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☒ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☒ Your request for inspection does not have your client's GIA report, kindly forward a copy.
☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☒ Our insured's driver has not reported the accident to us to date.
☒ Others: OFFICER-IN-CHARGE - STEVE LIM

Prepared by:		Pei Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
 Assignment Time: _____

Remarks:

Workshop use only:**Assessor attended workshop on:**

Date: _____
 Time: _____
 Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job.



Workshop Acknowledgement & Stamp.

Note: Our inspection is on a without admission to liability basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/06/2018 05:30
Date Of Accident	18/06/2018 23:35
Exact Location Of Accident	JUNCTION OF WOODLANDS AVE 1 AND AVE 2 TOWARDS SLE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJZ1480K
Insured/Policyholder	
Name Of Registered Owner	EAZI CAR LEASING & MARKETING PTE LTD
Co Reg No	200715161E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66840761

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	DMCSHQ18-000035
Cover Note Number	N.A.

Driver

Name of Driver	MUHAMMAD YASIN BIN KOMARI
NRIC No	S8436503C
Date Of Birth	09/11/1984
Occupation	INDOOR
Date Of Driving Pass	27/06/2016
Driving Experience	1 YEAR AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97939769
Fax Number	
Contact Number	OFFICE-97939769
Email Address	URI_BOYKA@ROCKETMAIL.COM

Address	BLK 484 SEGAR ROAD #02-330
Postcode	670484
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON THE DATE AND TIME MENTIONED I WAS WAITING FOR THE RED LIGHT TO TURN GREEN WHEN MY VEHICLE WAS HIT FROM THE REAR BY VEHICLE B. MY VEHICLE WAS STATIONARY WHEN IT WAS HIT. NO BODY WAS INJURED. STATEMENT WAS READ TO ME AND I ACKNOWLEDGED IT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL3366U
Vehicle Make/Model/Colour	VOLVO/S80 T4 1.6 AT/BLA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	HENG SU SAN
NRIC/Passport Number	S8202069A
Contact Number	94748831
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

ACCIDENT STATEMENT (2000 characters)

ON THE DATE AND TIME MENTIONED I WAS WAITING FOR THE RED LIGHT TO TURN GREEN WHEN MY VEHICLE WAS HIT FROM THE REAR BY VEHICLE B. MY VEHICLE WAS STATIONARY WHEN IT WAS HIT. NO BODY WAS INJURED. STATEMENT WAS READ TO ME AND I ACKNOWLEDGED IT.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
HASHIM BIN KAMARI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

21 June 2018 at 12:35 PM

Date/Time:

21 June 2018 at 12:36 PM

Sketch Plan

SKETCH PLAN

NOTICE

Directly the details of the accident to speed up the claims process.
 be completed by the Policyholder and/or the Authorised Driver.
 ed must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may
 companies to repudiate policy liability.
 acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
 ding may be referred to the Police for investigation.
 e forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
 A) for archiving and that copies of this report will for a fee be made available application by interested parties.
 t of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report
 able aforesaid.

the Personal Data Protection Act (PDPA)

knowledge, agree and consent that:

ly workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or
 onal data/personal information set out in this [form] and any other personal information provided by me or possessed by
 ively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured
 id in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the
 insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as
 e purpose(s) of:

handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to

the accident and/or my claims.

and/or dealing with my instructions or responding to any enquiries by me.

g my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve
 certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail

and/or

in applicable law is administering, processing, handling and/or dealing with my claims.

the "Purposes")

to have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use,

process my Personal Information for one or more of the above Purposes; and

formation may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents
 (lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

VERIFIED BY AJAX MARS

REPORTING OFFICER


Hashim Kamari

Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre
 Personnel

21/06/18.





Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5161E
Vehicle Details	
Vehicle No.:	SJZ1480K
Vehicle to be Exported:	No
Intended De-registration Date:	22 Jun 2018
Vehicle Make:	HONDA
Vehicle Model:	CIVIC 1.8L A
Primary Colour:	Blue
Manufacturing Year:	2006
Engine No.:	R18A11028290
Chassis No.:	JHMF16306S208757
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$21,153.00
Original Registration Date:	25 May 2006
First Registration Date:	25 May 2006
Transfer Count:	3
Actual ARF Paid:	\$23,269.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	24 May 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$23,024.00
COE Rebate Amount:	\$13,455.00
Total Rebate Amount:	\$13,455.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 22 Jun 2018

OK

sgCarMart.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

The continuing GLOBAL stressful thread! Part II

AIM (Acronym In MCF)

Where to buy cheap and good engine oil? Any Brand or P...

Honda Civic

Price Range

Depreciation

> 10 year

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Royal Kars » Honda Civic 1.8A (COE till 07/2021)

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Tyres

MICHELIN PILOT SPORT 4

AS RESPONSIVE AS YOU ARE

Trade Online

Start with \$30 Trading Bonus*

Trade Forex and CFDs on

Indices

Gold

Oil

Stocks

Read More

*T&Cs apply. Forex and CFD trading is high risk and can result in the loss of all your invested capital.

USAIN BOLT OFFICIAL SPONSOR

Honda Civic 1.8A (COE till 07/2021)

Overview

Financial

Accessories

Similar

Research

Photos

Map

PREMIUM AD

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price

\$24,800

Depreciation

\$7,980 /yr

Reg Date

11-Dec-2006

(3yrs 1mth 9days COE left)

Manufactured

2006

Mileage

-

Transmission

Auto

Engine Cap

1,799 cc

Road Tax

\$1,174 /yr

Power

103.0 kW (138 bhp)

View specs of the Honda Civic (2006-2012)

Curb Weight

1,219 kg

Features

17" Wedsport SA70 Offset +42/43 Rim And Tyre.
Brand New Crystal Blue Paint Job. IRoad V9S2 Car Camera. Hayden Rapid Cool 678 ATF Cooler.

Accessories

15 Step Adjustable Absorbers. Hardrace Rear Adjustable Camber Arms. Carbonetics High Temperature Performance Brakes With 330mm Front Rotors.

Description

New Engine Mountings. New Front Lower Arms. Changed Gearbox Oil Seals, Engine Gasket, Brake Fluid, Coolant, New Headlights. Well Maintained By Previous Owner! 100% Accident Free. Fuel Economical. Call Us Now To Arrange For Viewing Before Its Gone!

COE

\$25,815

OMV

\$20,324

ARF

\$22,357

Dereg Value

\$16,055 as of today (change)

No. of Owners

3

Type of Veh

Mid-Sized Sedan

Category

COE Car, Premium Ad Car

Availability

Available

PREMIUM AD

Add to Shortlist

Add to Compare

Add a Note

Posted on: 20-Jun-2018

Last Updated on: 21-Jun-2018

Tags: Honda Civic, 2006 Honda Civic, Honda, Civic, Used Honda

Seller Information

Company

Royal Kars

» dealer's pricelist

» 0 vehs sold | 8 vehs available

Address

11 Teck Whye Lane

Search cars nearby this location

Office No

92715723

Contact Person(s)

Jeevan

92715723

Useful Services

STA VEHICLE INSPECTION

Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation

Find out the market value for your car. Get a free Car Valuation.

Free Valuation

Upfront Payment

» more Financial Info

http://www.sgcarmart.com/used_cars/info.php?ID=748007&DL=3408

22-Jun-18

QUAN DE MOTOR TRADING

1 KAKI BUKIT AVENUE 6, #01-67
 AUTOBAY, SINGAPORE 417883
 HP: 96709191 FAX: 66840767

Ergo Insurance Pte Ltd
 5 Temasek Boulevard
 #04-01 Suntec Tower 5
 Singapore 038985

Attn: Motor Claims Department

Date: 21 June 2018

Accident on 18/06/2018 Involving vehicles SJZ1480K & SLL3366U
at junction of Woodlands Avenue 1 & Avenue 2 towards SLE
Estimate cost of repair to vehicle SJZ1480K Honda Civic

1 pc.	rear bumper	mp/pe	\$	638.00	—
2 pcs.	rear bumper side retainers @\$20.50	but	\$	41.00	—
1 set	rear bumper clips	per	\$	45.00	—
1 pc.	bootlid	sub/so	\$	610.00	—
1 pc.	bootlid rear logo	ru	\$	28.80	—
1 pc.	bootlid "CIVIC" emblem	ru	\$	32.20	—
1 pc.	bootlid "IVTEC" emblem	ru	\$	36.50	—
2 pcs.	bootlid reflectors @\$248.20	o/s cre	\$	496.40	rac
1 pc.	bootlid inner lock	twi	\$	198.60	—
1 pc.	bootlid weatherstrip	twi	\$	101.00	—
1 pc.	bootlid inner trim	11	\$	282.30	x
2 pcs.	bootlid hinges @\$148.60	n	\$	297.20	x
2 pcs.	taillamps @\$282.50	cm	\$	565.00	—
2 pcs.	taillamp housing panel @\$167.70	n	\$	335.40	x
1 pc.	rear end panel	306/yo	\$	296.60	—
1 pc.	rear end panel top garnish	twi	\$	160.80	—
1 pc.	rear floor panel	n	\$	911.40	x
1 pc.	rear floor panel top board	merged/pe	\$	316.00	—
2 pcs.	rear fenders @\$741.50	n	\$	1,483.00	x
2 pcs.	rear fender inner trims @\$242.80	11	\$	485.60	x
1 pc.	rear exhaust	11	\$	494.00	x
2 pcs.	rear exhaust mountings @\$36.00	11	\$	72.00	x
1 pc.	rear splash shield	11	\$	42.50	x
1 pc.	rear windscreen moulding	11	\$	68.20	x
			\$	8,037.50	
		Less 20%	\$	1,607.50	
			\$	6,430.00	

3317.7
 2654.16

not allowed
 1/5 = 4000
 5 day.
 22/6/18
 take photo after repair

Bal c/f \$ 6,430.00

S.Nett Items:

1 set	rear bumper reverse sensor	should	\$	300.00	200
1 pc.	rear end panel sealant	neu	\$	100.00	50
1 pc.	rear license plate w/holder	11	\$	50.00	X
1 set	rear floor panel Insulator	11	\$	300.00	X
1 pc.	rear windscreen sealant	11	\$	60.00	X

Labour Charges:

To check wiring	\$	80.00	30
To remove & refix reverse sensor	\$	100.00	50
To remove & refix seat & cushion upholstery	\$	150.00	80
To remove & refix rear exhaust	11 \$	120.00	X
To remove & reinstall rear windscreen	11 \$	150.00	X
To remove & refix petrol tank	11 \$	120.00	X
To transfer bootlid components	\$	100.00	60
To spray rust proofing	\$	200.00	80
Labour for panel beating, welding & renew parts	\$	2,000.00	800
To putty & spray painting	\$	1,600.00	1000

Total: \$ 11,860.00

5004.10

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD			Ref : CS/EGI18011388/Utd3e2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985			Date : 02-08-2018	
			Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLL 3366U	Veh. Inspected	SJZ 1480K	
Policy No.		Coverage (\$)	0.00	
Claim No.	SLL3366U/SL/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	22/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC (A)	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2006	
Chassis No.	JHMF16306S208757	Colour	BLACK	
Odometer	154389	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	DUNLOP	5 mm	
L/H Front Tyre	205/55 R16	DUNLOP	5 mm	
R/H Rear Tyre	205/55 R16	DUNLOP	5 mm	
L/H Rear Tyre	205/55 R16	DUNLOP	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/06/2018	Inspection Date	22/06/2018	
Survey held at	QUAN DE MOTOR TRADING BLK 1 KAKI BUKIT AVENUE 6 #01-67 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJZ 1480K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DENTED / DEFORMED	638.00	638.00
2	REAR BUMPER SIDE RETAINERS @\$20.50	BENT	41.00	41.00
1	SET REAR BUMPER CLIPS	NECESSARY	45.00	45.00
1	BOOTLID	BADLY DENTED	610.00	610.00
1	BOOTLID REAR LOGO	NECESSARY	28.80	28.80
1	BOOTLID "CIVIC" EMBLEM	NECESSARY	32.20	32.20
1	BOOTLID "IVTEC" EMBLEM	NECESSARY	36.50	36.50
2	BOOTLID REFLECTORS @\$248.20	O/S CRACKED	496.40	248.20
1	BOOTLID INNER LOCK	TWISTED	198.60	198.60
1	BOOTLID WEATHERSTRIP	TWISTED	101.00	101.00
1	BOOTLID INNER TRIM	NOT NECESSARY	282.30	-
2	BOOTLID HINGES @\$148.60	TO REPAIR SEE LABOUR	297.20	-
2	TAILLAMPS @\$282.50	CRACKED	565.00	565.00
2	TAILLAMP HOUSING PANEL @\$167.70	TO REPAIR SEE LABOUR	335.40	-
1	REAR END PANEL	BADLY DENTED	296.60	296.60
1	REAR END PANEL TOP GARNISH	TWISTED	160.80	160.80
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	911.40	-
1	REAR FLOOR PANEL TOP BOARD	WARPED / DEFORMED	316.00	316.00
2	REAR FENDERS @\$741.50	TO REPAIR SEE LABOUR	1,483.00	-
2	REAR FENDER INNER TRIMS @\$242.80	NOT NECESSARY	485.60	-
1	REAR EXHAUST	NOT NECESSARY	494.00	-
2	REAR EXHAUST MOUNTINGS @\$36.00	NOT NECESSARY	72.00	-
1	REAR SPLASH SHIELD	NOT NECESSARY	42.50	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	68.20	-
	LESS 20% DISCOUNT		-1,607.50	-663.54
			6,430.00	2,654.16

Report Ref No. CS/EG18011388/Utd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	300.00	200.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	100.00	50.00
1	REAR LICENCE PLATE W/HOLDER (SN)	NOT NECESSARY	50.00	-
1	SET REAR FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	300.00	-
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	60.00	-
			810.00	250.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		80.00	30.00
	TO REMOVE & REFIX REVERSE SENSOR.		100.00	50.00
	TO REMOVE & REFIX SEAT & CUSHION UPHOLSTERY.		150.00	80.00
	TO REMOVE & REFIX REAR EXHAUST.	NOT NECESSARY	120.00	-
	TO REMOVE & REINSTALL REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	TO REMOVE & REFIX PETROL TANK.	NOT NECESSARY	120.00	-
	TO TRANSFER BOOTLID COMPONENTS.		100.00	60.00
	TO SPRAY RUST PROOFING.		200.00	80.00
	LABOUR FOR PANEL BEATING, WELDING & RENEW PARTS. INCLUSIVE OF THE REPAIR OF BOOTLID HINGES, TAILLAMP HOUSING PANEL, REAR FLOOR PANEL AND REAR FENDERS.		2,000.00	800.00
	TO PUTTY & SPRAY PAINTING.		1,600.00	1,000.00
			4,620.00	2,100.00
GRAND TOTAL			11,860.00	5,004.16
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,000.00

Report Ref No. CS/EG18011388/Utd3e2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.