

MAXIMUS RACING PTE LTD

MR Performance Centre. No.7 Soon Lee Street, #05-05, Singapore 627608.

Enquiry Hotline : +65 62501198 / Fax : +65 62501081

Company Registration No. : 200507694R

**ESTIMATION FOR SLT366Y**

Reference No: Q-18-091

Requested By: AXA Insurance Pte Ltd

Date: 23/6/2018

Email: clams.windscreen@axa.com.sg

Terms: Cash

Address: 8, Shenton Way, #24-01, AXA Tower, Singapore, 068811

Item	Description	Qty	Unit Price	Disc %	Total Price
	Policy No // Accident Date: 1700070146 // 19/06/2018 Drive In: 20/06/2018 Vehicle Make/Model: Citroen Grand C4 Picasso 1.6 BlueHDI Vehicle Number: SLT 366 Y Manufacturing Year: 2017 Engine: 10JBHD3085580 Chassis No: VF73ABHZTHJ747765				
	<u>Labour Charges:</u>				
1	Remove and renew damaged parts, straighten and realign affected areas				\$ 800.00 300
2	Respray Affected Areas.				\$ 900.00 400
3	To Apply Cavity Wax Coating On Affected Areas				\$ 400.00 X
4	Labour To Check Front Lightings, Focus Headlamp And Water Leakage				\$ 120.00 30
5	Computerised 4Wheel Alignment				\$ 130.00 60
6	General Diagnostics to Reset, Re-calibrate using Citroen Original Software				\$ 500.00 80
	<u>Material & Fluid Charges:</u>				
1	Front Bumper				
2	Front Bumper Tow Hook Cover	1	\$ 1,680.00	10%	\$ 1,512.00 SR-
3	Front Bumper Lower Center Grill	1	\$ 45.00	10%	\$ 40.50 X
4	Front Bumper Top Grill	1	\$ 350.00	10%	\$ 315.00 X
5	Front Bumper Citroen Logo - Chrome	2	\$ 280.00	10%	\$ 252.00 X
6	Front Bumper Upper Panel Cover	1	\$ 220.00	10%	\$ 396.00 X
7	Front Bumper Side Bracket - Right	1	\$ 360.00	10%	\$ 324.00 X
8	Headlight - Right	1	\$ 98.00	10%	\$ 88.20
10	Fog Light - Right	1	\$ 990.00	10%	\$ 891.00
11	Fog Light Cover - Right	1	\$ 150.00	10%	\$ 135.00
12	Fog Light Chrome - Right	1	\$ 160.00	10%	\$ 144.00
13	Front Side Fender - Right	1	\$ 300.00	10%	\$ 270.00
14	Front Fender Splash Cover - Right	1	\$ 490.00	10%	\$ 441.00
		1	\$ 195.00	10%	\$ 175.50
PRICE BEFORE GST					\$ 7,834.20
ADD GST 7%					\$ 548.39
Grand Total:					\$ 8,382.59

Validity of the estimates is 2 weeks based from the date of quote. Estimated costs quoted are excluding GST. We would mention based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you.

Please be informed that a deposit of 50% of full amount is payable before commencement of work.

Authorised By: