

INS. CASE OWNER:

CC 6, Lpc 180

11404, Uha3n2

LKK:

IDAC:

ASSIGNMENT

Surveyor:

DOI:

Date:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

28/6

STV07557 X; YP 81026 X

02/08/18

FILE REVIEWED. OLD REPORTED RATE UNDER

TP.

EMAIL LIABILITY CLERK.

PENDING.

ORIGINAL TP LOP IN.

02/08/18

TYPE REPORT FOR WANDATE APPROVAL

REPORT CONT.

16/10/18

SEND WANDATE APPROVAL TO Lpc BY EMAIL.

LPC APPROVED WANDATE

SEND ACCEPTANCE EMAIL TO TP.

13/11/18

OHA. DV IN. ALL DOCUMENTS IN ORDER.

TO CLOSE.

RECEIVED 13 NOV 2018

PRELIMINARY ADVICE

Date/Time:

02/08/18

Sent By:

VIC

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$ 8,700.00

(6 days)

Reduction:

53 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

15/11/18

Confirm with:

NANCY

Email ☐ Call ☐

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

24

If NO or B 28, Ass. Lia:

Repair Cost: (w/ass)

S\$ 9,309.00

Loss of Rental (LOR):

S\$ 600.00

(6 days)

X \$100.00

Loss of Use (LOU):

S\$ —

(\$ x days)

Loss of Income (LOI):

S\$ —

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$ 200

Medical:

S\$ —

Disbursement:

S\$ —

(e.g. Tow/ Independent)

Legal Cost

S\$ —

Total:

S\$ 9,911.00

Global Sum S\$:

—

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$ 9,911.00

Name 1:

PASTECH AUTO PTB LTD

Payee 2: (Strike if N.A.)

S\$ —

Name 2:

—

Payee 3: (Strike if N.A.)

S\$ —

Name 3:

—

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$450.00

COPY SENT 13/11/18

ASS REC BY: *ADW/ELI*

REF:

LPC/

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
GD / TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: *5 JV 87557*
at Workshop n/s: *Ll.*
of: _____
Insured: *1/28/026*
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: *5 JV 87557* Yr Reg: *2 10*
Type: *CA/* M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: *Volkswagen Tiguan* 1984
Colour: *white* Insured / Std / NI / NA
Sp. Reading: *95647* T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: *WVG 6222 EN EAW 051970*
Gen. Cond: *Good* / Fair / Poor / Burnt
Steering: *Good* / Jammed / Leaked / Burnt or
Brake: *Good* / Jammed / Leaked / Burnt or
Mod: *Nil* / S/Rim / STD A/Rim or

Tyre Size: F: _____ R: *235/55-R17*
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front	Rear
R/Bal. <i>7</i> mm	R/Bal. <i>7</i> mm
L/Bal. <i>7</i> mm	L/Bal. <i>7</i> mm
D.O.A. <i>22/6/18</i>	D.O.A. <i>22/6/18</i>

Survey held at: _____
Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: *30*
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: *6* days Res.: Yes or No
Lum. Sum: *20* % 3 Val.: Yes or No
CA / REV / REP. / 24 HRS *11/2/020*
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
	<i>47A 16666 1yrs. 7mths. have left</i>
<i>6/7/18</i>	<i>confirmed L/S @ \$700 with Aler.</i>
	<i>(REV: \$9,706.82/53%)</i>

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Date/Time, File Return to?

2/

Add Fee: ☐ : Site Insp (\$)
☐ : Interview (\$)
☐ : Tech. Invs (\$)
☐ : Weekend (\$)

Survey Fee

Transportation:

\$ - RS. \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 18/18/18/VC05/020697
Our ref: CC6/LPC18011404/Uha3

Date: 02.08.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SJV 8755T


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 22.06.2018 at the premises of M/s FASTECH AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$	18,406.82
Revised Estimate Amount	: S\$	10,922.64
"Check" Items Amount	: S\$	-
Market Value	: S\$	30,000.00
LTA Reimbursement Value	: S\$	16,666.00
Nett Value	: S\$	13,334.00

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 6 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

Mei Kwan (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Wednesday, 27 June, 2018 9:31 AM
To: Mei Kwan (LKKAUTO)
Cc: MT_Claim_SG
Subject: RE: Direct Settlement - Accident Involving YP8102G (OI : LPC - TBA) and SJV8755T (TP : LKK REF - CC6/LPC18011404/Uha3) on 22.06.2018
Attachments: 27062018092550.pdf
Categories: HMK

Our Ref : 18/18/18/VC05/020697

Dear Mei Kwan,

Attached copy of insured's GIA report for your attention.

The premium for the policy has been settled.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Wednesday, 27 June, 2018 8:37 AM
To: MT_Claim_SG
Cc: GERALD POH WEE BIN; ERIC WOO JUN KIAT; ONG LI LI; Vic (LKKAUTO); Hsiao Tong (LKKAUTO); Admin A
Subject: RE: Direct Settlement - Accident Involving YP8102G (OI : LPC - TBA) and SJV8755T (TP : LKK REF - CC6/LPC18011404/Uha3) on 22.06.2018

Dear Sir / Madam,

We refer to the above matter.

Kindly assist to verify validity of our insured's policy, and let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

Mei Kwan | Admin


LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAUTO)
Sent: Monday, 25 June, 2018 7:14 PM
To: 'MT_Claim_SG' <mt_claim@lonpac.com>
Cc: 'GERALD POH WEE BIN' <geraldpoh@lonpac.com>; 'ERIC WOO JUN KIAT' <ericwoo@lonpac.com>; ONG LI LI <long@lonpac.com>; Vic (LKKAUTO) <vicalpeh@lkkauto.com>; Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>; Admin A <admin-a@lkkauto.com>

SINGAPORE ACCIDENT STATEMENT



IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 22/06/2018 15:30
Date Of Accident 22/06/2018 13:30
Exact Location Of Accident SLIP ROAD OF CTE TOWARDS PIE CHANGI AIRPORT
Country/State Of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number YP8102G
Insured/Policyholder
Name Of Registered Owner GREEN EARTH COMMODITY PTE LTD
Co Reg No 201216726Z
Email Address SUNIL.KUMAR@GREENEARTH.SG
Mobile Phone No
Alternative Phone No OFFICE-67472377

Vehicle Particulars

Manufacturer ISUZU
Model NPR85LU4Y-3.0 D (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken REPORTING ONLY
Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company LONPAC INSURANCE BHD
Type Of Coverage THIRD PARTY FIRE AND/OR THEFT
Fleet Policy NO
Policy Number Z18VC05000051
Cover Note Number

Driver

Name of Driver HARDEEP SINGH
Passport No/FIN G0825214P
Date Of Birth 08/05/1984
Occupation INDOOR
Date Of Driving Pass 25/04/2014
Driving Experience 4 YEARS AND 1 MONTH
Gender MALE
Mobile Number (LOCAL) +65-90984209
Fax Number
Contact Number
Email Address NOEMAIL

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



Inchcape
Pre-Owned

**WIDE RANGE OF PRE-OWNED
TOYOTA AND OTHER MAKES
AVAILABLE**

VISIT OUR NEW SHOWROOM FOR A PREMIUM PRE-OWNED EXPERIENCE @ 2 PANDAN CRES

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

See My Depreciation.



Priced To Sell.
Direct Owner Starts

ABWIN



Post an Ad

Advertiser Login

Ways of Selling

Browse by Category

Sort by

Advanced

4 vehicles

Volkswagen Tiguan

Search Selection

Volkswagen Tiguan



Volkswagen Tiguan 2.0A TSI

\$37,800

\$11,080 /yr

21-Sep-2010

1,984 cc

82

The Best 2010 Years Unit In Town, Fully Maintenance And Servicing History Since Day 1 With Low Mileage Done At 1050
Free, Flexible Loan Available. Sporty Black On Flawless Inte...

Sng Auto Trading

Posted: 22-Jun-2018 Tags: 2010 Volkswagen Tiguan, Volkswagen Tiguan, Volkswagen, Tiguan, Used Volkswagen



Volkswagen Tiguan 2.0A TSI

\$34,888

\$10,560 /yr

23-Jul-2010

1,984 cc

\$0 Drive Away, Don't Miss It, Call Now For More Details.

Posted: 18-May-2018 Tags: 2010 Volkswagen Tiguan, Volkswagen Tiguan, Volkswagen, Tiguan, Used Volkswagen



Volkswagen Tiguan 2.0A TSI

\$30,800

\$11,400 /yr

26-Jan-2010

1,984 cc

Major Wear And Tear Replaced Such As Shock Absorber, Water Pump And Belting Set, Timing Chain Set And Coolant Pip
Oil Every 5000km And Transmission Oil Every 25000km. Warra...

Posted: 28-Apr-2018 Tags: 2010 Volkswagen Tiguan, Volkswagen Tiguan, Volkswagen, Tiguan, Used Volkswagen



Volkswagen Tiguan 2.0A TSI

\$37,500

\$10,420 /yr

03-Nov-2010

1,984 cc

15

Spacious And Practical Family MPV. Well Maintained. 100% Accident Free. Under Consignment, Please Call For Viewing

Car Lingual

Posted: 23-Apr-2018 Tags: 2010 Volkswagen Tiguan, Volkswagen Tiguan, Volkswagen, Tiguan, Used Volkswagen

Save this search criteria, to get email alerts whenever a match is found.

Model

Price

Depreciation

Reg Date

Eng Cap

For Compare

ed ads

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4868H
Vehicle Details	
Vehicle No.:	SJV8755T
Vehicle to be Exported:	No
Intended De-registration Date:	22 Jun 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	TIGUAN 2.0T AUTO 5N12T3 4WD
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	CAW080961
Chassis No.:	WVGZZZ5NZAW051970
Maximum Power Output:	125.0 kW (167 bhp)
Open Market Value:	\$24,949.00
Original Registration Date:	11 Feb 2010
First Registration Date:	11 Feb 2010
Transfer Count:	2
Actual ARF Paid:	\$24,949.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Feb 2020
PARF Rebate Amount:	\$13,721.00
Intended COE Rebate Details	
COE Expiry Date:	10 Feb 2020
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$18,002.00
COE Rebate Amount:	\$2,945.00
Total Rebate Amount:	\$16,666.00

The information contained herein is correct as at 22 Jun 2018

OK

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6
#01-46/48/50 Autobay
SINGAPORE 417883

VEHCILE NO:SJV 8755T

not before
1/5 8700
6/1/18
22/6/18

QTY	PARTICULAR	AMOUNT
1 PCS	REAR WINDSCREEN MOULDING	per \$115.10
1 PCS	TAILGATE 1645.32	sub \$1,866.20
1 PCS	TAILGATE REAR LOGO	per \$68.00
1 PCS	TAILGATE 'TIGUAN' EMBLEM	per \$52.30
1 PCS	TAILGATE '2.0' LOGO	per \$48.00
1 PCS	TAILGATE 'TSI' EMBLEM	per \$49.50
1 PCS	TAILGATE REAR WIPERARM	11 \$118.30 X
1 PCS	TAILGATE REAR WIPER MOTOR	11 \$485.20 X
2 PCS	TAILGATE REFLECTORS @\$385.22	one \$770.44
1 PCS	TAILGATE INNER LOCK	two \$266.50
1 PCS	TAILGATE WEATHERSTRIP	two \$295.30
1 PCS	TAILGATE INNER TRIM BOARD 342.10	per/one \$366.20
1 SET	TAILGATE INNER TRIM BOARD CLIPS	per \$50.00
1 PCS	TAILGATE LICENCE PLATE LAMP GARNISH	one \$125.30
1 PCS	REAR BUMPER 1209.62	7.5 \$1,345.62
1 PCS	REAR BUMPER LOWER 462.12	7.5 \$466.12
2 PCS	REAR BUMPER REFLECTORS @\$82.05	one \$164.10
2 PCS	REAR BUMPER SIDE RETAINERS @\$66.50	sub \$133.00
1 SET	REAR BUMPER CLIPS	per \$50.00
1 PCS	REAR BUMPER REVERSE SENSORS WIRE	11 \$248.20 X
1 PCS	REAR END PANEL OUTER	sub \$685.30
1 PCS	REAR END PANEL INNER	per \$350.10 X
1 PCS	REAR END PANEL INNER TRIM	two \$199.23
1 PCS	REAR FLOOR PANEL	per \$1,042.50 X
1 PCS	REAR FLOOR PANEL TOP BOARD	11 \$662.30 X
1 PCS	REAR FLOOR PANEL TOOLS SPONGE	7.5 \$482.12
1 PCS	REAR BUMPER REINFORCEMENT	sub \$520.35
2 PCS	TAILLAMPS @\$466.12	one \$932.24
2 PCS	REAR FENDER INNER TRIMS @\$411.50	11 \$823.00 X
1 PCS	REAR EXHAUST	per \$1,220.30 X
2 PCS	REAR EXHAUST MOUNTING @\$38.00	11 \$76.00 X
		\$14,076.82

S.NETT

57

866584
823264

1 SET	REAR BUMPER REVERSE SENSOR	shub	\$280.00	200
1 PCS	REAR LICENSE PLATE W/HOLDER	sent	\$50.00	40
1 PCS	REAR END PANEL SEALANT	neu	\$50.00	✓
1 PCS	REAR WINDSCREEN SEALANT	neu	\$50.00	40

LABOUR CHARGES:

TO CHECK WIRING	\$80.00	30
TO DISMENTLE & REPLACING REVERSE SENSOR	\$100.00	50
TO DISMENTLE & REFIX REAR WINDSCREEN	\$150.00	20
TO DISMENTLE & REFIX REAR EXHAUST	\$100.00	60
TO DISMENTLE & REFIX SEAT, CUSHION UPHOLSTERY	\$150.00	80
TO DISMENTLE & REFIX PETROL TANK	11 \$100.00	X
TO TRANSFER TAILGATE MECHANISM	\$100.00	60
TO SPRAY RUST PROOFING	\$120.00	60
LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN	\$1,500.00	800
& REPLACING PARTS		
TO PUTTY & SPRAY PAINTING	\$1,500.00	1100

TOTAL \$18,406.82

10922.64

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC6/LPC18011404/Uha3n2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 14-11-2018



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YP 8102G	Veh. Inspected	SJV 8755T
Policy No.	Z18VC05000051	Coverage (\$)	0.00
Claim No.	18/18/18/VC05/020697	Excess (\$)	0.00
Assign From		Assign Date	22/06/2018

2. Vehicle Particulars & Condition

Make & Model	VOLKSWAGEN TIGUAN (A)	c.c	1984
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WVGZZZ5NZAW051970	Colour	WHITE
Odometer	95647	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/55 R17	BRIDGESTONE	7 mm
L/H Front Tyre	235/55 R17	BRIDGESTONE	7 mm
R/H Rear Tyre	235/55 R17	BRIDGESTONE	7 mm
L/H Rear Tyre	235/55 R17	BRIDGESTONE	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/06/2018	Inspection Date	22/06/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 8755T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR WINDSCREEN MOULDING	NECESSARY	115.10	115.10
1	TAILGATE	BADLY DENTED	1,866.20	1,645.32
1	TAILGATE REAR LOGO	NECESSARY	68.00	68.00
1	TAILGATE 'TIGUAN' EMBLEM	NECESSARY	52.30	52.30
1	TAILGATE '2.0' LOGO	NECESSARY	48.00	48.00
1	TAILGATE 'TSI' EMBLEM	NECESSARY	49.50	49.50
1	TAILGATE REAR WIPERARM	NOT NECESSARY	118.30	-
1	TAILGATE REAR WIPER MOTOR	NOT NECESSARY	485.20	-
2	TAILGATE REFLECTORS @\$385.22	CRACKED	770.44	770.44
1	TAILGATE INNER LOCK	TWISTED	266.50	266.50
1	TAILGATE WEATHERSTRIP	TWISTED	295.30	295.30
1	TAILGATE INNER TRIM BOARD	DEFORMED / CRACKED	366.20	342.10
1	SET TAILGATE INNER TRIM BOARD CLIPS	NECESSARY	50.00	50.00
1	TAILGATE LICENCE PLATE LAMP GARNISH	CRACKED	125.30	125.30
1	REAR BUMPER	DISTORTED	1,345.62	1,209.62
1	REAR BUMPER LOWER	DISTORTED	466.12	466.12
2	REAR BUMPER REFLECTORS @\$82.05	CRACKED	164.10	164.10
2	REAR BUMPER SIDE RETAINERS @\$66.50	BENT	133.00	133.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
1	REAR BUMPER REVERSE SENSORS WIRE	NOT NECESSARY	248.20	-
1	REAR END PANEL OUTER	BADLY DENTED	685.30	685.30
1	REAR END PANEL INNER	TO REPAIR SEE LABOUR	350.10	-
1	REAR END PANEL INNER TRIM	TWISTED	199.23	199.23
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,042.50	-
1	REAR FLOOR PANEL TOP BOARD	NOT NECESSARY	662.30	-
1	REAR FLOOR PANEL TOOLS SPONGE	TORN	482.12	482.12
1	REAR BUMPER REINFORCEMENT	BENT	520.35	520.35
2	TAILLAMPS @\$466.12	CRACKED	932.24	932.24
2	REAR FENDER INNER TRIMS @\$411.50	NOT NECESSARY	823.00	-

Report Ref No. CC6/LPC18011404/Uha3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST	TO REPAIR SEE LABOUR	1,220.30	-
2	REAR EXHAUST MOUNTING @\$38.00	NOT NECESSARY	76.00	-
	LESS 5% DISCOUNT		-	-433.50
			14,076.82	8,236.44
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR LICENCE PLATE W/HOLDER (SN)	BENT	50.00	40.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
			430.00	330.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACING REVERSE SENSOR.		100.00	50.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.		150.00	120.00
	TO DISMANTLE & REFIX REAR EXHAUST.		100.00	60.00
	TO DISMANTLE & REFIX SEAT CUSHION UPHOLSTERY.		150.00	80.00
	TO DISMANTLE & REFIX PETROL TANK.	NOT NECESSARY	100.00	-
	TO TRANSFER TAILGATE MECHANISM.		100.00	60.00
	TO SPRAY RUST PROOFING.		120.00	60.00
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS, INCLUSIVE OF THE REPAIR OF REAR END PANEL INNER, REAR FLOOR PANEL AND REAR EXHAUST.		1,500.00	800.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	1,100.00
			3,900.00	2,360.00
	GRAND TOTAL		18,406.82	10,926.44
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				8,700.00

Report Ref No. CC6/LPC18011404/Uha3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.