

PDI TUAS

PDI TUAS

GOH KIAN HUAT
121 BUKIT BATOK CENTRAL
#04-449
Singapore, 650121
Singapore

Tanpin 97445749
WP
20/6/18 21515
Resurvey before paint
sure @ lkkauto.com
03 days

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV031089
Quote No. SER/QUO/1800995
QuoteDate 22/06/18
Salesperson Lawrence Tan Say Chuan
Page 1

THIS IS NOT AN OFFICIAL TAX INVOICE

| Make | Model Description | Mileage | Service Advisor |
|--------------------|------------------------------|----------------------|------------------------|
| Volkswagen Passeng | GOLF A7 1.2 TSI TL BMT (DSG) | 37,631 | Kong Charmaine |
| License No. | VIN | Initial Registration | Sales Advisor |
| SGF8034K | WVWZZZAUZFW282894 | 29/09/15 | Lawrence Tan Say Chuan |
| Engine Code | Labor Type | Engine No. | Model Code |
| 1T | | CJZ 602825 | 5G12DZ |

| No. | Description | Qty. | UoM | Unit Price | Amount |
|-------------------|----------------------------|------|---------|------------|-----------------|
| P B&P ALEX LABOUR | LABOUR | 3 | UNIT | | 840 2,520.00 |
| P B&P ALEX PAINT | SPRAY PAINT | 3 | UNIT | | 800 2,400.00 |
| P B&P DIAG | PROGRAMMING & CALIBRATION | 1 | Time Un | | ✓ 480.00 |
| P B&P MECH | COMPULSORY TO DO AFTER AC | | | | |
| | CHECK WIRE HARNESS, ECU, S | 1 | Time Un | | ✓ 280.00 |
| | Nett | | | | |
| | Sum Labor | | | | 5,680.00 |
| P 5G0805915 9B9 | RETAINER | 1 | Pieces | | ? 187.63 |
| P 5G0807049A | BUMPER BRACKET LH | 1 | Pieces | | ? 19.54 |
| P 5G0807109H | BEAM | 1 | Pieces | | ✗ 531.87 |
| | Use Predecessor 5G0807109B | | | | |
| P 5G0807217BNGRU | FRONT BUMPER COVER | 1 | Pieces | | de 1,152.82 |
| P 5G0807248F | FOAM INSER | 1 | Pieces | | ✗ 40.17 |
| | Use Predecessor 5G0807248D | | | | |
| P 5G0807723D | BUMPER SUPP.PART LH | 1 | Pieces | | ? 27.60 |
| | Sum Item | | | | 1,959.63 |

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Payments to:

- BBN: - Acc.-No.:

PDI TUAS

PDI TUAS

GOH KIAN HUAT
121 BUKIT BATOK CENTRAL
#04-449
Singapore, 650121
Singapore

Phone No.
Fax No.
E-Mail

VAT Registration No. M20098505-2
Tax No. 199101494Z

Service Quote

Customer No. CV031089
Quote No. SER/QUO/1800995
QuoteDate 22/06/18
Salesperson Lawrence Tan Say Ch
Page 2

THIS IS NOT AN OFFICIAL TAX INVOICE

| Make | Model Description | Mileage | Service Advisor |
|--------------------|------------------------------|----------------------|------------------------|
| Volkswagen Passeng | GOLF A7 1.2 TSI TL BMT (DSG) | 37,631 | Kong Charmaine |
| License No. | VIN | Initial Registration | Sales Advisor |
| SGF8034K | WVWZZZAUZFW282894 | 29/09/15 | Lawrence Tan Say Chuan |
| Engine Code | Labor Type | Engine No. | Model Code |
| | 1T | CJZ 602825 | 5G12DZ |

| | |
|---------------------|----------|
| Sum Labor | 5,680.00 |
| Sum Item | 1,959.63 |
| Total SGD | 7,639.63 |
| 7% GST | 534.77 |
| Total SGD Incl. GST | 8,174.40 |

Explanations

P = Proportionately Charged

Payment Terms No Credit