



金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 30019

Vehicle Insured : SKP 2122 D
Accident Date : 17-Jun-2018

Date : 10-Sep-2018

Our Ref : 180575 (AIG ASIA) / SHUMAN

PAGE : 1

CHAN YEW KEE, DAVID (MR)
Singapore

ESTIMATED COST OF REPAIR FOR TOYOTA COROLLA ALTIS 1.6 A (2008) SFM4804G
=====

1 pc n/s rear bumper side retainer		11	58.00	✓
5 pcs rear bumper clips	@ S\$ 5.00	11	25.00	✓
1 pc n/s rear door protector		11	90.00	✓
1 pc n/s rear door outer chrome moulding		11	29.00	✓

			202.00	
	Less 25% :		-50.50	

				151.50

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts. 250.00 ✓

To putty and respray on affected
portions. 750.00 600

Total : S\$ 1,151.50
=====

Singapore Dollars One Thousand One Hundred and
Fifty One and Cents Fifty Only

810

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.