

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT			
SOMPO INSURANCE SINGAPORE PL		Ref: CS3/SMO1	8011478/R1z4d3e2
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWER SINGAPORE 048623		Date: 09-07-2018	
		Code: SMO	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Ve	h. GZ 830B	Veh. Inspected	SJC 3799A
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1802656/GPL	Excess (\$)	0.00
Assign Fro	om GRACE TEO	Assign Date	22/06/2018
2. Vehicle Particulars & Condition			
Make & Mo	odel TOYOTA WISH 1.8 A	c.c	1794
Engine No	. HIDDEN	Year of Reg.	2008
Chassis No	o. ZNE100378915	Colour	GREY
Odometer	216369 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front	Tyre 195/65 R15	NEUTON	5 mm
L/H Front 7	Tyre 195/65 R15	NEUTON	5 mm
R/H Rear T	yre 195/65 R15	NEUTON	5 mm
L/H Rear T	yre 195/65 R15	NEUTON	5 mm
4. Description of Damages			
THE VEHIC	LE SUSTAINED DAMAGES AT THE N	'S BODY AND REAR F	PORTION.
5. General Information			
Accident D	Date 21/06/2018	Inspect Date / Tir	ne 25/06/2018 (04:23 PM)
Survey hel	d at AMA AUTOMOTIVE PTE. LTD	AMA AUTOMOTIVE PTE. LTD.	
	36 TOH GUAN ROAD EAST #03-36 SINAGPORE 608580		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$10,000-\$12,500			
5b. Estimate Days of Repair			
ESTIMATED	ESTIMATED NORMAL PERIOD FOR REPAIR: 13 Working Days		

Report Ref No. CS3/SMO18011478/R1z4d3e2

Inspected By

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

Automotive Assessor BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.