From Person	Advice Goh of EC	ICS	
Estimated Co	dance closs of te	Bill to:	Dater line. 22/0/190
	5/TP RES / OD RES / EVA / INV / MV 7 CS		*
	chicle No: SIZ 3787P		Insured:
at Workshop	1st Autoworks		Tel: 6844 1985
of	23 Kaki Bukit Ave 4 # 0	14-01	
Policy No:	280		DMPC1800234H/D
Sum Insured:		Excess:	≠ 500.00
Make of Veh (Client's Recor			D.O.A. 09 06 208
~		8292 5	59S H.O.D. Endorsement:
	508pm 26 18 Person Contacted	Kalu	Valuation (BY) OFF
27 3007 1 1110	Person Contacted.	IVIV	300 Venicit Ex 1001
Date/Time	Action/Instruction ( TEstimate		1-
	S12 3787p-cs3/105180	80501	/R/24d3s2 DOA:09/0
1 1	Revert thu menimen		
-		( Lun )	9092 STGT
28/6/18	Janue approve mandate (:	- pr. /	
25/6/18 28/6/18 29/6/18 29/6/18	Interm Kelvin to procee	d repent	0212 3315

Weekend (\$

460

Lump Sum / I.B.I: (5-14.744.90

13646:90



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Inte	rnationale Des Experts En Auton	nobile
ECI	CS LTD		Ref : CS/ICS180114	79/Ard3
#10	EMASEK BOULEV -01 SUNTEC TOW GAPORE 0389878	ER ONE	Date: 25-06-2018  Code: ICS	
1.		Policy Part	ticulars :- OWN DAMAGE	
	Insured Veh.		Veh. Inspected	SLZ 3787P
	Policy No.		Coverage (\$)	0.00
	Claim No.	DMPC1800234H/DL	Excess (\$)	500.00
	Assign From	JANICE GOH	Assign Date	25/06/2018
2.		Vehicle I	Particulars & Condition	
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	(*)	Steering	
	Brakes		Modification	
	General			
3.		Co	nditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4.	Wall Live Edward	Desc	ription of Damages	
5.	WE amore	Ge	neral Information	
	Accident Date	09/06/2018	Inspection Date	25/06/2018
	Survey held at	1ST AUTOWORKS PTE LT	rD	
	220	23 KAKI BUKIT AVE 4 #04-01 (SOUNTH WING) SINGAPORE 415933		
5a.			Remarks	San Company of the

A)THE MARKET VALUE IS S\$-----(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

## Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

**ECICS Limited** 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Date:

25 Jun 2018

## Preliminary Advice

Vehicle No

: SLZ3787P

Accident Date

: 09/06/2018

Make

: OPEL ASTRA

Policy No.

: MPC18A00171400

Assignment Date

: 25/06/2018

Excess

: S\$0.00

Date of Inspection

: 25/06/2018

Est. Duration of Repair

: 6.00

Inspection At

: 1ST AUTOWORKS PTE LTD (HQ) 23 KAKI BUKIT AVE 4, #04-01

SINGAPORE 415933

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	34,015.40
Revised Amount	:S\$	14,744.90
Check Items (Estimated)	:S\$	4,012.20
Total	:S\$	18,757.10

Lump Sum Repair

:S\$

#### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	120,000.00
COE / PARF Rebate	:S\$	44,825.00
Salvage Value	:S\$	
Margin for Repair	:S\$	75,175.00

#### Remarks

	The vehicle is repairable at our adjusted amoun let us have your authorisation.	. We have	also	confirmed	excess	and policy	coverage.	Kindly
--	--	-----------	------	-----------	--------	------------	-----------	--------

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments:

## Janice Lee (LKKAuto)

From: Kelvin Chew <Kelvin.chew@alpinemotors.sg>

Sent: Friday, September 07, 2018 8:31 PM

To: SUR

Cc: suhaimi@firstautoworks.com.sg

Subject: SLZ 3787 P OPEL ASTRA ECICS OD DOA 09.06.2018 FINALIZE

Attachments: SLZ 3787 P FINALIZE (2).JPG; SLZ 3787 P FINALIZE (1).JPG

Hi Lkk,

attach is finalize report. survey by Mr. Adrian on 25.06.2018. part by part \$14,744.90 before excess \$500.00 @ 5 working days. kindly please confirm with me. thanks.

from, kelvin chew 8292 5595

The information contained in this message is intended only for the recipient, and may be a confidential attorney-client communication or may otherwise be privileged and confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, please be aware that any dissemination or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify us by replying to the message and deleting it from your computer.

## Nivitha (LKK Auto)

From:

motorsurvey <motorsurvey@ecics.com.sg>

Sent:

Friday, 22 June 2018 5:00 PM

To:

vincent.sim@alpinemotors.sg; assignments@lkkauto.com

Cc:

Kelvin Chew; suhaimi@alpinemotors.sg; chongyss@gmail.com; motorsurvey;

Desmond Lee Ker Wen (ECICS, Claims)

Subject:

RE: SLZ3787P- OPEL ASTRA - OWN DAMAGED CLAIM - ECICS - DOA 9-6-2018

Attachments:

SLZ3787P\_0001.jpg; SLZ3787P\_0002.jpg; GIA REPORT - SLZ 3787 P REVISED 2 .pdf

Dear Vincent

Thank you for your email.

We will appoint LKK for the OD survey.

Aside to LKK

Please assist to arrange OD survey. Policy excess \$500.00.

"Please be advised that this case is handle by Desmond Lee and our claim ref is DMPC1800234H/DL."

Thank you.

Regards, Janice Goh Claims Division DID: +65 6303 0182 FAX: +65 6338 9267

#### **ECICS Limited**

7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

\*\*Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding. \*\*

From: Vincent Sim [mailto:vincent.sim@alpinemotors.sg]

Sent: Friday, 22 June, 2018 1:46 PM

To: motorsurvey

Cc: Kelvin Chew; suhaimi@alpinemotors.sg; chongyss@gmail.com

Subject: SLZ3787P- OPEL ASTRA - OWN DAMAGED CLAIM - ECICS - DOA 9-6-2018

kindly dispatch surveyor on coming Monday morning (26-6-2018) as the owner is still driving the car estimate is as attached

Location will be at Person in charge ;-Suhaimi , Kelvin - 82925595 H/P. 68441985 - office phone E-mail: suhaimi@alpinemotors.sq

Add:

First Autoworks Pte Ltd 23, Kaki Bukit Ave 4 #04-01 (South Wing) singapore 415933 (Vicom Building) tel; 6844-1985

Regards, Vincent Sim- Claims Dept

vincent.sim@alpinemotors.sg

65113022 ext 343

The information contained in this message is intended only for the recipient, and may be a confidential attorney-client communication or may otherwise be privileged and confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, please be aware that any dissemination or copying of this communication is strictly prohibited. If you have received this communication in error, please immediately notify us by replying to the message and deleting it from your computer.



This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

# **Print Received Message**

This mail is associated with:

\*SLZ3787P (DMPC1800234H)

OD Jun 9 2018 4:00PM [CHONG YONGSI] 1st Autoworks Pte Ltd

From

ECICS Limited (HQ) (ECICS), sent on 28/06/2018 17:32 PM.

To

LKK\_HQ Alert - Adj Mandate Approved (S\$18757.10) - SLZ3787P - Claim Handler: Desmond Lee Subject

Approved:18757.10.

## Janice Lee (LKKAuto)

From:

Janice Lee (LKKAuto)

Sent:

Friday, June 29, 2018 9:35 AM kelvin.chew@alpinemotors.sg

To: Cc:

SUR

Subject:

SLZ 3787P OD DOA: 09/06/2018

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle SLZ 3787P (excess \$500/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>janicelee@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

Fax Number Contact Number

EMail Address

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

foresaid.	
	ACCIDENT STATEMENT
Date Of Report	11/06/2018 14:53
Date Of Accident	09/06/2018 16:35
Exact Location Of Accident	JUNCT RD OF OUTRAM PARK RD & TIONG BAHRU RD
Country/State of Loss	SINGAPORE
	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SLZ3787P
Insured/Policyholder	
Name Of Registered Owner	CHONG YONGSI
NRIC No	S8124484G
Email Address	CHONGYSSS@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96847397
Alternative Phone No	OFFICE-96847397
Vehicle Particulars	
Manufacturer	OPEL
Model	ASTRA-1.4 HB (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	ECICS LIMITED
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MPC18A00171400
Cover Note Number	
Driver	
Name of Driver	CHONG YONGSI
NRIC No	S8124484G
Date Of Birth	03/08/1981
Occupation	INDOOR
Date Of Driving Pass	28/04/2003
Driving Experience	15 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-96847397

OFFICE-96847397

CHONGYSSS@GMAIL.COM

Address

BLK 80 KIM SENG ROAD

#29-05

Postcode

239426

Was driver an employee of the Insured's Company

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

-

NO

Insurance Company of Driver's Own Vehicle

.

General Information of the Accident

Type Of Accident

COLLISION - CROSS JUNCTION

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

to the second of the second

140

Number of Passengers (Including Driver)

1

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

STATEMENT RECORDED BY SOO - PROGRESSIVE AUTOMOTIVE PTE LTD (6741 5336)

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SKJ4357L

Vehicle Make/Model/Colour

**Details Of Properties** 

Vehicle Category

PRIVATE CAR

Name of Driver

YEO HWEE HWEE, CANDY

NRIC/Passport Number

S8021393Z

Contact Number

91084130

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### Sketch Plan

#### SKETCH PLAN

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8 Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:


Oriver's Signature (If driver is not the policyholder) Date & Time: Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

## Sketch Plan #2

KETCH PLAN		
		Vehicle No A - SLZ 3 7 % B - SKJ43 5 7
	I A KO	
		Legend
		A BA
		Vehicle Bike
SCRIBE CIRCUMSTANCES	DE THE ACCIDENT	venice size
SCRIBE CIRCUMSTANCES		
I wan driving	and I can feel that a	it my eyest side there
is a fyre	epproaching forward to	
cause do in	port to I styped the	
Then we e	where contacts) driving	pulle to make
a dueston o	efter we used down 1	form this occident strock.
	41147	-
	****	
DECLARATION		D
/We declare the foregoing parti- Please be advised that your ins- stipulated timeframe from the	culars are true in every respect. urer may have a 14 day clause whereby the cla date of occurrence. Kindly check your policy fo	ilm against own policy must be made within the ir more details.
Chy		
Policyholder's Signature Date & Time:	Driver's Signature (If driver is not the policyholder)	Reporting Centre Personnel's Signature Name:
WHEN OF LINES	Date & Time:	NRIC/FIN No.:

Page 4 of 12

## DRIVER IC/DL Pg. 1







Date: 18/05/2017

NRIC No: S8124484G

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Motor Cars~< 3000kg with =<? passengers, exclusive 28 Apr 2003 of the driver; and other motor vehicles =< 2500kg Class 3

NP 428A

#### Addendum Sheet



## GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE

6 Raffles Quay #18-00 Singapore 048580 Tel (65) 6224 0010 Fax (65) 6224 0030 Operating Hours - Monday to Friday, 09:00 – 17:00 UEN: 544550206 / 657 Reg. No. M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the <u>same</u> Authorised Reporting Centre with whom you submitted the Original Report.

		ADD	DENDUM	
(A)		SON MAKING THE AMEND	(C) C750 T C 755	912 82870.
	Original Report No :	CI VI	Vehicle Registration No:	500
	Name(as shown in NRC):	Chay Jongsi	NRIC/FIN/Passport No :	581244846
	The state of the s	ticle Owner) (*) Please dele		
	Address	Blk 80 Kim Ser	y kond # 29-05	Singapore(23942b)
	Contact (Tel)		Mobile No. 968	47397
	Email Address :	Chiny ysss@gr		
	Date of Accident :	09/06/2018	Time of Accident:	16:35
	Place of Accident	Junet Rd of	Outran Park Rd 9	Trong Bahru R.
	Insurance Company		ELICS P/L.	,
(B)	ADDITIONALINFORM	MATION / AMENDMENTS:		
		on the above mentioned ac	cident and would like to include ad	ditional information or
	Lia Lia	1 OD C		
	Policyholder   Driver's Date:	Signature	Reporting Centre Perso Name: NRIC/FINNo.:	innel's Signature

Date:

## Addendum Sheet



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE GENERAL (1938)

GENERAL (1938)

Tel (65) 6224 0010 Fax (65) 6224 0030

Operating Hours - Monday to Friday, 09:00 – 17:00

UEN: 5665500200 / 657 Reg. No. M400017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

			Al	DDEN	DUM				
4)	PARTICULARS OF PER	SONMAKING	THEAME	NDMEN	ITS:				
	Original Report No :	mps 2	120 ass	564 -	Č / Vehicle Re	gistration N	lo:	SLZZA	9F8
	Name (as shown in NRC) :								
	(*Vehicle Driver / Veh	nicle Owner) ('	) Please d	elete as	appropriate				
	Address :	B1K 80	Cin	Suy	Road #	29-05		Singapore( >	39426
	Contact (Tel) :				Road #	9	684	7397	
	Email Address	Choi	~ usss	00	proil con	m			
	Date of Accident	9/6	118		Time of Ar	rident	16	:35	
	Email Address  Date of Accident  Place of Accident	Threat	16	· f	Dutra-	Park	Rd	9 Tion	Bahi
	Insurance Company:			F.C	105				-
	insurance company:								
)	ADDITIONALINFORM	MATION / AMI	ENDMENT	S:					
	Chang	1 th	5,	ndi	V -				
	-								
							1	P	
						1	4	5	
	5 N 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1						- 1		
	Policyholder / Driver's Date:	s Signature			Report Name:	ing Centre F	'ersonne	el's Signature	

NRIC/FINNo.: Date:

Pd

## > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	4484G
Vehicle No.:	SLZ3787P
Vehicle to be Exported:	Yes
Intended De-registration Date:	21 Jun 2018
Vehicle Make:	OPEL
Vehicle Model:	ASTRA HB 1.4 AT
Primary Colour:	Red
Manufacturing Year:	2017
Engine No.:	B1171707JCVX0835
Chassis No.:	W0LBE6EC0HG180792
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$19.655.00
Original Registration Date:	30 Apr 2018
First Registration Date:	30 Apr 2018
Transfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$19,655.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Apr 2028
PARF Rebate Amount: Intended COE Rebate Details	\$14,741.00
COE Expiry Date:	29 Apr 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$37,605.00
COE Rebate Amount:	\$30,084.00
Total Rebate Amount:	\$44,825.00
· 보고	

The information contained herein is correct as at 21 Jun 2018

# **OPEL PRICE GUIDE**

EFFECTIVE PERIOD: 19 APRIL - 9 MAY 2018



EFFECTIVE RESIDD: 14%	PARLE SERGI, EVIE				
PASSENGER MODELS		FUEL CONGUMPTION	VES BANORIG	TAX	RETAIL PRICE (with of COI)
1000	Gerodensi 1.2A Turbo (locovation Eventural		3	\$254	\$149,668*
- THE SECTION .	Crowsland 1.2A Turbio (Classic)	5.1		1254	\$175,888
A A	Crossland 1.2A Turbo (Enjoy)	5.4		\$254	\$119,000*
	Crossland C2A Turbe (Innovation) with extell us (ED)	2500	(8)	5754	\$120,000
	Astro Hotchback 1.0 Eow/ronic	43	9	5196	31193887
(2000m)	Astro Hatchback 1.9 Easytronic with Intelligent LHD!	43	3	5190	\$122,889*
	Astro Hotchback 1.4A Turbo		61	\$913	\$135,8881
	Astra Hotchbook 1.4A Turno with revillance (III)	0.5		5313	\$1,59,888
	Actro Sports Tourer 1.0 Easytronic	4.1		\$196	\$124,885
and alkania	Autro Sports Tourer 1.0 Equytronic with Intelligent (EE)	4.3		5196	\$177,885
II ON SHIP IN	Astro Sports Tourer 1.4A Turbo		C1		5:46,000
Stand Assessed Ave.	Astro Sports Fourer 1.4A Turbo with Intelligent EDF	3.4		\$310	\$140,888
=0	ZoSing Tourier 1.4A Tusbo with immiliana LEO*	36/6		\$300	\$1,39,6865
	Intignin Grond Sport 1.6A Turbo Diesal (Enjoy)		-	5041	\$1.40,000.0
1720-1	Insigning Grand Sport 1.5A Turbo (Innovation)	4.5		\$340	\$159,886*
COMPANIE OF THE PARTY OF THE PA	lesignia Grand Sport 1.5A Turbo (Innavation Premium Edition)	6.1		\$340	\$169,8085
America Assessment	Insignia Grand Sport 2.0A Turbo AWD (Innovation Premium Edition)	8.6	62	5805	\$174,888*
300	Inzignio Sports Tourer 2.0A Turbo AWD (Incovation Premain Edition	9.7		\$605	\$100,000
COMMERCIAL MODELS		FUEL CONSUMPTION   (Intoles) workered	CO: EMISSION (g/km)	NS ROAD TAX	RETAIL PRIC
100	Combe 1.6D (LWII)	\$0		\$213	\$49,778
Was.	Vivero 1.6D	15		\$213	\$79,835

#### Please approach our Opel Sales Executives for more information.









## Repair Estimate

Date: 20/06/2018

Reference: OPES Make: ASTRA

To Whom It May Concern

Dear Sir,

RE: VEHICLE .: SLZ3787P

CHASSIS NO.: W0LBE6EC0HG180792 ENGINE NO.: B1171707JCVX0835

Name of insured .: CHONG YONGSI

Date of accident .: 09.06.2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

#### **Parts**

No.	Qty	Part Description	Price	e (SGD)
1	1	FRT FENDER RH	X S	682.00
2		FRT FENDER INNERSHIELD RH HOLE NEC	× s	138.00
3	1	FRT DOOR RH Distant	s /	2,166.00
4	1	FRT DOOR LOCK RH	S	240.00
5	1	FRT DOOR LOCK CATCHER RH - Striker	S	84.00
6	1	FRT DOOR INNER TRIM RH	S	1,354.00
7	1	FRT DOOR RUBBER BEADING RH - Body Side Post Pro	S	196.00
8	1	FRT DOOR WEATHER STRIP RH	S /	208.00
9	1	FRT DOOR OUTER HANDLE RH N M	( \$	366.00
10	1	FRT DOOR OUTER HANDLE KNOB RH And h	\$	132.00
11	1	FRT DOOR HANDLE INNER BASE - Bracket Not Park	\$	232.00
12	1	FRT DOOR BLACK STICKER RH	\$/	110.00
13	1	FRT DOOR GLASS OUTER MLDG RH	S	152.00
14	1	FRT DOOR POWER WINDOW REGULATOR ASSY RH 700 MM	5 \$	666.00
15	1	FRT DOOR WIRE HARNESS RH ARREST AND ME	\ \$	596.00
16	1	RR DOOR RH Ostald	\$ /	2,480.00
17	1	RR DOOR HINGE UPP RH	8 /	160.00
18	1	RR DOOR HINGE LOW RH	8/	146.00
19	1	RR DOOR CHECKER RH - Link Check	S	142.00
20	1	RR DOOR LOCK RH	S	242.00
21	1	RR DOOR LOCK CATCHER RH - Striker	S	84.00
22	1	RR DOOR INNER TRIM RH	S	880.00
23	1	RR DOOR RUBBER BEADING RH - Body Side KITCHE	U.S	208.00
24	1	RR DOOR WEATHER STRIP RH New	\$ /	252.00
25	1	RR DOOR HANDLE INNER BASE - Bracket	\$	194.00
26	- 1	RR DOOR BLACK STICKER RH \ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\	\$ /	110.00
27	1	RR DOOR GLASS OUTER MLDG RH	\$	198.00
28	1	RR DOOR POWER WINDOW REGULATOR ASSY RH HOR Ple	\$	732.00
29	1	RR DOOR WIRE HARNESS RH	\$	388.00
30	1	RH CENTER PILLAR PANEL PAGE	\$ X	1,220.00
31	1	RH ROCKER PANEL 7	\$	1,220.00
32	1	FRT RH ROCKER PANEL STEP PLATE	\$ /	359.00
33	1	RR FENDER RH REALS	<b>S</b>	2,504.00
34	1	RR FENDER INNERSHIELD RH	1 s	150.00

35	1	RR FENDER OUTER QUARTER GARNISH RH NEW	\$	× 304.00
36	1	RR RIM RH	\$	/ 1,200.00
37	1	RR WHEEL BEARING RH - with Hub	S	496.00
38	1	RR SHOCK ABSORBER RH	, S	368.00
39	1	RR AXLE BEAM ASSY	( ) \$	3,029.00
40	1	RR AXLE BEAM BRACKET RH	S	152.00
41	1	RR BUMPER Pennis	S	1,966.00

Parts Total: \$

26,506.00

Less10%: \$

2,650.60

Total: \$

23,855.40

#### Labour

#### **Labour Description**

No.		Price	(SGD)
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair /replacement parts.	\$	3,250.00
2	Carry out spray painting on affected area, FRT FENDER RH, FRT DOOR RH, RR DOOR RH, RR FENDER RH, RR BUMPER, RH CENTRE PILLAR PANEL, RH ROCKER PANEL	\$	3,850.00
3	To disconnect front wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$	240.00
4	To conduct 4 wheel alignment	\$	220.00
<u>5</u>	To conduct transfer front rh door mechanism to new door panel	\$	650.00
6	To conduct transfer rear rh door mechanism to new door panel	\$	650.00
7	Remove and replace RHR under carriage parts	\$	650.00
8	Remove and refix seat cushion/upholstery & roof lining to facilitate repairs	\$	650.00

Labour Total: \$

10,160.00

#### Others

## Other Description

No.		Pric	ce (SGD)
	Other Total:	\$	
	TOTAL:	\$	34,015.40
	GST ( 7%):		2,381.08
	GRAND TOTAL :	\$	36,396.48

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

 To resurvey before after spray painting Yours faithfully To display damaged part(s) during resurvey Parts prices are subject to cor liation. . Third party survey is on a "Will ut Prejudice" basis . No illegal modification(s) is a liwed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Service Advisor Acknowledged by Repairer Signature: Date:

Adrin Ling
P/P 15/04/8
Not Anthorsed
Excess \$500.





#### FINALIZE

ECICS LIMITED

GST Ref. No:

20-0000274-Z

Vehicle No: SLZ3787P

Invoice No:

Chasis No: W0LBE6EC0HG180792 Engine No: B1171707JCVX0835

Invoice Date:

Date of accident :9/6/2018

AMOUNT SGD

## DESCRIPTION

No.	Qty.	Description	Price (SGD)
140.	4	FRT DOOR RH	\$ 2,166.00
1	1	FRT DOOR KH	\$ 208.00
3	1	FRT DOOR WEATHER STRIP RIT	\$ 110.00
4	1	RR DOOR RH	\$ 2,480.00
5	1	RR DOOR HINGE UPP RH	\$ 160.00
6	1	RR DOOR HINGE LOW RH	\$ 146.00
7	1	RR DOOR WEATHER STRIP RH	\$ 252.00
8	1	RR DOOR BLACK STICKER RH	\$ 110.00
9	1	RH CENTER PILLAR PANEL	\$ 1,220.00
10	1	FRT RH ROCKER PANEL STEP PLATE	\$ 359.00
11	1	RR RIM RH	\$ 1,200.00

#### Supplementry

1	S	

Total: \$ 8,411.00

Less 10%: \$

841.10

Parts Total: \$

7,569.90

## Labour

No.		Price	(SGD)
1	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIRED / REPLACEMENT PARTS.	S	2,600.00
2	CARRY OUT SPRAY PAINTING OF ACCIDENT AFFECTED AREA_FRT FENDER RH, FRT DOOR RH, RR DOR RH, RR FENDER RH, RR BUMPER, RH CENTRE PILLAR PANEL, RH ROCKER PANEL	s	3,300.00
3	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	s	120.00

4	TO CONDUCT 4 WHEEL ALIGNMENT	\$	180.00
5	TO CONDUCT TRANSFER FRONT RH DOOR MECHANISM TO NEW DOOR PANEL	s	325.00
6	TO CONDUCT TRANSFER REAR RH DOOR MECHANISM TO NEW DOOR PANEL	\$	325.00
7	REMOVE AND REFIX SEAT CUSHION / UPHOLSTERY & ROOF LINING TO FACILITATE REPAIRS.	s	325.00

Labour Total: \$ 7,175.00

## Other

No.	Price (SGD)
1 1	

Other Total: \$

Total: \$ 14,744.90 Excess: \$ 500.00 GST (7%): \$ 997.14 Grand Total: \$ 15,242.04

Yours Faithfully,

Kelvin Chew Service Advisor

Tel: 68441985 Fax:68445185

Please check and finalize with me



#### **AUTO GERAMANY PTE LTD**

7 Ubi Close, Alpine Centre, S408604



#### TAX INVOICE

ECICS LIMITED NO 10 EUNOS ROAD 8 SINGAPORE POST OFFICE CENTRE **#C9-04** SINGAPORE 408600

GST Ref. No:

M2-0111811-5

920.28

14,067.18

Vehicle No SLZ3787P

Chasis No: WOLBEGECOHG180792 Engine No: B1171707JCVX0836

GST (7%)

Grand Total: \$

Invoice No CGI-ASC-18IR07338E

Invoice Date 18-9-2018 Date of acadent 9/5/2016 AMOUNT SGD DESCRIPTION Description No. 13,646.90 Carry out lump sum repair on accident vehicle corresponding to supply of spare 1 parts labour and spray painting charges 13.646.90 Total: 3 500.00 Excess \$ 13,145.90 Less Excess: \$

AUTO GERMANY PTE LTD Yours Earthfully.

Vincent Sim Cisms Doot

Tel 65113022 per 343

ESOE

ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "Auto Germany Pie Ltd" PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.





# SATISFACTION NOTE

I CHONG YONGSI IC NO: S8124484G hereby certified that Vehicle no: SLZ3787P had been carried out to my entire Satisfaction & I agree that for the discharge of the repair from Auto Germany Pte Ltd for S500+ GST 7% ~S535.00 being payment of the insurance excess by Auto Germany Pte Ltd shall be in full discharge of all claims In respect of the damage to this vehicle which resulting from an accident which occurred on or about the day of 9-6-

Date	14/7/13	Signature _	A.
		IC NO & Name	SHELLY GO Chappy

# LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Email: sur@lkkauto.com;assignments@lkkauto.com Tel: 6256-3561 Fax: 6844-8805

## VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited

7 Temasek Boulevard, #10-01 Suntec Tower One

Singapore 038987

Our File No:

Engine No:

Chassis No:

Odometer:

CS/ICS18011479/ARD3N2

Date:

12/11/2018

REFERENCE

Insured/Claimant: Date of Loss:

CHONG YONGSI 09/06/2018

Policy No: Nature of Claim: MPC18A00171400

OD

Claim No: DMPC1800234H

B1171707JCVX0835

2066 km

WOLBE6EC0HG180792

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

**SLZ3787P** 

Make & Model: Reg. Date:

OPEL ASTRA, 1.4 HB (A) 30/04/2018 (Man. Year: 2017)

Colour: **Engine Capacity:**  Red 1399 cc

Market Value/New Car

S\$120,000.00

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: Front Left Side:

225/45R17 Bridgestone 6 mm Rear Tyre Size:

225/45R17

Front Right Side:

Bridgestone 6 mm

Rear Left Side: Rear Right Side: Bridgestone 6 mm Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts Miscellaneous Items	Repairer's 23,855.40 0.00	Adjuster's 6,471.90 0.00	Difference 17,383.50 0.00	<b>Diff %</b> 72.87
Labour Paintwork Labour	10,160.00 0.00	7,175.00 0.00	2,985.00 0.00	29.38
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$) - Excess (S\$)	<b>34,015.40</b> 500.00	<b>13,646.90</b> 500.00	<b>20,368.50</b> 0.00	<b>59.88</b> 0.00
+ GST 7.00/7.00% (S\$)	33,515.40 2,346.08	13,146.90 920.28	20,368.50 1,425.80	60.77 60.77
Nett Amount (S\$)	35,861.48	14,067.18	21,794.30	60.77

INSPECTION

Date of Assignment:

22/06/2018

Date Inspected:

25/06/2018 Inspected At:

AUTO GERMANY PTE LTD 7 UBI CLOSE, ALPINE CENTRE

SINGAPORE 408604

Estimated Period of Repair:

5.0 days

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

Reference Version: 1.0 (Last Synchronised: 12 Nov 2018) Part Source: MRM-SG

OPEL ASTRA 1.4 HB (A) (Catalogue:Merimen Singapore 1.0) 144 Parts:

(Price-denominated Standard List) Labour: Repairer's

Print Code: (Unsubmitted, no print-code for SLZ3787P)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page Validity:

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

No.		mended Parts Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRT FENDER RH	Repair	682.00 FL	*-FL
2	1	*FRT FENDER INNERSHIELD RH	Not Necessary	138.00 FL	*-FL
3	1	*FRT DOOR RH	Distorted	2,166.00 FL	
4	1		Not Necessary	240.00 FL	*-FL
5	1	*FRT DOOR LOCK CATCHER RH-STRIKER	Not Necessary	84.00 FL	*-FL
6	1	*FRT DOOR INNER TRIM RH	Not Necessary	1,354.00 FL	*-FL
7	1	*FRT DOOR RUBBER BEADING RH-BODY SIDE	Not Necessary	196.00 FL	*-FL
8	1	*FRT DOOR WEATHER STRIP RH	Necessary	208.00 FL	
9	1	*FRT DOOR OUTER HANDLE RH	Not Necessary	366.00 FL	*- FL
10	1	*FRT DOOR OUTER HANDLE KNOB RH	Not Necessary	132.00 FL	*-FL
11	1	*FRT DOOR HANDLE INNER BASE-BRACKET	Not Necessary		*-FL
12	1	*FRT DOOR BLACK STICKER RH	Necessary	110.00 FL	
13	1	*FRT DOOR GLASS OUTER MLDG RH	Not Necessary	152.00 FL	*-FL
14	1	*FRT DOOR POWER WINDOW REGULATOR ASSY RH			
15	1	*FRT DOOR WIRE HARNESS RH	Not Necessary		*-FL
16	1	*RR DOOR RH	Distorted		*2,480.00 FL
17	1	*RR DOOR HINGE UPP RH	Bent	160.00 FL	
18	1	*RR DOOR HINGE LOW RH	Bent	146.00 FL	
19	1	*RR DOOR CHECKER RH-LINK CHECK	Not Necessary		
20	1	*RR DOOR LOCK RH	Not Necessary		
21	1	*RR DOOR LOCK CATCHER RH-STRIKER	Not Necessary		
22	1	*RR DOOR INNER TRIM RH	Not Necessary		
23	1	*RR DOOR RUBBER BEADING RH-BODY SIDE	Not Necessary		
24	1	*RR DOOR WEATHER STRIP RH	Necessary	252.00 FL	
25	1	*RR DOOR HANDLE INNER BASE-BRACKET	Not Necessary		
26	1	*RR DOOR BLACK STICKER RH	Necessary	110.00 FL	
27	1	*RR DOOR GLASS OUTER MLDG RH	Not Necessary		To the state of th
28	1	*RR DOOR POWER WINDOW REGULATOR ASSY RH	Not Necessary		
29	1	*RR DOOR WIRE HARNESS RH	Not Necessary	1,220.00 FL	
30	1	*RH CENTER PILLAR PANEL	Repair		
31	1	*RH ROCKER PANEL	Repair	1,220.00 FL 359.00 FL	
32	1	*FRT RH ROCKER PANEL STEP PLATE	Necessary	2,504.00 FL	
33	1	*RR FENDER RH	Repair		
34	1	*RR FENDER INNERSHIELD RH	Not Necessary		
35	1	*RR FENDER OUTER QUARTER GARNISH RH	Not Necessary Cut		*1,200.00 Fl
36	1	*RR RIM RH	Not Necessary		
37	1	*RR WHEEL BEARING RH-WITH HUB	2000 1200 100 100 100 100 100 100 100 10		
38	1	*RR SHOCK ABSORBER RH	Not Necessary		170 22
39	1	*RR AXLE BEAM ASSY			
40	1	*RR AXLE BEAM BRACKET RH	Not Necessary	1,966.00 FI	
41	1	*RR BUMPER	Repair	1,900.00 F	
F=F	ranchis	e part. L=ListItemDisc List Item Discount on L Items 10	Sub Total (S\$		<b>7,191.00</b> 719.10

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
			Total Parts (S\$)	23,855.40	6,471.90
		Poport was ups	ubmitted during this print-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

ed Labour	Lab Tame	Repairer's	Amount
	Lab.Type	Repairers	Amount
		0000000	
LE/RENEW THE ACCIDENT DAMAGED PANEL SHAPE,STRAIGHTEN,ORIENTATE AND R/REPLACEMENT PARTS	New	3,250.00	2,600.00
SPRAY PAINTING ON AFFECTED AREA,FRT FRT DOOR RH,RR DOOR RH,RR FENDER ER,RH CENTRE PILLAR PANEL,RH NEL	New	3,850.00	3,300.00
ECT FRONT WIRE HARNESS OF COMPONENT TO FACILITATE CONNECT AND CHECK ELECTRICAL FTER REPAIR	New	240.00	120.00
4 WHEEL ALIGNMENT	New	220.00	180.00
TTRANSFER FRONT RH DOOR TO NEW DOOR PANEL	New	650.00	325.00
T TRANSFER REAR RH DOOR MECHANISM OR PANEL	New	650.00	325.00
D REPLACE RHR UNDER CARRIAGE PARTS	S New	650.00	5-
D REFIX SEAT CUSHION/UPHOLSTERY & TO FACILITATE REPAIRS	New	650.00	325.00
Gross Labour Cost (S\$)		10,160.00	7,175.00
			Gross Labour Cost (S\$) 10,160.00  Report was unsubmitted during this print-out.

< END OF ESTIMATES >