

22/03/2002

ASS. REC. BY:

REF:

CS/SMO18011591/Usd3⁰²

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Grace Teo

of

SMO

Date/Time:

26/6/18 @ 8:25am

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No.:

RU 4105 G

Insured:

GBD 4866 Y

at Workshop n/s:

Abwin Service

Tel:

6713 9417

of

No. 8 Kaki Bukit Ave 4 # 07-48 premier

Policy No.:

Claim No.:

CMTD1802447 / GPL

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

07/06/2018

CA / REV / REP. / REV 24 HRS ^{lup?}

H.O.D. Endorsement:

Date/Time:

10:46am @ 26/6/18

Person Contacted:

Linden

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

RU 4105 G-X

GBD 4866 Y-X

11/07/18

@ 16:03 p.m. revised PA to Grace Teo via email.

(06/11/13) wef

ASS. REC. BY: Marcus

REF:

Smo /

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: RU 41059at Workshop m/s Abw.1

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or NoLump Sum: 1.5 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: RU 41059 Yr Regn: 8, 06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or LMMake: Nissan Urvan C.C. 2953Colour: white A/C: Insured / Std / NI / NASp. Reading: 54680 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1TH4625-20715188Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195-215

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 Rear 6R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 7/6/18 D.O.I. 10/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

frt n/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

heading 512.40N for type N/CNote new parts replacement Repair work plp.20/7/18 Repair sum \$1800 confirmed with Linda.23/7/18 Reconfirmed sum of \$946 with Linda.(\$7,137.17 red - 88%)

RECEIVED 23 JUL 2018

Date/Time, File Pass to?

23/07/181) 2pist

Date/Time, File Return to?

2) _____

☐ : Preli. Report☒ : Final ReportDays Of Repair: 2Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I: (\$ 946.00 P/P)

250



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD18024471/GPL

Date: 11 July 2018

Our Ref: CS/SMO18011591/Usd3

The Motor Claims Department
Tenet Sompo Insurance Pte Ltd

Without Prejudice

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. RU 4105G.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 10-07-2018 at the premises of M/s Abwin Service Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>8,083.17</u>
Revised Estimate Amount	: S\$ <u>2,253.92</u>
"Check" Items Amount	: S\$ <u> </u>
Market Value	: S\$ <u> </u>
LTA Reimbursement Value	: S\$ <u> </u>
Nett Value	: S\$ <u> </u>

Description of Damage:

The vehicle sustained damages at the front n/s portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 3 Days

Yours faithfully,
Marcus Chua
Automotive Assessor

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Wednesday, 11 July 2018 4:03 PM
To: 'Teo, Grace'
Cc: 'Gnoh, Pau Loong'; sur@lkkauto.com; 'Nivitha (LKK Auto)'; assignments@lkkauto.com
Subject: RE: CMTD1802447/GPL - SUV(LKK)/ GBD4866Y & RU4105G ACC ON 07/06/2018
Attachments: RU 4105G - Preli Advise.pdf

Dear Grace,

Enclosed preliminary revised for RU 4105G.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 26 June 2018 10:49 AM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments@lkkauto.com
Cc: 'Gnoh, Pau Loong' <PauLoong.Gnoh@sompo.com.sg>; sur@lkkauto.com
Subject: RE: CMTD1802447/GPL - SUV(LKK)/ GBD4866Y & RU4105G ACC ON 07/06/2018

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [mailto:grace.teo@sompo.com.sg]
Sent: Tuesday, 26 June 2018 8:25 AM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Motor Claims <motorclaims@abwin.com.sg>; Ivan Teo <ivanteo@abwin.com.sg>; Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>
Subject: CMTD1802447/GPL - SUV(LKK)/ GBD4866Y & RU4105G ACC ON 07/06/2018

Our Reference: CMTD1802447/GPL

Dear LKK AUTO,

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Tuesday, 26 June 2018 8:25 AM
To: admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Motor Claims; Ivan Teo; Gnoh, Pau Loong
Subject: CMTD1802447/GPL - SUV(LKK)/ GBD4866Y & RU4105G ACC ON 07/06/2018

Our Reference: CMTD1802447/GPL

Dear LKK AUTO,

Please make arrangement to conduct the survey for RU4105G.

Please be informed that Gnoh Pau Loong the handler of this case.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Motor Claims [mailto:motorclaims@abwin.com.sg]
Sent: Monday, June 25, 2018 5:34 PM
To: Gnoh, Pau Loong
Cc: Ivan Teo; Chan, Shu Hui Agnes; Ye, Yong Kang Melvin; Teo, See Ling; Teo, Grace
Subject: RE: CMTD1802447/GPL - NR/ GBD4866Y & RU4105G ACC ON 07/06/2018

Dear Paul

We appoint LKK Auto Consultants to survey the vehicle.

Thank you
Regards

ABWIN 論輝

Abwin Service Pte Ltd

No. 8 Kaki Bukit Avenue 4

#07-48 Premier@Kaki Bukit Gate 2

Singapore 415875

Linda Liao

Motor Claim Executive

DID +65 6713 9417 HP:9751 9596

T +65 6713 9400 | F +65 6713 9415

[Website](#) | [Facebook](#) | [LinkedIn](#)

Looking to start a new business soon? Find out how we can provide you with a complete vehicle ownership solution and much more!

Click [here](#) to view our listing >>



From: Gnoh, Pau Loong [mailto:PauLoong.Gnoh@sompo.com.sg]

Sent: Monday, 25 June, 2018 10:35 AM

To: Motor Claims <motorclaims@abwin.com.sg>

Cc: Ivan Teo <ivanteo@abwin.com.sg>; Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>; Teo, See Ling <seeling.teo@sompo.com.sg>; Teo, Grace <grace.teo@sompo.com.sg>

Subject: RE: CMTD1802447/GPL - NR/ GBD4866Y & RU4105G ACC ON 07/06/2018

Importance: High

Without Prejudice

Dear Ms Linda,

With reference to your email below, we would like to direct settle this case, however, based on our driver's statement and sketch below,

Our driver mentioned that he only hit the left front headlamp of RU4105G.

While we note that your client's damage may have previous damage at the front lower bumper area which is not related to the accident.

To be fair and impartial, we suggest to appoint an independent surveyor to assess based on the accident circumstances and taking the vehicle Height measurement, to advise us if the bumper damage is consistent to this accident.

Please assist to select below our panel of surveyor below.


In addition to this email, please confirm that once the surveyor provides their verification on damages, we seek your confirmation that your client will Abide by the surveyor's survey report.

Please advise and confirm, thank you.

Pre-Repair Survey

	Motor Surveyor
1	Raleigh Services
2	LKK Auto Consultants
3	Priority Services

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

WHILE REVERBINGLY I ACCIDENTALLY HIT THE FRONT
HEADLAMP (LEFT) THERE WAS A SLIGHT CRACK. <i>WCH</i>
OF OTHER VEHICLE



Damage are to be verified by independent surveyor :



Best Regards

Gnoh Pau Loong

Claims Division

D: 6329 5217 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Motor Claims [<mailto:motorclaims@abwin.com.sg>]

Sent: Monday, 25 June, 2018 10:09 AM

To: Teo, Grace <grace.teo@sompo.com.sg>

Cc: Ivan Teo <ivanteo@abwin.com.sg>; Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Subject: RE: CMTD1802447/GPL - NR/ GBD4866Y & RU4105G ACC ON 07/06/2018

Dear Grace

Please advise liability as soon as possible.

Thank you

Regards

ABWIN 論
輝

Abwin Service Pte Ltd
No. 8 Kaki Bukit Avenue 4
#07-48 Premier@Kaki Bukit Gate 2
Singapore 415875

Linda Liao

Motor Claim Executive

DID +65 6713 9417 HP:9751 9596

T +65 6713 9400 | F +65 6713 9415

[Website](#) | [Facebook](#) | [LinkedIn](#)

Looking to start a new business soon? Find out how we can provide you with a complete vehicle ownership solution and much more!

Click [here](#) to view our listing >>



From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]

Sent: Monday, 11 June, 2018 5:21 PM

To: Motor Claims <motorclaims@abwin.com.sg>

Cc: Ivan Teo <ivanteo@abwin.com.sg>; Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Chan, Shu Hui Agnes <agnes.chan@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Subject: CMTD1802447/GPL - NR/ GBD4866Y & RU4105G ACC ON 07/06/2018

Our Claim Reference: CMTD1802447/GPL

Your Reference: RU4105G

Hi Linda,

We regret to inform that we are unable to revert on liability as we have yet to receive our insured's accident report.

Kindly advise should you still require us to conduct survey on a "Without Prejudice" basis.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Motor Claims [<mailto:motorclaims@abwin.com.sg>]

Sent: Monday, June 11, 2018 5:22 PM

To: Teo, Grace

Cc: Ivan Teo; Gnoh, Pau Loong; Ye, Yong Kang Melvin

Subject: RE: CMTD1802447/GPL - GBD4866Y & RU4105G ACC ON 07/06/2018

Dear All

Please advise the liability as soon as possible.

Thank you

Regards

ABWIN 安輝

Abwin Service Pte Ltd

No. 8 Kaki Bukit Avenue 4

#07-48 Premier@Kaki Bukit Gate 2

Singapore 415875

Linda Liao

Motor Claim Executive

DID +65 6713 9417 HP:9751 9596

T +65 6713 9400 | F +65 6713 9415

[Website](#) | [Facebook](#) | [LinkedIn](#)

Looking to start a new business soon? Find out how we can provide you with a complete vehicle ownership solution and much more!

Click [here](#) to view our listing >>



Sales & Purchase of Pre-owned Commercial & Private Vehicles | Vehicle Service Centre | Vehicle Hire Purchase | Motor Insurance | G

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]

Sent: Monday, 11 June, 2018 2:01 PM

To: Motor Claims <motorclaims@abwin.com.sg>

Cc: Ivan Teo <ivanteo@abwin.com.sg>; Gnoh, Pau Loong <PauLoong.Gnoh@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Subject: CMTD1802447/GPL - GBD4866Y & RU4105G ACC ON 07/06/2018

Our Claim Reference: CMTD1802447/GPL

Your Reference: RU4105G

Hi Linda,

We acknowledged receipt of your claim documents.

Kindly re-direct your future motor claims survey request to motorsurvey@sompo.com.sg

Please be informed that Gnoh Pau Loong the handler of this case.

Kindly advise us when the vehicle is in for the survey.

Our in-house surveyor has proposed the vehicle to be left at your premises for the day or at least half a day/ few hours for survey.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Motor Claims [<mailto:motorclaims@abwin.com.sg>]

Sent: Friday, June 08, 2018 4:55 PM

To: claimsreport

Cc: Ivan Teo

Subject: Re: RU4105G Against GBD4866Y Date of accident : 07/06/2018

Dear Sir/ Madam

Please arrange survey before repair, the van not in.

Thank you

Regards

ABWIN 安穩

Abwin Service Pte Ltd

No. 8 Kaki Bukit Avenue 4

#07-48 Premier@Kaki Bukit Gate 2

Singapore 415875

Linda Liao

Motor Claim Executive

DID +65 6713 9417 HP:9751 9596

T +65 6713 9400 | F +65 6713 9415

[Website](#) | [Facebook](#) | [LinkedIn](#)

Looking to start a new business soon? Find out how we can provide you with a complete vehicle ownership solution and much more!

Click [here](#) to view our listing >>



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/06/2018 20:12
Date Of Accident	07/06/2018 16:20
Exact Location Of Accident	LOADING BAY OF 39 ARTILLERY AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	RU4105G
-----------------------------	---------

Insured/Policyholder

Name Of Registered Owner	SENTOSA DEVELOPMENT CORPORATION
Co Reg No	T08GB0048K
Email Address	GARY_ZHU@SENTOSA.GOV.SG
Mobile Phone No	(LOCAL) +65-96858253
Alternative Phone No	OFFICE-96858253

Vehicle Particulars

Manufacturer	NISSAN
Model	URVAN-3.0 D (M)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5083736033-01
Cover Note Number	

Driver

Name of Driver	GARY ZHU ZHIXIN
NRIC No	S8216138D
Date Of Birth	24/05/1982
Occupation	OUTDOOR
Date Of Driving Pass	15/12/2009
Driving Experience	8 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96858253
Fax Number	
Contact Number	
Email Address	GARY_ZHU@SENTOSA.GOV.SG

Address	316C YISHUN AVE 9 #11-168
Postcode	763316
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH

Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD4866Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ANG SIN KIAT
NRIC/Passport Number	S1364053Z
Contact Number	88000418
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN



A - RU4105G

B - GBD4866Y

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Van was parked ^{at loading bay} when lorry GBD4866Y reverse and hit front left head lamp no injuries reported, 2 witness was on site

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 07/06/2018

1700hrs

Reporting Centre Personnel's Signature
Name: Airwan De Souza
NRIC/FIN No.: S8234717H

Sketch Plan #2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Sentosa Development Corporation
38 Ardrey Avenue, Sentosa
Singapore 099558
Tel: 6275 0388 Fax: 6274 7749
E-mail: administrator@sentosa.com.sg

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 07/06/2018
1700hrs.

Reporting Centre Personnel's Signature
Name: Aiman De Souza
NRIC/FIN No.: S8234717H

Please arrange to survey vehicle at
8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT
SINGAPORE 415875

ABWIN 諭輝

Date : 08/06/2018
TP Vehicle No. : GBD-4866-Y
To : SOMPO INSURANCE SINGAPORE PTE. LTD.
Attn : Motor Claim Department

LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596

Owner : SENTOSA DEVELOPMENT CORPORATION
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5083736033-01
Vehicle No. : RU -4105-G
Make & Model : NISSAN URVAN 3.0M

Accident Date: 07/06/2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

List Item

1	BONNET	111 500	\$1,250.60	X
1	BONENT EMBLEM " SENTOSA"	11	\$150.00	X
1	FRONT GRILLE	11	\$350.00	X
1	FRONT BUMPER FOG LAMP COVER LH	130.10N 116 101	\$198.60	X
1	FRONT BUMPER FOG LAMP COVER RH	11	\$198.60	X
1	FRONT BUMPER FOG LAMP RH	11	\$325.60	X
1	FRONT BUMPER FOG LAMP LH	11	\$325.60	X
1	FRONT BUMPER LOWER GARNISH	11	\$258.60	X
	Sub Total		\$3,057.60	
	Discount 30% on Parts		(\$917.28)	
			\$2,140.32	

Nett Item

1	RH HEADLAMP	11	\$353.70	X
1	LH HEADLAMP	11	\$353.70	X
1	LH SIGNAL LAMP	186.30 11	\$450.60	X
1	RH SIGNAL LAMP	11	\$450.60	X
1	FRONT BUMPER RETAINER RH	11	\$75.00	X
1	FRONT BUMPER RETAINER LH	11	\$75.00	X
1	FRONT BUMPER BRACKET LH	11	\$85.60	X
1	FRONT BUMPER BRACKET RH	11	\$85.60	X
1	FRONT BUMPER	650.80 11	\$656.70	X
	Sub Total		\$2,586.50	
	Discount 10% on Parts		(\$258.65)	
			\$2,327.85	

Special Nett

1	FRONT NUMBER PLATE	11	\$65.00	X
1	FRONT BUMPER CLIPS	11	\$50.00	X
	Sub Total		\$115.00	

Date : 08/06/2018
 TP Vehicle No. : GBD-4866-Y
 To : SOMPO INSURANCE SINGAPORE PTE. LTD.
 Attn : Motor Claim Department

LINDA LIAO
 ABWIN SERVICE PTE LTD
 DID: 67139417
 Fax: 67139415
 HP: 97519596

Owner : SENTOSA DEVELOPMENT CORPORATION
 NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Certificate No. : 5083736033-01
 Vehicle No. : RU -4105-G
 Make & Model : NISSAN URVAN 3.0M

Accident Date: 07/06/2018

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

Labour & Misc

TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS
 TO SPRAY PAINT ON AFFECTED AREAS
 TOWING CHARGE *Two Trip*
 TO CHECK LIGHTING AND FOCUS HEADLAMP
 Sub Total

\$1,500.00 *280*
11 \$1,600.00 *X*
 \$250.00 *160*
 \$150.00 *20*
 \$3,500.00

Sub Total \$8,083.17
 GST 7% \$565.82
 Total \$8,648.99

p- 540
102
486

labor - 4260
946

LKK Auto Centre hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO18011591/Usd3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 28-07-2018



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 4866Y	Veh. Inspected	RU 4105G
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1802447/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	26/06/2018

2. Vehicle Particulars & Condition

Make & Model	NISSAN URVAN (M)	c.c	2953
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	JN1TG4E25Z0715198	Colour	WHITE
Odometer	54680	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	BRIDGESTONE	6 mm
L/H Front Tyre	195 R15	BRIDGESTONE	6 mm
R/H Rear Tyre	195 R15	BRIDGESTONE	6 mm
L/H Rear Tyre	195 R15	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/06/2018	Inspection Date	10/07/2018
Survey held at	ABWIN SERVICE PTE LTD No. 8 KAKI BUKIT AVENUE 4 #07-48 PREMIER@KAKI BUKIT GATE 2 SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. RU 4105G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BONNET (SCRATCHED)	NOT CONSISTENT WITH THE IMPACT	1,250.60	-
1	BONNET EMBLEM "SENTOSA"	NOT NECESSARY	150.00	-
1	FRONT GRILLE	NOT NECESSARY	350.00	-
1	FRONT BUMPER FOG LAMP COVER LH (TWISTED)	NOT CONSISTENT WITH THE IMPACT	198.60	-
1	FRONT BUMPER FOG LAMP COVER RH	NOT NECESSARY	198.60	-
1	FRONT BUMPER FOG LAMP RH	NOT NECESSARY	325.60	-
1	FRONT BUMPER FOG LAMP LH	NOT NECESSARY	325.60	-
1	FRONT BUMPER LOWER GARNISH	NOT NECESSARY	258.60	-
	LESS 30% DISCOUNT		-917.28	-
			2,140.32	-
<u>NETT ITEMS</u>				
1	RH HEADLAMP (N)	NOT NECESSARY	353.70	-
1	LH HEADLAMP (N)	CRACKED	353.70	353.70
1	LH SIGNAL LAMP (N)	CRACKED	450.60	186.30
1	RH SIGNAL LAMP (N)	NOT NECESSARY	450.60	-
1	FRONT BUMPER RETAINER RH (N)	NOT NECESSARY	75.00	-
1	FRONT BUMPER RETAINER LH (N)	NOT NECESSARY	75.00	-
1	FRONT BUMPER BRACKET LH (N)	NOT NECESSARY	85.60	-
1	FRONT BUMPER BRACKET RH (N)	NOT NECESSARY	85.60	-
1	FRONT BUMPER (DENTED)(N)	NOT CONSISTENT WITH THE IMPACT	656.70	-
	LESS 10% DISCOUNT		-258.65	-54.00
			2,327.85	486.00
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	65.00	-
1	FRONT BUMPER CLIPS (SN)	NOT NECESSARY	50.00	-
			115.00	-
<u>LABOUR</u>				
	TO STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS.		1,500.00	280.00
	TO SPRAY PAINT ON AFFECTED AREAS.	NOT NECESSARY	1,600.00	-
	TOWING CHARGE (TWO TRIP).		250.00	160.00

Report Ref No. CS/SMO18011591/Usd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK LIGHTING AND FOCUS HEADLAMP.		150.00	20.00
			3,500.00	460.00
GRAND TOTAL			8,083.17	946.00
RECOMMENDED COST OF REPAIRS				946.00

Report Ref No. CS/SMO18011591/Usd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.