

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SH 6210D

DATE 25/6/2018 11:50

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>x repair</i>			\$ 603.60
	Rear Bumper Clips 10 pcs <i>x 11</i>			\$ 22.00
	Rear Fender (RH) <i>x repair</i>			\$ 2,020.10
	Rear Fender Inner Lining (RH) <i>x 500</i>			\$ 164.40
	Rear Windscreen Moulding <i>x 11</i>			\$ 60.00
	Front Door Glass (RH) <i>1st</i>			\$ 379.55
	Front Door Mirror (RH) <i>Broken</i>			\$ 980.50
	Frt & Rear Wheel Hub-Cap (RH) <i>Front - changed</i>	<i>Per x 500</i>	\$ 150.70	\$ 301.40
	SUB TOTAL			\$ 4,531.55
	LESS 20%			\$ 906.31
	DISCOUNTED TOTAL			\$ 3,625.24
	Rear Bumper Advertisement Logo <i>✓ 11</i>			\$ 50.00
	Rear Bumper Rubber Mat <i>x 11</i>			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) <i>11</i>		\$ 100.00	\$ 200.00
	Rear Windscreen Sealant <i>x 11</i>			\$ 46.00
	Rear Door Comfortdelgro & Apps Sticker (RH) <i>11</i>			\$ 80.00
	Front Door Coloured Comfort Logo (RH) <i>11</i>			\$ 75.00
	Front Door Advertisement Logo (RH) <i>11</i>			\$ 100.00
	Front Fender Advertisement Logo (RH) <i>11</i>			\$ 100.00
				\$ 701.00
	Labour Charge			
	Panel Beating			\$ 1,000.00
	Spray Painting Charge			\$ 1,500.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Reverse Sensor			\$ 120.00
	Four Wheel Alignment			\$ 120.00
	TOTAL LABOUR			\$ 3,110.00
	ESTIMATE TOTAL			\$ 7,436.24
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Kalvin (11/11/18)
25/6/18 1510hrs
2 days
Before Paint p LK

PP