



Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005 92313188

ESTIMATE

Repair Code : CLM14598

Date in : 11/06/2018

Vehicle Num. : SLR8347K

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31253161/LEB5953180

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT LH DOOR / Bmc	1	852.00	852.00
FRONT LH DOOR BLACK TAPE / ABC	1	35.00	35.00
FRONT LH DOOR GLASS OUTER MOULDING X Lann	1	58.00	58.00
FRONT LH DOOR SIDE MIRROR X	1	606.00	606.00
FRONT LH DOOR SIDE MIRROR COVER / Cut	1	78.00	78.00
FRONT LH FENDER ARCH GARNISH / SER	1	201.00	201.00
REAR LH DOOR TRANSPARENT STICKER / ABC	1	35.00	35.00
REAR LH FENDER ARCH GARNISH / Cut	1	201.00	201.00
ROCKER GARNISH LH / Cut	1	377.00	377.00
Subtotal before discount			2,443.00
Percentage discount 20%			488.60
Sub-total 1			1,954.40
FRONT LH FENDER ARCH GARNISH CLIPS - SET /	1	50.00	50.00
REAR LH FENDER ARCH GARNISH CLIPS - SET /	1	50.00	50.00
ROCKER GARNISH LH CLIPS - SET /	1	100.00	100.00
Subtotal before discount			200.00
Percentage discount 0%			0.00
Sub-total 2			200.00
Parts-total			2,154.40

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005 92313188

ESTIMATE

Repair Code : CLM14598

Date in : 11/06/2018

Vehicle Num. : SLR8347K

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31253161/LEB5953180

LABOUR

To remove, reinstall window glass. (to FR)

40 100.00

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

60 120.00

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

500 750.00

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

400 750.00

To apply anti-rust chemical on repaired and replaced panel.

40 120.00

Labour Total

1,840.00

Parts & Labour Total

3,994.40

*** This is a computer-generated document which requires no signature.***

page 2

SDays.

1ump sum repair

After repair photos.

Guo Qiang - 8288 0282

27/6/18