



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147
 Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
 E-mail: ryan@kanfs.net/ patricia@kanfs.net
 Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
 Tel: (65) 6481 5150 Fax: (65) 6481 8683

AXA INSURANCE SINGAPORE PTE LTD
 8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811

DATE : 25-06-2018

VEHICLE NO. : SLV9160D
 ACCIDENT DATE : 22-06-2018 15:50
 THIRD PARTY REF. : CB7553D

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEICLE SLV9160D HONDA CIVIC

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	FRONT FENDER RH <i>50d520</i>	537.00
2	1	FRONT FENDER LAMP RH <i>scr</i>	18.20
3	1	FRONT FENDER SHIELD RH <i>Torn/ol</i>	94.80
4	10	FRONT FENDER SHIELD CLIP @ \$3.50 <i>new</i>	35.00
			<hr/>
			685.00
			ADD 20 %
			<hr/>
			137.00
			<hr/>
			TOTAL (A)
			<hr/>
			822.00

*not authorized
 take
 28/6/18
 1/5 #1050
 3 days
 take photo of the rep*

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM	30.00	<i>20</i>
2	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS	450.00	<i>300</i>
3	1	SPRAYPAINTING CHARGES	400.00	<i>✓</i>
4	1	TO CHECK ALIGNMENT	80.00	<i>60</i>
			<hr/>	
			TOTAL (D)	
			<hr/>	
			960.00	

ESTIMATE TOTAL

1,782.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

45 1050

1328
1062.4