

ASS. REC. BY:

REF: CS/CTL18011644/Ksbnz | Special Instruction:

SUPERVISOR:

Kenneth

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTL

Date/Time:

26062018 3:33pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJF 1395D

Insured:

SJE 1631C

at Workshop m/s

Cheng Hoe Motor

Tel:

6755 6142

of

Bik 7019 Yishun Ind Park A # 01-374

Policy No:

DMPCSN 3030841705

Claim No:

SNM18D03145022

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23062018

CA / REV / REP. / REV 24 HRS wpi

Bik 10 AMK Ind Park 2A #01-04

H.O.D. Endorsement:

Date/Time:

26062018

11:30pm

Person Contacted:

June

Vehicle

IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SJF 1395D - CS3 / MS615003838 / Miguel DCA: 041815
	SJE 1631C - NA / INC180114413 / h14 DCA: 230618
12/19	\$5028 Confirmed Effects
12/09/18	Confirmed P/R \$5,028.00 @ 8 days with Kenneth (\$2,430.00 Red - 33%)

ASS. REC. BY:

REF: CT21


Kenneth

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s Cheng Hoe
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: JK 1395D Yr Regn: 08, 17
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Mit Attrax c.c. 1193
 Colour: M.P. White A/C: Insured / Std / NI / NA
 Sp. Reading 51286 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: NMB STA13A1414 005492
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Mod: NII / S/Rim / STD A/Rim or _____
 Tyre Size: F: _____
 R: 185/60R15

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 8-142 days Res.: Yes or No
 Lum Sum: 1.B.1 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. 2 mm R/Bal. 8 mm
 L/Bal. 2 mm L/Bal. 8 mm
 D.O.A. 23/6/18 D.O.I. 26/6/18
 Survey held at _____
 Des. of Damages: Frit / Rear / O/S / N/S / UIC / Rooftop or _____
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>27/6</u>	<u>File pass to Corinne</u>
RECEIVED - 3 SEP 2018	

Date/Time, File Pass to? 13/09/18
 1) Typist
 Date/Time, File Return to? _____

: Prell. Report
 : Final Report

Days Of Repair: 8
 Resurvey No. of Trip: 2

Report Format : _____
 Lump Sum / I.B.I: (\$) 5,028.00 p/c

Add Fee: : Site Insp (\$))
 : Interview (\$))
 : Tech Invs (\$))
 : Weekend (\$))

Survey Fee: _____
 Transportation: _____
 S + RS: \$ _____
 Fixos: _____
 Others: _____

TOTAL 220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	25 Jun 2018 Sendback Est	25 Jun 2018 15:42 S\$7,458.00	26 Jun 2018 15:23 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS									
Insured:	ANG SWEE HONG PAUL, ID: S1804971F								
Main Claimant:	CHIA HUI HONG, Co. Reg. No.: 53360655A								
Vehicle Reg. No.:	SJF1395D	Date of Loss:	23/06/2018 15:00 - :59 [10 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D03145C02	Policy/Cover Note No.:	DMPCSN3030841705						
Vehicle Reg. No. (Insured):	SJE1631C	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/07/2018]								
Driver/Custodian (Insured):	ANG SWEE HONG PAUL (/ Male), NRIC: S1804971F								
Adj Asg. Remarks:	EST \$7980.06 , CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED									
			View All Compose Case Mail						
There are no mail for this case.									
ALL ASSOCIATED TASKS									
			View All Search Tasks Create New Task Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

PARF/COE Rebate Enquiry

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	0655A
Vehicle Details	
Vehicle No.:	SJF1395D
Vehicle to be Exported:	No
Intended De-registration Date:	25 Jun 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	ATTRAGE 1.2 CVT
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	3A92UGA7120
Chassis No.:	MMBSTA13AHH005492
Maximum Power Output:	57.0 kW (76 bhp)
Open Market Value:	\$13,011.00
Original Registration Date:	14 Aug 2017
First Registration Date:	14 Aug 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Aug 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	13 Aug 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,801.00
COE Rebate Amount:	\$39,096.00
Total Rebate Amount:	\$42,846.00

The information contained herein is correct as at 25 Jun 2018

OK



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761
Tel : 67556142 Fax : 67557719
Email: chmotor@singnet.com.sg

TP INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
ANG SWEE HONG PAUL

Singapore

PARTICULARS OF CLAIM

Claim Type:	Third Party	Ref. No:	TP/CHINA(SJE1631C)
Policy No:		Date of Loss:	23/06/2018
Vehicle Reg. No.:	SJF1395D	Driveable?	
Party At Fault:	UNKNOWN	Driver (Insured):	ANG SWEE HONG PAUL
Driver (TP):	CHIA HUI HONG		
Make/Model:	mitsubishi attrage, 1.2 CVT (A)	Vehicle Reg. Date:	14/08/2017
Vehicle Colour:	White	Chassis No:	MMBSTA13AHH005492
Engine No:	3A92UGA7120		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Remarks:	VEHICLE CURRENTLY LYING AT ANG MO KIO WORKSHOP.		
Present Location:	CHENG HOE MOTOR PTE LTD (ANG MO KIO)		

Not Authorized
Resurvey B4 paint 8-12 days

COST OF CLAIMS	Amount
Parts	3,518.00
Miscellaneous Items	240.00
Labour	3,700.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	7,458.00
+ GST 7.00% (\$\$)	522.06
Nett Amount (\$\$)	7,980.06

This claim is handled by: SHARON CHIONG BENG CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 25 Jun 2018)
Parts: N/A MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Cheng Hoe Motor Pte Ltd/SJF1395D/25/06/2018 15:42
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	R 0.00	0.00	*380.00 F
2	1		*REAR BUMPER LH REFLECTOR	MJCM 0.00	0.00	*15.00 F
3	2		*REAR BUMPER SIDE RETAINERS (\$18/PCE)	D 0.00	0.00	*36.00 F
4	6		*REAR BUMPER CLIPS (\$2/PCE)	M 0.00	0.00	*12.00 F
5	2		*TAILLAMPS (\$180/PCE)	MJCM 0.00	0.00	*360.00 F
6	1		*RH TAILLAMP PANEL		0.00	R *62.00 F
7	1		*REAR BOOT	R 0.00	0.00	*490.00 F
8	1		*REAR BOOT INNER LOCK	D 0.00	0.00	*130.00 F
9	1		*REAR BOOT INNER RUBBER	Dd D 0.00	0.00	*115.00 F
10	1		*REAR BOOT LOGO	M 0.00	0.00	*32.00 F
11	1		*REAR BOOT EMBLEM (ATTRAGE)	M 0.00	0.00	*35.00 F
12	1		*REAR BOOT EMBLEM (MIVEC)	M 0.00	0.00	*35.00 F
13	2		*REAR BOOT HINGES (\$120/PCE)		0.00	R *240.00 F
14	2		*REAR FENDERS (\$495/PCE)		0.00	R *990.00 F
15	1		*REAR SPARE TYRE TOP BOARD	CM 0.00	0.00	*138.00 F
16	1		*SMART KEY SENSOR		0.00	R *70.00 F
17	1		*REAR END PANEL	R 0.00	0.00	*298.00 F
18	1		*REAR END PANEL INNER TOP GARNISH	MJCM 0.00	0.00	*80.00 F
Total Parts (S\$)						3,518.00

F=Franchise part.

Cheng Hoe Motor Pte Ltd/SJF1395D/25/06/2018 15:42. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	REAR WINDSCREEN GLASS GUM	40.00 <i>nn</i>
2	1	SET REVERSE SENSOR	200.00 <i>nn</i>
Sub Total (\$)			240.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	REMOVE & REFIX REAR WINDSCREEN GLASS	New	100.00 <i>nn</i>
2	REMOVE & REFIX SEAT,CARPET,GARNISH,ETC	New	120.00 <i>100</i>
3	PANEL BEATING	New	1,800.00 <i>2000</i>
4	PUTTY & RESPRAY PAINT	New	1,500.00 <i>1400</i>
5	REMOVE & REFIX REVERSE CARMERA & RESET SYSTEM	New	60.00 <i>50</i>
6	RUSTPROOFING	New	120.00 <i>80</i>
Gross Labour Cost (\$)			3,700.00

Cheng Hoe Motor Pte Ltd/SJF1395D/25/06/2018 15:42. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants Pte Ltd (Co.Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18011644/KSBN2
Date: 14/09/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3030841705
Claimant Vehicle No :	SJF1395D	Insured Vehicle No :	SJE1631C
Date of Loss:	23/06/2018	Nature of Claim:	TP
		Claim No:	SNM18D03145C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJF1395D	Engine No:	3A92UGA7120
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AHH005492
Reg. Date:	14/08/2017 (Man. Year: 2017)	Odometer:	51286 km
Colour:	Metallic Pearl White		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Bridgestone 2 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 2 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,518.00	2,218.00	1,300.00	36.95
Miscellaneous Items	240.00	200.00	40.00	16.67
Labour	3,700.00	2,610.00	1,090.00	29.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,458.00	5,028.00	2,430.00	32.58
+ GST 7.00/7.00% (S\$)	522.06	351.96	170.10	32.58
Nett Amount (S\$)	7,980.06	5,379.96	2,600.10	32.58

INSPECTION

Date of Assignment:	26/06/2018 Present Location:	Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected:	26/06/2018 Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761

Estimated Period of Repair: 8.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 14 Sep 2018)
Parts: N/A MITSUBISHI ATTRAGE 1.2 CVT (A) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJF1395D)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	380.00 F	*380.00 F
2	1		*REAR BUMPER LH REFLECTOR	Mtg Cracked	15.00 F	*15.00 F
3	2		*REAR BUMPER SIDE RETAINERS (\$18/PCE)	Distorted	36.00 F	*36.00 F
4	6		*REAR BUMPER CLIPS (\$2/PCE)	Necessary	12.00 F	*12.00 F
5	2		*TAILLAMPS (\$180/PCE)	Mtg Cracked	360.00 F	*360.00 F
6	1		*RH TAILLAMP PANEL	Bent	62.00 F	*62.00 F
7	1		*REAR BOOT	Bent	490.00 F	*490.00 F
8	1		*REAR BOOT INNER LOCK	Distorted	130.00 F	*130.00 F
9	1		*REAR BOOT INNER RUBBER	Dented/Distorted	115.00 F	*115.00 F
10	1		*REAR BOOT LOGO	Necessary	32.00 F	*32.00 F
11	1		*REAR BOOT EMBLEM (ATTRAGE)	Necessary	35.00 F	*35.00 F
12	1		*REAR BOOT EMBLEM (MIVEC)	Necessary	35.00 F	*35.00 F
13	2		*REAR BOOT HINGES (\$120/PCE)	Repair	240.00 F	*- F
14	2		*REAR FENDERS (\$495/PCE)	Repair	990.00 F	*- F
15	1		*REAR SPARE TYRE TOP BOARD	Cracked	138.00 F	*138.00 F
16	1		*SMART KEY SENSOR	Serviceable	70.00 F	*- F
17	1		*REAR END PANEL	Bent	298.00 F	*298.00 F
18	1		*REAR END PANEL INNER TOP GARNISH	Mtg Cracked	80.00 F	*80.00 F
Total Parts (S\$)					3,518.00	2,218.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	REAR WINDSCREEN GLASS GUM (Not Necessary)	40.00	0.00
2	1	SET REVERSE SENSOR (Dented)	200.00	200.00
Sub Total (S\$)			240.00	200.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX REAR WINDSCREEN GLASS	New	100.00	-
2	REMOVE & REFIX SEAT,CARPET,GARNISH,ETC	New	120.00	100.00
3	PANEL BEATING	New	1,800.00	1,000.00
4	PUTTY & RESPRAY PAINT	New	1,500.00	1,400.00
5	REMOVE & REFIX REVERSE CARMERA & RESET SYSTEM	New	60.00	50.00
6	RUSTPROOFING	New	120.00	60.00
Gross Labour Cost (S\$)			3,700.00	2,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >