

SS. REC. BY:

REF:

CS/CTU8011652/Vg b 9/1

Special Instruction:

SUPERVISOR

ASSIGNMENT (Office)

From (Person):

Jowyn Tay

of

CTU

Date/Time:

26062018 338pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

9LW 3946U

Insured:

AZ 55508

at Workshop m/s

Kah Motor

Tel:

8288 6309

of

6A Manda Estate

Policy No:

DMCV 9N17 62611700

Claim No:

9NM18D 03131C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23062018

CA / REV / REP. / REV 24 HRS WP

H.O.D. Endorsement:

Date/Time:

26062018

Person Contacted:

Jason

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	9LW 3946U - X
	AZ 55508 - 9LW/9LW 10000000 / K200262
18/7/18 @ 10.00am	confirmed with Jason Heng final fig. @ 7008.92, 6 days by email. CPD @ 1200.58, 15%.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Jun 2018		25 Jun 2018 15:38 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

Insured:	[Created by insurer]		
Main Claimant:	WANG AI		
Vehicle Reg. No.:	SLW2946U	Date of Loss:	23/06/2018 00:00 - :59
Claim Type:	TP / SNM18D03131C02	Policy/Cover Note No.:	DMCVSN1762611700
Vehicle Reg. No. (Insured):	GZ5550B	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Kah Motor Co Sdn Bhd (HQ) 6A MANDAI ESTATE, SINGAPORE 729903, 729903 Mandai - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/07/2018]		
Adj Asp. Remarks:	EST \$11,312.42 , CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

View All

Compose Case Mail

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
No results.						Assigned By	Completed On	Created On	Done?

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 18 July 2018 10:06 AM
To: 'Jason Heng'
Cc: Sathya Sai (LKK Auto); SUR
Subject: RE: Finalization - SLW2946U

Dear Jason,

WITHOUT PREJUDICE

Confirm final fig \$7,008.92 before GST and 6 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jason Heng [mailto:jasonheng@honda.com.sg]
Sent: Tuesday, 17 July 2018 9:53 AM
To: Sebastian Yeang (LKK Auto) <SebastianYeang@lkkauto.com>
Cc: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Subject: Finalization - SLW2946U
Importance: High

Dear Sathya,

We enclosed the total final repair costs for,

Vehicle No.	SLW2946U
Final Repair Costs (exclude GST)	\$7,008.92
Repair Period* (Days)	8 days

***Note: Repair period does include Sunday and Public Holiday.**

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

In addition, I have attached photos of before paint, '?' items and supplementary parts (if any) for your records.

NB: I will be leaving Kah Motors after July and to avoid any issues or delays with closing, I would appreciate if you can come back to me soonest.

Thank you for your assistance, support and cooperation during my time with Kah Motors.

Regards,

Jason

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/06/2018 13:34
Date Of Accident	23/06/2018 09:30
Exact Location Of Accident	JUNCTION TO WOODLANDS AVE 12 TOWARDS SLE SLIP RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW2946U
Insured/Policyholder	
Name Of Registered Owner	WANG AI
NRIC No	S8274643I
Email Address	WANGAI@GMAIL.COM
Mobile Phone No	(LOCAL) +65-81836621
Alternative Phone No	OTHERS-81836621

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT000538
Cover Note Number	

Driver

Name of Driver	FU XIN
NRIC No	S8855904E
Date Of Birth	14/11/1988
Occupation	INDOOR
Date Of Driving Pass	11/06/2018
Driving Experience	0 YEAR AND 0 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-92376516
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	690F WOODLANDS DR 75 #11-10
Postcode	736690
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : WANG SIJIA GENDER: : FEMALE
Passenger 2	NAME: : XU XIAO FENG GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GZ5550B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	TAN AH GUAN
NRIC/Passport Number	S2762063I
Contact Number	97453239
Address	
Postcode	
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Nature Of Damage

No. Of Passenger (Including Driver)

Vehicle No SLW2946U**SKETCH PLAN**

Annex D

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

A = SLW2946U

B = GZ5550B



Woodlands Ave 12

Please continue to Annex E

Sketch Plan Pg. 2

Vehicle No

SLW29468

Annex E

Describe Circumstances of the Accident

- At the junction of Woodlands Ave 12 towards SE.
- The traffic ^{light} is changed from Green to yellow signal, so I stop my car and wait for the traffic light to turn Green.
- Then the rear car No. G3 5508B hit my car back.
- No one was injured

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel



KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	Document No.	: SQT18002588	Page	1
Registration No	: SLW2946U	Date	: 23. Jun 2018		
Chassis No	: MRHFC5650HT000846	Customer No.	: WZC008		
Model	: CIVIC 1.6 VTI YM2017	Svc Advisor	:		
Owner's Name	: WANG AI	Engine No	: R16B22001301		
Ins Policy No.	: TP DIRECT SETTLEMENT	Date Time	: 23. Jun 2018 1:50:29 PM		
Date of Accident	: 23/6/2018	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	THIRD PARTY CLAIMS (J/NO:) OWNER: WANG AI OWNER INSURER: TOKIO MARINE INSURANCE ACC DATE: 23/6/18 SURVEYED BY: DATE: TP INSURER: CHINA TAIPING INSURANCE (S'PORE) PTE L TP VEH: GZ5550B						
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER ✓CRK	1	617.20	25	462.90	32.40	495.30
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER ✓return	1	38.20	25	28.65	2.01	30.66
71593-TEA-T01	SPACERR,RR.BUMPER SIDE ✓return	1	11.50	25	8.62	0.60	9.22
71598-TEA-T01	SPACERL,RR.BUMPER SIDE ?	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIPBUMPER ✓NEC	7	2.00	25	10.50	0.74	11.24
71503-TEA-T00	GARNISHR,RR.BUMPER SIDE X	1	7.60	25	5.70	0.40	6.10
71508-TEA-T00	GARNISHL,RR.BUMPER SIDE X	1	7.60	25	5.70	0.40	6.10
71505-TBA-A00	BRACKETR,RR.BUMPER SIDE ?	1	2.20	25	1.65	0.12	1.77
71555-TBA-A00	BRACKETL,RR.BUMPER SIDE ?	1	2.20	25	1.65	0.12	1.77
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER ? BT	1	173.00	25	129.75	9.08	138.83
68500-TEA-N00ZZ	LID COMP TRUNK ✓DT	1	472.10	25	354.07	24.78	378.85
75722-TBA-A00	EMBLEM SETRR. ✓NEC	1	11.50	25	8.62	0.60	9.22
75725-TEA-T01	EMBLEMRR. ✓NSC	1	10.60	25	7.95	0.56	8.51
74890-TEA-T11ZB	GARNISH ASSYRR.LICENSE ? VE	1	97.70	25	73.27	5.13	78.40
68610-TEA-T10ZZ	HINGE COMPR,TRUNK ✓DT	1	43.50	25	32.62	2.28	34.90
68660-TEA-T10ZZ	HINGE COMPL,TRUNK ✓DT	1	43.50	25	32.62	2.28	34.90
74865-TEA-T01	WEATHERSTRIPTRUNK LID ✓BT	1	70.00	25	52.50	3.68	56.18
84640-TEA-Z01ZA	LINING ASSYRR.PANEL ?	1	50.30	25	37.72	2.64	40.36
66100-TEC-307ZZ	PANEL SETRR. ? BT	1	236.00	25	177.00	12.39	189.39
33500-TEA-T01	TAILLIGHT ASSYR. ✓BR	1	253.80	25	190.35	13.32	203.67
33550-TEA-T01	TAILLIGHT ASSYL. X	1	273.10	25	204.82	14.34	219.16



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SLW2946U
Chassis No : MRHFC5650HT000846
Model : CIVIC 1.6 VTI YM2017
Owner's Name : WANG AI
Ins Policy No. : TP DIRECT SETTLEMENT
Date of Accident : 23/6/2018

Document No. : SQT18002588 **Page** 2
Date : 23. Jun 2018
Customer No. : WZC008
Svc Advisor :
Engine No : R16B22001301
Date | Time : 23. Jun 2018 1:50:29 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
34150-TEX-Y01	LIGHT ASSYR.LID X	1	118.70	25	89.02	6.23	95.25
34155-TEX-Y01	LIGHT ASSYL.LID X	1	118.70	25	89.02	6.23	95.25
39680-TEX-Y41ZT	SENSOR ASSYPARKING ?	4	79.80	25	239.40	16.76	256.16
91540-TAA-003	CLIPHARNES BAND ?	4	0.20	25	0.60	0.04	0.64
32131-TEA-R00	SUB CORDRR.BUMPER CORNER SENS ?	1	27.20	25	20.40	1.43	21.83
38387-TZ5-A01	ANTENNA ASSYL.F. ?	1	58.10	25	43.57	3.05	46.62
74940-SZW-003	BUZZER ASSYSMART ?	1	60.10	25	45.07	3.15	48.22
Sum Item					2362.36	165.36	2,527.72

BOSUN	SUNDRIES N4	1	100.00	20	100.00	7.00	107.00
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	160.00	10	160.00	11.20	171.20
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	160.00	10	160.00	11.20	171.20
BOJSE	BODY JOINT SEALANT FOR TRUNK	1	100.00	10	100.00	7.00	107.00
BOJSE	BODY JOINT SEALANT FOR END PANEL	1	100.00	10	100.00	7.00	107.00
BOMISC1	RESET & CALIBRATE REAR VIEW CAMERA (N)	1	160.00	✓	160.00	11.20	171.20
BOMISC1	RESET & CALIBRATE SMART ENTRY SYSTEM (N)	1	160.00	✓	160.00	11.20	171.20
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00	50	650.00	45.50	695.50
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN	1	3920.00	2240.00	3920.00	274.40	4194.40
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2700.00	1350.00	2700.00	189.00	2889.00
Sum Labor					8210.00	574.70	8,784.70

Survey By

Date & Time

Excess

Status

Signature

Total Amount 10,572.36 740.06 11,312.42

Total (Inclusive of GST)

11,312.42

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sathya Sai
2/7/18

- Part by Part

- Question mark items photo

- Photo before paint.

Printed on 23/6/2018 2:06:01 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

829.50

5-6 days
4/7/18



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZC008 / CHINA TAIPING
Chassis No: MRHFC5650HT000846
License No: SLW2946U
Mileage: 7018
Engine No: R16B22001301

Document No: SVO18038334
Printed By: JASONHENG
Order Date: 2. July 2018
Order Time: 2:45:31 PM
Service Advisor: JASON HENG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	THIRD PARTY CLAIMS (J/NO: 09213)						
	OWNER: WANG AI						
	OWNER INSURER: TOKIO MARINE INSURANCE						
	ACC DATE: 23/6/18						
	SURVEYED BY:						
	DATE:						
	TP INSURER: CHINA TAIPING INSURANCE (S'PORE) PTE L						
	TP VEH: GZ5550B						
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	✓CRK 25	462.90	32.40	495.30
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	38.20	✓Defect 25	28.65	2.01	30.66
71593-TEA-T01	SPACERR,RR.BUMPER SIDE	1	11.50	✓Defect 25	8.62	0.60	9.22
91505-TM8-003	CLIPBUMPER	7	2.00	✓NEC 25	10.50	0.74	11.24
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1	173.00	✓OT 25	129.75	9.08	138.83
68500-TEA-N00ZZ	LID COMP TRUNK	1	472.10	✓OT 25	354.07	24.78	378.85
75722-TBA-A00	EMBLEM SETRR.	1	11.50	✓NEC 25	8.62	0.60	9.22
75725-TEA-T01	EMBLEMRR.	1	10.60	✓NEC 25	7.95	0.56	8.51
74890-TEA-T11ZB	GARNISH ASSYRR.LICENSE	1	97.70	✓Vokker 25	73.27	5.13	78.40
68610-TEA-T10ZZ	HINGE COMPR.TRUNK	1	43.50	✓OT 25	32.62	2.28	34.90
68660-TEA-T10ZZ	HINGE COMPL.TRUNK	1	43.50	✓OT 25	32.62	2.28	34.90
74865-TEA-T01	WEATHERSTRIPTRUNK LID	1	70.00	✓OT 25	52.50	3.68	56.18
66100-TEC-307ZZ	PANEL SETRR.	1	236.00	✓OT 25	177.00	12.39	189.39
33500-TEA-T01	TAILLIGHT ASSYR.	1	253.80	✓BR 25	190.35	13.32	203.67
66114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE	1	26.00	✓CRK 25	19.50	1.37	20.87
	SUM PARTS:				1,588.92	111.22	1,700.14
BOSUN	0701	1	20.00	✓	20.00	1.40	21.40
	SUNDRIES						
BML021	1757	1	160.00	✓	160.00	11.20	171.20
	INSPECT RR LIGHTING MECHANISMS, PERFORM WATER TEST.(N)						
BA02R	0671	1	160.00	✓	160.00	11.20	171.20
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)						
BOJSE	0671	1	80.00	✓	80.00	5.60	85.60
	BODY JOINT SEALANT FOR TRUNK						
BOJSE	0671	1	80.00	✓	80.00	5.60	85.60
	BODY JOINT SEALANT FOR END PANEL						
BOMISC1	0671	1	160.00	✓	160.00	11.20	171.20
	RESET & CALIBRATE REAR VIEW CAMERA (N)						
BOMISC1	0671	1	160.00	✓	160.00	11.20	171.20
	RESET & CALIBRATE SMART ENTRY SYSTEM (N)						
BMI03D	0671	1	560.00	✓	560.00	39.20	599.20
	REMOVE & INSTALL REAR COMPARTMENT LININGS GARNISHES.(N)						
BKRP02M	0671	1	2,240.00	✓	2,240.00	156.80	2,396.80
	CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN RR FLOOR PAN & RENEW DAMAGE PARTS.						



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZC008 / CHINA TAIPING

Chassis No: MRHFC5650HT000846

License No: SLW2946U

Mileage: 7018

Engine No: R16B22001301

Document No: SVO18038334

Printed By: JASONHENG

Order Date: 2. July 2018

Order Time: 2:45:31 PM

Service Advisor: JASON HENG

BP05R	1610	1	1,800.00	1,800.00	126.00	1,926.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)					
			SUM LABOUR:	5,420.00	379.40	5,799.40
			TOTAL SGD	7,008.92	490.62	7,499.54
Total Payable (SGD)						7,499.54

GST Amount is calculated from individual line(s)

1588.92
+ 5420.00

\$ 7008.92
confirmed



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: S8274643I / WANG AI
Chassis No: MRHFC5650HT000846
License No: SLW2946U
Mileage: 7018
Engine No: R16B22001301

Document No: SVO18038334
Printed By: JASONHENG
Order Date: 2. July 2018
Order Time: 2:45:31 PM
Service Advisor: JASON HENG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	SUPPLEMENTARY PART						
66114-TBA-A00ZZ	STIFFENER,R.RR.PANEL SIDE	1	26.00	25	19.50	1.37	20.87
	SUM PARTS:				19.50	1.37	20.87
	TOTAL SGD				19.50	1.37	20.87
	Total Payable (SGD)						20.87

GST Amount is calculated from individual line(s)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Jun 2018		25 Jun 2018 15:38 Edit Adj Rpt	S\$7,008.92 Edit Estimates	S\$7,008.92 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	ID: -								
Main Claimant:	WANG AI								
Vehicle Reg. No.:	SLW2946U	Date of Loss:	23/06/2018 00:00 - :59 [4 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D03131C02	Policy/Cover Note No.:	DMCVSN1762611700						
Vehicle Reg. No. (Insured):	GZ5550B	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Kah Motor Co Sdn Bhd (HQ) 6A MANDAI ESTATE, SINGAPORE 729903, 729903 Mandai - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sathya Sai Kathirrasen] ... [Final Rpt due 04/07/2018]								
Adj Asg. Remarks:	EST \$11,312.42 , CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLW2946U (SNM18D03131C02)
[GZ5550B]
TP
WANG AI
Jun 23 2018 12:00AM
[-]
Kah Motor Co Sdn Bhd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/07/18 10:11	General View		 Load JPG	☒
2	04/07/18 10:11	General View		 Load JPG	☒
3	04/07/18 10:11	General View		 Load JPG	☒
4	04/07/18 10:11	General View		 Load JPG	☒
5	04/07/18 10:11	General View		 Load JPG	☒
6	04/07/18 10:11	General View		 Load JPG	☒
7	04/07/18 10:11	General View		 Load JPG	☒
8	04/07/18 10:11	General View		 Load JPG	☒
9	04/07/18 10:11	General View		 Load JPG	☒
10	04/07/18 10:11	General View		 Load JPG	☒
11	04/07/18 10:11	General View		 Load JPG	☒
12	04/07/18 10:11	General View		 Load JPG	☒
13	04/07/18 10:11	General View		 Load JPG	☒
14	04/07/18 10:11	General View		 Load JPG	☒
15	04/07/18 10:11	General View		 Load JPG	☒
16	04/07/18 10:11	General View		 Load JPG	☒
17	04/07/18 10:11	General View		 Load JPG	☒
18	04/07/18 10:11	General View		 Load JPG	☒
19	04/07/18 10:11	General View		 Load JPG	☒
20	04/07/18 10:11	General View		 Load JPG	☒
21	04/07/18 10:11	General View		 Load JPG	☒
22	04/07/18 10:11	General View		 Load JPG	☒
23	04/07/18 10:11	General View		 Load JPG	☒
24	04/07/18 10:11	General View		 Load JPG	☒
25	04/07/18 10:11	General View		 Load JPG	☒
26	04/07/18 10:11	General View		 Load JPG	☒
27	04/07/18 10:11	General View		 Load JPG	☒
28	04/07/18 10:11	General View		 Load JPG	☒
29	04/07/18 10:11	General View		 Load JPG	☒
30	04/07/18 10:11	General View		 Load JPG	☒
31	04/07/18 10:11	General View		 Load JPG	☒
32	04/07/18 10:11	General View		 Load JPG	☒
33	04/07/18 10:11	General View		 Load JPG	☒
34	04/07/18 10:11	General View		 Load JPG	☒
35	04/07/18 10:11	General View		 Load JPG	☒
36	04/07/18 10:11	General View		 Load JPG	☒
37	04/07/18 10:11	General View		 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	04/07/18 10:11	Chassis Number	 Load JPG	☒
39	04/07/18 10:11	Odometer Reading	 Load JPG	☒
40	04/07/18 10:11	General View	 Load JPG	☒
41	04/07/18 10:11	General View	 Load JPG	☒
42	04/07/18 10:11	General View	 Load JPG	☒
43	17/07/18 12:06	Dismantled Parts	 Load JPG	☒
44	17/07/18 12:06	Dismantled Parts	 Load JPG	☒
45	17/07/18 12:06	Dismantled Parts	 Load JPG	☒
46	17/07/18 12:06	Dismantled Parts	 Load JPG	☒
47	17/07/18 12:06	Dismantled Parts	 Load JPG	☒
48	17/07/18 12:06	Dismantled Parts	 Load JPG	☒
49	17/07/18 12:06	Dismantled Parts	 Load JPG	☒
50	17/07/18 12:06	Dismantled Parts	 Load JPG	☒
51	17/07/18 12:06	Dismantled Parts	 Load JPG	☒
52	17/07/18 12:06	Dismantled Parts	 Load JPG	☒
53	17/07/18 12:06	Dismantled Parts	 Load JPG	☒
54	17/07/18 12:06	Dismantled Parts	 Load JPG	☒
55	17/07/18 12:07	BEFORE PAINT	 Load JPG	☒
56	17/07/18 12:07	BEFORE PAINT	 Load JPG	☒
57	17/07/18 12:07	BEFORE PAINT	 Load JPG	☒
58	17/07/18 12:07	BEFORE PAINT	 Load JPG	☒
59	17/07/18 12:07	BEFORE PAINT	 Load JPG	☒
60	17/07/18 12:07	BEFORE PAINT	 Load JPG	☒
61	17/07/18 12:07	BEFORE PAINT	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/06/18 15:37	REPAIR EST	 Load PDF	
2	25/06/18 15:37	TP GIA REPORT	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/07/18 16:46	SUPPLEMENTARY PART	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18011652/VQBQ2

Date: 24/07/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN1762611700

Claimant Vehicle
No : SLW2946UInsured Vehicle
No : GZ5550B

Date of Loss: 23/06/2018

Nature of Claim: TP

Claim
No: SNM18D03131C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLW2946U

Make & Model: HONDA CIVIC, 1.6 (A)

Reg. Date: 05/02/2018 (Man. Year: 2017)

Colour: Grey

Engine Capacity: 1597 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: R16B22001301

Chassis No: MRHFC5650HT000846

Odometer: 7018 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R16

Rear Tyre Size: 215/55 R16

Front Left Side: Hankook 6 mm

Rear Left Side: Hankook 6 mm

Front Right Side: Hankook 6 mm

Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,481.86	1,608.92	872.94	35.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,110.00	5,400.00	2,710.00	33.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,591.86	7,008.92	3,582.94	33.83
+ GST 7.00/7.00% (S\$)	741.43	490.62	250.81	33.83
Nett Amount (S\$)	11,333.29	7,499.54	3,833.75	33.83

INSPECTION

Date of Assignment: 25/06/2018

Date Inspected: 02/07/2018 Inspected At:

Kah Motor Co Sdn Bhd (HQ)
6A MANDAI ESTATE, SINGAPORE
729903
Singapore 729903

Estimated Period of Repair: 6.0 days

Adjuster: Sathya Sai Kathirrasen

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 Jul 2018)
Parts: 143	HONDA CIVIC 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLW2946U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACE ASSY ,RR.BUMPER	Cracked	462.90 FS	*462.90 FS
2	1		*GARNISH,RR.BUMPER LOWER	Deformed	28.65 FS	*28.65 FS
3	1		*SPACERR.RR.BUMPER SIDE	Deformed	8.62 FS	*8.62 FS
4	1		*SPACERL.RR.BUMPER SIDE	Not Necessary	8.62 FS	*- FS
5	7		*CLIPBUMPER	Necessary	10.50 FS	*10.50 FS
6	1		*GARNISHR.RR.BUMPER SIDE	Not Necessary	5.70 FS	*- FS
7	1		*GARNISHL.RR.BUMPER SIDE	Not Necessary	5.70 FS	*- FS
8	1		*BRACKETR.RR.BUMPER SIDE	Not Necessary	1.65 FS	*- FS
9	1		*BRACKETL.RR.BUMPER SIDE	Not Necessary	1.65 FS	*- FS
10	1		*BEAM COMPRR.BUMPER	Dented	129.75 FS	*129.75 FS
11	1		*LID COMP TRUNK	Dented	354.07 FS	*354.07 FS
12	1		*EMBLEM SETRR	Necessary	8.62 FS	*8.62 FS
13	1		*EMBLEMRR	Necessary	7.95 FS	*7.95 FS
14	1		*GARNISH ASSYRR.LICENSE	Deformed	73.27 FS	*73.27 FS
15	1		*HINGE COMPR.TRUNK	Dented	32.62 FS	*32.62 FS
16	1		*HINGE COMPL.TRUNK	Dented	32.62 FS	*32.62 FS
17	1		*WEATHERSTRIPTRUNK LID	Bent	52.50 FS	*52.50 FS
18	1		*LINING ASSYRR.PANEL	Not Necessary	37.72 FS	*- FS
19	1		*PANEL SETRR	Broken	177.00 FS	*177.00 FS
20	1		*TAILLIGHT ASSYR	Broken	190.35 FS	*190.35 FS
21	1		*TAILLIGHT ASSYL	Not Necessary	204.82 FS	*- FS
22	1		*LIGHT ASSYR.LID	Not Necessary	89.02 FS	*- FS
23	1		*LIGHT ASSYL.LID	Not Necessary	89.02 FS	*- FS
24	4		*SENSOR ASSYPARKING	Not Necessary	239.40 FS	*- FS
25	4		*CLIPHARNES BAND	Not Necessary	0.60 FS	*- FS
26	1		*SUB CORDRR.BUMPER CORNER SENS	Not Necessary	20.40 FS	*- FS
27	1		*ANTENNA ASSYL.F	Not Necessary	43.57 FS	*- FS
28	1		*BUZZER ASSYSMART	Not Necessary	45.07 FS	*- FS
29	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
30	1		*STIFFENER,R.RR PANEL SIDE	Necessary	19.50 FS	*19.50 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	2,481.86	1,608.92
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	INSPECT RR LIGHTING MECHANISMS.PERFORM WATER	New	160.00	160.00
2	REMOVE & RENEW REVERSE SENSORS	New	160.00	160.00
3	BODY JOINT SEALANT FOR TRUNK	New	100.00	80.00
4	BODY JOINT SEALANT FOR END PANEL	New	100.00	80.00
5	RESET & CALIBRATE REAR VIEW CAMERA	New	160.00	160.00
6	RESET & CALIBRATE SMART ENTRY SYSTEM	New	160.00	160.00
7	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	650.00	560.00
8	CUT OFF & RENEW RR PANEL .STRAIGHTEN	New	3,920.00	2,240.00
9	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	2,700.00	1,800.00
Gross Labour Cost (\$\$)			8,110.00	5,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >