



AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way  
AIG Building  
#07-16  
Singapore (079120)

# CarCrafters Singapore Pte Ltd

48 Toh Guan Road East  
#05-155, Enterprise Hub  
Singapore 608586

## Repair Estimate

Tel: 6267 9916

Fax: 6267 9313

www.carcrafters.sg

Date : 26/6/2018

Vehicle Num : SKJ7828A

Make/Model : VOLKSWAGEN CC 1.8 TSI

Chassis No : WVVZZZ3CZCE702764

Accident Date : 25/6/2018

| S/N | PARTS                                                                                                            | QTY   | PRICE       | TOTAL        |
|-----|------------------------------------------------------------------------------------------------------------------|-------|-------------|--------------|
| 1   | LOWER SPOILER                                                                                                    | 1 pc  | \$ 260.00   | \$ 260.00    |
| 2   | MOULDING CHROME CENTRE                                                                                           | 1 pc  | \$ 225.00   | \$ 225.00    |
| 3   | DECORATIVE MOULDING CHROME LH                                                                                    | 1 pc  | \$ 150.00   | \$ 150.00    |
| 4   | DECORATIVE MOULDING CHROME RH                                                                                    | 1 pc  | \$ 150.00   | \$ 150.00    |
| 5   | REAR BUMPER                                                                                                      | 1 pc  | \$ 1,350.00 | \$ 1,350.00  |
| 6   | REAR BUMPER GUIDE PIECE LH                                                                                       | 1 pc  | \$ 60.00    | \$ 60.00     |
| 7   | TAILLIGHT GUIDE PIECE LH                                                                                         | 1 pc  | \$ 22.00    | \$ 22.00     |
| 8   | FOAM INSERT LH                                                                                                   | 1 pc  | \$ 35.00    | \$ 35.00     |
| 9   | REINFORCEMENT                                                                                                    | 1 pc  | \$ 320.00   | \$ 320.00    |
| 10  | ATTACHMENT STRIP                                                                                                 | 1 pc  | \$ 60.00    | \$ 60.00     |
| 11  | END PANEL                                                                                                        | 1 pc  | \$ 540.00   | \$ 540.00    |
| 12  | APRON                                                                                                            | 1 pc  | \$ 395.00   | \$ 395.00    |
| 13  | TRUNK LID                                                                                                        | 1 pc  | \$ 1,600.00 | \$ 1,600.00  |
| 14  | STRIKER                                                                                                          | 1 pc  | \$ 32.00    | \$ 32.00     |
| 15  | HOOD LATCH                                                                                                       | 1 pc  | \$ 125.00   | \$ 125.00    |
| 16  | PARKING SENSOR                                                                                                   | 2 pcs | \$ 155.00   | \$ 310.00    |
| 17  | LED TAILLIGHT INNER LH                                                                                           | 1 pc  | \$ 395.00   | \$ 395.00    |
| 18  | LED TAILLIGHT OUTER LH                                                                                           | 1 pc  | \$ 430.00   | \$ 430.00    |
| 19  | REFLECTOR LH                                                                                                     | 1 pc  | \$ 45.00    | \$ 45.00     |
| 20  | LED LICENSE PLATE LIGHT                                                                                          | 1 pc  | \$ 60.00    | \$ 60.00     |
|     |                                                                                                                  |       |             |              |
|     | <b>TOTAL PARTS</b>                                                                                               |       |             | \$ 6,564.00  |
|     | <b>LABOUR</b>                                                                                                    |       |             |              |
| 1   | To remove/ replace/ refit & panel beat of rear bumper, lower spoiler, trunk lid, end panel & other affected area |       |             | \$ 1,300.00  |
| 2   | To putty & respray rear bumper, lower spoiler, trunk lid, end panel & other affected accident area               |       |             | \$ 1,300.00  |
| 3   | To check accident affected wiring system & recover.                                                              |       |             | \$ 50.00     |
| 4   | To remove, refix rear sensor.                                                                                    |       |             | \$ 50.00     |
| 5   | To recode & decode engine management system & fault code clearing after repair works.                            |       |             | \$ 100.00    |
|     |                                                                                                                  |       |             |              |
|     | <b>TOTAL</b>                                                                                                     |       |             | \$ 9,364.00  |
|     | <b>GST 7%</b>                                                                                                    |       |             | \$ 655.48    |
|     | <b>GRAND TOTAL</b>                                                                                               |       |             | \$ 10,019.48 |