

INS. CASE OWNER:

hemme Tan

CC3, A16 180

11667, RI wa39

LKK:

IDAC:

Surveyor:

Ramu

DOI:

ASSIGNMENT

21/8

Date / Time:

26/6/18

Registered in Merimen:

26/6/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLP 32997

Name of Insured:

Ang heok Suan

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

25/6/18

Claim No.:

6x168 6692056

Policy No.:

1700011757

Make / Model:

Audi A6

Place of Accident:

ITE

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Lau Yow Huan

Driver Tel No.:

9455522 (VL: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLQ 248X



INSRS:

WSP:

Tel:

Liability:

RMKS:

PML



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time:

28/6/18

SLQ 248X-X, SLP 32997-X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

28/6/18

vian

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

21/8/18

Confirm with:

Caroline

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

57

Repair Cost:

S\$

7481.39

Loss of Rental (LOR):

S\$

500.00

(

5 days)

x100

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

745

Medical:

S\$

Disbursement:

S\$

(e.g Tow/ Independent)

Legal Cost

S\$

Total:

S\$

7488.84

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

7488.84

Name 1:

Performance Motors Ltd.

Payee 2: (Strike if N.A.)

S\$

500.00

Name 2:

mok Sin Fen

Payee 3: (Strike if N.A.)

S\$

Name 3:

Mon 04/07 @ 10AM
08R

SLQ248X

BMW Dealer
Performance Motors Limited
A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X



303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Tel. 63190100 (Sales & Admin) 63190111 (AfterSales) Fax. 64747770	280, Kampong Arang Road East Coast Centre Singapore 438180 Tel. 63190888 (AfterSales) Fax. 63449773	318, Alexandra Road Sime Darby Business Centre Singapore 159944 Tel. 63190528 (AfterSales) 63190533/530 (Motorrad) Fax. 64796601 (AfterSales) 64796624 (Motorrad)
-----------------------------------------------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

25 JUN 2018

Estimate No. : b1 47423	Page No. : 1 of 5
Date Estimated : 25/06/2018	
Prepared By : Han Kwan Yong	

- ESTIMATE REPAIR FOR - Mok Sin Yen (Mo ShanYing) 46 Lakeside Drive #08-13 Singapore 648324	- ACCOUNT - 40000 Cash Sales - Service Singapore
--------------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ248X	V944700	27/06/2017	116d	0

DESCRIPTION	VALUE
To replace rear bumper & attachments, boot lid including to knock out tail panel and dented area caused by the accident	2550 2975.00
To respray rear bumper, boot lid and tail panel	2399 2666.00
To carry out body cavity preservation. (Per panel).	nn X 118.00
To conduct water leak tests.	nn X 75.00
To remove and install boot compartment carpet and garnish to facilitate repairs.	231 271.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
To supply rear emboss number plate. <i>BT</i>	83 83.00 <i>83</i>
Sundries. <i>Nu</i>	7 150.00 <i>80</i>

Total Labour 1: **6,515.00**

DESCRIPTION	QTY	PRIC	VALUE
BOOTLID	1	1,108.45	repair 1,108.45
REAR BUMPER CARRIER	1	385.25	BT 385.25
REAR BUMPER CENTRE GUIDE (M)	1	57.45	chr 57.45
REAR BUMPER TOWING EYE COVER PRIMED	1	54.50	SULX 54.50
REAR BUMPER LH MOUNT	1	142.55	nn 142.55
REAR BUMPER RH MOUNT	1	142.55	nn 142.55
REAR BUMPER PRIMED (RFC)	1	947.35	BT 947.35
REAR PDC HOLDER SET	1	23.10	nn 23.10
EMBLEM GROMMET	2	0.80	nn 1.60
PLAQUE 82MM	1	69.50	nn 69.50
LH REFLECTOR	1	35.20	XSL 35.20
RH REFLECTOR	1	35.20	XSL 35.20

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Rempang Arany Road
East Coast Centre
Singapore 438180
Tel. 63198888 (AfterSales)
Fax. 63449771

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796524 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 47423
Date Estimated : 25/06/2018
Prepared By : Han Kwan Yong

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ248X	V944700	27/06/2017	116d	0

DESCRIPTION

NUMBER PLATE LIGHT LED
DECOUPLING RING PDC TORQUE CONVERTE
RR PDC SENSOR GLACIER SILVER
REVERSING CAMERA
(DG) CLEANER R1 (100ML)
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)
(DG/SL) ADHESIVE SET K6
(DG/SL) GLASS PRIMER 30ML (VP206)

QTY PRIC

2	23.20
2	5.05
2	368.80
1	681.10
1	23.85
2	131.55
1	53.05
1	27.85

VALUE

46.40
10.10
737.60
681.10
23.85
263.10
53.05
27.85

Total Parts : 4,845.75

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 2nd Party / Uninsured losses / Direct Settlement

Regn No. Claim No.

Date&Time 02/07/18 09:45 Excess S\$

Surveyor's Name P. K. L. Sign

Surveyor's Tel 90010068 Authorised Yes / No

Authorised Date Time

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail

No. of Working Days Recommend 6 days

Labour 1	:	6,515.00
Parts	:	4,845.75
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	795.25
Grand Total	:	12,156.00

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sincere Group
Co. Reg. No. 197401559W, GST Reg. No. M2-002081-3



FINAL REPORT

Estimate No. : b1 47423
Date Estimated : 25/06/2018
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Mok Sin Yen (Mo ShanYing)
46 Lakeside Drive
#08-13

Singapore 648324

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN NO	CHASSIS NO	REGN DATE	MODEL	MLEAGE
SLQ248X	V944700	27/06/2017	116d	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace rear bumper and attachments include making good the boot lid, tail end panel and knocking out dents caused by the accident	2550.00		2,550.00	
To respray rear bumper, boot lid and tail end panel	2399.00		2,399.00	
To remove and install boot compartment carpet and garnish to facilitate repairs	231.00		231.00	
To check electrical wiring systems and lightings at the rear section for proper function,	150.00		150.00	
To supply rear emboss number plate.	83.00		83.00	
Sundries,	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
REAR BUMPER CARRIER	385.25	1.00		385.25
# HOLDER CAMERA SYSTEM *	32.75	1.00		32.75
REAR BUMPER CENTRE GUIDE (M)	57.45	1.00		57.45
REAR BUMPER PRIMED (RFC)	947.35	1.00		947.35
REAR PDC HOLDER SET	23.10	1.00		23.10
(DG/SL) ADHESIVE SET K6	53.05	1.00		53.05

SUPPLEMENTARY ITEMS

Total Labour :	5,493.00
Total Parts :	1,498.95
Total Labour & Parts :	6,991.95
Deduction for Excess :	
Total Repair Costs less Excess:	6,991.95
GST @7%:	489.44
Grand Total :	7,481.39

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 191401559W, GST Reg. No. M2-0020981-X



SUPPLEMENTARY

Estimate No. : b1 47423
Date Estimated : 25/06/2018
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Mok Sin Yen (Mo ShanYing)
46 Lakeside Drive
#08-13

Singapore 648324

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SLQ248X	V944700	27/06/2017	116d	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# HOLDER CAMERA SYSTEM *	32.75	1.00		32.75

CRA ✓

Total Labour :	
Total Parts :	32.75
Total Labour & Parts :	32.75

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63180100 (Sales & Admin)
63180111 (AfterSales)
Fax. 64747770

380, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63180528 (AfterSales)
63180533/530 (Motorrad)
Fax. 64786601 (AfterSales)
64786624 (Motorrad)

GST REG. NO : M2 - 0020081 - X**E S T I M A T E**

Estimate No. : **b1 47423**
Date Estimated : **25/06/2018**
Prepared By : **Han Kwan Yong**

Page No. : **5 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ248X	V944700	27/06/2017	116d	0

- 17.7 The Customer shall pay an amount to access his personal data in the manner stated in Clause 17.6(a) above.
- 17.8 The Customer shall have the right to correct any inaccuracies in his personal data free of charge. If the Customer wishes to exercise this right, the Customer shall:
- (a) put his request in writing;
 - (b) provide the Vendor with enough information to identify himself (e.g. the Customer's account number, username, registration details); and
 - (c) specify the information that is incorrect and what it should be replaced with.
- The Vendor shall reply to the Customer as soon as practicable upon its receipt of the Customer's request.
- 17.9 The Customer's access or correction request will not be granted as of right; the Vendor's ability to accede to the Customer's access or correction request is subjected to the prohibitions and exceptions set out or which may be set out in the Singapore Personal Data Protection Act ("PDPA") and its accompanying regulations.
- 17.10 The Customer shall have the right to ask the Vendor to stop collecting, using or disclosing his personal data for any of the abovementioned purposes set out in Clauses 17.1 and 17.2. If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or:
- (a) put his request in writing by way of an email sent to the Vendor;
 - (b) provide the Vendor with his name, NRIC number, mobile number, email and Vehicle registration number to identify the Customer; and
 - (c) if the Customer's objection is not to direct marketing in general, but to direct marketing by a particular channel (e.g. voice call, SMS, MMS, fax, mailers or email), the Customer has to specify the channel he is withdrawing his consent to.
- 17.11 In the event that the Customer withdraws consent to the collection, use or disclosure of his personal data such that it materially affects this Agreement and it renders the Vendor unable to, or such that it becomes difficult for the Vendor to perform or properly perform or discharge its obligations under this Agreement, at law, under the warranty undertakings, or its role as a responsible dealer of BMW vehicles, the Vendor may at its discretion, be entitled to terminate this Agreement with the Customer.
- 17.12 The obtaining the Customer's consent for the collection, use or disclosure of his personal data under this clause 17 is subject to the exceptions set out or which may be set out in the PDPA.
- 17.13 The Customer shall address all communications pertaining to this Clause 17 to:

The Data Protection Officer
Performance Motors Limited

Address:
Sime Darby Performance Centre
303 Alexandra Road
Singapore 159941

Email address:
dataprotection@pml.com.sg

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

380, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190885 (AfterSales)
Fax. 63463773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190531/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X**E S T I M A T E**

Estimate No. : **b1 47423**
Date Estimated : **25/06/2018**
Prepared By : **Han Kwan Yong**

Page No. : **3 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ248X	V944700	27/06/2017	116d	0

Terms & Conditions of Service

- All requests for servicing, repairs, replacements or installations to the Vehicle (collectively, "Repairs") are subject to acceptance by Performance Motors Limited ("PML") and PML shall have the absolute discretion to reject or deny any request for the Repairs.
- The list of the Repairs or quantum of charges for the Repairs printed overleaf are estimates only and PML shall be entitled to carry out additional repairs or replacements ("Additional Works") if, in its absolute discretion, Additional Works are necessary provided that, where the cost of additional Works exceed S\$250, PML shall obtain the customer's prior consent (whether given orally or otherwise) before carrying out the additional Works.
- Subject to clause 2 above and save in the case of manifest error or gross negligence, in the event where PML's estimation of the Repairs recommended for the Vehicle differs from the Customer's own estimation of repairs needed, PML's estimate shall prevail.
- The Vehicle accepted by PML for the Repairs shall remain, at all times, at the Customer's own risk while the Vehicle undergoes the Repairs at PML's premises. PML's visual inspection and record of the physical condition of the Vehicle made prior to the commencement of the Repairs shall be binding and conclusive as between PML and the Customer. The Customer shall ensure that all valuables are removed from the Vehicle prior to delivering it to PML for the Repairs. PML shall not be liable, in any way, for theft, fire, accident, loss of or damage to the Vehicle, its contents or accessories whatsoever.
- The Vehicle may be driven on the road if and when PML, in its absolute discretion, decides that it is necessary for the purposes of carrying out tests in connection with the Repairs. Should any damage occur to the Vehicle in such an instance, PML's liability will be limited to the rectification of damage, free of charge.
- PML's entire liability whether, in respect of faulty workmanship or otherwise, shall be limited to the rectification of any faulty workmanship or other faults, free of charge, such faults being reasonably determined by PML to have been caused by PML in the course of the Repairs. The Customer shall, nevertheless, be responsible for all costs for the disassembly, diagnosis, inspection of the Vehicle etc., at PML's current labour charge-out rate, necessarily incurred for the purpose of determining the cause of the fault(s) if it is found that the fault(s) is or are not caused by PML.
- Except as provided in clause 6 above, PML makes no warranty (whether expressed or implied) in respect of the Repairs and shall not, to the fullest extent permitted by law, be liable under any circumstances for special, consequential or incidental damages including but not limited to the loss of use of or depreciation in value of the Vehicle.
- Unless otherwise agreed by PML in writing, the Customer shall pay the costs of the Repairs owing to PML, in cash, upon the completion of the Repairs and before the Customer collects the Vehicle. In the event any credit is granted by PML at its absolute discretion, and the Customer fails to make payment of the costs of the Repairs (or any part thereof) by the agreed payment date, interest shall be imposed on the sum remaining unpaid at the rate of 1% per month (or part thereof) from the due date of payment until the date all payments are actually received by PML. PML reserves the right, at any time, to suspend or withdraw any credit facility granted to the Customer without assigning any reason whatsoever.
- The Customer shall collect the Vehicle within 48 hours from the date PML notifies the Customer, (whether orally or otherwise), that the Vehicle is ready for collection. In the event that the Customer fails to collect the Vehicle within 48 hours, the Customer shall, in addition to the costs of the Repairs owing to PML, pay all storage charges, at a rate to be determined by PML provided always that the Customer shall not, under any circumstances, hold PML liable for any loss of or damage to the Vehicle, its contents or accessories or for any deterioration in the quality of or damage to the Vehicle arising from such storage. In the event that the Customer fails to collect the Vehicle for more than 14 days, PML shall be entitled, at its absolute discretion, to dispose of the Vehicle & deduct, from the proceeds of disposal, PML's costs in connection with the disposal as well as all other monies owing to PML.
- If PML does not receive any notification of faulty workmanship from the Customer within 7 days from the date the Customer collects the Vehicle from PML, the Customer shall be deemed to have accepted the Repairs as satisfactory.
- If the Vehicle is sent to PML for the Repairs by any person other than the Customer, PML shall be entitled, without need to make any inquiry, to treat such third party as acting for and on the Customer's behalf. PML shall be entitled to rely on this ostensible authority to carry out the repairs in compliance with such third party's instructions and the Customer shall not hold PML liable for any loss or damage suffered by the Customer as a result and shall pay for the costs of the Repairs owing to PML and further indemnify PML against all claims, losses, expenses, damages suffered or incurred by PML arising from PML's reliance on such authority and/or compliance with such instructions.
- PML may, in its absolute discretion and upon the Customer's request, provide a driver to deliver the Vehicle from the Customer to PML's premises or vice versa provided always that the driver shall, during the time of such conveyance of the Vehicle, be deemed to be the servant of the Customer and not that of PML's and the Customer shall not hold PML liable for any accident, loss of or damage to the Vehicle or its contents or accessories while the same is under the custody of the driver.
- These Terms & Conditions of Service including all annexes and attachments hereto contains the entire agreement between PML and the Customer with respect to the Services described in the Repair Order and supersedes all previous agreements and understandings between PML and the Customer relating to the subject matter herein. No amendments or changes to these Terms & Conditions of Service shall be effective unless made in writing and signed by authorized representatives of both PML and the Customer.
- If any term or provision of these Terms & Conditions of Service shall be held to be invalid, illegal or unenforceable, the remaining terms and provisions of these Terms & Conditions of Service not affected by such invalidity, illegality or unenforceability shall remain in force and effect.

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559M GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X**E S T I M A T E**

Estimate No. : **b1 47423**
Date Estimated : **25/06/2018**
Prepared By : **Han Kwan Yong**

Page No. : **4 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ248X	V944700	27/06/2017	116d	0

15. A person not party to these Terms & Conditions of Service shall have no right under any legislation for the enforcement of contractual terms by a third party (whether in force now or to be enacted in the future and as the same may be modified, adapted or supplemented from time to time) to enforce any term in these Terms & Conditions of Service.
16. The laws of the Republic of Singapore shall govern the validity and interpretation of these Terms & Conditions of Service and the Parties submit to the exclusive jurisdiction of the Courts of the Republic of Singapore.
17. The Sime Darby Motors Group companies in Singapore are committed to ensuring that your personal data is protected. The purpose of this document is to explain how we collect information about you, the procedures that we have in place to safeguard your privacy and how you can instruct us if you prefer to limit the use of that information.
- 17.1 The Vendor shall collect and use the Customer's personal data for any of the following purposes, including but not limited to:
- (a) the registration of the Vehicle with the relevant transportation authorities, including but not limited to Land Transport Authority;
 - (b) sharing of the Customer's personal data with the Vendor's principal, its related corporations and contractors, whether within Singapore or overseas, and/or insurance companies, so as to provide the necessary warranties and/or extended warranties for the Vehicle to the Customer;
 - (c) sharing of the Customer's personal data with financial institutions and motor vehicle insurers, on the Customer's behalf, in order for the Customer to obtain financing for the purchase of the Vehicle and the motor insurance on the Vehicle and when necessary, to obtain the loan amounts outstanding from financial institutions, on the Customer's behalf so as to assist the Customer in effecting the Vehicle loan redemptions;
 - (d) servicing of Vehicle and to update the Vendor's after-sales service records. The relevant personal data shall be used by the Vendor, its appointed after-sales service dealers, agents and sub-contractors and/or the Vendor's principal and/or its related corporations whether within or outside Singapore to provide the relevant after-sales service and/or to repair the Vehicle and to communicate with the Customer on any matter relating to the provision of the services in general including to notify the Customer by any means, including by short message services ("SMS") of the next/ subsequent date/mileage for routine service for the Vehicle;
 - (e) administrative, research and analysis purposes to enable it to monitor and improve the services it provides; and
 - (f) organizing events for the Customer, to inform the Customer of such events by any means (including through SMS, multi-media services ("MMS"), phone call, fax, magazines, or brochures) any new products, promotions or services provided by the Vendor in Singapore.
- 17.2 The Vendor shall also disclose the Customer's personal data:
- (a) to its service providers, for example, providers of web hosting or maintenance services, for the purpose of supplying itself with the inter connected servers and/or web site links with the relevant authorities;
 - (b) to its customer service agencies whether within or outside Singapore for administrative, research and analysis purposes to enable it to monitor and improve the services it provides;
 - (c) to the Vendor's service providers and/or the Vendor's principal, its related corporations and contractors whether within or outside Singapore for the purpose of organizing events for the Customer, to inform the Customer of and send to the Customer by any means (including through SMS, MMS, phone call, fax, magazine or brochures) any new products or promotions or services that are provided by the Vendor and/or the Vendor's principal whether within or outside Singapore;
 - (d) to the Vendor's business partners for the purpose of carrying out product promotions;
 - (e) to the Vendor's stakeholders and the Vendor's principal and its/their related corporations and contractors for the purpose of carrying out audits;
 - (f) to the Vendor's principal and/or the Vendor's stakeholders and their respective related corporations and contractors whether within or outside Singapore for the purposes of carrying out audits; and
 - (g) to the Vendor's principal and its related corporations whether located within or outside Singapore for the purpose of responding to any of the Customer's enquiries.
- 17.3 The Vendor shall retain the Customer's personal data either for the period of the business relationship or, for the requisite retention periods as stipulated in any contractual arrangements or under any applicable law, whichever is later.
- 17.4 If the Vendor amends any provision in this clause 17, it will notify the Customer via e-mail and may place notices on the Vendor's web site. The Vendor's email to the Customer shall require the Customer's consent to its change of use of the Customer's personal data. Continued use of the Vendor's services shall signify the Customer's agreement to any such changes.
- 17.5 The personal data the Customer provides may be transferred to the Vendor's principal within or outside Singapore for surveys and research purposes conducted with the objective of enhancing the Customer's satisfaction.
- 17.6 The Customer shall have a right to request a copy of the personal data the Vendor holds about the Customer and information about the ways in which the Customer's personal data has been or may have been used or disclosed within a year before the date the Customer's request. If the Customer wishes to exercise this right, the Customer shall complete the Vendor's prescribed form and/or:
- (a) put his request in writing and indicate whether he would like to have a copy of his personal data or he wishes to have information about the ways in which his personal data is used or disclosed during the past year or both;
 - (b) include proof of his identity and address (e.g. a copy of the Customer's driving licence and a recent credit card bill); and
 - (c) specify the personal data he wants access to, including any account or reference numbers where applicable.

The Vendor shall reply to the Customer as soon as reasonably possible upon its receipt of the Customer's request.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**AIG THIRD PARTY EXPRESS SETTLEMENT
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008
(PAYMENT BREAKDOWN)**

Vehicle No:	SLD 248X	Model:	
Date of Accident:	25-6-2018		

Global Sum Settlement	: [] Yes [] No	
Repair Estimate	: \$	12156.00
Final Repair Cost	: \$	7481.39
Loss of Use	: \$	
Rental (if any)	: \$	500.00
LTA / GIA Search Fee	: \$	7.45
Others:	: \$	
	: \$	
Final Settlement Sum	: \$	7988.84

Is Third Party Workshop GIA Registered? [] YES [] NO (Kindly indicate below)	
A) For Non GIA Registered Workshop:	Agreed Liability _____ (%)
B) For GIA Registered Workshop:	BOLA Applicable: Yes/No BOLA Scenario No: _____
BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	
Remarks	

Payment Instruction: Payee's Breakdown		
1)	Performance Motors Ltd	: \$ 7481.39
2)	Performance Motors Ltd	: \$ 7.45
3)	Mok Sin Yen	: \$ 500.00

Signed by appointed surveyor _____

Date _____

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;
Survey Report; Medical Report/ Bill (if any))



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18011667/wa3

28 June 2018

ANG GEOK SUAN
2A Hougang Street 11
01-07
Singapore 538752

Dear Sir/Madam,

ACCIDENT INVOLVING SLP 3299J AND SLQ 248X ON 25/06/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd. to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Vivian Lau
Case Handler
DID: 6841 8625
FAX: 6741 4108
EMAIL: Vivianlau@lkkauto.com

c.c AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)


AUTHORISATION TO ACT
(AIG Express Third Party Claim)

I, Mr Mok Sin Yen (the third party claimant) of 46 Lakeside Drive #08-13, S(648324) (address), owner of SLQ248X (vehicle no.) hereby authorize PERFORMANCE MOTORS LTD ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle no. SLQ248X that was damaged pursuant to the accident which occurred on 25/06/18 (date) along PIE Towards Changi (location) involving vehicle no/s SLP3299J ("the accident").


I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 7 (day) of 7 (month) 2018 (year)


Signed by "the third party claimant"
(with chop if applicable)

HAN KWAN YONG
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941


Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Express Third Party Claim)

"We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$ 7481.39 (Repair Cost), S\$ 500.00 (Loss of rental/use), S\$ 7.45 (Disbursement), for vehicle no. SLQ 248X that was damaged pursuant to the accident which occurred on 25-6-18 (date) along PIE TOWARDS CHANGI (location) involving vehicle no/s SLP 299J. This is pursuant to the inspection conducted on 2-7-18 (date) at "the workshop".


We/I confirm that we/I are/am authorized by the owner Mok Sin Yen ("the third party claimant") of vehicle no. SLQ 248X make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLQ 248X (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.


This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 24 (day) of 8 (month) 2018 (year)

MRB 

Signed by appointed surveyor

HAN KWAN YONG
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159341


Signed by "the workshop" (with chop)

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

260, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax: 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190828 (AfterSales)
63190533/530 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



SERVICE TAX INVOICE

Repair Order No. : B1 1280230

Date IN : 02/07/2018

Cust. Svc. Advisor: Han Kwan Yong

Page No. : 1 of 2

Invoice Number : 1994682 / WSB

Invoice Date : 07/08/2018

Payment Terms : 30 Days From Invoice

Invoice By : Sharon Heng

- CUSTOMER INFORMATION -

Mdm Mok Sin Yen (Mo ShanYing)
46 Lakeside Drive
#08-13

Singapore 648324

- INVOICE TO - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ248X	V944700	27/06/2017	116D	22937

- - - - LABOUR 1 - - - -

To replace rear bumper and attachments including to make good the rear boot lid, tail end panel and knock out dented area caused by the accident.

To remove and install body parts in order to carry out painting job.

To respray rear bumper, rear boot lid and tail end panel.

To remove and install boot compartment carpet and garnish to facilitate repairs.

To check electrical wiring systems and lightings at the rear section for proper function.

Sundries.

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

DATE OF ACCIDENT : 25.6.2018. 3RD PARTY CAR : SLP3299J.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR RASUL FROM LKK AUTO CONSULTANTS PTE LTD ON 2.7.2018 AT 2.55 PM. AUTHORISED REPAIR BY MS VIVIAN LAU FROM LKK ON 28.6.2018 VIA E-MAIL. PROPOSE CAR RENTAL = \$500.00. THE AMOUNT IS SUBJECTED TO INSURANCE COMPANY CONFIRMATION.

LTA SEARCH FEE = \$7.45.

NETT

2,550.00

2,399.00

231.00

150.00

80.00

0.00

0.00

0.00

Total Labour 1: 5,410.00

- - - - PARTS - - - -

REAR BUMPER PRIMED (RFC)

REAR PDC HOLDER SET

(DG/SL) ADHESIVE SET K6

REAR BUMPER CARRIER

REAR BUMPER CENTRE GUIDE (M)

HOLDER CAMERA SYSTEM

Qty	Retail Price
1	947.35
1	23.10
1	53.05
1	385.25
1	57.45
1	32.75

NETT

947.35

23.10

53.05

385.25

57.45

32.75

Total Parts : 1,498.95

- - - - LABOUR 2 - - - -

To supply rear silver emboss lettering black base number plate with bracket.

NETT

83.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401555M GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64756601 (AfterSales)
64756624 (Motorrad)

SERVICE TAX INVOICERepair Order No. : **B1 1280230**Date IN : **02/07/2018**Cust. Svc. Advisor: **Han Kwan Yong**Page No. : **2 of 2**Invoice Number : **1994682 / WSB**Invoice Date : **07/08/2018**Payment Terms : **30 Days From Invoice**Invoice By : **Sharon Heng**Total Labour 2: **83.00**

Labour Charges : **5,413.00**
Parts Charges : **1,498.95**
Lubricant/Misc : **80.00**

Total Labour & Parts Charges : **S\$ 6,991.95**
Less Insurance Excess : **S\$ 0.00**
Invoice Total Amount Exclude GST : **S\$ 6,991.95**
GST @ 7% : **S\$ 489.44**
Invoice Total Amount Include GST : **S\$ 7,481.39**

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 7,481.39**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



HA 201807-004582

RENTAL AGREEMENT

Hirer's Name Mok Sin Yen		Date of Birth 30.01.1975	Passport/ Nric No. S7503143 B.	Nationality
Address 46 LAKESIDE DR.		Occupation	Driving Licence No.	Date of Expiry
Postal Code 408-13		Contact No. 668327	Mobile Phone No. 92386569	
Joint Hirer's / Guarantor's Name		Date of Birth	Passport/ Nric No.	Nationality
Address		Occupation	Driving Licence No.	Date of Expiry
Postal Code		Contact No.	Mobile Phone No.	

CHECK OUT

Date 2.7.18	Time 11.50a	Mileage KM	
Date 7.7.18	Time 11am	Mileage KM	Remarks

CHECK IN

Date	Time	Mileage	Remarks
7.7.18	11am	100 KM	

IMPORTANT NOTES:

- Car is restricted to SINGAPORE use. See clause 1(f) for non-compliance.
- No refund will be given for vehicle that returns early.
- Own Damage Liability – First \$1500 for damage to vehicle plus loss of earnings while damaged vehicle is under repair.
- Third Party Liability – First \$2000 for any Third Party Accident Claim.
- Additional Excess of \$3000 for drivers under 24yrs old or above 70yrs and/or less than 2yrs driving experience.
- Hirer is responsible for all parking fines & traffic summons.
- Extension:- One day's advance notice is required otherwise no extension will be allowed.
- Vehicle should be returned at the same time as collection except on Saturday where return time is before 10am.
- Vehicle returned after office hour will be charged to the next working day.
- Hourly extension is charged at 1/5 of the daily rate.
- As preventive maintenance, please check water & engine oil daily.
- Please check that you have not left any of your personal belongings in the vehicle. Our company and staff will not be responsible for any loss of belongings after the vehicle is returned.
- For the comfort of other users, please refrain from smoking, eating or carrying of pets in the car. A cleaning charge of \$200 will be imposed for smoky, smelly or dirty vehicle.
- Carrying of PASSENGERS in commercial vehicle is strictly prohibited. Only WORKERS covered under hirer's workmen compensation are allowed.

	UNIT		RATE (\$)	TOTAL (\$)
RATE	5	@	100/- unit	
DISCOUNT				
GST @ 7%				
TOTAL				500/-
EXTENSION				
SLQ248X				
DEPOSIT (refundable) \$5				
CHANGED OVER FROM VEH.				DATE

(We have read and agree to the terms and conditions of the rental agreement above and as set overleaf.)
(We declare that all information given on this form is true and accurate.)

Hirer's Signature

Joint Hirer's/ Guarantor's Signature

for CHAN'S & SONS ENTERPRISE

VEHICLE NO. <u>SICA 476 H</u>	MODEL
FROM	RETURN

*Estimate Date. For actual return date CHECK IN

OPERATING HOURS: MONDAY TO FRIDAY 8.30AM TO 5.30PM. SATURDAY 8.30AM TO 12.30PM. CLOSED ON SUNDAY & PUBLIC HOLIDAY

CHAN'S & SONS ENTERPRISE

363 Sembawang Road
Singapore 758379
Tel: 67532536 Fax: 67567565
GST Reg No: 51-936900-M

chan's
www.chans.com.sg

TAX INVOICE

MOK SIN YEN

BLK 46 #08-13
LAKESIDE DRIVE
SINGAPORE

ATTN : MOK SIN YEN

INVOICE : AR1807-0156
DATE : 09/07/2018
TERMS : C.O.D
STAFF ID : IZA
AGREEMENT NO. : HA201807-0082

DESCRIPTION	AMOUNT (SGD)
-------------	--------------

Vehicle Reg No : SKA476A 467.29
Make / Model :
Rental Dates : Rental Billing From 02/07/2018 To 07/07/2018
Period : 5 days
Rental Rate : S\$ 100.00 Per Day (Including GST)
Reference No :

AMOUNT : S\$
FIVE HUNDRED DOLLARS ONLY

NON-TAXABLE VALUE : 0.00
TAXABLE VALUE : 467.29
GST 7% : 32.71

TOTAL S\$: 500.00

Please make your cheques payable to : **CHAN'S & SONS ENTERPRISE**



For Official Use Only

Payment Date :	F / Amt
CS / CC / CH :	
CS / CC / CH :	

CHANS & SONS ENTERPRISE

363 Sembawang Road, Goodlink Park,
Singapore 758379
Tel: 67532536 Fax: 67567565
GST Reg No: 51-936900-M

chan's
www.chans.com.sg

Hirer:

MOK SIN YEN

OFFICIAL RECEIPT

DESCRIPTION	AMOUNT (SGD)
-------------	--------------

Official Receipt No : **201807-0083**
Account of : **MOK SIN YEN**
Date Issued : **09/07/2018**
Vehicle Reg No. : **SKA476A**
Rental Dates : **02/07/2018**
Amount Received : **S\$ 500.00**
Payment Type: : **VISA** **V100117** **S\$ 500.00**
Payment for Invoice : **AR1807-0156**
Comments :

TOTAL AMOUNT RECEIVED	S\$ 500.00
------------------------------	-------------------

* This is a computer generated document. No signature is required.

Member of  **ARTAS**

363 Sembawang Road Goodlink Park Singapore 758379 T 67532536 F 67567565 E sales@chans.com.sg

SALE
Card Num: XXX XXX XXX 4429 Manual
REF NUM: 12004200000 Card TYPE: VISA
APPN CUR: 459472 THE NBN: 000000
EXP DATE: ** **
TOTAL : SGD 500.00
I AGREE TO PAY THE ABOVE TOTAL AMOUNT
ACCORDING TO THE CARD ISSUER AGREEMENT
RECEIVED COPY
REGIONAL (SFT) 1/5/5-46



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 25 Jun 2018 / 15:45:41

Receipt Date/Time : 25 Jun 2018 / 15:45:41

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180625-001856

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
Result of Insurance Enquiry - SLP3299J				
As at 25 Jun 2018/10:00:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SLP3299J Enquiry Fee 20180625154421688422	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
		xxxxxxx5164	Credit Card: Visa/MasterCard	7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express















CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	27 Jun 2018 Edit Reg		02 Jul 2018 00:00 Edit Adj Rpt	S\$6,991.95 Edit Estimates	S\$6,991.95 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: ANG GEOK SUAN , ID: 51380022G									
Main Claimant: MOK SIN YEN , ID: S75031438									
Vehicle Reg. No.: SLQ248X		Date of Loss: 25/06/2018 10:00 - :59 [11 Months and 29 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 6716866920SG		Policy/Cover Note No.: 1700011757 (Comprehensive)							
Vehicle Reg. No. (Insured): SLP3299J		Policy No. (Claimant): SD17V07968/VPC/ROO							
Excess:									
Repairer: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Tan, Bennie-WZ - 6419 1718] Bennie-WZ.Tan@aig.com									
Claimant's Insurer: Liberty Insurance Pte Ltd (HQ) - Tel: 6221 8611									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 05/07/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLQ248X (6716866920SG)
[SLP3299J]
TP
MOK SIN YEN
Jun 25 2018 10:00AM
[ANG GEOK SUAN]
Performance Motors Limited

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page			<input checked="" type="checkbox"/>		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	(Draft)		Third Party Express Settlement – Payment Breakdown												1			Edit		
Photos/Images															3 per page			<input checked="" type="checkbox"/>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	21/08/18 18:59		General View												1			Load JPG <input checked="" type="checkbox"/>		
2	21/08/18 18:59		General View												1			Load JPG <input checked="" type="checkbox"/>		
3	21/08/18 18:59		General View												1			Load JPG <input checked="" type="checkbox"/>		
4	21/08/18 18:59		General View												1			Load JPG <input checked="" type="checkbox"/>		
5	21/08/18 18:59		General View												1			Load JPG <input checked="" type="checkbox"/>		
6	21/08/18 18:59		General View												1			Load JPG <input checked="" type="checkbox"/>		
7	21/08/18 18:59		General View												1			Load JPG <input checked="" type="checkbox"/>		
8	21/08/18 18:59		General View												1			Load JPG <input checked="" type="checkbox"/>		
9	21/08/18 18:59		General View												1			Load JPG <input checked="" type="checkbox"/>		
10	21/08/18 18:59		General View												1			Load JPG <input checked="" type="checkbox"/>		
11	21/08/18 18:59		General View												1			Load JPG <input checked="" type="checkbox"/>		
12	21/08/18 18:59		General View												1			Load JPG <input checked="" type="checkbox"/>		
13	21/08/18 18:59		General View												1			Load JPG <input checked="" type="checkbox"/>		
14	21/08/18 18:59		General View												1			Load JPG <input checked="" type="checkbox"/>		
15	21/08/18 18:59		General View												1			Load JPG <input checked="" type="checkbox"/>		
16	21/08/18 18:59		General View												1			Load JPG <input checked="" type="checkbox"/>		
17	21/08/18 18:59		General View												1			Load JPG <input checked="" type="checkbox"/>		
18	21/08/18 18:59		General View												1			Load JPG <input checked="" type="checkbox"/>		
19	21/08/18 18:59		General View												1			Load JPG <input checked="" type="checkbox"/>		
20	21/08/18 18:59		General View												1			Load JPG <input checked="" type="checkbox"/>		
21	21/08/18 18:59		General View												1			Load JPG <input checked="" type="checkbox"/>		
22	21/08/18 18:59		General View												1			Load JPG <input checked="" type="checkbox"/>		
23	21/08/18 18:59		General View												1			Load JPG <input checked="" type="checkbox"/>		
24	21/08/18 18:59		General View												1			Load JPG <input checked="" type="checkbox"/>		
25	21/08/18 18:59		General View												1			Load JPG <input checked="" type="checkbox"/>		
26	21/08/18 18:59		General View												1			Load JPG <input checked="" type="checkbox"/>		
27	21/08/18 18:59		General View												1			Load JPG <input checked="" type="checkbox"/>		
28	21/08/18 18:59		General View												1			Load JPG <input checked="" type="checkbox"/>		
29	21/08/18 18:59		General View												1			Load JPG <input checked="" type="checkbox"/>		
30	21/08/18 18:59		General View												1			Load JPG <input checked="" type="checkbox"/>		
31	21/08/18 18:59		Reinspection Photo												1			Load JPG <input checked="" type="checkbox"/>		
32	21/08/18 18:59		Reinspection Photo												1			Load JPG <input checked="" type="checkbox"/>		
33	21/08/18 18:59		Reinspection Photo												1			Load JPG <input checked="" type="checkbox"/>		
34	21/08/18 18:59		Reinspection Photo												1			Load JPG <input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	21/08/18 18:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	21/08/18 18:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	21/08/18 18:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	21/08/18 18:59	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/06/18 19:46	TP GIA REPORT	 Load PDF	
2	26/06/18 19:46	TP ESTIMATE	 Load PDF	
3	04/07/18 09:23	TP ESTIMATE - MARKED	 Load PDF	
4	27/08/18 09:31	WORKSHOP INVOICE	 Load PDF	
5	27/08/18 09:31	AUTHORISATION TO ACT FORM	 Load PDF	
6	27/08/18 09:31	Release Voucher	 Load PDF	
7	27/08/18 09:31	RENTAL RECEIPT	 Load PDF	
8	27/08/18 09:31	LTA SEARCH	 Load PDF	
9	27/08/18 09:31	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	27/06/18 12:08	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLP3299J (Insd veh)	Model:	BMW 116D 1.5 (A)
	SLQ248X (TP veh)		
Date of Accident:	25/06/2018		

Global Sum Settlement	: [] Yes	: [X] No	
Repair Estimate	: \$		12,191.05
Final Repair Cost	: \$		7,481.39
Loss of Use	: \$		days at \$0.00 per day
Rental (if any)	: \$		500.00 5 days
LTA / GIA Search Fee	: \$		7.45
Others:	: \$		0.00
	: \$		
Final Settlement Sum	: \$		7,988.84

Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	: \$	7,488.84
2)	Mok Sin Yen	: \$	500.00
3)		: \$	

JOANNE LEE KHANG MIN

27 Aug

2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18011667/R1WA3Q2

Date: 27/08/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1700011757

Claimant Vehicle No : SLQ248X

Insured Vehicle No : SLP3299J

Date of Loss: 25/06/2018

Nature of Claim:

TP

Claim No: 6716866920SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLQ248X

Make & Model: BMW 116D, 1.5 (A)

Reg. Date: 27/06/2017 (Man. Year: 2017)

Colour: Grey

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 34589896B37D15A

Chassis No: WBA1V72070V944700

Odometer: 22937 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16

Rear Tyre Size: 205/55 R16

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,111.50	1,661.95	3,449.55	67.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,282.00	5,330.00	952.00	15.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,393.50	6,991.95	4,401.55	38.63
+ GST 7.00/7.00% (S\$)	797.55	489.44	308.11	38.63
Nett Amount (S\$)	12,191.05	7,481.39	4,709.66	38.63
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		7,988.84		

INSPECTION

Date of Assignment: 02/07/2018

Date Inspected: 02/07/2018 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL**Manager:** VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR EMBOSS NUMBER PLATE	Bent	83.00 FS	*83.00 FS
2	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
3	1		*BOOTLID	Repair	1,108.45 FS	*- FS
4	1		*REAR BUMPER CARRIER	Bent	385.25 FS	*385.25 FS
5	1		*REAR BUMPER CENTRE GUIDE (M)	Cracked	57.45 FS	*57.45 FS
6	1		*REAR BUMPER TOWING EYE COVER PRIMED	Serviceable	54.50 FS	*- FS
7	1		*REAR BUMPER LH MOUNT	Serviceable	142.55 FS	*- FS
8	1		*REAR BUMPER RH MOUNT	Serviceable	142.55 FS	*- FS
9	1		*REAR BUMPER PRIMED (RFC)	Deformed	947.35 FS	*947.35 FS
10	1		*SET REAR PDC HOLDER	Necessary	23.10 FS	*23.10 FS
11	2		*EMBLEM GROMMET	Not Necessary	1.60 FS	*- FS
12	1		*PLAQUE 82MM	Not Necessary	69.50 FS	*- FS
13	1		*LH REFLECTOR	Serviceable	35.20 FS	*- FS
14	1		*RH REFLECTOR	Serviceable	35.20 FS	*- FS
15	2		*NUMBER PLATE LIGHT LED	Serviceable	46.40 FS	*- FS
16	2		*DECOUPLING RINGPDC TORQUE CONVERTE	Serviceable	10.10 FS	*- FS
17	2		*RR PDC SENSOR GLACIER SILVER	Serviceable	737.60 FS	*- FS
18	1		*REVERSING CAMERA	Serviceable	681.10 FS	*- FS
19	1		*(DG) CLEANER R1 (100ML)	Not Necessary	23.85 FS	*- FS
20	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Not Necessary	263.10 FS	*- FS
21	1		*(DG/SL) ADHESIVE SET K6	Necessary	53.05 FS	*53.05 FS
22	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Not Necessary	27.85 FS	*- FS
23	1		*HOLDE CAMERA SYSTEM	Cracked	32.75 FS	*32.75 FS
Total Parts (S\$)					5,111.50	1,661.95

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER & ATTACHMENTS ,BOOT LID INCLUDING TO KNOCK OUT TAIL PANEL AND DENTED AREA CAUSED BY THE ACCIDENT	New	2,975.00	2,550.00
2	TO RESPRAY REAR BUMPER,BOOT LID AND TAIL PANEL	New	2,666.00	2,399.00
3	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	0.00
4	TO CONDUCT WATER LEAK TESTS	New	75.00	0.00
5	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	231.00
6	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (S\$)			6,282.00	5,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >