



Email : darren@completevms.com.sg ( )  
lily@completevms.com.sg ( )  
lihui@completevms.com.sg ( )

KOH SOON LEE  
BLK 416 SAUJANA ROAD #05-50  
SINGAPORE 670416

Attention : THE OWNER  
Contact : 81382870

Estimate : ES006383

Date : 26/06/2018  
Vehicle Num. : SJT931P  
Make/Model : HONDA JAZZ GLI 1.3A-2009  
Chassis/Eng# : MRHGE68509P021559/L13Z1170340E  
Accident Date : 25/06/2018  
Claim No. :  
Reference :  
Policy No. :

*Not Notified*  
*11km 84650t*  
*Running After Paim*  
*6 days*

S/N Quantity Particular Unit Price Amount S\$

- LIST ITEMS :
1. 1 TAIL GATE
  2. 1 TAIL GATE W/SCREEN MOULDING
  3. 1 TAIL GATE OUTER HANDLE
  4. 1 TAIL GATE INNER LOCK
  5. 1 TAIL GATE INNER TRIM
  6. 1 TAIL GATE RUBBER SEAL
  7. 2 TAIL LAMP
  8. 1 REAR BUMPER
  9. 2 REAR BUMPER SIDE RETAINER
  10. 2 REAR BUMPER BRACKET
  11. 6 REAR BUMPER CLIP
  12. 1 REAR BUMPER TOW COVER
  13. 1 REAR END PANEL
  14. 1 REAR END PANEL TOP GARNISH
  15. 1 REAR FENDER MUDFLAP L/H
  16. 1 SPARE TIRE PANEL
  17. 1 SPARE TIRE PANEL TOP GARNISH

List TotalS\$ :  
20.00% Discount S\$ :

*my car*  
*notified*  
*11km 84650t*  
*Running After Paim*  
*6 days*

|           |          |   |
|-----------|----------|---|
| <i>B1</i> | 995.50   | ✓ |
| <i>nn</i> | 165.00   | ✓ |
| <i>nn</i> | 165.10   | X |
| <i>nn</i> | 204.80   | ✓ |
| <i>nn</i> | 234.50   | ✓ |
| <i>nn</i> | 139.10   | ✓ |
| <i>nn</i> | 772.40   | ✓ |
| <i>nn</i> | 588.90   | ✓ |
| <i>nn</i> | 31.40    | ✓ |
| <i>nn</i> | 96.60    | X |
| <i>nn</i> | 39.00    | ✓ |
| <i>nn</i> | 26.00    | ✓ |
| <i>nn</i> | 396.60   | ✓ |
| <i>nn</i> | 172.80   | ✓ |
| <i>nn</i> | 87.00    | ✓ |
| <i>nn</i> | 810.70   | X |
| <i>nn</i> | 335.00   | X |
| <hr/>     |          |   |
|           | 5,260.40 |   |
|           | 1,052.08 |   |
| <hr/>     |          |   |
|           | 4,208.32 |   |

- SPECIAL NETT ITEMS :
1. 1 TAIL GATE W/SCREEN SEALANT
  2. 1 JAZZ EMBLEM
  3. 1 HONDA LOGO
  4. 1 REAR BUMPER LOWER LIP
  5. 1 REVERSE SENSOR SET

Special Nett Total S\$ :

*nn*  
*nn*  
*nn*  
*nn*  
*nn*

|           |          |   |
|-----------|----------|---|
| <i>nn</i> | 65.00    | ✓ |
| <i>nn</i> | 38.80    | ✓ |
| <i>nn</i> | 48.50    | X |
| <i>nn</i> | 588.00   | ✓ |
| <i>nn</i> | 280.00   | ✓ |
| <hr/>     |          |   |
|           | 1,020.30 |   |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

CONTINUE / ...



Email : darren@completevms.com.sg ( )  
lily@completevms.com.sg ( )  
lihui@completevms.com.sg ( )

KOH SOON LEE  
BLK 416 SAUJANA ROAD #05-50  
SINGAPORE 670416

Attention : THE OWNER  
Contact : 81382870

Estimate : ES006383

Date : 26/06/2018  
Vehicle Num. : SJT931P  
Make/Model : HONDA JAZZ GLI 1.3A-2009  
Chassis/Eng# : MRHGE68509P021559/L13Z1170340E  
Accident Date : 25/06/2018  
Claim No. :  
Reference :  
Policy No. :

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

|                                                                                                                                         |  |  |          |      |
|-----------------------------------------------------------------------------------------------------------------------------------------|--|--|----------|------|
| LABOUR :                                                                                                                                |  |  |          |      |
| REMOVE & REINSTALL TAIL GATE W/SCREEN GLASS                                                                                             |  |  | 180.00   | 120k |
| TRANSFER TAILGATE COMPONENT TO NEW GATE                                                                                                 |  |  | 150.00   | 60k  |
| CHANGE TAIL LAMP AND CHECK LIGHTING                                                                                                     |  |  | 65.00    | 20k  |
| RUST PROOFING TREATMENT                                                                                                                 |  |  | 100.00   | 60k  |
| SPRAY PAINT DAMAGED AREA AFFECTED                                                                                                       |  |  | 1,100.00 | 900k |
| TO CUT OFF REAR END PANEL, SPARE TIRE PANEL, KNOCK AND STRAIGHTEN TAMP LAMP PANELS, REAR CHASSIS FRAMES, AND CHANGE ALL NECESSARY PARTS |  |  | 1,300.00 | 800k |
| Labour Total S\$ :                                                                                                                      |  |  | 2,895.00 |      |

SingDollars : Eight Thousand One Hundred Twenty-Three & Cents Sixty-Two Only

Total S\$ : 8,123.62  
=====

COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun



COMPLETE VMS PTE LTD The Premier One-Stop Vehicle Accident Claims Centre  
176 Sin Ming Drive, #03-14, Sin Ming Autocare Complex, Singapore 575721  
(Tel) 6455 0012 (Fax) 6554 0012 (Web) www.completevms.com.sg

Email : darren@completevms.com.sg ( )  
lily@completevms.com.sg ( )  
lihui@completevms.com.sg ( )

KOH SOON LEE  
BLK 416 SAUJANA ROAD #05-50  
SINGAPORE 670416

Attention : THE OWNER  
Contact : 81382870

### Supplementary Estimate : ES006387

Date : 27/06/2018  
Vehicle Num. : SJT931P  
Make/Model : HONDA JAZZ GLI 1.3A-2009  
Chassis/Eng# : MRHGE68509P021559/L13Z11703405  
Accident Date : 27/06/2018  
Claim No. :  
Reference :  
Policy No. :

| S/N | Quantity | Particular | Unit Price | Amount S\$ |
|-----|----------|------------|------------|------------|
|-----|----------|------------|------------|------------|

|    |   |                                              |    |        |
|----|---|----------------------------------------------|----|--------|
| 1. | 1 | LIST ITEMS :<br>REAR FENDER INNER TRIM L/H   | cm | 385.00 |
|    |   | List TotalS\$ :                              |    | 385.00 |
|    |   | 20.00% Discount S\$ :                        |    | 77.00  |
|    |   |                                              |    | 308.00 |
| 1. | 1 | SPECIAL NETT ITEMS :<br>EMERGENCY SIGN BOARD | cm | 190.00 |
|    |   | Special Nett Total S\$ :                     |    | 190.00 |

SingDollars : Four Hundred Ninety-Eight Only

Total S\$ : 498.00  
=====

### COMPLETE VMS PTE LTD

This is only an estimate bases on our preliminary inspection and does not cover additional parts and labour time which may be required after the work has begun