

ASS. REC. BY:

REF: CS/FCI18011706/R19d3

n2

Special Instruction:

Surveyor:

CWS

ASSIGNMENT (Office)

From (Person):

Lurene jaw

of

FCI

Date/Time: 26/6/18 @ 6:10pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SIN 1256E

Insured:

SHB 2079E

at Workshop in/s:

8ng Ah tee

Tel:

6268 6183

of

Blk 3, Pioneer Rd north # 01-18

Policy No:

Claim No:

D18005006MFSTH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

24/06/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

1006cm @ 27/6/18

Person Contacted:

jaye

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate
	SIN 1256E - CS/CAI15006339/Ugok3	DOA: 12/04/2015
	SHB 2079E - CC3/EQI18008089/Kub3	DOA: 01/05/2018
20/7/18 @ 1.57pm	revised to Lurene by email.	
19/12/18 @ 3.20pm	confirmed with Sharon final fig 61311, 3 days.	
	(Red 51160.80, 47%)	
	no lump sum.	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18011706/R1qd3	
36 ROBINSON ROAD #16-01 CITY HOUSES SINGAPORE 068877		Date : 27-06-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 2079E	Veh. Inspected	SJN 1256E
Policy No.		Coverage (\$)	0.00
Claim No.	D18005006MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	27/06/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	24/06/2018	Inspection Date	
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18005006MFSH

Date: 20 July 2018

Our Ref: CS/FCI18011706/R1qd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJN 1256E .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 18/07/2018 at the premises of M/s SNG AH TEE . and have the following to report:-

Workshop Estimate Amount	: S\$ 2,471.80 .
Revised Estimate Amount	: S\$ 1,167.75 .
"Check" Items Amount	: S\$ 870.00 .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages
at the front portion.



Yours faithfully

Rasul
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	26-06-2018	Our Ref No. D18005006MFSH
Accident Date	24-06-2018	Claim Type. Third Party
Insured Vehicle	SHB2079E	Third Party Vehicle. SJN1256E
Survey Location	BLK 3 PIONEER ROAD NORTH #01-18	
Contact Person.	JOYCE TAN	
Contact No.	62686183/ 0	Fax No. 62681429
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Sharon Sng <sharon@sngahtee.com>
Sent: Wednesday, 19 December 2018 3:20 PM
To: Shiau Chan (LKKAUTO)
Subject: RE: SJN1256E - FINALISE & BEFORE PAINT ITEMS

Hi Shiau Chan

confirm. thanks.

Best Regards

Sharon Sng

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



-Please note that all offer/acceptance is made without prejudice.-

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Tuesday, December 18, 2018 2:19 PM
To: Sharon Sng <sharon@sngahtee.com>; Rasul (LKKAUTO) <Rasul@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SJN1256E - FINALISE & BEFORE PAINT ITEMS

Dear Sharon,

WITHOUT PREJUDICE

Offer final fig \$1,311.00 before GST and 3 repair days.

Kindly confirm.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Sharon Sng <sharon@sngahtee.com>
Sent: Friday, 14 December 2018 3:38 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; Rasul (LKKAUTO) <Rasul@lkkauto.com>
Subject: SJN1256E - FINALISE & BEFORE PAINT ITEMS

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 20 July 2018 1:52 PM
To: 'Claim Workflow System'; assignments
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005006MFSH/1
Attachments: CSFCI18011706R1qd3.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SJN 1256E.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 27 June 2018 10:10 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005006MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 26 June 2018 6:10 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005006MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	3281G

Vehicle Details

Vehicle No.:	SJN1256E
Vehicle to be Exported:	No
Intended De-registration Date:	14 Jul 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	3ZZ4832127
Chassis No.:	MR053ZEE106129505
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,084.00
Original Registration Date:	03 Feb 2009
First Registration Date:	03 Feb 2009
Transfer Count:	2
Actual ARF Paid:	\$16,084.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	02 Feb 2019
PARF Rebate Amount:	\$8,042.00

Intended COE Rebate Details

COE Expiry Date:	02 Feb 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$2,693.00
COE Rebate Amount:	\$148.00
Total Rebate Amount:	\$8,190.00

The information contained herein is correct as at 27 Jun 2018

OK

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ004004

FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIMS DEP

36 ROBINSON ROAD #16-01

CITY HOUSE SINGAPORE 068877

ATTENTION:

CONTACT: 6222 2311

FAX NO: 6507 3849

DATE: 16/07/2018
ACCIDENT DATE: 24/06/2018
VEHICLE NO: SJN1256E
CHASSIS/ENG.NO: MR053ZEE106129505
VEHICLE MODEL: TOYOTA ALTIS
CLAIM NO: D18005006MFSH
POLICY NO:
REMARK: 1256 FIRST CAP TP
AGST SHB2079E

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC	FRT BUMPER	437.00	25	327.75 PE /	327.75 /
2	2	PC	FRT BUMPER SIDE RETAINER	56.00	25	42.00 X M	84.00 X
3	10	PC	FRT BUMPER CLIPS	5.50	25	4.13 M	41.30 41.2
4	1	PC	FRT BUMPER REINFORCEMENT	345.00	25	258.75 7.50	258.75 X
5	1	PC	FRT BUMPER LOWER GRILLE	103.00	25	77.25 7.50	77.25 /
6	1	PC	FRT GRILLE ASSY	315.00	25	236.25 8.50	236.25 /
7	1	PC	FRT GRILLE EMBLEM	75.00	25	56.25 M	56.25 /
8	1	PC	FRT HEADLAMP(RH)	712.00	25	534.00 7.50	534.00 X
9	1	PC	FRT BUMPER TOP SEAL	55.00	25	41.25 M	41.25 /

SUB-TOTAL: 1,656.80

** SPECIAL NETT PRICE **							
1	1	PC	FRT NUMBER PLATE	35.00		35.00 B1 /	35.00 /
SUB-TOTAL							35.00

** WORK LABOUR **							
TO CHECK WIRING						30.00 /	30.00
TO KNOCK, WELD, REMOVE & REPLACE ABOVE PARTS						350.00 200	350.00
TO SPRAY PAINTING ON AFFECTED AREAS						400.00 200	400.00

JOYCE

PAGE: 1 of 2

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O.E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.

Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com

RCB. Reg. / GST Reg. No: 200810440N

EST/QUOTE NO. SQ004004

FIRST CAPITAL INSURANCE LIMITED
MOTOR CLAIMS DEP

36 ROBINSON ROAD #16-01
CITY HOUSE SINGAPORE 068877

ATTENTION:

CONTACT: 6222 2311

FAX NO: 6507 3849

DATE: 16/07/2018
ACCIDENT DATE: 24/06/2018
VEHICLE NO: SJN1256E
CHASSIS/ENG.NO: MR053ZEE106129505
VEHICLE MODEL: TOYOTA ALTIS
CLAIM NO: D18005006MFSH
POLICY NO:
REMARK: 1256 FIRST CAP TP
AGST SHB2079E

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
SUB-TOTAL							780.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

From
40 90010068
3 days
3/18
18/07/18 @ 1800
Resy. b.f. paint
20/7/18

JOYCE

PAGE: 2 of 2

2537.75
SUB-TOTAL: S\$ 2,471.80
ADD 7% GST: S\$ 173.03
GRAND TOTAL: S\$ 2,644.83

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.

孫亞弟汽車燒焊私人有限公司

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com EST/QUOTE NO. SQ004004

RCB. Reg. / GST Reg. No: 200810440N

FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIMS DEP

36 ROBINSON ROAD #16-01

CITY HOUSE SINGAPORE 068877

ATTENTION:

CONTACT: 6222 2311

FAX NO: 6507 3849

DATE: 16/07/2018
ACCIDENT DATE: 24/06/2018
VEHICLE NO: SJN1256E
CHASSIS/ENG.NO: MR053ZEE106129505
VEHICLE MODEL: TOYOTA ALTIS
CLAIM NO: D18005006MFSH
POLICY NO:
REMARK: 1256 FIRST CAP TP
AGST SHB2079E

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
** LIST PRICE **							
1	1	PC*	FRT BUMPER	437.00	25	327.75 PE✓	327.75✓
2	2	PC	FRT BUMPER SIDE RETAINER	56.00	25	42.00 X	84.00X
3	10	PC	FRT BUMPER CLIPS	5.50	25	4.13 M-	41.30✓
4	1	PC	FRT BUMPER REINFORCEMENT	345.00	25	258.75 ?	258.75X
5	1	PC*	FRT BUMPER LOWER GRILLE	103.00	25	77.25 ?	77.25✓
6	1	PC	FRT GRILLE ASSY	315.00	25	236.25 SU-	236.25✓
7	1	PC	FRT GRILLE EMBLEM	75.00	25	56.25 M-	56.25✓
8	1	PC	FRT HEADLAMP(RH)	712.00	25	534.00 ?	534.00X
9	1	PC	FRT BUMPER TOP SEAL	55.00	25	41.25 M-	41.25✓

**** FRT Fog Lamp Chrome RH-1pc - ms -** SUB-TOTAL: 1,656.80
\$780.05

** SPECIAL NETT PRICE **							
1	1	PC	FRT NUMBER PLATE	35.00		35.00 B1-	35.00
SUB-TOTAL							35.00✓

** WORK LABOUR **							
TO CHECK WIRING				30.00		30.00	
TO KNOCK, WELD, REMOVE & REPLACE ABOVE PARTS				350.00	20%	350.00	
TO SPRAY PAINTING ON AFFECTED AREAS				400.00	20%	400.00	

JOYCE

PAGE: 1 of 2

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD

E & O E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.
Quotation is only valid for 14 days.

19/7/2018 11:55 am

P/P via whatsapp confirm.

B/4 point send photo with Dmg

Frt Bumper

孫亞弟汽車燒焊私人有限公司 SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3, Pioneer Road North, #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Email: sngahtee@singnet.com.sg

Website: www.sngahtee.com EST/QUOTE NO. SQ004004

RCB, Reg. / GST Reg. No: 200810440N

FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIMS DEP

36 ROBINSON ROAD #16-01

CITY HOUSE SINGAPORE 068877

ATTENTION :

CONTACT : 6222 2311

FAX NO: 6507 3849

DATE : 16/07/2018
ACCIDENT DATE : 24/06/2018
VEHICLE NO : SJN1256E
CHASSIS/ENG.NO : MR053ZEE106129505
VEHICLE MODEL : TOYOTA ALTIS
CLAIM NO : D18005006MFSH
POLICY NO :
REMARK : 1256 FIRST CAP TP
AGST SHB2079E

S/N.	QTY	UNIT	DESCRIPTION	PRICE	DISC %	DISC/MARKUP	TOTAL AMT
------	-----	------	-------------	-------	--------	-------------	-----------

SUB-TOTAL 780.00

total \$ 1311.05

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

From
Hp 90010008

3 days

45

18/07/18 @ 1800

Revy after repair

JOYCE

PAGE: 2 of 2

SUB-TOTAL : S\$ 2,471.80

ADD 7% GST. S\$ 173.03

GRAND TOTAL : S\$ 2,644.83

ON BEHALF OF SNG AH TEE PANEL & SERVICE PTE LTD

E & O.E

Disclaimer clause:

The above estimate/quotation is meant for solely the intended party stated above and in any event, we are not liable to any other parties arising from the circumstances of this or any action taken in reliance on such estimates or quotations.

Quotation is only valid for 14 days.

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Blk 3 Pioneer Road North #01-18 Singapore 628457

Tel: 6268 6183 (4 Lines) Fax: 6268 1429

Your Ref:

Date : 14/12/2018

ATTN:THE MOTOR CLAIMS DEPT
FIRST CAPITAL INSURANCE LIMITED

SUPPLEMENTARY ESTIMATE COST OF REPAIR

Vehicle Reg No. SJN1256E
Date of Accident 24-Jun-18
Type of Claim TP FIRST
Survey By _____

Model / Year

Policy No.

Prepared By

Chassis No.

TOYOTA ALTIS

SHARON

S/NO Description

Qty List Price Amount

1 FRT FOGLAMP CHROME RH

1

\$ 88.00

LESS 25%

\$ 88.00

\$ 22.00

\$ 66.00

RM 66.00 /



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18011706/R1qd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 21-12-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 2079E	Veh. Inspected	SJN 1256E	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18005006MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	26/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA ALTIS 1.6	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	MR053ZEE106129505	Colour	GREY	
Odometer	154639	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	BRIDGESTONE	5 mm	
L/H Front Tyre	205/55 R16	BRIDGESTONE	5 mm	
R/H Rear Tyre	205/55 R16	BRIDGESTONE	5 mm	
L/H Rear Tyre	205/55 R16	BRIDGESTONE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/06/2018	Inspection Date	18/07/2018	
Survey held at	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJN 1256E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRT BUMPER	DEFORMED	437.00	437.00
2	FRT BUMPER SIDE RETAINER @\$56.00	NOT NECESSARY	112.00	-
10	FRT BUMPER CLIPS @\$5.50	NECESSARY	55.00	55.00
1	FRT BUMPER REINFORCEMENT	SERVICEABLE	345.00	-
1	FRT BUMPER LOWER GRILLE	CRACKED	103.00	103.00
1	FRT GRILLE ASSY	SCRATCHED	315.00	315.00
1	FRT GRILLE EMBLEM	NECESSARY	75.00	75.00
1	FRT HEADLAMP (RH)	SERVICEABLE	712.00	-
1	FRT BUMPER TOP SEAL	NECESSARY	55.00	55.00
1	FRT FOGLAMP CHROME RH (ADDITIONAL)	MISSING	88.00	88.00
	LESS 25% DISCOUNT		-574.25	-282.00
			1,722.75	846.00
SPECIAL NETT ITEMS				
1	FRT NUMBER PLATE (SN)	BENT	35.00	35.00
			35.00	35.00
LABOUR				
	TO CHECK WIRING.		30.00	30.00
	TO KNOCK, WELD, REMOVE & REPLACE ABOVE PARTS.		350.00	200.00
	TO SPRAY PAINTING ON AFFECTED AREAS.		400.00	200.00
			780.00	430.00
GRAND TOTAL			2,537.75	1,311.00
RECOMMENDED COST OF REPAIRS				1,311.00

Report Ref No. CS/FCI18011706/R1qd3n2

MARKET VALUE: \$12,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$8,190.00=NETT VALUE: \$3,810.00

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC1813303
INV Date 21/12/2018
Reference CS/FCI18011706/R1qd3n2
Code FCI2

**PROFESSIONAL SERVICE FEE**

Vehicle No. SJN 1256E
Insured Veh. SHB 2079E
Claim No. D18005006MFSH
Policy No.
Accident Date 24/06/2018
Inspection Date 18/07/2018

Description	Total
Survey Inspection	245.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	245.00
GST (7%)	17.15
Grand Total	262.15

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd