

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
 143 Cecil Street #01-01 GB Building
 069542

Attention : Motor Claim Department
 Contact : 338 7288 Fax No. : 880 4838

Estimate : ES000196

Date : 26/06/2018
 Vehicle Num. : SLQ 7567D(LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 21/06/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BOOT LID R		850.00
2.	1	REAR WINDSCREEN GLASS MOULDING X		250.00
3.	1	REAR BOOT PRIUS EMBLEM X		100.00
4.	1	REAR BOOT HYBRID EMBLEM (PRIUS) X		100.00
5.	1	REAR BOOT LOCK ASSY X		280.00
6.	1	REAR BOOT INNER TRIM BOARD X		345.00
7.	1	REAR BOOT HAND GRIP COVER X		120.00
8.	1	REAR BOOTLID OUTER GARNISH X		680.00
9.	1	REAR BUMPER ✓DMG		500.00
10.	1	REAR LOWER BUMPER ✓Deform		560.00
11.	1	REAR BUMPER TOW COVER ✓MS		100.00
12.	1	REAR BUMPER REINFORCEMENT ✓DT		340.00
13.	2/LH,RH	REAR BUMPER EXTENSION FILLER ✓CRK	190.00	380.00
14.	1	REAR BUMPER CENTER DUST COVER ?		230.00
15.	2/LH,RH	REAR BUMPER DUST COVER ?	240.00	480.00
16.	1	REAR END PANEL ✓DT		750.00
17.	1	REAR END PANEL TOP GARNISH ✓Deform		170.00
18.	2/LH,RH	REAR FENDER INNER TRIM BOARD X	450.00	900.00
19.	1	FRONT BONNET ✓DT		900.00
20.	1	FRONT BONNET LOCK ✓DM		180.00
21.	2/LH,RH	FRONT BONNET HINGE ✓DT	220.00	440.00
22.	1	FRONT BONNET INSULATOR ✓DT		384.00
23.	1	FRONT BUMPER ✓DMG		550.00
24.	1	FRONT BUMPER TOYOTA LOGO ✓NEC		150.00
25.	1	FRONT BUMPER RADIATOR GRILLE ✓BR		340.00
26.	1	FRONT BUMPER LOWER GRILLE X		150.00
27.	1	FRONT BUMPER REINFORCEMENT X		340.00
28.	1	FRONT BUMPER REINFORCEMENT FOAM ✓CRK		100.00
29.	1	FRONT TOP SUPPORT PANEL ✓DT		370.00

Sathya Sai
 24/6/2018
 98072012

- Part by Part repair
 - Question mark item photo
 - Photo before paint.

10 days

CONTINUE / ...

LKH Auto Cons the Repairer • To resurvey before painting • To display during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification is allowed • Supplementary items must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature	To be notify the Repairer • To resurvey before painting • To display during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification is allowed • Supplementary items must be resurveyed and is subject to final approval from Insurance Company
---	---

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD
 143 Cecil Street #01-01 GB Building
 069542

Attention : Motor Claim Department

Contact : 338 7288 Fax No. : 880 4838

Estimate : ES000196

Date : 26/06/2018
 Vehicle Num. : SLQ 7567D(LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 21/06/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
30.	2/LH,RH	FRONT SIDE SUPPORT PANEL ?	280.00	560.00
31.	2/LH,RH	FRONT HEADLAMP ASSY ✓CRK	2,550.00	5,100.00
32.	2/LH,RH	FRONT HEADLAMP TOP PANEL ✓BT	77.00	154.00
33.	1	FRONT SUPPORT PANEL TOP GARNISH ✓CRK		230.00
34.	1	FRONT INTAKE AIR DUET X		210.00
35.	1	FRONT INLET AIR DUET X		255.00
36.	1	AIR FLOW BOX ✓cut		400.00
37.	1	CONDENSER ASSY ?		1,400.00
38.	1	RADIATOR ?		1,845.00
39.	1	FRONT BUMPER TOP RUBBER MOULDING ✓BT		55.00
40.	2/LH,RH	FRONT RADIATOR TOP SIDE AIR GUIDE X	140.00	280.00
41.	1	FRONT RADIATOR LOWER SIDE AIR GUIDE X		130.00
42.	2/LH,RH	FOG LAMP ASSY X	980.00	1,960.00
List TotalS\$:				23,618.00
25.00% Discount S\$:				5,904.50
				17,713.50

SPECIAL NETT ITEMS :				
1.	1	REAR BOOT INNER TRIM BOARD CLIP	50.00	30
2.	1	REAR BOOTLID OUTER GARNISH CLIPS	50.00	30
3.	1	REAR BUMPER CLIP	50.00	30
4.	1	REVERSE SENSOR	280.00	✓ 0 mg
5.	1	REAR END PANEL TOP GARNISH CLIPS	50.00	30
6.	1	TOWING CHARGE	60.00	✓
7.	1	REAR WINDSCREEN SEALANT	120.00	X
8.	1	FRONT BONNET INSULATOR CLIP	50.00	30
9.	1	FRONT BUMPER CLIP	50.00	30
10.	1	FRONT SUPPORT PANEL TOP GARNISH CLIPS	50.00	30
11.	1	COOLANT	120.00	60

CONTINUE / ...

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03
 Halcyon 2, S'pore 577200
 Tel No. : 6451 3933 Fax No. : 6455 7576
 E-Mail : worldaut@singnet.com.sg
 Website : www.worldauto.com.sg
 Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

AXA INSURANCE SINGAPORE PTE LTD

143 Cecil Street #01-01 GB Building
 069542

Attention : Motor Claim Department

Contact : 338 7288 Fax No. : 880 4838

Estimate : ES000196

Date : 26/06/2018
 Vehicle Num. : SLQ 7567D(LCR)
 Make/Model : TOYOTA PRIUS HYBRID
 Chassis/Eng# :
 Accident Date : 21/06/2018
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
12.	1	AIRCON GAS		150.00 20
		Special Nett Total S\$:		1,080.00
		LABOUR :		
		TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES		180.00 100
		REMOVE & REFIT REAR WINDSCREEN GLASS		180.00 X
		WIRINGS CHECK AND RECTIFY WHERE NECESSARY		180.00 100
		LABOUR TO REMOVE REAR ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.		1,600.00 1000
		PUTTY & SPRAY PAINT REAR & ALL AFFECTED AREAS (INNER/ OUTER)		1,200.00 800
		LABOUR TO REMOVE FRT ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT, CUT/WELD, STRAIGHTEN PANEL WHERE NECESSARY & REPLACE ABOVE PARTS.		1,200.00 600
		PUTTY & SPRAY PAINT FRT & ALL AFFECTED AREAS (INNER/ OUTER)		1,000.00 600
		AIRCON SYSTEM REPAIRS INCLUDING REPLACING ABOVE PARTS, PERFORM AIRCON LEAK TEST AND REFILL AIRCON GAS.		280.00 150
		Labour Total S\$:		5,820.00
E. & O.E.			Total S\$:	24,613.50
				=====

for WORLD AUTO PTE LTD