

ASS. REC. BY:

REF: CS / UOTI 8011746 / R1Hbz2 | Special Instruction:

Survivor:

Rasul

ASSIGNMENT (Office)

From (Person): Chan Li Si of UOI Date/Time: 27062018

Estimated Cost: Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLE 4307X Insured: Public Liability

at Workshop m/s SK Automobile Tel: 93877852

of 1 Soon Lee St # 04-44 / 45

Policy No: Claim No:

Sum Insured: Excess:

Make of Veh: D.O.A. 22062018  
(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time: 27062018 10.12am Person Contacted: Tyson Vehicle: IN / OUT

Date/Time	Action/Instruction ( ✓ ) Estimate
	SLE 4307X - x Susan
	Public Liability -x 678951.55
20/11/18	Confirm LIS \$ 7250 @ 11 days with Susan
	Red: \$16,258.72, 69%.

Signature: *Paul*

REF: *UOL*

5745G

### ASSIGNMENT

From: \_\_\_\_\_ Date: *27062018*

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SLE 4307X*

at Workshop m/s: *SK Automobile*

of: *1 Soon Ltd St #04-44 /45*

Insured: \_\_\_\_\_


Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_



(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: *SLE 4307X* Yr Regn: *2016 / 2ndy*

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Honda Vezel 1.5X A* c.c. *1496*

Colour: *Black* A/C: *Insured / Std / NI / NA*

Sp. Reading: *035653* T/Radio: *Insured / Std / NI / NA*

Eng/No: \_\_\_\_\_

C/No: *Ru11114249*

Gen. Cond: Good / ☒ Fair / Poor / Burnt

Steering: *In order* / Jammed / Leaked / Burnt or

Brake: *In order* / Jammed / Leaked / Burnt or

Modi: *Nil* / STD A/Rim or

Tyre Size: F: *215/60R16* R: *1"*

BS / ☒ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: *6* mm R/Bal. *6* mm

L/Bal. *6* mm

D.O.A. *22/06/18*

Rear: *6* mm L/Bal. *6* mm

D.O.I. *27/06/18*

Survey held at: *SK AUTOMOBILE*

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

*N/S / Rear*

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<i>10/12</i>	<i>Re-confirmed LS &amp; Foot with repainer by Advion. (Red. 16, 508.72, 702)</i>

RECEIVED 21 NOV 2018

Date/Time, File Pass to? ☐ : Preli. Report

1) *typist* ☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: *11*

Resurvey No. of Trip: *1*

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee: *1700 195*

Transportation: *50*

*50*

Photos: *OSP*

Others: *21/11/18*

*64*

TOTAL

*13X15=195*

*1700 195*

*50*

*50*

*64*

*529*

Report Format: *TP*

Lump Sum / H.B.I. (\$ *7250.00 Foot*)

## Janice Lee (LKKAUTO)

---

**From:** Pioneer Workshop <pioneer@skauto.com.sg>  
**Sent:** Tuesday, November 20, 2018 3:42 PM  
**To:** Janice Lee (LKKAUTO)  
**Cc:** Rasul (LKKAUTO); Simon Koh; SK Admin; Julie Johari; Susan Koh  
**Subject:** Re: SLE4307X AFTER PAINT PHOTO  
**Attachments:** ~WRD000.jpg

Hi Jannice

Thank you for your email.

We confirm acceptance of your Offer (Lump Sum) @ \$7,250.00 and 11 working days.

THANK YOU

Best Regards  
Susan  
C/O SK Automobile Pte Ltd

On Mon, Nov 19, 2018 at 5:05 PM Janice Lee (LKKAUTO) <[JaniceLee@lkkauto.com](mailto:JaniceLee@lkkauto.com)> wrote:

Dear Susan,

Kindly confirm L/S \$7,250.00 @ 11 DAYS

Thank you.

Best Regards,

**Jannice Lee (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [jannicelee@lkkauto.com](mailto:jannicelee@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Catherine Chong (LKK Auto)

---

**From:** CHAN LI SI <lisi@uoi.com.sg>  
**Sent:** Wednesday, 27 June, 2018 10:21 AM  
**To:** assignments@lkkauto.com  
**Subject:** FW: Accident on 22 June 2018 @ Jurong Cold Storage  
**Attachments:** SLE4307X.zip  
  
**Importance:** High

Dear Shiau Chan,

As spoken, please assist on this WP survey on vehicle SLE4307X.

Please find enclosed the GIA report and quotation for our surveyor's reference.

Password: uoi2018

Regards,

**Chan Li Si**

Executive  
Claims

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909  
Main • (65) 6222 7733 | DID • (65) 6490 9330 | Fax • (65) 6327 3869 | Email • [lisi@uoi.com.sg](mailto:lisi@uoi.com.sg)

### UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

---

**From:** CHAN LI SI  
**Sent:** Wednesday, 27 June, 2018 10:18 AM  
**To:** 'Tyson Koh' <tysonkoh@skauto.com.sg>  
**Cc:** SK Admin <hueylee@skauto.com.sg>; Simon Koh <simon@skauto.com.sg>; KY <kyleong@skauto.com.sg>; assignments@lkkauto.com  
**Subject:** RE: Accident on 22 June 2018 @ Jurong Cold Storage

Dear Tyson,

Thank you for the confirmation. The surveyor from LKK will contact you today for the survey arrangement.

Regards,

**Chan Li Si**

Executive  
Claims

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909  
Main • (65) 6222 7733 | DID • (65) 6490 9330 | Fax • (65) 6327 3869 | Email • [lisi@uoi.com.sg](mailto:lisi@uoi.com.sg)

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

**From:** Tyson Koh [<mailto:tysonkoh@skauto.com.sg>]

**Sent:** Wednesday, 27 June, 2018 10:05 AM

**To:** CHAN LI SI <[lisi@uoi.com.sg](mailto:lisi@uoi.com.sg)>

**Cc:** SK Admin <[hueylee@skauto.com.sg](mailto:hueylee@skauto.com.sg)>; Simon Koh <[simon@skauto.com.sg](mailto:simon@skauto.com.sg)>; KY <[kyleong@skauto.com.sg](mailto:kyleong@skauto.com.sg)>

**Subject:** Re: Accident on 22 June 2018 @ Jurong Cold Storage

Dear Miss Chan,

We agree to appoint M/s LKK Auto Consultants Pte Ltd.

Please update us on the date and date of inspection.

We do :

1. accidents ( without touching your insurance )
2. rentals ( all types pending availability )
3. buy/sell ( all types pending availability )

Anything just give me a call.

Thank You & Kind regards,

Tyson Koh

HP: 93827852 (24HRS)

This email and any files transmitted with it are confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error please notify SK Automobile Pte Ltd. This message contains confidential information and is intended only for the individual named. If you are not the named addressee you should not disseminate, distribute or copy this e-mail. Please notify the sender immediately by e-mail if you have received this e-mail by mistake and delete this e-mail from your system. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited.

On Wed, Jun 27, 2018 at 8:48 AM, CHAN LI SI <[lisi@uoi.com.sg](mailto:lisi@uoi.com.sg)> wrote:

Dear Tyson,

I refer to the above matter.

We confirm that we are the Public Liability Insurers of Jurong Cold Storage.

We would like to arrange for a without prejudice pre repair inspection of your client's vehicle.

Pursuant to the amended Pre-action Protocol for Non-Injury Motor Accident (NIMA), we enclose a list of our Surveyors, for your attention.

In this case, we propose to appoint M/s LKK Auto Consultants Pte Ltd.

Please seek your client's instruction for the repair after the inspection has been completed and inform our Surveyors to carry out a Post-Repair Inspection.

Please confirm in writing if you are agreeable to the surveyor appointment for our necessary action. All our rights are reserved.

Regards,

**Chan Li Si**

Executive

Claims

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909

Main • (65) 6222 7733 | DID • (65) 6490 9330 | Fax • (65) 6327 3869 | Email • [lisi@uoi.com.sg](mailto:lisi@uoi.com.sg)

#### UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

**From:** Tyson Koh [<mailto:tysonkoh@skauto.com.sg>]

**Sent:** Tuesday, 26 June, 2018 6:22 PM

**To:** CHAN LI SI <[lisi@uoi.com.sg](mailto:lisi@uoi.com.sg)>

**Cc:** SK Admin <[hueylee@skauto.com.sg](mailto:hueylee@skauto.com.sg)>; Simon Koh <[simon@skauto.com.sg](mailto:simon@skauto.com.sg)>; KY <[kyleong@skauto.com.sg](mailto:kyleong@skauto.com.sg)>

**Subject:** Accident on 22 June 2018 @ Jurong Cold Storage

Dear Sir / Mdm,

We act on behalf of our client for above matter.

Attached GIA report, estimate and surveyor request for your perusal, kindly assists to arrange a surveyor to conduct a pre-repair inspection.

Location : 1 Soon Lee Street #04-44/45

Pioneer Centre

Singapore 627605

Contact No : Kumar 6262 4438

Pls note that we have checked and confirmed it is under UOI insurance:

---Public Liability Policy: DHOL110050621700

Please let me know if you have further query.

Thank You & Kind regards,

Tyson Koh

HP: 93827852 (24HRS)

This email and any files transmitted with it are confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error please notify SK Automobile Pte Ltd. This message contains confidential information and is intended only for the individual named. If you are not the named addressee you should not disseminate, distribute or copy this e-mail. Please notify the sender immediately by e-mail if you have received this e-mail by mistake and delete this e-mail from your system. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited.

## Catherine Chong (LKK Auto)

---

**From:** CHAN LI SI <lisi@uoi.com.sg>  
**Sent:** Monday, 2 July, 2018 2:45 PM  
**To:** Catherine Chong (LKK Auto); assignments@lkkauto.com  
**Cc:** 'SUR'  
**Subject:** RE: Accident on 22 June 2018 @ Jurong Cold Storage

Dear Catherine,

Kindly note my file reference is L11D54401807.

Regards,

**Chan Li Si**

Executive  
Claims

United Overseas Insurance Limited

3 Anson Road, #28-01 Springleaf Tower, Singapore 079909  
Main • (65) 6222 7733 | DID • (65) 6490 9330 | Fax • (65) 6327 3869 | Email • [lisi@uoi.com.sg](mailto:lisi@uoi.com.sg)

### UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

---

**From:** Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]  
**Sent:** Wednesday, 27 June, 2018 10:25 AM  
**To:** CHAN LI SI <lisi@uoi.com.sg>; assignments@lkkauto.com  
**Cc:** 'SUR' <sur@lkkauto.com>  
**Subject:** RE: Accident on 22 June 2018 @ Jurong Cold Storage

Dear Li Si,

Thank you for the assignment.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CHAN LI SI [mailto:lisi@uoi.com.sg]  
**Sent:** Wednesday, 27 June, 2018 10:21 AM  
**To:** [assignments@lkkauto.com](mailto:assignments@lkkauto.com)  
**Subject:** FW: Accident on 22 June 2018 @ Jurong Cold Storage  
**Importance:** High

Dear Shiau Chan,

As spoken, please assist on this WP survey on vehicle SLE4307X.





honda vezel

Price Range ▾

Depreciation ▾

2016 ▾

Vehicle Type ▾

Advanced Search

Home » Used Cars » Privilege Group Pte Ltd » Honda Vezel 1.5A X

## Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

## Car Tyres



## Honda Vezel 1.5A X

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

## Car Details

Price	\$74,500	?
Depreciation	\$8,560 /yr View models with similar depreciation	?
Reg Date	27-Jul-2016 (8yrs 1mth 4days COE left)	?
Manufactured	2016	?
Mileage	20,000 km (10.5k /yr)	?
Transmission	Auto	?
Engine Cap	1,495 cc	?
Road Tax	\$682 /yr	?
Power	96.0 kW (128 bhp) View specs of the Honda Vezel (2014)	?
Curb Weight	1,190 kg	?
Features	Honda Infamous 1.5L I-VTEC Engine Producing 128BHP, Keyless Ignition, Electronic Brakes, CTBA, VSC, Cruise Control, Eco Mode, Digital Aircons.	?
Accessories	Leather Seat, Sports Rims, Pioneer Player With Steering Controls/USB/Bluetooth, Reverse Camera And Sensors, Fog Lights, Retractable Side Mirrors.	?
Description	\$0 Down Payment Available! 100% Approval! 100% Accident Free! In House Loan Or Bank Loan Available! Low Mileage Done. High Over Trade Welcome! Call Now.	?
COE	\$47,020	?
OMV	\$20,271	?
ARF	\$10,380	?
Dereg Value	\$45,865 as of today (change)	?
No. of Owners	2	?
Type of Veh	SUV	?
Category	PARF Car	?
Availability	Available	?

Add to Shortlist

Add to Compare

Add a Note

Posted on: 22-Jun-2018 | Last Updated on: 22-Jun-2018

Tags: Honda Vezel, 2016 Honda Vezel, Honda, Vezel, Used Honda

## Upfront Payment

» more Financial info

Transfer Fee	\$25	?
Down Payment	\$22,350 (change)	Maximum 70% Loan ?
1st Instalment	\$750	?
Total Upfront Payment	\$23,125 (excluding insurance)	?



Location Map



Price Analysis

## Seller Information

Company	Privilege Group Pte Ltd » dealer's pricelist » 16 vehs sold   9 vehs available
Address	37 Jalan Pemimpin #01-01 Search cars nearby this location
Location	Mapex
Office No	88581155
Contact Person(s)	Desmond 83821155 Alan 86855511 Chester 88665511

## Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation

Compare

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 5745E

### Vehicle Details

Vehicle No.: SLE4307X  
Vehicle to be Exported: No  
Intended De-registration Date: 22 Jun 2018  
Vehicle Make: HONDA  
Vehicle Model: VEZEL 1.5X A  
Primary Colour: Black  
Manufacturing Year: 2016  
Engine No.: L15B4034218  
Chassis No.: RU11114249  
Maximum Power Output: 96.0 kW (128 bhp)  
Open Market Value: \$20,124.00  
Original Registration Date: 21 Jul 2016  
First Registration Date: 21 Jul 2016  
Transfer Count: 0  
Actual ARF Paid: \$10,174.00

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 20 Jul 2026  
PARF Rebate Amount: \$7,630.00

### Intended COE Rebate Details

COE Expiry Date: 20 Jul 2026  
COE Category: A - Car up to 1600cc & 97kW (130bhp)  
COE Period(Years): 10  
QP Paid: \$52,301.00  
COE Rebate Amount: \$42,238.00  
**Total Rebate Amount: \$49,868.00**

The information contained herein is correct as at 22 Jun 2018

OK

\$ 74,500.00  
\$ 49,868.00  
←  
\$ 24,632.00

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	23/06/2018 13:34
Date Of Accident	22/06/2018 10:40
Exact Location Of Accident	JURONG COLD STORE BUILDING
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE4307X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAY AIK MING, DANIEL
NRIC No	S8525745E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96246346
Alternative Phone No	OTHERS-96246346

### Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 G (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5092485281
Cover Note Number	

### Driver

Name of Driver	TAY AIK MING, DANIEL
NRIC No	S8525745E
Date Of Birth	07/08/1985
Occupation	INDOOR
Date Of Driving Pass	28/08/2008
Driving Experience	9 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96246346
Fax Number	
Contact Number	OTHERS-96246346
Email Address	NOEMAIL

Address	BLK 246 #10-300 BANGKIT ROAD
Postcode	670246
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Make/Model/Colour	FORKLIFT
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF INJURED PERSON 1

Name	TAY AIK MING, DANIEL
Approximate Age	

Injuries Sustain	
Injured person in which vehicle?	SLE4307X
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	
Address	BLK 246 #10-300 BANGKIT ROAD
Postcode	673443

## Accident Sketch Plan Pg. 1

### SKETCH PLAN


#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.


  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

IDAC KAKI BUKIT(VAC)  
23 KAKI BUKIT AVE 4  
Singapore 415933  
Reporting Centre Personnel's Signature  
Name: \_\_\_\_\_  
Tel: 67492305  
Fax: 67492305  
Email: [feedback@singnet.com.sg](mailto:feedback@singnet.com.sg)

# Accident Sketch Plan Pg. 1

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 22/06/2018 at about 10:40am,  
I was driving my vehicle SLE 4301X(A) exiting Jurong Cold Store building going towards AYE. I was 30meter away from the building exit when suddenly a Forklift (under Jurong Cold Store) reversed and hit onto the left portion of my vehicle. Due to the impact, the left side of my vehicle was seriously damaged. Someone was injured.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

IDAC KAKI BUKIT(VAC)  
23 KAKI BUKIT AVE 4  
Singapore 415933

Reporting Centre Personnel's Signature  
Name: Email: vackb@singnet.com.sg  
NRIC/FIN No.:



TO	: UOI	DATE	: 26-Jun-18
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: SLE4307X
ADDRESS	:	MODEL	: HONDA VEZEL
TEL. NO.	:	CHASSIS NO	:
OWNER'S INSURANCE	:		
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>	DATE :		
	TIME :		
THIRD PARTY REQUESTOR / CONTACT	: KUMAR 9897 3736		

## QUOTATION SUMMARY

### CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR LH	1	\$ 1,249.00	\$ 1,249.00
2	FRONT DOOR HINGE LH	2	\$ 120.00	\$ 240.00
3	FRONT DOOR WEATHER STRIP LH	1	\$ 225.00	\$ 225.00
4	FRONT DOOR OUTER WEATHERSTRIP LH	1	\$ 214.00	\$ 214.00
5	FRONT DOOR UNDER RUBBER LH	1	\$ 110.00	\$ 110.00
6	FRONT DOOR INNER LOCK LH	1	\$ 491.60	\$ 491.60
7	FRONT DOOR INNER TRIM BOARD LH	1	\$ 354.00	\$ 354.00
8	FRONT DOOR POWER WINDOW MOTOR LH	1	\$ 354.00	\$ 354.00
9	FRONT DOOR GLASS REGULATOR	1	\$ 489.00	\$ 489.00
10	FRONT DOOR SPEAKER LH	1	\$ 397.40	\$ 397.40
11	FRONT FRAME WEATHERSTRIP	1	\$ 285.00	\$ 285.00
12	DOOR CENTRE PILLAR OUTER LH	1	\$ 989.00	\$ 989.00
13	DOOR CENTRE PILLAR INNER LH	1	\$ 654.00	\$ 654.00
14	DOOR CENTRE PILLAR INNER TRIM BOARD LH	1	\$ 410.00	\$ 410.00
15	REAR DOOR LH	1	\$ 930.00	\$ 930.00
16	REAR DOOR HINGE LH (UPPER & LOWER)	1 pc	\$ 101.90	\$ 203.80
17	REAR DOOR CHECKER LH	1	\$ 148.80	\$ 148.80
18	REAR DOOR WEATHER STRIP LH (INNER)	1	\$ 185.60	\$ 185.60



19	REAR DOOR WEATHER STRIP LH (FRONT)	1	\$ 168.00	\$ 168.00	at
20	FRONT DOOR UNDER RUBBER LH	1	\$ 110.00	\$ 110.00	at
21	REAR DOOR LOCK CATCH LH	1	\$ 42.70	\$ 42.70	X } su
22	REAR DOOR POWER WINDOW MOTOR LH	1	\$ 385.00	\$ 385.00	X } su
23	REAR DOOR GLASS REGULATOR LH	1	\$ 489.00	\$ 253.30 489.00	? M /
24	REAR DOOR SPEAKER LH	1	\$ 397.40	\$ 397.40	X } su
25	REAR DOOR INNER LOCK LH	1	\$ 289.00	\$ 289.00	X } su
26	REAR DOOR INNER TRIM BOARD LH	1	\$ 635.00	\$ 475.20 635.00	? M /
27	REAR FENDER LH	1	\$ 1,267.00	\$ 900 1,267.00	M /
28	REAR FENDER COWLING LH	1	\$ 105.60	\$ 105.60	at
29	REAR FENDER WHEEL ARCH LH	1	\$ 218.00	\$ 150 218.00	su
30	REAR BUMPER	1	\$ 869.00	\$ 869.00	X } su
31	REAR BUMPER LEFT SIDE	1	\$ 451.00	\$ 235 451.00	at
32	REAR BUMPER SIDE RETAINER	2	\$ 65.90	\$ 131.80	X } su
33	ROCKER PANEL LH	1	\$ 1,469.00	\$ 660.60 1,469.00	M /
34	ROCKER PANEL GARNISH	1	\$ 660.00	\$ 225.40 660.00	su
35	REAR AXLE	1	\$ 1,518.00	\$ 1,518.00	X } su
36	REAR WHEEL BEARING	1	\$ 230.00	\$ 230.00	? M /
37	REAR SHOCK ABSORBER LH	1	\$ 385.70	\$ 385.70	X } su
38	ABS SENSOR	1	\$ 417.00	\$ 417.00	X } su
39	REAR WHEEL HUP LH	1	\$ 270.00	\$ 270.00	X } su

TOTAL PRICE \$ 18,438.40  
 LESS 20% \$ 3,687.68  
**SUB TOTAL PRICE \$ 14,750.72**

**SPECIAL NETT ITEMS**

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT DOOR TRIM BOARD CLIP SET	1	\$ 65.00	\$ 65.00
2	FRONT DOOR SEALANT	1	\$ 60.00	\$ 60.00
3	SIDE SKIRT CLIPS SET	1	\$ 80.00	\$ 80.00
4	CENTER PILLER SEALANT	1	\$ 60.00	\$ 60.00
5	CENTER PILLER INNER TRIM CLIPS	1	\$ 65.00	\$ 65.00
6	REAR BUMPER CLIPS SET	1	\$ 65.00	\$ 65.00
7	REAR DOOR TRIM BOARD CLIP SET	1	\$ 55.00	\$ 55.00
8	REAR FENDER INNER STEP GARNISH SET	1	\$ 500.00	\$ 500.00
9	REAR FENDER SEALANT	1	\$ 60.00	\$ 60.00
10	REAR FENDER COWLING CLIP SET	1	\$ 48.00	\$ 48.00
11	REAR FENDER WHEEL ARCH CLIP SET	1	\$ 60.00	\$ 60.00
12	REAR WHEEL SPORT RIM LH	1	\$ 1,200.00	\$ 1,200.00
13	REAR WHEEL TYRE LH	1	\$ 320.00	\$ 320.00

**TOTAL \$ 2,638.00**

## CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, WELD ,CUT, ADJUST, KNOCK	\$ 2,200.00	1200 <del>1200</del>
2	TO SPRAY PAINT	\$ 2,000.00	900
3	TUFF COAT	\$ 200.00	140
4	CHECKING : WIRING, LIGHTING etc.,	\$ 180.00	30
5	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 250.00	80
6	REMOVE & REFIX AUDIO SPEAKER & CHECKING	\$ 120.00	60
7	TRANSFER FRONT DOOR MECHANISM	\$ 80.00	60
8	TRANSFER REAR DOOR MECHANISM	\$ 80.00	60
9	CONDUCT WATER LEAKAGE TEST	\$ 120.00	30
10	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 450.00	100
11	FOUR WHEEL ALIGNMENT	\$ 120.00	60
12	REMOVE & REFIX ABS SENSOR	\$ 320.00	X nn

TOTAL

\$ 6,120.00

## ESTIMATE REPORT

TOTAL PARTS COST : \$ 17,388.72  
 TOTAL LABOUR COST : \$ 6,120.00  
 TOTAL REPAIR COST : \$ 23,508.72

## APPROVED DETAILS

EXCESS :  
 NO. OF WORKING DAY : 11 days

RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :

SURVEYED BY :

CONTACT NUMBER :

FAX NUMBER :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resurvey after repair

To check parts price

*[Signature]*  
27/1/18




## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD		Ref : CS/UOI18011746/R1rbn2		
3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909		Date : 11-12-2018		
		Code : UOI2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SLE 4307X	
Policy No.		Coverage (\$)	0.00	
Claim No.	L11D54401807	Excess (\$)	0.00	
Assign From	CHAN LI SI	Assign Date	27/06/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA VEZEL 1.5X A	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	RU11114249	Colour	BLACK	
Odometer	35653	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	22/06/2018	Inspection Date	27/06/2018	
Survey held at	1 SOON LEE STREET #04-44/45			
Repairer	SK AUTOMOBILE PTE LTD			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		11 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 4307X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	FRONT DOOR LH	BENT	1,249.00	1,249.00
2	FRONT DOOR HINGE LH @\$120.00	SERVICEABLE	240.00	-
1	FRONT DOOR WEATHER STRIP LH	NECESSARY	225.00	195.20
1	FRONT DOOR OUTER WEATHERSTRIP LH	SERVICEABLE	214.00	-
1	FRONT DOOR UNDER RUBBER LH	NECESSARY	110.00	110.00
1	FRONT DOOR INNER LOCK LH	CRACKED	491.60	200.00
1	FRONT DOOR INNER TRIM BOARD LH	NOT NECESSARY	354.00	-
1	FRONT DOOR POWER WINDOW MOTOR LH	NOT NECESSARY	354.00	-
1	FRONT DOOR GLASS REGULATOR	NOT NECESSARY	489.00	-
1	FRONT DOOR SPEAKER LH	NOT NECESSARY	397.40	-
1	FRONT FRAME WEATHERSTRIP	NOT NECESSARY	285.00	-
1	DOOR CENTRE PILLAR OUTER LH	TO REPAIR SEE LABOUR	989.00	-
1	DOOR CENTRE PILLAR INNER LH	NOT NECESSARY	654.00	-
1	DOOR CENTRE PILLAR INNER TRIM BOARD LH	NOT NECESSARY	410.00	-
1	REAR DOOR LH	BENT	930.00	930.00
2	REAR DOOR HINGE LH (UPPER & LOWER) @\$101.90	LOWER BENT / UPPER SERVICEABLE	203.80	101.90
1	REAR DOOR CHECKER LH	SERVICEABLE	148.80	-
1	REAR DOOR WEATHERSTRIP LH (INNER)	CUT	185.60	185.60
1	REAR DOOR WEATHERSTRIP LH (FRONT)	CUT	168.00	168.00
1	FRONT DOOR UNDER RUBBER LH	CUT	110.00	110.00
1	REAR DOOR LOCK CATCH LH	SERVICEABLE	42.70	-
1	REAR DOOR POWER WINDOW MOTOR LH	SERVICEABLE	385.00	-
1	REAR DOOR GLASS REGULATOR LH	BENT	489.00	253.30
1	REAR DOOR SPEAKER LH	SERVICEABLE	397.40	-
1	REAR DOOR INNER LOCK LH	SERVICEABLE	289.00	-
1	REAR DOOR INNER TRIM BOARD LH	CUT	635.00	479.20
1	REAR FENDER LH	BENT	1,267.00	900.00
1	REAR FENDER COWLING LH	CUT	105.60	105.60
1	REAR FENDER WHEEL ARCH LH	SCRATCHED	218.00	150.00
1	REAR BUMPER	SERVICEABLE	869.00	-
1	REAR BUMPER LEFT SIDE	CUT	451.00	235.00
2	REAR BUMPER SIDE RETAINER @\$65.90	SERVICEABLE	131.80	-

Report Ref No. CS/UOI18011746/R1rnb2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	ROCKER PANEL LH	BENT	1,469.00	660.80
1	ROCKER PANEL GARNISH	SCRATCHED	660.00	225.40
1	REAR AXLE	SERVICEABLE	1,518.00	-
1	REAR WHEEL BEARING	BENT	230.00	230.00
1	REAR SHOCK ABSORBER LH	SERVICEABLE	385.70	-
1	ABS SENSOR	SERVICEABLE	417.00	-
1	REAR WHEEL HUP LH	SERVICEABLE	270.00	-
	LESS 20% DISCOUNT		-3,687.68	-1,297.80
			14,750.72	5,191.20
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET FRONT DOOR TRIM BOARD CLIP (SN)	NECESSARY	65.00	40.00
1	FRONT DOOR SEALANT (SN)	NECESSARY	60.00	40.00
1	SET SIDE SKIRT CLIPS (SN)	NECESSARY	80.00	40.00
1	CENTER PILLER SEALANT (SN)	NOT NECESSARY	60.00	-
1	CENTER PILLER INNER TRIM CLIPS (SN)	NECESSARY	65.00	40.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	65.00	50.00
1	SET REAR DOOR TRIM BOARD CLIP (SN)	NECESSARY	55.00	40.00
1	SET REAR FENDER INNER STEP GARNISH (SN)	NECESSARY	500.00	235.00
1	REAR FENDER SEALANT (SN)	NECESSARY	60.00	40.00
1	SET REAR FENDER COWLING CLIP (SN)	NECESSARY	48.00	30.00
1	SET REAR FENDER WHEEL ARCH CLIP (SN)	NECESSARY	60.00	40.00
1	REAR WHEEL SPORT RIM LH (SN)	SCRATCHED	1,200.00	300.00
1	REAR WHEEL TYRE LH (SN)	SERVICEABLE	320.00	-
			2,638.00	895.00
	<b><u>LABOUR</u></b>			
	TO PANEL BEAT, WELD, CUT, ADJUST, KNOCK. INCLUSIVE OF THE REPAIR OF DOOR CENTRE PILLAR OUTER LH.		2,200.00	1,200.00
	TO SPRAY PAINT.		2,000.00	900.00
	TUFF COAT.		200.00	140.00
	CHCKING; WIRING, LIGHTING, ETC.		180.00	30.00
	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR.		250.00	80.00
	REMOVE & REFIX AUDIO SPEAKER & CHECKING.		120.00	60.00
	TRANSFER FRONT DOOR MECHANISM.		80.00	60.00
	TRANSFER REAR DOOR MECHANISM.		80.00	60.00

Report Ref No. CS/UOI18011746/R1rbn2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	CONDUCT WATER LEAKAGE TEST.		120.00	30.00
	REMOVE AND REFIX REAR UNDERCARRIAGE.		450.00	100.00
	FOUR WHEEL ALIGNMENT.		120.00	60.00
	REMOVE & REFIX ABS SENSOR.	NOT NECESSARY	320.00	-
			6,120.00	2,720.00
GRAND TOTAL			23,508.72	8,806.20

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,000.00
---	--	--	--	----------

Report Ref No. CS/UOI18011746/R1rbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.