

KH BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

AIG Asia Pacific Insurance Pte. Ltd
AIG Building
78 Shenton Way #08-16
Singapore (079120)
ATTN: MOTOR CLAIM DEPARTMENT
Tel : 6419 3000 Fax : 6835 7416

Not Notified
11 Sep @ 2250
Resony After Rain

ACCIDENT REPAIR ON : SKB3302T

Date: 20/06/2018

MODEL : FORD MONDEO

Page : 1 of 2

POLICY NO : GA126811

CHASSIS NO : WF0DXXGBBDBD84677

MANUFACTURING YEAR : 2011

DATE / TIME OF ACCIDENT: 25/06/2018 Time: 2030Hrs ALONG WEST COAST HIGHWAY TWDS CITY

THIRD PARTY VEHICLE NO : SKU6128K

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

<u>Replacement Of Parts</u>		Quantity	Unit Price	Condition	Amount	
S/N			S\$		S\$	
1	Bootlid	1	2363.00		R 2,363.00	X
2	Bootlid Emblem	1	138.00	NN	138.00	+
3	Bootlid Lettering "Mondeo"	1	140.00		140.00	-
4	Bootlid Lettering "Ecoboost"	1			-	
5	Bootlid Finisher	1	328.00		328.00	✓
6	Bootlid Weatherstrip	1	316.00		316.00	X
7	Boot Lid Lamp LH	1	570.00		570.00	X
8	Boot Lid Lamp RH	1	570.00		570.00	X
9	Bootlid Gasket LH	1			-	
10	Bootlid Gasket RH	1			-	
11	Rear Bumper	1	1560.00		1,560.00	✓
12	Rear Bumper Side Retainer LH	1	110.00		110.00	X
13	Rear Bumper Side Retainer RH	1	110.00		110.00	✓
14	Rear Bumper Centre Bracket	1	120.00		120.00	X
15	Rear Bumper Bracket (17B930)	1	55.00		55.00	X
16	Rear Bumper Lower Spoiler	1	550.00		550.00	X
17	Rear Bumper Sensor	4	120.00		480.00	Y
18	Rear Bumper Sensor Ring	4			-	
19	Rear Bumper Reflector LH	1	103.00		103.00	X
20	Rear Bumper Reflector RH	1	103.00		103.00	X
21	Rear Bumper Tow Cover	1	55.00		55.00	✓
22	Rear Bumper Reinforcement	1	1095.00		1,095.00	X
23	Rear Bumper Sponge	1			-	
24	Rear Bumper Lock Assy	1			-	
25	Rear End Panel	1	395.00		395.00	X
26	Rear End Panel Top Garnish	1	170.00		170.00	X
27	Tail Lamp LH	1	703.00		703.00	X
28	Tail Lamp RH	1	703.00		703.00	X
29	Tail Lamp Bracket LH	1			-	
30	Tail Lamp Bracket RH	1			-	
31	Rear Fender LH	1	2420.00		2,420.00	X
32	Rear Fender RH	1	2420.00		2,420.00	X
33	Rear Fender Shield LH	1	395.00		395.00	X
34	Rear Fender Shield RH	1	395.00		395.00	X

35	Exhaust Silencer Tip	1	1250.00	<i>n</i> 1,250.00 <i>X</i>
				Sub-Total: 17,617.00
				Less Discount 20% 3,523.40
				Total Parts: 14,093.60

\$2193.00 - 20% = \$1754.40

Special Nett Items

1	Anti-rust coating	4	80.00	<i>n</i> 320.00 <i>X</i>
2	Rear Bumper Clips	10	3.50	<i>n</i> - 35.00 ✓
3	Rear End Panel Top Garnish Clips	10	6.00	<i>n</i> 60.00 <i>X</i>
4	Rear Fender Shield Clips	20	4.00	<i>n</i> 80.00 <i>X</i>
				Total Parts: 460.00

\$35

Labour Charges For Front and Side Portion

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.		1,500.00	400
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities		1,500.00	600
3	Provide skill labour to disconnect and check electrical wiring		30.00	20
4	Remove and refit rear end panel lining and garnish to facilitate repair		100.00	<i>n</i> <i>X</i>
5	Remove and replace bumper sensors		100.00	600
6	Realign Exhaust Pipe		50.00	60
7	Remove and replace exhaust pipe/system to facilitate repair recommended specification		120.00	<i>n</i> <i>X</i>
	Total Labour:		3,400.00	
				<i>\$1080</i>
			Total Parts & Labour: 17,953.60	
			GST 7% 1,256.75	
			Grand Total: 19,210.35	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Estimate Repair Duration

10 days
4 days

ACCIDENT VEHICLE OF : SKB33021

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: ANTHONY

Survey attended by:

Name : _____
 Company : _____
 Date : _____
 Time : _____
 Contact No: _____
 Email : _____

Part = \$1754.40
SIN = \$35.00
Labour = \$1080.00

Total: \$2869.40 - 20%

= \$2295.52