

22/03/2002

ASS. REC. BY:

REF:

CS3/SMD18011827 / GZ4622

Special Instruction:

Surveyor

ASSIGNMENT (Office)From (Person): Grace Teo of SMD Date/Time: 28062018 11:20am

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: Jsm 1744 Insured: SLX 5943Cat Workshop m/s Asia Motorsport Tel: 6745 3811of 568 Geylang RdPolicy No: _____ Claim No: CMTD1802695 / THE

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 23062018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

29-06-2018 @ morning

H.O.D. Endorsement: _____

Date/Time: 28062018 1:20pm Person Contacted: Mr. Woo Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	<u>Jsm 1744 - X</u>
	<u>SLX 5943C - X</u>
<u>5/7/18</u>	<u>asmanfled</u>

(08/11/13) wef

ASS. REC. BY:

REF: 3MO

ASSIGNMENT

From:

Date: 29/6/2018

Estimated Cost:

ON ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: JSM 1744

at Workshop m/s Asia Motorsport

of 568 Geylang Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Morning

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1 up}

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

JSM1744

Yr Regn: - /

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha 135 LC c.c 135

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

10857

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

70/90-17

R:

80/90-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

MAXXIS

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

4

mm

L/Bal.

mm

D.O.A.

D.O.I.

29-06-18

Survey held at

w/s

2:30pm

Des. of Damages: ☒ Frt / ☒ Rear / ☒ O/S / ☒ N/S / ☒ U/C / Rooftop or

and

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Estimated repair range \$3,000 - \$3,500

RECEIVED 18 JUL 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

100

Transportation:

60

S + RS, SI

Photos

Others

TOTAL

160

Report Format: PR2

Lump Sum / I.B.I.: (\$)

Catherine Chong (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Thursday, 28 June, 2018 11:20 AM
To: Asia Motorsports Solution Pte Ltd; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Choo, Thelma; Henry, Irene James
Subject: CMTD1802695/THE - SUV(LKK)/ ACCIDENT INVOLVING SLX5943C & JSM1744 ON 23 JUNE 2018

Our Reference: CMTD1802695/THE

Your Reference: JSM 1744

Without Prejudice

Date: 28th June 2018

Attention:
M/S ASIA MOTORSPORTS SOLUTION PTE LTD

Dear Sir/ Madam,

ACCIDENT INVOLVING SLX5943C & JSM1744 ON 23.06.18

We refer to your email reply of 27/06/18.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Yours faithfully,

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Asia Motorsports Solution Pte Ltd [mailto:asiamotorsports@hotmail.com]

Sent: Wednesday, June 27, 2018 5:43 PM

To: Teo, Grace; Claims - Motor Survey; claimsreport

Cc: Choo, Thelma; Henry, Irene James

Subject: Re: ACCIDENT INVOLVING JSM 1744 & SLX 5943 C ON 23 JUNE 2018 - OUR COUNTER-PROPOSED LIST OF MOTOR SURVEYORS AS SINGLE JOINT EXPERT

Your Ref:

Our Ref: JSM 1744

27 June 2018

Sompo Insurance Singapore Pte Ltd

50 Raffles Place

#05-01/06

Singapore Land Tower

Singapore 048623

PROPERTY CLAIM

(WITHOUT PREJUDICE

TO: Any Personal Injury
Claims)

Attn: Claims Department

Dear Sir/Mdm,

ACCIDENT INVOLVING JSM 1744 & SLX 5943 C ON **23 JUNE 2018** - OUR COUNTER-PROPOSED LIST OF MOTOR SURVEYORS AS SINGLE JOINT EXPERT

Thank you so much for your reply dated 27 June 2018. However, we regret to inform that we will not be selecting or appointing any motor surveyors from your proposed list.

As required by the new regulations, please find appended below our counter proposed list of motor surveyors for your appointment as Single Joint Expert:

Forensic Consultants Pte Ltd
HJL Auto Appraiser Services
KTO Automobile Assessors
Mc-Coy Appraiser Pte Ltd
YB Lim Appraisal Services
LCW Appraiser Pte Ltd
Treasures Appraisal Services
Pal's Appraiser Pte Ltd
Sincere Appraisal Services
Prudent Adjustors Services

We will appreciate if your kind office can revert by **29 June 2018 (Friday), 1800H** on your selection from the above list, failing which we will appoint a motor surveyor from our list after **29 June 2018 (Friday), 1800H**.

Thank you and we hope to hear from you soonest.

Regards,
Asia Motorsports
6745 3811
6746 5110 (fax)
asiamotorsports@hotmail.com

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Wednesday, June 27, 2018 2:43 PM
To: Asia Motorsports Solution Pte Ltd
Cc: Choo, Thelma; Henry, Irene James
Subject: CMTD1802695/THE - PRI/ ACCIDENT INVOLVING SLX5943C & JSM1744 ON 23 JUNE 2018

Our Reference: CMTD1802695/THE
Your Reference: JSM 1744

Without Prejudice

Date: 27th June 2018

Attention:
M/S ASIA MOTORSPORTS SOLUTION PTE LTD

Dear Sir/ Madam,

ACCIDENT INVOLVING SLX5943C & JSM1744 ON 23.06.18

We refer to your Notice of Accident dated 27/06/2018.

Please be informed that Thelma Choo the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Asia Motorsports Solution Pte Ltd [mailto:asiamotorsports@hotmail.com]

Sent: Wednesday, June 27, 2018 10:52 AM

To: Claims - Motor Survey; claimsreport

Subject: NOTICE OF ACCIDENT: ACCIDENT INVOLVING JSM 1744 & SLX 5943 C ON 23 JUNE 2018

Your Ref:

Our Ref: JSM 1744

27 June 2018

Sompo Insurance Singapore Pte Ltd

50 Raffles Place

#05-01/06

Singapore Land Tower

Singapore 048623

PROPERTY CLAIM

(WITHOUT PREJUDICE

TO: Any Personal Injury

Claims)

Attn: Claims Department

Dear Sir/Mdm,

NOTICE OF ACCIDENT: ACCIDENT INVOLVING JSM 1744 & SLX 5943 C ON 23 JUNE 2018

We are instructed to notify you of a road traffic accident on **23 June 2018** at about **3.30 pm** at **Woodlands Ave 12 towards BKE** involving our client's vehicle registration number **JSM 1744** and vehicle registration number **SLX 5943 C** driven by your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client/we proceed to repair the damaged vehicle, please let us know within **2 working days** of your receipt of this notice and your proposed list of 10 recommended motor surveyors for our appointment.

Kindly note that if we do not hear from you by **29 June 2018 (Friday), 1100H**, we will be forwarding **our proposed list of 10 motor surveyors** for your appointment, in accordance to the new regulations.

Thank you and we hope to hear from you soonest.

Regards,
Asia Motorsports Solution Pte Ltd
6745 3811
6746 5110 (fax)
asiamotorsports@hotmail.com



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS3/SMO18011827/Gz4be2 Date: 19-07-2018 Code: SMO	
				
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SLX 5943C	Veh. Inspected	JSM 1744	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1802695/THE	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	28/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA 135LC	c.c	135	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour	BLACK	
Odometer	10857 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	70/90-17	MAXXIS	4 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	80/90-17	MAXXIS	4 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND FRONT PORTION.				
5. General Information				
Accident Date	23/06/2018	Inspect Date / Time	29/06/2018 (02:30 PM)	
Survey held at	ASIA MOTORSPORTS SOLUTION PTE LTD 568 GEYLANG ROAD SINGAPORE 389514			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$3,800				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	

Report Ref No. CS3/SMO18011827/Gz4be2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.