22/03/2002 ASS. REC. BY:			RE	F:	(3)	FCL180	11959	1/	Usbr	12  Sp	ecial Instruc	stion:		
Furvajor : '					ASS	IGNMI	ENT (	Offi	ce)			2/75/15/16/	2000	
From (Person):	(Ws)	Theus	Jun	)	of		FC				Date/Tim	ne: 03092	810	541pm
Estimated Cost;							Bill							,
To Inspect Veh						SUSC.	CS			Insured	l: 5	SHC 997	<del>M</del>	
at Workshop m						stech				Tel	:6	74b 5405	0	
of	-		31k	1	Kaki	Bukit	AND	6	+01					
Policy No:							Cl	aim l	Vo:		D1800	5158 M7	SH	
Sum Insured:								Exce	SSS					
Make of Veh: (Client's Record)											D.O.A.	3006	2018	
CA / REV /	REP. / I	EV 2	HR	s 1]	120						H.O.D	Endorsement		
Date/Time:		ACIIPAL TO		P	erson C	ontacted;					Vehicle	IN OUT		
Date/Time	Action/In	structi	on (		1)	Estinut	ę.							
	Shp 3	AU5C	-	0	3 /701	13114	587/	Hlu	1634	2		14	A: 0	811615
	1					11006			72 Feb.			1	OF. 3	11801
04/07/18	@4	:37	p.n	2.	re						e Gor	n ngo	me-	10
	Luren	c v	:4	er	al.						-			
	1													

(08H1/H3) Wef . REF:	Fc1/
· · · · · A	ASSIGNMENT
From. Date	Veh No: SGP 3905 CYr Regn: (4/12 06
Estimated Cost:	Type: M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD PWS/TP RES/OD RES/EVA/INV/MV	Truck/Trailer of A
To Inspect Vehicle No. Say 39050	Make: mit colt 0.0 1499
at Workshop m/s	Colour W-& A/C: Insured / Std / NI / NA
of	Sp.Reading 354760 T/Radio: Insured / Std / NI / NA
Insured: SHC 997M	Eng/No:
Policy No.	CINO: 0 JMYL 7223W62001075
Claims No.	Gen. Cond Good / Fair / Hoor / Burnt
Sum Insured: Excess:	Steering: I Jammed / Leaked / Burnt or
(Client's Record)	Brake: Ingree / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil /S/Rim / STD A/Rim or
(Della, Casalisa)	Tyre Size: F: 195/55 25
(Policy Condition)  Remark: The veh had commenced its  N/S  O	R:
repair at the time of inspection.	BS / DUN / EXNOVA / GY / FS / LIZA / MIC OHTSU / PIR / SUMI / TOYO / YOKO or
Ball or Market Value: 2300	2 11
IDA Accident Rport Consistent? : Yes or No	R/Bal A P/Dat 6
GN / PR Seet Consistent? : Yes or No	L/Bal / Dec 1/Bal
Est Repairs: days Res.: Yes or No	D.O.A. 20/1/1/ D.O.I. 2/7/10
Lum Sum: Zo % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS COL IS INVITA	Des. of Damages: Frt. / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / C	0
Date: Person Contacted:  Date / Time   Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time   Action / Instruction	1669 and (831
-1-1	301 1011 3011
NITIE CONFINA 1/5 658	669 net 583/
(\$9,499 Red - 62%)	
MU - \$ 23,500/- RECEN	VED 2 3 JUL 2018
Net - \$5.851/-	
Date/Time, File Pass to? Prof. Panort	Dave Of Panalss 2
23/04/18 : Final Report	Days Of Repair: 8 5XIS: 75  Resurvey No. of Trip: 2 Survey Fee: 170+75
Dats/Time/ File Return to?	Resurvey No. of Trip: 2 Survey Fee: 170+75
2) Add F	Table   Tabl
	Interview (\$ ) Photos (\$\) 105
Report Format :	: Tech. Invs (\$ ) Others 2/12/18
Lump Sum / I.B.I: (\$ 5,800.00 L/s)	:Weekend (\$
	TOTAL 500



MS First Capital Insurance Limited Go Reg. No. 195000106C GST Reg. No. M2-0001676-9 6 Raffles Quay #21-00 Singapore 048580 Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Motor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877 Tel: (65) 6507 3848 Fax: (65) 6507 3849 www.msfirstcapital.com.se

#### MOTOR SURVEY ASSIGNMENT

Date

03-07-2018

Our Ref No. D18005158MFSH

**Accident Date** 

30-06-2018

Claim Type. Third Party

Insured Vehicle

SHC0997M

Third Party Vehicle. SGP3905C

Survey Location

1 KAKI BUKIT AVENUE 6 #01-46/48/50AUTOBAY

Contact Person.

NANCY LAM

Contact No.

67465405/0

Fax No. 67458520

Survey Type

WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

NA

Fax No. 68416315

Contact Number.

NA

#### FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

FASTECH AUTO PTE LTD

Attention, NIL

Cc: TP Solicitor

NA

TP Solicitor Fax No. NA

Officer Incharge

LURENE

#### IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

# > Back to OneMotoring

**Enquire PARF/COE Rebate for Registered Vehicle** 

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0534H
Vehicle Details	
Vehicle No.:	SGP3905C
Vehicle to be Exported:	No
ntended De-registration Date:	02 Jul 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	COLTPLUSSPRT
Primary Colour:	White
Manufacturing Year:	2006
Engine No.:	4A910031219
Chassis No.:	JMYLTZ23W6Z001075
Maximum Power Output:	77.0 kW (103 bhp)
Open Market Value:	\$15,591.00
Original Registration Date:	14 Dec 2006
First Registration Date:	14 Dec 2006
Transfer Count:	3
Actual ARF Paid:	\$17,151.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	±2
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	13 Dec 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$25,636.00
COE Rebate Amount:	\$17,669.00
Total Rebate Amount: Message	\$17,669.00

The information contained herein is correct as at 02 Jul 2018

applicable), whichever is earlier.

#### SGCARMART.COM

Login Sign up

New Cars

Used Cars 1

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

CHEAPEST CAR

NSURANCE RENEWAL

Advertiser Loom





**GET A CHEAPER QUOTE NOW!** 

Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD!

2017 Mercedes E200d, Price Negotiable For Fast Deal!



Rare Diesel Unit, Very Fuel Efficient, High Torque, Workshop Warranty Until 2022 Direct Owner StarAd



Browse by Category V

Mitsubishi Colt

Sort by Date Posted

✓ 20 results/page ✓

6 vehicles

Post an Ad

Make Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Submit I

Status

Search Selection

Mitsubishi Colt

> 10 year(s)

Advanced Search 162

Available

Available

Mitsubishi Colt Plus 1.5A (COE till 08/2021)

\$22,800

\$7,200 /vr

13-Sep-2006

1,499 cc

Hatchback

1 Owner, Well Maintained Condition, Call Now For An Appointment, Drive Away With Minimum Down Payment, Flexible In House Loan Packages Available.

Posted: 30-Jun-2018 Tags: 2006 Mitsubishi Colt, Mitsubishi Colt, Mitsubishi, Colt, Used Mitsubishi



Mitsubishi Colt Version-R Turbo (COE till 08/2022)

\$27,800

\$6,720 /yr

21-Aug-2007

1,468 cc 90,158 km Sports

Available

New Arrival Sporty Red Mitsubishi Colt Version-R Turbo! Super Low Mileage, See To Believe! Well Maintain By Careful Owner And Accident Free. Expensive Parts And Accessories, Call Us Now.

Sng Auto Trading

Posted: 30-Jun-2018 Tags: 2007 Mitsubishi Colt, Mitsubishi Colt, Mitsubishi, Colt, Used Mitsubishi



Mitsubishi Colt Plus 1.5A (New 5-yr COE)

\$30,800

\$6,160 /yr

11-Jun-2008

1,499 cc

Hatchback

Sports

Available

Available

\$0 Drive Away And \$0 Down Payment Available, No Worries About Down Payment, Bank And In House Loan Available, Low Interest Rate, Low Down

Posted: 30-Jun-2018 Tags: 2008 Mitsubishi Colt, Mitsubishi Colt, Mitsubishi, Colt, Used Mitsubishi



Mitsubishi Colt Version-R. Turbo (COE till 05/2022)

\$34,900

\$9,050 /yr

11-May-2007

1,468 cc

135,000 km

Look No Further, Low Mileage That Is Serviced By Agent. Direct Owner's White Sports Car, May 2007 Mitsubishi Colt Turbo Version-R With Black

Tags: 2007 Mitsubishi Colt, Mitsubishi Colt, Mitsubishi, Colt, Used Mitsubishi

Car Buying

Car Selling

Seats. Selling Due To Upgrading To New Car. Genuine Mileage...

Payment Or No Down Payment Available, High Trade In, Fast And ...

Car Ownership

Buying a pre-owned car, but Unsure of its Condition?

Car Aftermarket

On The Move

Lifestyle

Get, STA Car Evaluation



Mitsubishi Colt Ralliart Version-R 1.5M (New 5-yr COE)

\$36,800

\$7,360 /vr

26-Jun-2008

1.468 cc

Sports

Available

Up To 90% Loan Available! Grab This Rare Colt Version R Manual Model Now! Well Taken Care By Previous Owner, Engine Gasket Seal And Air Cold Cooling Coil Just Replace Months Ago Only, Smooth, Powerful...

Posted: 01-Jun-2018 Tags: 2008 Mitsubishi Colt. Mitsubishi Colt. Mitsubishi, Colt. Used Mitsubishi



Mitsubishi Colt Version-R Turbo (COE till 12/2027)

\$56,800

\$5,980 /yr

29-Feb-2008

1,468 cc

110,800 km

Sports

Available

Rare 2 Owner Only! Completely Stock And Beautiful Condition With Mileage! New Nardo Grey Paint Job! Major Servicing And Change Of Timing Belt Done! Well Taken Care, Regular Serviced And Grooming Done ...

Posted: 19-May-2018 Tags: 2008 Mitsubishi Colt, Mitsubishi Colt, Mitsubishi, Colt, Used Mitsubishi Compare

### Shirley Hiew (LKK Auto)

From: Shirley

Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>

Sent: Wednesday, 4 July 2018 5:37 PM

To: LURENEJAW@MSFIRSTCAPITAL.COM.SG; 'Claim Workflow System'

Cc: ASSIGNMENTS@LKKAUTO.COM; sur@lkkauto.com; 'Catherine Chong (LKK Auto)'

Subject: RE: SURVEY ASSESSMENT - D18005158MFSH/1

Dear Lurene,

Please be informed that we have inspected the vehicle SGP 3905C on 02/07/2018.

We are pending for estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Sur@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]

Sent: Tuesday, 3 July 2018 5:47 PM

To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; ASSIGNMENTS@LKKAUTO.COM

Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; sur@lkkauto.com

Subject: RE: SURVEY ASSESSMENT - D18005158MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [mailto:cwsmotorclaims@msfirstcapital.com.sg]

Sent: Tuesday, 3 July, 2018 5:41 PM To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18005158MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team Claim Workflow System Motor Claims Department MS First Capital Insurance Limited

Tel: 6507 3848 Fax: 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

FASTECH AUTO PTE LTD 1 Kaki Bukit Ave 6 #01-46,48,50 Autobay SINGAPORE 417883

#### VEHICLE NO:SGP 3905C

#### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prajudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

2/1/18

QTY	PARTICULAR (NETT ITEM)	AMOUNT
1 PCS	TAILGATE ALS. 00	Bodly >> \$981.00
1 PCS	TAILGATE REAR LOGO	nu \$35.00
1 PCS	TAILGATE 'COLT' EMBLEM	see \$38.00/
1 PCS	TAILGATE 'PLUS' EMBLEM	ru \$36.00
1 PCS	TAILGATE 'C&C' LOGO	Ju \$38.00
1 PCS	TAILGATE INNER LOCK	m/Jn \$166.00
1 PCS	TAILGATE INNER TRIM BOARD	√ ↑ \$245.00 X
1 SET	TAILGATE INNER TRIM BOARD CLIPS	Au \$45.00
1 PCS	TAILGATE WEATHERSTRIP	Tu, \$191.00
2 PCS	TAILGATE REFLECTORS @\$265.00	11 \$530.00 X
1 PCS	REAR WINDSCREEN MOULDING	M \$110.00
1 PCS	REAR BUMPER 625.	D/5 \$681.00
2 PCS	REAR BUMPER REFLECTORS @\$60.00 45x2-90	3no \$120.00
2 PCS	REAR BUMPER SIDE RETAINERS @\$65.00 39x2-7f	Zel \$130.00 —
1 SET	REAR BUMPER CLIPS	nu \$45.00
1 PCS	REAR BUMPER BEAM	\$112.00
1 PCS	REAR END PANEL OUTER 481.00	3. dry is \$605.00
1 PCS	REAR END PANEL INNER	NS \$499.00 X
1 PCS	REAR END PANEL TOP GARNISH	4m \$105.00
2 PCS	TAILLAMPS@\$485.00 385x2= 770	cm \$970.00
2 PCS	TAILLAMP HOUSING PANELS @\$188.00	\$376.00
1 PCS	REAR FLOOR PANEL SYS.	crupled/ Luc \$911.00
1 PCS	REAR FLOOR PANEL TOP BOARD Tray 425	1 Viv ( \$460.00
2 PCS	REAR FENDERS @\$899.00	↑ \$1,798.00
2 PCS	REAR FENDER INNER TRIMS @\$285.00	MS7010 \$570.00 12C
1 PCS	REAR EXHAUST	1 \$442.00 X
2 PCS	REAR EXHAUST MOUNTINGS @\$35.00	, ハヘ <sub>\$70.00</sub> ×
		\$10,309.00
	S.NETT	- 1
1 SET	REAR BUMPER REVERSE SENSOR	shotal \$280.00200
1 PCS	REAR LICENCE PLATE W/HOLDER	Bent \$50.00 40
1 PCS	REAR WINDSCREEN SEALANT	\$50.00 40
1 PCS	REAR END PANEL SEALANT	ru \$50.00 V

1-4814.1

LABOUR CHARGES:		3
TO CHECK WIRING		\$80.00 30
TO DISMENTLE & REPLACING REVERSE SENSOR		\$80.00 50
TO DISMENTLE & REFIX REAR WINDSCREEN		\$150.00 / 20
TO DISMENTLE & REFIX SEAT, CUSHION UPHOLSTREY		\$120.00 &
TO DISMENTLE & REFIX PETROL TANK	11	\$100.00 🗶
TO DISMENTLE & REFIX REAR EXHAUST		\$100.00 60
TO MOUNT VEHICLE ON CAR O-LINER	17	\$380.00 ⊀
TO TRANFER TAILGATE MECHANISM		\$100.00 6 O
TO SPRAY RUST PROOFING		\$150.00 10 0
LABOUR FOR PANEL BEATING, CUT, WELD STRAIGHTENED	:	\$1,800.00 (200
& REPLACING PARTS		
TO PUTTY & SPRAY PAINTING	1	\$1,500.00 ( 100

TOTAL \$15,299.00

3130



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

FIRS	T CAPITAL INSUF	RANCE LTD	Ref : CS/FCI180119	59/Usbn2
36 R #16-0	OBINSON ROAD 01 CITY HOUSESI	NGAPORE 068877	Date: 24-07-2018  Code: FCI2	
1.		Policy Particular	s :- THIRD PARTY CLA	IM
	Insured Veh.	SHC 997M	Veh. Inspected	SGP 3905C
	Policy No.		Coverage (\$)	0.00
	Claim No.	D18005158MFSH	Excess (\$)	0.00
	Assign From	LURENE	Assign Date	03/07/2018
2.		Vehicle Par	ticulars & Condition	
	Make & Model	MITSUBISHI COLT (A)	c.c	1499
	Engine No.	HIDDEN	Year of Reg.	2006
	Chassis No.	JMYLTZ23W6Z001075	Colour	WHITE
	Odometer	354750	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3.		Cond	litions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	195/55 R15	MICHELIN	6 mm
	L/H Front Tyre	195/55 R15	MICHELIN	6 mm
	R/H Rear Tyre	195/55 R15	MICHELIN	6 mm
	L/H Rear Tyre	195/55 R15	MICHELIN	6 mm
4.		Descrip	otion of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE	REAR PORTION.	
	DAMAGES SEE D	ETAILS.		
5.			ral Information	Carried Charles
	Accident Date	30/06/2018	Inspection Date	03/07/2018
	Survey held at	FASTECH AUTO PTE LTD		
		1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a.			Remarks	
	B)THE INSPECTI	NSISTENT TO ACCIDENT REP ON WAS CONDUCTED ON A"\ CE TO YOUR INSTRUCTIONS	NITHOUT PREJUDICE" BA	SIS. ISED REPAIRS.
			ite Days of Repair	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGP 3905C

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS		710 191113	3030
1	TAILGATE	BADLY DENTED	981.00	825.00
1	TAILGATE REAR LOGO	NECESSARY	35.00	35.00
1	TAILGATE "COLT" EMBLEM	NECESSARY	38.00	38.00
1	TAILGATE "PLUS" EMBLEM	NECESSARY	36.00	36.00
1	TAILGATE "C&C" LOGO	NECESSARY	38.00	38.00
	TAILGATE INNER LOCK	TWISTED / JAMMED	166.00	166.00
	TAILGATE INNER TRIM BOARD	NOT NECESSARY	245.00	
1	SET TAILGATE INNER TRIM BOARD CLIPS	NECESSARY	45.00	45.00
1	TAILGATE WEATHERSTRIP	TWISTED	191.00	191.00
2	TAILGATE REFLECTORS @\$265.00	NOT NECESSARY	530.00	8
1	REAR WINDSCREEN MOULDING	NECESSARY	110.00	110.00
1	REAR BUMPER	DISTORTED	681.00	625.00
2	REAR BUMPER REFLECTORS @\$60.00	BROKEN	120.00	90.00
	REAR BUMPER SIDE RETAINERS @\$65.00	BENT	130.00	78.00
1	SET REAR BUMPER CLIPS	NECESSARY	45.00	45.00
	REAR BUMPER BEAM	DISTORTED	112.00	112.00
1	REAR END PANEL OUTER	BADLY DENTED	605.00	485.00
1	REAR END PANEL INNER	NO SUCH PARTS	499.00	10
1	REAR END PANEL TOP GARNISH	TWISTED	105.00	105.00
2	TAILLAMPS @\$485.00	CRACKED	970.00	770.00
2	TAILLAMP HOUSING PANELS @\$188.00	TO REPAIR SEE LABOUR	376.00	83
1	REAR FLOOR PANEL	CRUMPLED / BUCKLED	911.00	845.00
1	REAR FLOOR PANEL TOP TRAY	TWISTED	460.00	425.00
2	REAR FENDERS @\$899.00	TO REPAIR SEE LABOUR	1,798.00	
2	REAR FENDER INNER TRIMS @\$285.00	N/S TORN	570.00	285.00
1	REAR EXHAUST	TO REPAIR SEE LABOUR	442.00	
2	REAR EXHAUST MOUNTINGS @\$35.00	NOT NECESSARY	70.00	1

Report Ref No. CS/FCI18011959/Usbn2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LESS 10% DISCOUNT		1,7	-534.90
			10,309.00	4,814.10
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
	REAR LICENCE PLATE W/HOLDER (SN)	BENT	50.00	40.00
	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
	The territorian and the second of the second		430.00	330.00
	LABOUR			
	TO CHECK WIRING.		80.00	30.00
	TO DISMENTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO DISMENTLE & REFIX REAR WINDSCREEN.	1	150.00	120.00
	TO DISMENTLE & REFIX SEAT, CUSHION UPHOLSTERY.		120.00	80.00
	TO DISMENTLE & REFIX PETROL TANK.	NOT NECESSARY	100.00	3
	TO DISMENTLE & REFIX REAR EXHAUST.		100.00	60.00
	TO MOUNT VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	
	TO TRANFER TAILGATE MECHANISM.		100.00	60.0
	TO SPRAY RUST PROOFING.		150.00	100.0
	LABOUR FOR PANEL BEATING, CUT, WELD STRAIGHTENED & REPLACING PARTS. INCLUSIVE OF THE REPAIR OF TAILLAMP HOUSING PANELS, REAR FENDERS AND REAR EXHAUST.		1,800.00	0000000
	TO PUTTY & SPRAY PAINTING.		1,500.00	1,100.0
			4,560.00	2,800.0
	GRAND TOTAL		15,299.00	7,944.1

RECOMMENDED COST OF LUMP SUM REPAIRS	5,800.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS/FCI18011959/Usbn2

MARKET VALUE: \$23,500.00 (EST)-LTA REIMBURSEMENT VALUE: \$17,669.00=NETT VALUE: \$5,831.00

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.