

SMRT Accident Vehicle Repair Estimates

G 117

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF419A
Ref. No : TAX/06/18/2120
Reg. Date : 28/06/2013
Vehicle Type : TAXI
Make : LONDON
Model : TX4
Name of Driver : TAY THIAM CHONG
BENJAMIN(ZHENG
TIANCONG)
Type of Accident : OTHERS
Date / Time of Accident : 26/06/2018 09:15:00 AM
Accident Reported Date / Time : 26/06/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024096714
Special Instruction to ARC, if any :
SJV4048C
Prepared Date : 26/06/2018 11:15:50 AM



Sathya Sai
29/6/2018

3 days

- Lump Sum Repair
- Question mark item photo
- Photo after paint.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : LJU97C7B3DS000224

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,014.00	0.00
Total Spray Painting Charges :	1,692.00	0.00
Total Material Charges :	3,770.43	3,770.43
Other Charges :	340.00	0.00
TOTAL :	6,816.43	0.00
Lum Sum Total :	6,800.00	0.00
No. of Repair Days :	6.00	0.00 3 days
Prepared / Adjusted By :		
Arc / Surveyor Sing Off Date :	27/06/2018 09:12:13 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 27/06/2018 09:11:21 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount : 0.00	Prepared Date : 6/27/2018 9:13:30 AM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	1,014.00	0.00 600
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY BUMPER BEAM	180.00	0.00 ?
TO RESPRAY FRONT PANEL	378.00	0.00 ?
TO RESPRAY FRONT FENDER RH	378.00	0.00 200
TO REPSRAY FRONT HOOD	378.00	0.00 200
Total Spray Painting & Panel Beating	1,692.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 50
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 50
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	340.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
JHM667			FRONT BUMPER ASSY ✓CRK	1	951.74	10.00	856.57	Replace	Replace	No
7000596			FRONT BUMPER FOAM ?	1	306.52	10.00	275.87	Replace	Replace	No
11880004 41			FRONT BUMPER CROSS MEMBER ASSY ?	1	218.16	10.00	196.34	Replace	Replace	No
11880004 33			PLATE-LICENSE BLANK ?	1	12.62	10.00	11.36	Replace	Replace	No
	FRONT		FRONT NUMBER PLATE ✓BR	1	35.00	0.00	35.00	Replace	Replace	No
			NUMBER PLATE FRAME ✓CRK	1	12.00	0.00	12.00	Replace	Replace	No
AKG2500			BONNET ASSY R	1	2,345.04	10.00	2,110.54	Replace	Replace	No
11880009 46			LATCH ASSEMBLY-BONNE X	1	135.27	10.00	121.74	Replace	Replace	No
11820001 44			PANEL ASSEMBLY FRONT ?	1	229.84	10.00	206.86	Replace	Replace	No
309017			GRILLE-SURND-CHROME X	1	251.77	10.00	226.59	Replace	Replace	No
11820001 50			FENDER ASSEMBLY-FRON RH R	1	591.36	10.00	532.22	Replace	Replace	No
11880004 31			LINER-FRONT WHEELARC ?	1	142.17	10.00	127.95	Replace	Replace	No
TOTAL MATERIALS								4,713.04	4,713.04	
TOTAL MATERIALS(Discounted)							3,770.43	3,770.43		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									