

ESTEEM PERFORMANCE PTE LTD

BLK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-259 SINGAPORE 569536

Tel:64841221 Fax:64847829

Spare Parts

Vehicle No. : SLQ 4036 P
 Make & Model : TOYOTA ALTIS
 Chassis No : MR053REH104561718

Submit By : CARMEN LIM
 Year Manufacture : 2016
 Engine No. : _____
Cost / List

Supplementary

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	RH FRONT LOWER ARM BALL JOINT <i>RT</i>	1	\$175.60		✓
2	ANTI ROLL BAR <i>RT</i>	1	\$379.40		✓
3	ANTI ROLL BAR BRACKET RH <i>RT</i>	1	\$51.70	missing	✓
4	AUTO OIL <i>no oil</i>	4 LTR	\$105.70		X
5	RH FRONT FENDER INNER GARNISH <i>CM</i>	1	\$95.70		✓
6		1			
7		1			
8		1			
9		1			
10		1			
11		1			
12		1			
13		1			
14		1			
15		1			
16		1			
17		1			
18		1			
19		1			
20		4			
21		1			
22		1			
23		1			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

208-10