



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :	Customer :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :

Quotation No. : QO18/06-1301	Quotation Date : 28/06/2018	Terms : 30 DAYS
Vehicle No. : SLL7112J	Chassis No. : JM6BN22A8H0145555	Third Party Insurer :
Model : MAZDA 3		Date of Accident : 26/06/2018
Remarks : TP INSURER: AIG, INSURED'S VEHICLE NO: SKH3315A, DOA: 26.06.2018		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
1	BOOTLID	1	958.0000	958.00
2	BOOTLID CENTER LOGO BADGE	1	75.0000	75.00
3	BOOTLID MAZDA 3 BADGE	1	54.0000	54.00
4	BOOTLID SKYACTIV BADGE	1	64.0000	64.00
5	BOOTLID PUSH BUTTON LOCK SENSOR	1	458.0000	458.00
6	BOOTLID LOCK	1	153.0000	153.00
7	BOOTLID LOCK STRIKER BOTTOM	1	35.0000	35.00
8	BOOTLID WEATHERSTRIP	1	130.0000	130.00
9	BOOTLID REFLECTOR	2	265.0000	530.00
10	BOOTLID INNER TRIM COVER	1	121.0000	121.00
11	BOOTLID INNER TRIM COVER CLIPS	4	5.0000	20.00
12	BOOTLID HINGE	2	148.0000	296.00
13	BOOTLID HINGE COVER	2	34.0000	68.00
14	BOOTLID HINGE COVER CLIPS	6	5.0000	30.00
15	BOOTLID RUBBER STOPPER	2	16.0000	32.00
16	REAR END PANEL	1	506.0000	506.00
17	REAR END PANEL INNER TRIM	1	86.0000	86.00
18	REAR END PANEL INNER TRIM CLIPS	4	5.0000	20.00
19	REAR END PANEL LOWER EXTENSION PANEL	1	112.0000	112.00
20	REAR BUMPER	1	1,075.0000	1,075.00
21	REAR BUMPER REINFORCEMENT	1	538.0000	538.00
22	REAR BUMPER TOW COVER	1	17.0000	17.00
23	REAR BUMPER SIDE RETAINER	1	37.0000	37.00

C/F 0.00



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :	Customer :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :

Quotation No. : QO18/06-1301	Quotation Date : 28/06/2018	Terms : 30 DAYS
Vehicle No. : SLL7112J	Chassis No. : JM6BN22A8H0145555	Third Party Insurer :
Model : MAZDA 3	Date of Accident : 26/06/2018	
Remarks : TP INSURER: AIG, INSURED'S VEHICLE NO: SKH3315A, DOA: 26.06.2018		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
24	REAR BUMPER SIDE RETAINER HOLDER	2	74.0000 X	148.00
25	REAR BUMPER SIDE RETAINER HOLDER RIVETS	6	6.0000 X	36.00
26	REAR BUMPER CLIPS	8	5.0000 <i>mu</i> ✓	40.00
27	REAR BUMPER REFLECTOR	<i>2 IPC - RH</i>	51.0000 ?	102.00
28	REAR BUMPER SCREW SPACER	2	8.0000 ?	16.00
29	REAR BUMPER SPACER SCREW	2	8.0000 ?	16.00
30	REAR LAMP	2	509.0000 ?	1,018.00
31	REAR LAMP PANEL	2	377.8000 <i>Repair</i>	755.60
32	REAR LAMP CLIP HOLDER	6	10.0000 ?	60.00
33	REAR WINDSCREEN GLASS WEATHERSTRIP	1	68.0000 X	68.00
34	REAR WINDSCREEN GLASS MOULDING	1	45.0000 X	45.00
35	REAR LICENCE PLATE LAMP	2	72.0000 X	144.00
36	O/S REAR FENDER	1	1,175.0000 <i>*Repair</i>	1,175.00
37	REAR FENDER INNER PANEL	1	635.0000 X	635.00
38	REAR FENDER INNER COWLING	1	146.0000 X	146.00
39	REAR FENDER INNER COWLING CLIPS	6	5.0000 X	30.00
40	O/S REAR FENDER AIR VENT	1	72.0000 X	72.00
41	O/S REAR FENDER LOWER EXTENSION PANEL	1	155.8000 X	155.80
42	O/S REAR FENDER INNER TRIM	1	236.0000 X	236.00
43	REAR FENDER INNER TRIM CLIPS	6	5.0000 X	30.00
44	LESS 20% ITEM (1-43)	1	-2,068.6800	-2,068.68
45	REAR WINDSCREEN SEALANT	1	180.0000 X	180.00

C/F 0.00



PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :	Customer :
PEGASUS ENGINEERING & TRADING PTE LTD 74 KIAN TECK ROAD SINGAPORE 628800 Officer in Charge : ALVIN LOW WAI LUN Tel : Email :	GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax No. :

Quotation No. : QO18/06-1301	Quotation Date : 28/06/2018	Terms : 30 DAYS
Vehicle No. : SLL7112J	Chassis No. : JM6BN22A8H0145555	Third Party Insurer :
Model : MAZDA 3		Date of Accident : 26/06/2018
Remarks : TP INSURER: AIG, INSURED'S VEHICLE NO: SKH3315A, DOA: 26.06.2018		

ITEM	DESCRIPTION	Qty	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
46	REAR LICENCE PLATE	1	80.0000 X	80.00
47	REAR BUMPER PARKING SENSOR	1	400.0000 200.00	400.00
48	TO CHECK ELECTRICAL LIGHTING CONCERNED.	1	60.0000 30	60.00
49	TO RUST-PROOFING OF THE AFFECTED AREAS.	1	180.0000 80	180.00
50	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.	1	150.0000 20.60	150.00
51	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	1	100.0000 X	100.00
52	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	1	120.0000 60	120.00
53	TO REINSTALL OF REAR BUMPER PARKING SENSOR.	1	120.0000 60	120.00
54	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME.	1	1,600.0000 600	1,600.00
55	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	1,400.0000 800	1,400.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul

Hp 90010068

6 days

L/S

28/06/18 @ 1610

Resurvey after repair

Sub Total	12,664.72
GST(7.00%)	886.53
Total (SGD)	13,551.25

Please conduct the survey at
Pegasus Engineering @ 74 Kian Teck Road Singapore 628800