

B9.

CC 61 CTI 180

12023 / Upa3n2

LKK:

IDAC:

Surveyor:

MARUW

DOI:

31/1/18

Date:

31/1/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJA 17914

Name of Insured:

TAN 241 TAN, COIN

Insured Tel No.:

HP:

93836978

Excess Sec II :SS

D.O.A.:

28/6/2018

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

SNM1800326002

Policy No.:

0MPCSN3089661700

Make / Model:

7-NOS

Place of Accident:

PTE (TUAS)

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SKD 158 C



INSRS:

WSP:

Tel:

Liability:

RMKS:

Fastech



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

6/1/18

CH1

SKD 158 C - X

SJA 17914 - KA/C71/8211912/24 : OIA 28/6/2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

If NO or B 28, Ass. Lia:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

9/1/18

784W-U

PRELIMINARY ADVICE Date/Time:

31/1/18

Sent By:

CH

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

3/6/19

Confirm with:

Torun

Email

Call

Final Liability:

%

100

(

Agreed / Assessed)

BOLA S/N No.

28C5CC.014M

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

18190.00

Loss of Rental (LOR):

S\$

1260.00

(

9 days)

> \$140.00

Loss of Use (LOU):

S\$

-

(\$

x

days)

Loss of Income (LOI):

S\$

-

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

7.45

Medical:

S\$

-

Disbursement:

S\$

-

Legal Cost

S\$

-

Total:

S\$

19457.45

Global Sum S\$:

19450.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

19450.00

Name 1:

Fastech Auto Pte Ltd

Payee 2: (Strike if N.A.)

S\$

-

Name 2:

Payee 3: (Strike if N.A.)

S\$

-

Name 3:

(06/11/13) wef

ASS. REC. BY: M. Davis

REF:

C71/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKD158Cat Workshop m/s PL.

of _____

Insured: SJA17914

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: £8,500

IBAC Accident Report: _____ Consistent?: Yes or No

GA / PR Seen: 2 Consistent?: Yes or NoEst. Repairs: 13 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or NoCA / REV / REP. / 24 HRS 3.1.1.2014

Date: _____ Person Contacted: _____

Date / Time Action / Instruction

L7A 41075, low mileage, good condition
have 6.14 oshy etc. 2.4.15 7mls rep 15,500 net 17,425

27/8/18 confirmed L/S \$17,000 with Alan.

(Ref \$ 44125.25/726)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I.: (\$ _____)

Veh No: SKD158C Yr Regn: 31/1 11Type: C / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: BMW 320i cc 1995Colour: white A/O: Insured / Std / NI / NASp. Reading: £3800 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAKD52090E 492244Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/35ZR18R: 265/30ZR19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 24/6/18 D.O.I. 3/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & fl.

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I.: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS: \$ _____

Photos

Others

TOTAL



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find out more



Post an Advertisement

Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Honda Stream 1.8A RSZ



\$2800 Downpayment Monthly
From \$738 Onwards. Lowest
3.68%P.A@GV Cars Financing
GV Credit Pte Ltd StarAd





VIEW OUR PROFILE

Browse by Category

▼

Sort by Date Posted

▼

20 results/page

▼

2 vehicles

bmw 320 coupe

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	bmw 320 coupe		Any	Any	2011	Any	Any	Any	Available
	BMW 3 Series 320i Coupe Sunroof		\$51,800	\$12,110 /yr	03-May-2011	1,995 cc	103,000 km	Sports	Available
Graded B by 									
Interest Rate From 1.99% Onwards Or Balloon Scheme Available, Perfect Paintwork/Rims, 1 Owner Unit, PML Agent Servicing Done. Last Major Service Done With Receipts In APR 2018 At 102119KM. 1 Yr Engine...									
Posted: 28-Jun-2018 Tags: 2011 BMW 320i, BMW 320i, BMW, 320i, Used BMW									
	BMW 3 Series 320i Coupe Sunroof		\$61,777	\$12,520 /yr	25-Nov-2011	1,995 cc	69,000 km	Sports	Available
Owner Selling Off As Garage Full. Extremely Low Mileage, Park Under Shelter And Extremely Well Taken Care Of. No Repairs Needed. Black Exterior With The Sexy Red Leather Interior. Welcome Trade In/Scr...									
Posted: 11-May-2018 Tags: 2011 BMW 320i, BMW 320i, BMW, 320i, Used BMW									

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired ads

20 results/page

SELL BY CONSIGNMENT

SELL DIRECT AT THE PRICE YOU WANT!

NO SALE = NO CHARGES!

bmw 320

Price Range

Depreciation

2011

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Munich Alpina Pte Ltd » BMW 3 Series 320i Sunroof

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Commercial Vehicle

18GB & HUGE
IPHONE
DISCOUNTS.Only with
Combo XO
at \$78/mth.

Singtel

BMW 3 Series 320i Sunroof

Overview

Financial

Accessories

Similar

Research

Photos

Map

PREMIUM AD

Add to Shortlist

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price \$64,888**Depreciation** \$16,560 /yr

View models with similar depreciation

Reg Date 31-Mar-2011

(2yrs 8mths 27days COE left)

Manufactured 2010**Mileage** 27,000 km (3.7k /yr)**Transmission** Auto**Engine Cap** 1,995 cc**Road Tax** \$1,208 /yr**Power** 115.0 kW (154 bhp)

View specs of the BMW 3 Series Sedan (2005-2012)

Curb Weight 1,390 kg**Features** Powerful And Responsive 2.0L Inline 4 Engine, 6 Speed Steptronic Auto Transmission, SRS Airbags, ABS, DTC, PDC, Cruise Control, Electronic Memory Seat.**Accessories** Sunroof, Navigation System, Multi Function Sports Steering Wheel, Cruise Control, Auto Rain And Light Sensors, Cruise Control, Info Board.**Description** A Beautiful Black Beast With Black Interior Single Owner, Very Lowest Mileage In The Market. Always Parked Under Covered Car Park. Car In Great Condition. Regular Servicing And Inspection Done. Body Grooming Also Done Regularly. Rare Car. Guarantee A Low Price. Why Wait? Call/SMS Today To Arrange A Viewing! Up To 80% Financing Possible Trade In Welcome! Viewing Strictly By Appointment.**COE** \$59,073**OMV** \$38,964**ARF** \$38,964**Dereg Value** \$39,579 as of today (change)**No. of Owners** 1**Type of Veh** Luxury Sedan**Category** PARF Car, Premium Ad Car, Low Mileage Car**Availability** Available

PREMIUM AD

Add to Shortlist

Add to Compare

Add a Note

Posted on: 13-May-2018 | Last Updated on: 29-Jun-2018

Tags: BMW 320i, 2011 BMW 320i, BMW, 320i, Used BMW



Seller Information

Company	Munich Alpina Pte Ltd	
	» dealer's pricelist	
	» 68 vehs sold 107 vehs available	
Address	31 Bukit Batok Crescent #01-15	
	Search cars nearby this location	
Contact Person(s)	Joseph	82021811
	Damien	97825861

Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

Vehicle Evaluation



Find out the market value for your car. Get a free Car Valuation.

Free Valuation



LOOKING FOR AN
INDEPENDENT SPECIALIST?

Find the specialty Workshops for your vehicle.

bmw 320

Price Range

Depreciation

2011

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Think One Automobile & Trading » BMW 3 Series 320i

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Tyres



BMW 3 Series 320i

Overview

Financial

Accessories

Similar

Research

Photos

Map



Think One Automobile



Add to Shortlist

Tweet

Add to Compare

Add a Note

Report Error

More Actions

Share

Car Details

Price \$54,500

Depreciation \$13,700 /yr

View models with similar depreciation

Reg Date 16-Mar-2011

(2yrs 8mths 12days COE left)

Manufactured 2010

Mileage 120,000 km (16.4k /yr)

Transmission Auto

Engine Cap 1,995 cc

Road Tax \$1,208 /yr

Power 115.0 kW (154 bhp)
View specs of the BMW 3 Series Sedan (2005-2012)

Curb Weight 1,390 kg

Features -

Accessories -

Description Fully Agent Maintained With Records! Lowest Price In The Market. No Further Discount. Serious Buyer Are Welcome!

COE \$61,894

OMV \$34,991

ARF \$34,991

Dereg Value \$37,714 as of today (change)

No. of Owners 1

Type of Veh Luxury Sedan

Category PARF Car

Availability Available

Add to Shortlist

Add to Compare

Add a Note

Posted on: 01-Jul-2018 | Last Updated on: 02-Jul-2018

Tags: BMW 320i, 2011 BMW 320i, BMW, 320i, Used BMW



Location Map

Seller Information

Company

Think One Automobile & Trading

» dealer's pricelist

» 97 vehs sold | 176 vehs available

Address

61 Ubi Avenue 2 #05-02/03

Search cars nearby this location

Location

Automobile Megamart

Office No

68413300

Contact Person(s)

Jun Hao
Jacky83006820
94594387

MR PORTER

Compare

Upfront Payment

» more Financial info

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	5364Z

Vehicle Details

Vehicle No.:	SKD158C
Vehicle to be Exported:	No
Intended De-registration Date:	03 Jul 2018
Vehicle Make:	B.M.W.
Vehicle Model:	320i AT ABS D/AB 2WD 2DR GAS/D SR
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	A634I692N46B20BD
Chassis No.:	WBAKD52090E492244
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$37,589.00
Original Registration Date:	31 Jan 2011
First Registration Date:	31 Jan 2011
Transfer Count:	2
Actual ARF Paid:	\$37,589.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jan 2021
PARF Rebate Amount:	\$22,553.00

Intended COE Rebate Details

COE Expiry Date:	30 Jan 2021
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$76,102.00
COE Rebate Amount:	\$18,522.00
Total Rebate Amount:	\$41,075.00

The information contained herein is correct as at 03 Jul 2018

OK

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 5364Z

Vehicle Details

Vehicle No.: SKD158C

Vehicle to be Exported: No

Intended De-registration Date: 03 Jul 2018

Vehicle Make: B.M.W.

Vehicle Model: 320i AT ABS D/AB 2WD 2DR GAS/D SR

Primary Colour: White

Manufacturing Year: 2010

Engine No.: A634I692N46B20BD

Chassis No.: WBAKD52090E492244

Maximum Power Output: 115.0 kW (154 bhp)

Open Market Value: \$37,589.00

Original Registration Date: 31 Jan 2011

First Registration Date: 31 Jan 2011

Transfer Count: 2

Actual ARF Paid: \$37,589.00 18794

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 30 Jan 2021

PARF Rebate Amount: \$22,553.00

Intended COE Rebate Details

COE Expiry Date: 30 Jan 2021

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$76,102.00

COE Rebate Amount: \$18,522.00

Total Rebate Amount: \$41,075.00

The information contained herein is correct as at 03 Jul 2018

OK



1600 850 4888 (Within Singapore)
(65) 6680 4888 (International)
(65) 6680 4740
customer.care@axa.com.sg
www.axa.com.sg

03479

Policyholder name	NGAN WEE LING CHARMAN	Certificate
Cover	Comprehensive	Coverage
Plan name	Private APW	Engine
NCD applicable	60%	
Vehicle registration number	SKD155C	
Period of insurance	From 31/07/2017 to 30/07/2018 (both dates inclusive)	
Finance loan company	UNITED OVERSEAS BANK LIMITED	

4. For persons whose driving on the Pollypadder's order is with 45-51 passengers

It is only for social, domestic and other purposes and for the State's charitable purposes.

Additional clauses & endorsements to your policy

AXA Insurance Pte Ltd

Red

important note

REPUBLIC OF SINGAPORE
IDENTITY CARD NO S7735364Z



14898

NGAN WEE LING, CHARMIAN

顏 偉 鈴

RACE

CHINESE

DATE OF BIRTH

12-12-1977

COUNTRY OF BIRTH

SINGAPORE

SEX

F

12506

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number S7735364Z

Name

NGAN WEE LING, CHARMIAN

Birth Date 12 Dec 1977

Issue Date 22 Dec 2003



1187451
LIC No S7735364Z



DATE OF EXPIRY

09-01-2008

ADDRESS

APT BLK 204A COMPASSVALE DRIVE
#10-449
SINGAPORE 541204

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

		PASS DATE
Class 2B	Motorcycles not exceeding 200 cc	17 Mar 2000
Class 2A	Motorcycles between 201 cc and 400 cc	14 Aug 2001
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	16 Nov 1995

HP 428A



FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6

#01-46,48,50 Autobay

SINGAPORE 417883

Not Authorized
n/bk
r/s # 17.000
13dy.
3/7/18

VEHICLE NO:SKD 158C

QTY	PARTICULAR		
1 PCS	BOOTLID	1881.12	20/cent \$2,118.30 ✓
1 PCS	BOOTLID REAR LOGO	62.50	nu \$68.00 ✓
1 PCS	BOOTLID '320i' EMBLEM		nu \$65.00 ✓
2 PCS	BOOTLID HINGES @\$166.00		11 \$332.00 X
1 PCS	BOOTLID INNER LOCK		741 \$299.08 ✓
1 PCS	BOOTLID INNER TRIM		11 \$295.43 X
1 SET	BOOTLID INNER TRIM CLIPS		11 \$50.00 X
2 PCS	BOOTLID REFLECTORS @\$420.00		cm \$840.00 ✓
1 PCS	BOOTLID WEATHERSTRIP		twi \$312.00 ✓
1 PCS	REAR BUMPER	1315.22	dis \$1,850.00 ✓
1 PCS	REAR BUMPER LOWER DIFFUSER	366.05	dis \$640.00 ✓
1 PCS	REAR BUMPER REINFORCEMENT	695.00	341 \$720.00 ✓
2 PCS	REAR BUMPER SIDE HOLDERS @\$305.00	135 x 2 = 270	341 \$420.00 ✓
1 PCS	REAR BUMPER TOWING COVER		to.1 \$30.00 ✓
4 PCS	REAR BUMPER PDC SENSORS @\$305.00	225 x 3 = 675	shld \$1,220.00 3 pcs
1 PCS	REAR BUMPER PDC SENSORS WIRE		11 \$313.54 X
1 PCS	REAR BUMPER TOP GUIDE	161.00	cm \$205.00 ✓
1 PCS	REAR BUMPER LOWER GUIDE		11 \$202.00 X
1 SET	REAR BUMPER CLIPS		nu \$50.00 ✓
2 PCS	REAR BUMPER LOWER COVERS @\$115.00		11 \$230.00 X
1 PCS	REAR END PANEL	1012.00	341 \$1,068.00 ✓
1 PCS	REAR END PANEL TOP GARNISH		twi/cm \$290.50 ✓
1 PCS	REAR FLOOR PANEL		11 \$1,120.20 X
1PCS	REAR FLOOR PANEL TOP BOARD		nu \$650.00 ✓
1 PCS	REAR FLOOR PANEL CENTRE WELL (FIBRE)	680	341 \$882.00 ✓
2 PCS	REAR FENDERS @\$2150.00		11 \$4,300.00 X
2 PCS	REAR FENDER INNER TRIM @\$320.00		MSR \$640.00 12L
2 PCS	TAILLAMPS @\$680.00	625 x 2 = 1250	cm \$1,360.00 ✓
1 PCS	REAR EXHAUST MUFFLER		11 \$1,480.00 X
1 PCS	REAR EXHAUST HEAT SHIELD	188.05	341 \$311.30 ✓
2 PCS	REAR EXHAUST MOUNTINGS @\$45.00		11 \$90.00 X
1 PCS	CENTRE EXHAUST PIPE		11 \$1,880.00 X
1 PCS	BONNET	2098.20	341 \$2,135.00 ✓
1 PCS	BONNET LOGO	62.50	nu \$80.00 ✓
2 PCS	BONNET DAMPERS @\$170.00		11 \$340.00 X
2 PCS	BONNET HINGES @\$140.00	132 x 2 = 264	341 \$280.00 ✓

52

\$51,835.25

1 PCS	S.NETT		
1 PCS	REAR LICENCE PLATE W/HOLDER	320	\$100.00 50
1 PCS	REAR END PANEL SEALANT	120	\$80.00 50
1 PCS	REAR EXHAUST CHROME	220	\$200.00 100
1 PCS	REAR FLOOR PANEL CENTRE WELL SEALANT	120	\$100.00 50
1 PCS	FRONT LICENCE PLATE W/HOLDER	320	\$100.00 50
1 BOT	RADIATOR COOLANT	120	\$80.00 50
LABOUR CHARGES:			
	TO CHECK WIRING		\$100.00 30
	TO DISMENTLE & REPLACING PDC SENSOR		\$100.00 50
	TO DISMENTLE & REFIX BOOTLID MECHANISM		\$180.00 80
	TO DISMENTLE & REPLACING REAR EXHAUST		\$380.00 100
	TOWING CHARGE KING ROLLER		\$180.00 120
	TO REPROGRAMME & CLEAR FAULT CODE		\$200.00 100
	TO MOUNT VEHICLE ON CAR O-LINER	11	\$380.00 x
	TO DISMENTLE AIR CON ASSY,VACUUM AND CHARGE IN GAS		\$150.00 100
	TO DISMENTLE & REFIX SEAT,CUSHION,UPHOLSTREY		\$180.00 100
	TO SPRAY RUST PROOFING		\$180.00 100
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTENED		\$3,800.00 2000
	& REPLACING PARTS		
	TO PUTTY & SPRAY PAINTING		\$2,800.00 1800
	TOTAL		\$61,125.25

4930

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Mei Kwan (LKKAUTO)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Thursday, 5 July, 2018 2:07 PM
To: Mei Kwan (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving SJA1791U (OI : CTI - SNM18D03260C02) AND SKD158C(TP : LKK REF - CC6/CTI18012023/Upa3) on 28/06/2018
Attachments: leeSZ_SNM18D03260C01-SJA1791U-
LKKDirectSettlementAccidentLtr_CLCR95.792.pdf; MNA118084219-SJA1791U.pdf
Categories: HMK

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Chong Boon Sen

Lucas Lee
Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6181
Fax (65) 6222 7175/6224 7478
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Mei Kwan (LKKAUTO) [mailto:Meikwan@lkkauto.com]
Sent: Wednesday, 4 July, 2018 6:18 PM
To: Claims Dept of CTI
Cc: Chong Boon Sen; Angie Foo; Hsiao Tong (LKKAUTO); Vic (LKKAUTO); Admin A
Subject: Direct Settlement - Accident Involving SJA1791U (OI : CTI - TBA) AND SKD158C(TP : LKK REF - CC6/CTI18012023/Upa3) on 28/06/2018

WITHOUT PREJUDICE

Dear Sir / Madam,



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033
Website: www.sg.cntaiping.com
Co. Reg. No. 200208384E

Our Reference: **SNM18D03260/C01/1**

Date : **05 JULY 2018**

via Ordinary & Registered Mail

**TAN ZHI TAI , COLIN
BLK 210 PETIR ROAD
#21-479
SINGAPORE 670210**

Dear Sir / Madam

**ACCIDENT INVOLVING SJA1791U AND SKD158C ON 28 JUNE 2018
ALONG PIE TUAS BEFORE BKE EXIT**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SKD158C** , is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,

Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : HSIAO TONG

Ref : CC6/CTI18012023/UPA3

Contact No : 67423197

via Email : HSIAOTONG@LKKAUTO.COM

CC : Agent - (AN0006A) - ALFA CREDIT PTE LTD

F01/LKKDS-2013

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Monday, 24 December 2018 8:41 AM
To: 'Claims Dept of CTI'
Cc: Vic (LKKAUTO); Admin A; Chong Boon Sen
Subject: <Seek Mandate> : Direct Settlement - Accident Involving SJA1791U (OI : CTI - SNM18D03260C02) AND SKD158C(TP : LKK REF - CC6/CTI18012023/Upa3) on 28/06/2018 / OUR REF: SNM18D03260C02
Attachments: LKKInspection.pdf; LKKAdjustment1.pdf; LKK Survey Photos.pdf; LKK Resurvey Photos 1.pdf; LKK Resurvey Photos 2.pdf; LKK Resurvey Photos 3.pdf; TP LOD_SKD158C.pdf

Your ref : **SNM18D03260C02**
Our ref : CC6/CTI18012023/Upa3q2

Dear Sirs/Madam,

ACCIDENT INVOLVING SJA 1791U(OI) / SKD 158C(TP) / OTHERS ON 28/06/2018

We refer to the above matter.

The said chain collision involved 5 vehicles whereby our insured was the 4th vehicle. In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%. We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer Third Party repairer " **FASTECH AUTO PTE LTD**" at **\$19,547.45(all-in)**.

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair (w/GST)	\$65,404.02	\$ 18,190.00
2. Loss of Rental (9days x \$180.00)	\$ 1,620.00	\$ 1,350.00 (9days x \$150.00)
3. LTA/ GIA Search Fee	\$ 7.45	\$ 7.45
Total	\$67,031.47	<u>\$ 19,547.45</u>

**13 days recommendation for repair.

Market Value	: \$ 58,500.00 (est)
LTA Rebate	: \$ 41,075.00 (est)
Nett Value	: <u>\$ 17,425.00 (est)</u>

Enclosed here with all the relevant documents for your perusal.

For your approval please.

Hsiao Tong (LKKAUTO)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Monday, 3 June 2019 2:48 PM
To: Hsiao Tong (LKKAUTO)
Cc: Admin A
Subject: RE: <Seek Mandate> : Direct Settlement - Accident Involving SJA1791U (OI : CTI - SNM18D03260C02) AND SKD158C(TP : LKK REF - CC6/CTI18012023/Upa3) on 28/06/2018 / OUR REF: SNM18D03260C02

Dear Hsiao Tong,

Pls proceed as recommendation.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Hsiao Tong (LKKAUTO) [mailto:chewht@lkkauto.com]
Sent: Sunday, 31 March, 2019 9:55 AM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Admin A <admin-a@lkkauto.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: RE: <Seek Mandate> : Direct Settlement - Accident Involving SJA1791U (OI : CTI - SNM18D03260C02) AND SKD158C(TP : LKK REF - CC6/CTI18012023/Upa3) on 28/06/2018 / OUR REF: SNM18D03260C02

2nd REMINDER

Dear Sirs/Mdm,

We refer to mandate request dated 24/12/2018.

Kindly let us have your instruction/approval.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Wednesday, 23 January 2019 2:45 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: Admin A <admin-a@lkkauto.com>; 'Chong Boon Sen' <boonsen.chong@sg.cntaiping.com>

Subject: RE: <Seek Mandate> : Direct Settlement - Accident Involving SJA1791U (OI : CTI - SNM18D03260C02) AND SKD158C(TP : LKK REF - CC6/CTI18012023/Upa3) on 28/06/2018 / OUR REF: SNM18D03260C02

REMINDER

Dear Sirs/Mdm,

We refer to your below email.

Kindly let us have your instruction.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Monday, 24 December 2018 8:41 AM

To: 'Claims Dept of CTI' <claimsdept@sg.cntaiping.com>

Cc: Vic (LKKAuto) <vicalpeh@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: <Seek Mandate> : Direct Settlement - Accident Involving SJA1791U (OI : CTI - SNM18D03260C02) AND SKD158C(TP : LKK REF - CC6/CTI18012023/Upa3) on 28/06/2018 / OUR REF: SNM18D03260C02

Your ref : **SNM18D03260C02**

Our ref : CC6/CTI18012023/Upa3q2

Dear Sirs/Madam,

ACCIDENT INVOLVING SJA 1791U(OI) / SKD 158C(TP) / OTHERS ON 28/06/2018

We refer to the above matter.

The said chain collision involved 5 vehicles whereby our insured was the 4th vehicle.
In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%.
We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer Third Party repairer " **FASTECH AUTO PTE LTD**" at **\$19,547.45(all-in).**

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair (w/GST)	\$65,404.02	\$ 18,190.00
2. Loss of Rental (9days x \$180.00)	\$ 1,620.00	\$ 1,350.00 (9days x \$150.00)

3. LTA/ GIA Search Fee	\$ 7.45	\$ 7.45
Total	\$67,031.47	\$ 19,547.45

**13 days recommendation for repair.

Market Value	: \$ 58,500.00 (est)
LTA Rebate	: \$ 41,075.00 (est)
Nett Value	: \$ 17,425.00 (est)

Enclosed here with all the relevant documents for your perusal.

For your approval please.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Wednesday, 3 October 2018 8:06 AM

To: 'Chong Boon Sen' <boonsen.chong@sg.cntaiping.com>; 'Claims Dept of CTI' <claimsdept@sg.cntaiping.com>

Cc: Vic (LKKAuto) <vicalpeh@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving SJA1791U (OI : CTI - TBA) AND SKD158C(TP : LKK REF - CC6/CTI18012023/Upa3) on 28/06/2018 / OUR REF: SNM18D03260C02

Dear Sirs/Madam,

We refer to the above matter.

Enclosed for your perusal is: -

- Estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Sent: Thursday, 5 July 2018 1:45 PM

To: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>

Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving SJA1791U (OI : CTI - TBA) AND SKD158C(TP : LKK REF - CC6/CTI18012023/Upa3) on 28/06/2018 / OUR REF: SNM18D03260C02

Dear Mei Kwan,

Pls find Insured report and note our reference.

Regards,

Chong Boon Sen

Claims Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 63896171

Fax: 62247175

Email: boonsen.chong@sg.cntaiping.com

Website: www.sg.cntaiping.com

Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Mei Kwan (LKKAuto) [<mailto:Meikwan@lkkauto.com>]

Sent: Wednesday, 4 July, 2018 6:18 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Angie Foo <angie.foo@sg.cntaiping.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: Direct Settlement - Accident Involving SJA1791U (OI : CTI - TBA) AND SKD158C(TP : LKK REF - CC6/CTI18012023/Upa3) on 28/06/2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case.

We had inspected TP vehicle SKD 158C at M/s Fastech Auto Pte Ltd - Kaki Bukit.

Enclosed for your perusal is:

- TP GIA report
- Photographs of TP vehicle in its damaged condition

Please note that the estimated cost of repair is not ready yet.

We will revert to you on preliminary advice in due course.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action

Kindly take note that the case handler in-charge is Hsiao Tong and she can be contacted at DID: 6742 3197.

To check availability of the case handler , you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Hsiao Tong (LKKAuto)

From: Jason Fastech Auto <jason@fastechauto.com.sg>
Sent: Tuesday, 4 June 2019 2:41 PM
To: Hsiao Tong (LKKAuto); 'Nancy Lam'
Subject: RE: ACCIDENT INVOLVING VEHICLE SKD 158C AND SJA 1791U ON 28.06.2018 *LKK
REF: CC6/CTI18012023/Upa3q2

Without Prejudice

Dear Sirs/Mdm,

We do accept your offer as below.

Regards,
Lina
For and on behalf of Jason
Fastech Auto Pte Ltd
Tel: 6746 5405
Fax: 6745 8520

From: Hsiao Tong (LKKAuto) [mailto:chewht@lkkauto.com]
Sent: Tuesday, June 4, 2019 8:19 AM
To: Nancy Lam <nancy.lam@fastechauto.com.sg>; Jason Fastech Auto (jason@fastechauto.com.sg)
<jason@fastechauto.com.sg>
Subject: RE: ACCIDENT INVOLVING VEHICLE SKD 158C AND SJA 1791U ON 28.06.2018 *LKK REF:
CC6/CTI18012023/Upa3q2

Without Prejudice

Dear Sirs/Mdm,

We refer to your below email.

We propose settlement at a global sum of \$19,450.00(all-in).

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nancy Lam <nancy.lam@fastechauto.com.sg>

Sent: Thursday, 9 May 2019 2:03 PM

To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>

Subject: ACCIDENT INVOLVING VEHICLE SKD 158C AND SJA 1791U ON 28.06.2018

Without prejudice,

Dear Hsiao Tong,

Please refer to our LOD dated 03.09.2018.

We have yet to receive any reply pertaining to the claim settlement.

Please revert.

Regards,

Nancy Lam

Fastech Auto Pte Ltd

Tel: 6746 5405

Fax: 6745 8520



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI18012023/Upa3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 10-07-2019



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJA 1791U	Veh. Inspected	SKD 158C
Policy No.	DMPCSN3089661700	Coverage (\$)	0.00
Claim No.	SNM18D03260/C01/1	Excess (\$)	0.00
Assign From		Assign Date	03/07/2018

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 320i (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WBAKD52090E492244	Colour	WHITE
Odometer	83800	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/35Z R19	MICHELIN	6 mm
L/H Front Tyre	235/35Z R19	MICHELIN	6 mm
R/H Rear Tyre	265/30Z R19	MICHELIN	6 mm
L/H Rear Tyre	265/30Z R19	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	28/06/2018	Inspection Date	03/07/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	13 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKD 158C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BOOTLID	DENTED / BENT	2,118.30	1,881.12
1	BOOTLID REAR LOGO	NECESSARY	68.00	62.50
1	BOOTLID '320I' EMBLEM	NECESSARY	65.00	65.00
2	BOOTLID HINGES @\$166.00	NOT NECESSARY	332.00	-
1	BOOTLID INNER LOCK	TWISTED	299.08	299.08
1	BOOTLID INNER TRIM	NOT NECESSARY	295.43	-
1	SET BOOTLID INNER TRIM CLIPS	NOT NECESSARY	50.00	-
2	BOOTLID REFLECTORS @\$420.00	CRACKED	840.00	840.00
1	BOOTLID WEATHERSTRIP	TWISTED	312.00	312.00
1	REAR BUMPER	DISTORTED	1,850.00	1,315.22
1	REAR BUMPER LOWER DIFFUSER	DISTORTED	640.00	366.05
1	REAR BUMPER REINFORCEMENT	BENT	720.00	695.00
2	REAR BUMPER SIDE HOLDERS @\$305.00	BENT	420.00	270.00
1	REAR BUMPER TOWING COVER	TORN	30.00	30.00
4	REAR BUMPER PDC SENSORS @\$305.00	SHORTED (3 PCS ONLY)	1,220.00	675.00
1	REAR BUMPER PDC SENSORS WIRE	NOT NECESSARY	313.54	-
1	REAR BUMPER TOP GUIDE	CRACKED	205.00	161.00
1	REAR BUMPER LOWER GUIDE	NOT FITTED	202.00	-
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
2	REAR BUMPER LOWER COVERS @\$115.00	NOT FITTED	230.00	-
1	REAR END PANEL	BADLY DENTED	1,068.00	1,012.00
1	REAR END PANEL TOP GARNISH	TWISTED / CRACKED	290.50	290.50
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,120.20	-
1	REAR FLOOR PANEL TOP BOARD	WARPED	650.00	650.00
1	REAR FLOOR PANEL CENTRE WELL (FIBRE)	BROKEN	882.00	680.00
2	REAR FENDERS @\$2150.00	TO REPAIR SEE LABOUR	4,300.00	-
2	REAR FENDER INNER TRIM @\$320.00	N/S DEFORMED	640.00	320.00
2	TAILLAMPS @\$680.00	CRACKED	1,360.00	1,250.00

Report Ref No. CC6/CTI18012023/Upa3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR EXHAUST MUFFLER	TO REPAIR SEE LABOUR	1,480.00	-
1	REAR EXHAUST HEAT SHIELD	BENT	311.30	188.05
2	REAR EXHAUST MOUNTINGS @\$45.00	NOT NECESSARY	90.00	-
1	CENTRE EXHAUST PIPE	TO REPAIR SEE LABOUR	1,880.00	-
1	BONNET	BUCKLED	2,135.00	2,098.20
1	BONNET LOGO	NECESSARY	80.00	62.50
2	BONNET DAMPERS @\$170.00	NOT NECESSARY	340.00	-
2	BONNET HINGES @\$140.00	BENT	280.00	264.00
1	BONNET INNER HANDLE W/CABLE	NOT NECESSARY	92.00	-
1	BONNET INSULATOR	NOT NECESSARY	193.00	-
1	SET BONNET INSULATOR CLIPS	NOT NECESSARY	50.00	-
1	BONNET LOCK LEVEL	BENT	190.00	190.00
2	BONNET LOCK CATCHES @\$25.00	NOT NECESSARY	50.00	-
2	BONNET MECHANISM LOCK L/R @\$266.00	TWISTED	532.00	532.00
2	BONNET RUBBER GUIDE STOPPERS @\$15.00	NOT NECESSARY	30.00	-
1	BONNET WEATHERSTRIP	NOT NECESSARY	92.00	-
1	FRONT BUMPER	DISTORTED	1,615.00	1,415.32
1	FRONT BUMPER INNER SPONGE	TORN	98.00	98.00
1	FRONT BUMPER REINFORCEMENT	BENT	712.00	699.02
1	FRONT BUMPER NUMBER PLATE GARNISH	NOT FITTED	110.00	-
1	FRONT BUMPER TOW COVER N/S	TORN	35.00	35.00
2	FRONT BUMPER FOG LAMPS @\$280.00	NOT NECESSARY	560.00	-
2	FRONT BUMPER SIDE HOLDERS @\$115.00	BENT	230.00	230.00
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	FRONT BUMPER CENTRE GRILLE	NOT NECESSARY	56.00	-
2	FRONT BUMPER REINFORCEMENT BRACKETS @\$105.00	N/S BENT	210.00	105.00
1	FRONT BUMPER TOP RUBBER SEAL	TORN	45.00	45.00
2	FRONT GRILLES @\$180.00	BROKEN	360.00	332.00
2	HEADLAMPS @\$2800.00	N/S BROKEN / O/S CRACKED	5,600.00	4,130.00
2	HEADLAMP LOWER BRACKETS @\$185.00	CRACKED	370.00	230.00

Report Ref No. CC6/CTI18012023/Upa3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	HEADLAMP NOZZLE N/S	CRACKED	180.00	175.30
1	HEADLAMP TOP BRACKET N/S	NO SUCH PARTS	166.00	-
1	FRONT SUPPORT PANEL	BENT	627.00	545.05
1	ENGINE TOP COVER	NOT NECESSARY	289.30	-
1	AIR CLEANER BOX	NOT NECESSARY	766.50	-
2	ENGINE MOUNTINGS L/R @\$350.00	TORN	700.00	630.00
1	FRONT AIR CON CONDENSER AIR GUIDE ASSY	TORN	199.20	199.20
1	AIR CON CONDENSER	BENT / PUNCTURE	1,220.00	1,008.20
1	AIR CON SUCTION HOSE	NOT NECESSARY	295.00	-
1	AIR CON DISCHARGE HOSE	NOT NECESSARY	298.00	-
1	AIR CON TEMPERATURE SENSOR	NOT NECESSARY	155.00	-
1	RADIATOR	BENT / CRACKED	922.00	891.00
1	RADIATOR AUXILLIARY FAN ASSY	CRACKED / JAMMED	1,550.00	1,388.50
1	RADIATOR BY PASS HOSE	NOT NECESSARY	92.00	-
1	RADIATOR LOWER HOSE	NOT NECESSARY	122.50	-
1	RADIATOR TOP HOSE	NOT NECESSARY	133.50	-
2	FRONT FENDERS @\$919.00	TO REPAIR SEE LABOUR	1,838.00	-
2	FRONT FENDER INNER SHIELDS @\$211.30	NOT NECESSARY	422.60	-
1	FRONT OIL COOLING PIPE	NOT NECESSARY	266.30	-
2	FRONT HEARESTS @\$650.00	SERVICEABLE	1,300.00	-
2	FRONT SAFETY BELT BUCKLES @\$290.00	NOT NECESSARY	580.00	-
2	FRONT HEADREST REPAIR KITS @\$155.00	ACTIVATED	310.00	310.00
1	AIR BAG CONTROL UNIT	NOT NECESSARY	955.00	-
	LESS 5% DISCOUNT		-	-1,353.79
			51,835.25	25,722.02
	SPECIAL NETT ITEMS			
1	REAR LICENCE PLATE W/HOLDER (SN)	BROKEN	100.00	50.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	80.00	50.00
1	REAR EXHAUST CHROME (SN)	DENTED	200.00	100.00
1	REAR FLOOR PANEL CENTRE WELL SEALANT (SN)	NECESSARY	100.00	50.00
1	FRONT LICENCE PLATE W/HOLDER (SN)	BROKEN	100.00	50.00

Report Ref No. CC6/CT118012023/Upa3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BOT RARIATOR COOLANT (SN)	NECESSARY	80.00	50.00
			660.00	350.00
	LABOUR			
	TO CHECK WIRING .		100.00	30.00
	TO DISMANTL & REPLACING PDC SENSOR .		100.00	50.00
	TO DISMANTLE & REFIX BOOTLID MECHANISM .		180.00	80.00
	TO DISMANTLE & REPLACING REAR EXHAUST .		380.00	100.00
	TOWING CHARGE KING ROLLER .		180.00	120.00
	TO REPROGRAMME & CLEAR FAULT CODE.		200.00	100.00
	TO MOUNT VEHICLE ON CAR O-LINER.	NOT NECESSARY	380.00	-
	TO DISMANTLE AIR CON ASSY ,VACUUM AND CHARGE GAS.		150.00	100.00
	TO DISMANTLE & REFIX SEAT,CUSHION ,UPHOLSTERY .		180.00	100.00
	TO SPRAY RUST PROOFING.		180.00	100.00
	LABOUR FO PANEL BEATING ,CUT ,WELD ,STRAIGHTENED & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL,REAR FENDERS,REAR EXHAUST MUFFLER,CENTRE EXHAUST PIPE AND FRONT FENDERS.		3,800.00	2,000.00
	TO PUTTY & SPRAY PAINTING.		2,800.00	1,800.00
			8,630.00	4,580.00
GRAND TOTAL			61,125.25	30,652.02
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				17,000.00

Report Ref No. CC6/CTI18012023/Upa3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.