

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 04 Jul 2018

Preliminary Advice

Insured Vehicle No : SKP7394C

TP Vehicle No : SJF2465D

Make : TOYOTA WISH

Date of Inspection : 03/07/2018

Inspection At : Keng Hock Auto

BLK 7 SIN MING INDUSTRIAL ESTATE C #01-84

Singapore 575642

Accident Date : 01/07/2018

Assignment Date : 03/07/2018

Est. Duration of Repair : 6 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,172.90
Revised Amount	:S\$	5,923.44
Check Items (Estimated)	:S\$	1,234.88
Total	:S\$	7,158.32

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.