

SERVICE ESTIMATE

94349 - C00001 SL: SERVICE SALES - PC

Mr Wu XiaLu

Blk 254 Bishan Street 22

#23-452

Singapore 570254

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Mr Wu XiaLu

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 1

Inv.date. : 02/07/2018

WIP No. : 12812

Veh.In/Out:

*Tel.No. : Mobile: 91059158

Reg.No. : SLV8926T

Reg.date : 19/01/2018

Mileage : 0

Chassis No: VF1RFB00059266511

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802	TO REPLACE REAR LH FENDER,	0	2700.00	0		2,700.00	S
800	TO PUTTY SPRAY PAINT ON REAR	0	1600.00	0		1,600.00	S
LH FENDER, REAR END PANEL, LH							
ROCKER PANEL, ETC							
802	TO REPLACE REAR WINDSCREEN	0	450.00	0		450.00	S X
802	TO REMOVE & INSTALL REAR BOOT	0	1350.00	0		1,350.00	S 800
COMPARTMENT PARTS							
802	TO REMOVE & INSTALL INTERIOR P	0	1800.00	0		1,800.00	S ?
0080	TO INSTALL REAR WINDSCREEN FIL	0	280.00	0		280.00	S ?
280	TO CHECK WIRING INCLUDE	0	330.00	0		330.00	S ✓
RESETTING OF ALL ELECTRICAL							
MODULES							
	FENDER REAR LH M4S	1.0 EA	1539.00			1,539.00	S Rx
	QTR GLASS LH	1.0 EA	269.40			269.40	S X
	WINDSCREEN REAR	1.0 EA	633.20			633.20	S X
	WINDSCREEN SEALANT	3.0 EA	112.10			336.30	S X
	PRIMER	3.0 EA	176.60			529.80	S X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Taufik 97495749

16/7/18

sur@lkkauto.com

7 days

SERVICE ESTIMATE

94349 - C00001 SL: SERVICE SALES - PC

Mr Wu XiaLu

Blk 254 Bishan Street 22

#23-452

Singapore 570254

Closed by : Michelle Ong Siew Be

Svc Consultant :

Remarks : Mr Wu XiaLu

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2

Inv.date. : 02/07/2018

WIP No. . : 12812

Veh.In/Out:

*Tel.No. . : Mobile: 91059158

Reg.No. . : SLV8926T

Reg.date. : 19/01/2018

Mileage . : 0

Chassis No: VF1RFB00059266511

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	ADHESIVE SEALER FL2	1.0 EA	425.40			425.40	S X
	BODY PANEL SEALANT X	1.0 EA	937.50			937.50	S X

			Gross Total.	13,180.60
Labour Total	8,510.00		Net.....	13,180.60
Parts Total	4,670.60		GST @ 7.0%	922.64
Package Total	0.00		Total.....	14,103.25
			Paid.....	0.00
			Please Pay..	14,103.25

GST: S=StdRated; O=OutOfScope; Z=ZeroRated