



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 19700268K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 33256

AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way,
#27-01 AXA Tower
Singapore 068811

Supplementary 1 To QTN: 32721

DATE : 14/11/2018

CLAIM NO. : 11153

POLICY NO. :

FROM : RAYMOND

VEHICLE NO. : FBG9417L
MAKE/MODEL : YAM / FZ16

S/N	Description	Action	Qty	Unit Price	Amount
1	DUCT CYL BLOCK P/N: 60482	Replace	1.00	\$36.00	36.00
2	SHROUD AIR P/N: 50471	Replace	1.00	\$35.00	35.00
3	STEERING CONE SET P/N: 33765	Replace	1.00	\$53.00	53.00
4	TUBE TOOL P/N: 54588	Replace	2.00	\$60.00	120.00
5	COVER TAIL RH (BLACK) P/N: 60469	Replace	1.00	\$60.00	60.00
SUB TOTAL					\$304.00
GST @ 7 %					\$21.28
GRAND TOTAL					\$325.28

30% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO: 2002-1-0023
ISO 9001: 2015