

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

02 JUL 2018

Estimate No. : b1 47477
Date Estimated : 28/06/2018
Prepared By : Han Kwan Yong

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Krishnaveni D/O P Kasivisvanathan
4 Jalan Minggu**- ACCOUNT - 40000**
Cash Sales - Service
Singapore

Singapore 577337

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKE4355T	VP92739	01/03/2012	X1 sDrive18i	0

DESCRIPTION

To replace rear bumper & attachments including to knock out dented area caused by the accident.

850 1,275.00

To respray rear bumper

934 1,038.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

150 177.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

Sundries.

? 80.00

Total Labour 1: 2,747.00

DESCRIPTION

BODY NUT
RR BUMPER TOW HOOK COVER (SE
RR BUMPER CTR GUIDE
RR BUMPER CARRIER
RR BUMPER LOWER COVERING
RR BUMPER LH GUIDE
RR BUMPER RH GUIDE
RR BUMPER (PRIMED)
RR BUMPER BOTTOM (XLINE/PDC)
EXPANDING RIVET
RR BUMPER LH REFLECTOR
RR BUMPER RH REFLECTOR
DECOUPLING RING PDC TORQUE CONVERTE
BUMPER PDC SENSOR (SCHWARZ)- ELBOW

QTY	PRIC	VALUE
10	0.90	? 9.00
1	62.10	de 62.10
1	61.35	? 61.35
1	411.25	? 411.25
1	31.45	? 31.45
1	56.95	? 56.95
1	56.95	? 56.95
1	831.40	de 831.40
1	322.35	de 322.35
30	1.35	uic 40.50
1	35.20	x 35.20
1	35.20	? 35.20
2	5.05	? 10.10
2	236.85	? 473.70

Total Parts : 2,437.50

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X**E S T I M A T E**

Estimate No. : **b1 47477**
Date Estimated : **28/06/2018**
Prepared By : **Han Kwan Yong**

Page No. : **2 of 5**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKE4355T	VP92739	01/03/2012	X1 sDrive18i	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 1/6/18 09:15 Excess S\$ _____

Surveyor's Name Tan Jia Sign [Signature]

Surveyor's Tel 97498169 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail tanjia@pml.com

No. of Working Days Recommend 03 days

Labour 1	:	2,747.00
Parts	:	2,437.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	362.92
Grand Total	:	5,547.42

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **