

1/03/2007

REF: CS/CT118612130/11sbm2 Special Instruction:

S. REC. BY:

SURVEYOR

Tauhteh

ASSIGNMENT (Office)

From (Person):

Huang Shiang Yi

of

CTI

Date/Time: 08072018 444pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKU 2893K

Insured:

GBD 9172A

at Workshop m/s

Wearnes

Tel:

8126 1237

of

249 Alexandra Rd

Policy No:

DmCVSN3054321700

Claim No:

SNM18D03795C0

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

03072018

CA / REV / REP. / REV 24 HRS w/p

Date/Time:

0807 2018 9:00am

Person Contacted:

Paul

H.O.D. Endorsement

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKU 2893K -x
	GBD 9172A - CCA/CCR170097716/Kpa3g2 DOA: 1/5/2017

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Jul 2018		03 Jul 2018 16:44 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:									
Main Claimant:	HITACHI CAPITAL ASIA PACIFIC PTE LTD								
Vehicle Reg. No.:	SKU2893K	Date of Loss: 03/07/2018 00:00 - :59							
Claim Type:	TP / SNM18D03295C02	Policy/Cover Note No.: DMCVSN3054321700							
Vehicle Reg. No. (Insured):	GBD9192A	Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer:	Wearnes Automotive Pte Ltd (Alexandra Road) 249 Alexandra Road, 159935 Alexandra - Tel: 63789370								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Hwang Shiang Yi - 63896541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 12/07/2018]								
Adj Asg. Remarks:	EST \$21,820.60, CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18012130/T1sb

3 ANSON ROAD #16-00
SPRINGLEAF TOWERSINGAPORE 079909

Date : 04-07-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 9192A	Veh. Inspected	SKU 2893K
Policy No.	DMCVSN3054321700	Coverage (\$)	0.00
Claim No.	SNM18D03295C02	Excess (\$)	0.00
Assign From	MERIMEN (HWANG SHIANG YI)	Assign Date	04/07/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	03/07/2018	Inspection Date	
Survey held at	WEARNES AUTOMOTIVE PTE LTD 249 ALEXANDRA ROAD SINGAPORE 159935		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	03/07/2018 14:02
Date Of Accident	03/07/2018 11:45
Exact Location Of Accident	KAKI BUKIT AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKU2893K
Insured/Policyholder	
Name Of Registered Owner	HITACHI CAPITAL ASIA PACIFIC PTE LTD
Co Reg No	199400399N
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67341222
Vehicle Particulars	
Manufacturer	LAND ROVER
Model	EVOQUE-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPX/P1643179
Cover Note Number	

Driver

Name of Driver	ISKANDAR BIN MOHAMAD KHIR
NRIC No	S8418441A
Date Of Birth	23/06/1984
Occupation	INDOOR
Date Of Driving Pass	22/05/2007
Driving Experience	11 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-92350815
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	28 JALAN LEMPENG #10-06
Postcode	128807
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Refer to attached

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD9192A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Complete and submit this Form to Allied World's Authorized Reporting Centre ("ARC") for filling.
2. Please report correctly the details of the accident to speed up the claims process.
3. This Form must be completed by the Policyholder and/or the Authorised Driver.
4. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
5. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
6. Any false reporting may be referred to the Traffic Police Department for investigation.

ACCIDENT STATEMENT

Date and Time of Accident: Date: 03/07/18 Time: 1146
 Exact Location of Accident: KAKI BUKIT AVE 1

DETAILS OF OWN VEHICLE

Vehicle Registration Number: SKW 2893K

INSURED / POLICYHOLDER (OWN VEHICLE)

Name of Registered Owner (See Insurance Cert.): HITACHI CAPITAL ASIA PACIFIC
 Personal Identification - NRIC (Singaporean/PR): 199400399N
 - FIN/Passport Number:
 - Not Applicable

VEHICLE PARTICULARS (OWN VEHICLE)

Vehicle Make / Model: Manufacturer LR Model ELANVA
 Type of Vehicle*
 Saloon MPV CRV Van Lorry
 Bus M/cycle Others

Exact Purpose for which vehicle was being used at time of accident
 Are you claiming under your own Insurance policy for repair to your vehicle?
 Yes No (If No, PIs select: Third Party Reporting)
 Vehicle Category*
 Private Commercial Motorcycle

INSURANCE COMPANY (OWN VEHICLE)

Name of Insurance Company*: AIA
 Type of Policy: Comprehensive Third Party Fire & Theft TP Only
 Fleet Policy: Yes No
 Policy Number: VPX 1P1643179
 Motor CI: Same as Insured above

DRIVER

Name of Driver: ISKANDAR BIN MOHAMAD KHIR
 Personal Identification - NRIC (Singaporean/PR): S8418441A
 - FIN/Passport Number:
 Date of Birth: 23 dd / 06 mm / 84 yy
 Driving Date Pass: 22 dd / 05 mm / 07 yy
 Year of Driving Experience: Year(s) Month(s)
 Occupation: Indoor Outdoor
 Gender: Male Female
 Contact Number / Mobile Phone / Fax No.: 9235 0815

Address of Driver	28 JUAN LAWRENZ #10-06	Postcode (12807)
Email Address		
Was driver an employee of the Insured's Company?	<input type="radio"/> Yes <input checked="" type="radio"/> No	
If No, Relationship of the Driver with the Insured	HIRER	
Vehicle Registration Number of Driver's Own	<input type="radio"/> Yes <input checked="" type="radio"/> No	
Vehicle Registration Number of Driver's Own Vehicle (if applicable)		
Insurance Company of Driver's Own Vehicle (if applicable)		

GENERAL INFORMATION OF THE ACCIDENT

Type of Collision (Eg. Chain collision, Head-On collision, Side Swipe, Front to Rear)	HEAD-REAR		
Weather Conditions	<input checked="" type="radio"/> Clear	<input type="radio"/> Raining	<input type="radio"/> Others, _____
Road Surface	<input checked="" type="radio"/> Dry	<input type="radio"/> Wet	<input type="radio"/> Others, _____

OTHER INFORMATION

Was any foreign vehicle involved in this accident?	<input type="radio"/> Yes <input checked="" type="radio"/> No
Was any body injured in the accident?	<input type="radio"/> Yes <input checked="" type="radio"/> No
Was any other vehicle or property damaged?	<input checked="" type="radio"/> Yes <input type="radio"/> No
Was there any video captured by Car Camera?	<input checked="" type="radio"/> Yes <input type="radio"/> No
Number of Passengers (Including Driver)	01

DETAILS OF POLICE ACTION

Was the Accident reported to the Police?	<input type="radio"/> Yes <input type="radio"/> No (If Yes, please state which Police Station.)
Police Station Name	
Police Station Address	
Police Station Contact	Tel No. _____ Fax No. _____
Was notice of intended Prosecution given?	<input type="radio"/> Yes <input checked="" type="radio"/> No (If Yes, against whom?)

DETAILS OF OTHER VEHICLE / PROPERTY 1

Vehicle Registration Number	QBD 9192A
Vehicle Make/ Model/ Colour	
Details of Properties	
Name of Driver	
Personal Identification - NRIC (Singaporean/PR)	
- FIN/Passport Number	
Contact Number	
Address	
Name of Insurance Company	CNTP
Nature of Damage	
No. of Passenger (Including Driver)	

(Note - Please use page 8 if you need to add more vehicles)

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Driving along Kaki Bukit Ave 1. And stopping at traffic light junction. ~~while~~ while stationary, Opel car came ~~drive~~ drove by Mr Arinandan Saravanan hit the back of my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SERVICE ESTIMATE

60697 - C00001 SL: SERVICE SALES - PC
 Hitachi Capital Asia Pacific Pte Ltd
 Attn: Mr Kelvin Tan
 8 Holland Ave
 #05-06
 Singapore 271008

GST Reg.No:M28920628X
 Inv.No. : B&P 0 Page 1
 Inv.date. : 03/07/2018
 WIP No. : 14586
 Veh.In/Out:
 *Tel.No. : Mobile: 94306388
 Reg.No. : SKU2893K
 Reg.date : 15/07/2015
 Mileage : 0
 Chassis No: SALVA2AG1FH041525

Closed by : Paul Ong Qing Yong
 Svc Consultant :
 Remarks : Hitachi Capital Asia

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, REAR BOOTLID, ETC	0	3600.00	0		3,600.00	S
900	TO PUTTY SPRAYPAINT ON REAR BUMPER, BOOTLID, ETC	0	3000.00	0		3,000.00	S
802	TO REPLACE REAR WINDSCREEN	0	1200.00	0		1,200.00	S ✓
0080	TO INSTALL REAR WINDSCREEN FIL	0	280.00	0		280.00	S ✓
802	TO REMOVE & REFIT REAR BOOTLID PARTS	0	1200.00	0		1,200.00	S 600
R06	REAR NUMBER PLATE & HOLDER	0	60.00	0		60.00	S X m
280	TO CHECK WIRING INCLUDE	0	486.00	0		486.00	S ✓
RESETTING OF ALL ELECTRICAL MODULES							
	LLR064614/BOOT REAR PANEL - TAILGATE TRI	1.0 EA	3570.40			3,570.40	S
	REAR LOGO "RANGE" EV	1.0 EA	173.70			173.70	S
	REAR LOGO "ROVER" EV	1.0 EA	173.50			173.50	S
	NAME PLATE	1.0 EA	91.20			91.20	S

1200
 2400
 1000
 2000
 3,213.36
 X m
 156.33
 net 156.15
 net 82.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Tanpin 97495749
 'wp'
 18/7/18 @ 10am
 Resurvey before paint
 see @ lkkauto.com
 5 days.
 23/7/18

SERVICE ESTIMATE

60697 - C00001 SL: SERVICE SALES - PC
 Hitachi Capital Asia Pacific Pte Ltd
 Attn: Mr Kelvin Tan
 8 Holland Ave
 #05-06
 Singapore 271008

GST Reg.No:M28920628X
 Inv.No. : B&P 0 Page 2
 Inv.date. : 03/07/2018
 WIP No. : 14586
 Veh.In/Out:
 *Tel.No. : Mobile: 94306388
 Reg.No. : SKU2893K
 Reg.date. : 15/07/2015
 Mileage : 0
 Chassis No: SALVA2AG1FH041525

Closed by : Paul Ong Qing Yong
 Svc Consultant :
 Remarks : Hitachi Capital Asia

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	LOGO 'EVOQUE Si4' BL	1.0 EA	164.80			164.80	S <i>net</i> 148.32
	LLR002238/WINDSCREEN	4.0 EA	5.90			23.60	S <i>net</i> 21.24
	LLR049347/WINDSCREEN	1.0 EA	1261.70			1,261.70	S <i>net</i> 1,135.53
	ADHESIVE AND SEALER	2.0 EA	116.10			232.20	S <i>net</i> 209.98
	LLR058060/BUMPER - R	1.0 EA	2639.30			2,639.30	S <i>net</i> 2375.37
	HEAT SHIELD REAR EVO	1.0 EA	123.80			123.80	S <i>? X net</i>
	BRACKET - BUMPER MOU	1.0 EA	60.60			60.60	S <i>net</i> 54.54
	BRACKET - BUMPER MOU	1.0 EA	67.70			67.70	S <i>net</i> 60.93
	BUMPER MOULDING REAR	1.0 EA	130.60			130.60	S <i>cut</i> 117.54
	BUMPER BRACKET REAR	1.0 EA	119.90			119.90	S <i>net</i> 107.91
	BUMPER BRACKET REAR	1.0 EA	80.00			80.00	S <i>net</i> 72
	BODY PANEL SEALANT X	1.0 EA	878.80			878.80	S <i>X net</i>
	ADHESIVE SEALER FL2	1.0 EA	425.40			425.40	S <i>net</i> 382.66

Gross Total. 20,393.10

Labour Total 9,826.00
 Parts Total 10,567.10
 Package Total 0.00

Net..... 20,393.10
 GST @ 7.0% 1,427.52
 Total..... 21,820.60
 Paid..... 0.00
 Please Pay.. 21,820.60

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

62

SERVICE ESTIMATE

0 - C00010 SL: CHINA TAIPING INSURANCE (SINGAPORE)
 CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD GST Reg.No:M28920628X
 3 ANSON ROAD Inv.No. . : B&P 0 Page 1
 #16-00, SPRINGLEAF TOWER Inv.date. : 14/08/2018
 SINGAPORE 079909 WIP No. . : 14586
 Veh.In/Out: 16/07/2018 07/08/2018

Closed by : Paul Ong Qing Yong
 Svc Consultant : ACC
 Remarks : Hitachi Capital Asia

*Tel.No. . : 63896111
 Reg.No. . : SKU2893K
 Reg.date . : 15/07/2015
 Mileage . . : 74,897
 Chassis No: SALVA2AG1FH041525

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, REAR BOOTLID, ETC	0	2400.00	0		2,400.00	S
800	TO PUTTY SPRAYPAINT ON REAR BUMPER, BOOTLID, ETC	0	2000.00	0		2,000.00	S
802	TO REPLACE REAR WINDSCREEN	0	1200.00	0		1,200.00	S
0080	TO INSTALL REAR WINDSCREEN FIL	0	280.00	0		280.00	S
802	TO REMOVE & REFIT REAR BOOTLID PARTS	0	600.00	0		600.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0	486.00	0		486.00	S
	1 LLR064614/BOOT REAR	1.0 EA	3570.40	10		3,213.36	S
	5 REAR LOGO 'RANGE' EV	1.0 EA	173.70	10		156.33	S
	4 REAR LOGO 'ROYER' EV	1.0 EA	173.50	10		156.15	S
	5 NAME PLATE	1.0 EA	91.20	10		82.08	S
	6 LOGO 'EVOQUE Si4' BL	1.0 EA	164.80	10		148.32	S
	7 LLR002238/WINDSCREEN	4.0 EA	5.90	10		21.24	S



SERVICE ESTIMATE

0 - C00010
 CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
 3 ANSON ROAD
 #16-00, SPRINGLEAF TOWER
 SINGAPORE 079909

SL: CHINA TAIPING INSURANCE (SINGAPORE)

GST Reg.No:M28920628X
 0 Page 2
 Inv.No. . : B&P
 Inv.date. : 14/08/2018
 WIP No. . : 14586
 Veh.In/Out: 16/07/2018 07/08/2018
 *Tel.No. . : 63896111
 Reg.No. . : SKU2893K
 Reg.date. : 15/07/2015
 Mileage . : 74,897
 Chassis No: SALVA2AG1FH041525

Closed by : Paul Ong Qing Yong
 Svc Consultant : ACC
 Remarks : Hitachi Capital Asia

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
8	LLR049347/WINDSCREEN	1.0 EA	1261.70	10		1,135.53	S
9	ADHESIVE AND SEALER	2.0 EA	116.10	10		208.98	S
10	LLR058060/BUMPER - R	1.0 EA	2639.30	10		2,375.37	S
12	BRACKET - BUMPER MOU	1.0 EA	60.60	10		54.54	S
13	BRACKET - BUMPER MOU	1.0 EA	67.70	10		60.93	S
14	BUMPER MOULDING REAR	1.0 EA	130.60	10		117.54	S
15	BUMPER BRACKET REAR	1.0 EA	119.90	10		107.91	S
16	BUMPER BRACKET REAR	1.0 EA	80.00	10		72.00	S
18	ADHESIVE SEALER FL2	1.0 EA	425.40	10		382.86	S

			Gross Total.	15,259.14
Labour Total	6,966.00		Net.....	15,259.14
Parts Total	8,293.14		GST @ 7.0%	1,068.14
Package Total	0.00		Total.....	16,327.28
			Paid.....	0.00
			Please Pay..	16,327.28

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118012130/T1SBN2
Date: 17/08/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3054321700
Claimant Vehicle No :	SKU2893K	Insured Vehicle No :	GBD9192A
Date of Loss:	03/07/2018	Nature of Claim:	TP
		Claim No:	SNM18D03295C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKU2893K	Engine No:	010714232612204PT
Make & Model:	LAND ROVER EVOQUE, 2.0 (A)	Chassis No:	SALVA2AG1FH041525
Reg. Date:	15/07/2015 (Man. Year: 2015)	Odometer:	74897 km
Colour:	Black		
Engine Capacity:	1999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	10,627.10	8,293.14	2,333.96	21.96
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,766.00	6,966.00	2,800.00	28.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	20,393.10	15,259.14	5,133.96	25.17
+ GST 7.00/7.00% (S\$)	1,427.52	1,068.14	359.38	25.18
Nett Amount (S\$)	21,820.62	16,327.28	5,493.34	25.17

INSPECTION

Date of Assignment: 03/07/2018
Date Inspected: 18/07/2018 Inspected At:

Wearnes Automotive Pte Ltd (Alexandra Road)
249 Alexandra Road
Singapore 159935

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Aug 2018)
Parts: M1-SUV	LAND ROVER EVOQUE 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKU2893K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LLR064614/BOOT REAR	Cracked	3,570.40 FS	*3,213.36 FS
2	1		*PANEL-TAILGATE TRI	Not Necessary	349.90 FS	*- FS
3	1		*REAR LOGO RANGE EV	Necessary	173.70 FS	*156.33 FS
4	1		*REAR LOGO ROVER EV	Necessary	173.50 FS	*156.15 FS
5	1		*NAME PLATE	Necessary	91.20 FS	*82.08 FS
6	1		*LOGO EVOQUE SI4 BL	Necessary	164.80 FS	*148.32 FS
7	4		*LLR002238/WINDSCREEN	Necessary	23.60 FS	*21.24 FS
8	1		*LLR049347/WINDSCREEN	Necessary	1,261.70 FS	*1,135.53 FS
9	2		*ADHESIVE AND SEALER	Necessary	232.20 FS	*208.98 FS
10	1		*LLR058060/BUMPER-R	Deformed	2,639.30 FS	*2,375.37 FS
11	1		*HEAT SHIELD REAR EVO	Not Necessary	123.80 FS	*- FS
12	1		*BRACKET-BUMPER MOU	Necessary	60.60 FS	*54.54 FS
13	1		*BRACKET-BUMPER MOU	Necessary	67.70 FS	*60.93 FS
14	1		*BUMPER MOULDING REAR	Cut	130.60 FS	*117.54 FS
15	1		*BUMPER BRACKET REAR	Necessary	119.90 FS	*107.91 FS
16	1		*BUMPER BRACKET REAR	Necessary	80.00 FS	*72.00 FS
17	1		*BODY PANEL SEALANT X	Not Necessary	878.80 FS	*- FS
18	1		*ADHESIVE SEALER FL2	Necessary	425.40 FS	*382.86 FS
19	1		*REAR NUMBER PLATE & HOLDER	Not Necessary	60.00 FS	*- FS
Total Parts (\$\$)					10,627.10	8,293.14

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER,REAR BOOTLID,ETC	New	3,600.00	2,400.00
2	TO PUTTY SPRAYPAINT ON REAR BUMPER,BOOTLID,ETC	New	3,000.00	2,000.00
3	TO REPLACE REAR WINDSCREEN	New	1,200.00	1,200.00
4	TO INSTALL REAR WINDSCREEN FIL	New	280.00	280.00
5	TO REMOVE & REFIT REAR BOOTLID PARTS	New	1,200.00	600.00
6	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	New	486.00	486.00
Gross Labour Cost (S\$)			9,766.00	6,966.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >