

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 47523
Date Estimated : 02/07/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Foo Chit Yang Justina
993 Bukit Timah Road
#08-15

Singapore 589631

- ACCOUNT - 115

United Overseas Insurance Ltd
3 Anson Road #28-01 Springleaf Tower

Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDK6188Y	VZ48971	30/10/2014	218iA AT	0

DESCRIPTION

To replace rear tail gate, rear bumper, front bumper, both kidney grill, reinforcement & all attachments cause by accident.

2125 3,400.00

Painting on rear bumper, tailgate, front bumper & front bonnet

2665 3,619.00

To replace rear windscreen glass

488 574.00

To conduct water leak tests.

64 75.00

To supply and install rear windscreen solar film.

X 531.00

To check electrical wiring systems for proper function.

150 177.00

To replace left headlight including program and conduct tests for proper function.

451 531.00

To carry out body cavity preservation.
(Per panel).

100 118.00

To supply front emboss number plate.

b7✓ 83.00

Sundries.

? 150.00

Total Labour 1: 9,258.00

DESCRIPTION

TRUNK LID
CROSSLINK FRT
FRT IMPACT ABSORBER
FRT LH BOTTOM DEFORMATION ELEMENT
FRT RH BOTTOM DEFORMATION ELEMENT
FRT BUMPER BOTTOM CARRIER
FRT FLAP TOWING EYE PRIMED

QTY	PRIC
1	1,174.95
1	121.35
1	47.80
1	84.30
1	84.30
1	143.60
1	41.80

bt✓ 1,174.95
? 121.35
de✓ 47.80
? 84.30
? 84.30
? 143.60
de✓ 41.80

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 47523**
Date Estimated : **02/07/2018**
Prepared By : **Kevin Leong Wai Kit**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDK6188Y	VZ48971	30/10/2014	218iA AT	0

DESCRIPTION	QTY	PRIC	VALUE
GRILLE BUMPER MIDDLE CLOSED (PDC)	1	96.20	96.20
FRT BUMPER PANEL PRIMED (PMA)	1	842.00	842.00
GRILLE SIDE OPEN LH (LUXURY LINE+PD	1	95.85	95.85
GRILLE SIDE OPEN RH (LUXURY LINE+PD	1	95.85	95.85
FRT BUMPER TOP CARRIER	1	368.90	368.90
REAR BUMPER PANEL PRIMED (PDC)	1	966.25	966.25
RR BUMPER LH SIDE GUIDE	1	47.85	47.85
RR BUMPER RH SIDE GUIDE	1	47.85	47.85
REAR BUMPER CARRIER	1	423.80	423.80
SUPPORT	1	37.35	37.35
REAR BUMPER TRIM STRIP (CHROM)	1	107.55	107.55
RR BUMPER LH INNER SIDE GUIDE	1	58.55	58.55
RR BUMPER RH INNER SIDE GUIDE	1	58.55	58.55
SET MOUNTS PDC SENSOR REAR	1	62.95	62.95
FRT LH GRILLE (LUXURY)	1	86.05	86.05
FRT RH GRILLE (LUXURY)	1	86.05	86.05
LETTERING 218 I	1	62.55	62.55
GROMMET	1	0.75	0.75
PLAQUE 74MM	1	69.50	69.50
REAR FLAP TOWING EYE PRIMED	1	41.80	41.80
REAR WINDOW ESG	1	632.25	632.25
FRONT PANEL V STRUT	1	110.25	110.25
TRUNK LID SEALING	1	97.85	97.85
LH HEADLIGHT LED TECHNOLOGY	1	2,137.85	2,137.85
DECOUPING RING PDC TORQUE CONVERTER	8	5.05	40.40
(DG) CLEANER R1 (100ML)	1	23.85	23.85
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	2	131.55	263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	27.85

Total Parts : **8,687.70**

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____
Drawn Date: **19/7/18** Excess S\$ _____
Surveyor's Name: **Tan Jiah** Sign: **Tan Jiah**
Surveyor's Tel: **97495749** Authorised Yes / No _____

Authorized Date _____ Time _____
RESIDUAL PHOTO BY SURVEYOR (Yes / No) PML Yes / No _____
Surveyor's E-mail: **tanjiah@lkkauto.com**
No. of Working Days Recommend: **6 days**

LKK Auto Consultants hence notify the Repairer

- To return _____
- To dis: _____
- Parts: _____

• Third party	Labour 1	Prejudice basis	9,258.00
• No illegal	Parts		8,687.70
• Supplies	Labour 2		0.00
is subje	Excess		0.00
Acknowledged by	Total GST @ 7%		1,256.20
Signature:			
Date:	Grand Total		19,201.90

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **