



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638994
Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)
Fax: +65 6863 0425 (Service) +65 6862 1347 (Parts)
Website: www.goldbell.com.sg
Co. Reg No. 198003963G

Page 1 / 2

ESTIMATE

Date	: 26/06/2018	Reg No	: YP2373E
To	: AXA INSURANCE SINGAPORE PTE LTD	Model	: FEB21ER4SDEB C/C MT
Attn.	:	Chassis No	: FEB21EA20464
Office / Mobile	:	Engine No	: 4P10C13278
Email Address	:	Quotation No.	: 64937
		Ref. No.	: GBE/SVC/SALES-4653/180626
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 14/06/2018
Attn.	: LILEWEI	Policy No.	: D18MTPCVE001567
Office / Mobile	: +65 6864 0637	Claim Type	: TP CLAIM - AXA
Email / Fax No.	: LiLewei@goldbell.com.sg	Workshop	: 29 TANJONG PENJURU

SPECIAL NETT ITEMS

1	VERTICAL WOOD	2	4000.00
2	HORIZONTAL WOOD	6	3300.00
3	REAR DECK LOWER RAIL	1	550.00
4	FLOOR WOODEN PANEL	6	5100.00
5	REAR WOODEN STEP PANEL	1	450.00
6	REAR BUMPER	1	850.00
7	REAR BUMPER BRACKET	2	360.00
8	I - STRIP	2	200.00
9	J - STRIP	2	240.00
10	REAR NUMBER PLATE	1	20.00
11	"60 KM/H" STICKER	1	20.00
12	REAR DECK PANEL	1	950.00
13	REAR DECK SIDE PANEL	1	2000.00
14	U - BOLT	6	1080.00
15	BOLT AND NUT (SET)	8	280.00
16	TAIL LAMP TOP BRACKET LHS	1	150.00

PARTS TOTAL: 19550.00

LABOUR CHARGES

1	TO REMOVE, REFIX AND REALIGN REAR DECK ASSY, TO REPLACE ALL DAMAGED PARTS.	4000.00
2	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTIC CHECK	180.00
3	SUNDRIES	80.00
4	TO CARRY OUT SPRAY PAINTING.	450.00

LABOUR TOTAL : 4,710.00

SUB-TOTAL : 24,260.00

GST @ 7% for \$ 24,260.00 1,698.20

GRAND TOTAL (S\$) : 25,958.20