

REPAIR ESTIMATE*

DATE 29/6/2018 9:41

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Door (RH)			\$ 1,351.10
	Front Door (RH)			\$ 1,403.05
	Front Door Outer Handle (RH)			\$ 38.75
	Front Door Mirror (RH)			\$ 980.50
	Front & Rear Wheel Rim (LH/RH)		\$ 351.90	\$ 703.80
	Front & Rear Wheel Nut 6.80x 5pcs		\$ 6.80	\$ 34.00
	Front & Rear Wheel Bearing		\$ 258.50	\$ 517.00
	Front & Rear Wheel Stud 6.80 x 5pcs		\$ 6.80	\$ 34.00
	SUB TOTAL			\$ 5,007.80
	LESS 20%			\$ 1,001.56
	DISCOUNTED TOTAL			\$ 4,006.24
	Rear Door Comfortdelgro & Apps Sticker (RH)			\$ 80.00
	Front Door Coloured Comfort Logo (LRH)			\$ 75.00
	Front & Rear Tyre (RH)		\$ 216.00	\$ 432.00
				\$ 587.00
	Labour Charge			
	Panel Beating-Repair Rear Fender			\$ 900.00
	Spray Painting Charge			\$ 1,250.00
	Wiring Charge			\$ 80.00
	Tuff Kote			\$ 80.00
	Towing Charge-King Dolly			\$ 150.00
	Transfer of Door		\$ 120.00	\$ 240.00
	Remove/Refix Undercarriage			\$ 400.00
	Four Wheel Alignment			\$ 120.00
	N/A 2 LKX 27/18 160° P.R. 4 DAW BY PAINT PHOTO			
	TOTAL LABOUR			\$ 3,220.00
	ESTIMATE TOTAL			\$ 7,813.24
			7856.76	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.