

# LOH HENG

Automotive Repair Services  
Accident Insurance Claims

06 July 2018

Lonpac Insurance Pte Ltd

Singapore

Attn. : Motor Claim Department

Re : I Quotation

Vehicle no. SKK4826U VW Jetta

*Not Authorized  
L1 Sing @ 1  
Resurvey After Paint  
3 days*

S/N	Description	Amount (S\$)
<b>Parts Replacement</b>		
	Rear bumper <i>Pericom</i>	\$ 864.00 ✓
	Rear bumper reinforcement	\$ 748.00 ?
	Rear lower spoiler <i>NA</i>	\$ 446.00 ✓
	Reverse sensor	\$ 142.00 X
	Rear exhaust <i>NA</i>	\$ 1,137.00 X
	Sub total:	\$ 3,337.00
<b>Labour Charges</b>		
	To remove and refix new parts ,panel beating tail panel	\$ 390.00 2500
	To putty and spray paint on rear panel and new parts.	\$ 650.00 4000
	<b>Total:</b>	\$ 4,377.00

*Rear bumper moulding. \$ 216.00 odd ✓*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Block 176 #03-08 Sin Ming Autocare  
Sin Ming Drive  
Singapore 575721  
Tel : 64532237 / 64530797  
Fax : 64556384