

SE OWNER:

CC 4, Asm

180

12321, Aug 3<sup>52</sup>

LKK-

IDAC:

55694

## ASSIGNMENT

DOI:

5/7/18

Date / Time:

5/7/2018

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.

Name of Insured

Insured Tel No.

Excess Sec II :SS

Is driver the owner?

( YES / NO )

HP:

D.O.A: 5/7/2018

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLV3022J



INSRS:

WSP:

Tel:

Liability:

RMKS:

modern



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

REQ. DL &amp; LO EMPLOYMENT

TP VIDEO UPLOADED IN SMART  
OI SIGNALLLED TO TURN RIGHT  
TP PROCEEDED STRAIGHT.

- LIABILITY REVIEW

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

S\$

(

days) Reduction:

FINAL SETTLEMENT

Date/Time:

Confirm with

Final Liability:

S\$

(

days) BOLA S/N No.:

Repair Cost:

S\$

(

days)

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

(

days)

Loss of Income (LOI):

S\$

(

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

Legal Cost

S\$

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Payee 1:

S\$

Name 1:

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

Confirm by:

Email

Call

If NO or B 28, Ass. Lia:

28-6-19 @ 345 w/ MR YEN

CAN REJECT.

OI SHOWED SIGNAL

&amp; TP SHOULD SLOW

DOWN. NO OVERTAKING

@ THE JUNCTION.

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Email

Call

COPY

W7/19

REF:

ASS. REG. BY: Adrian King

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLV 3022J.

Yr Regn:

2015 May.

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Peugeot 308

C.C. 1199

Colour

Bronze

A/C: Insured / Std / NI / NA

Sp. Reading

62100

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VF3LPHNYWES264942

Gen. Cond: Good / Fair / Poor / BurntSteering: Inden / Jammed / Leaked / Burnt orBrake: Inden / Jammed / Leaked / Burnt orModi: Nil S/Rim / STD A/Rim or

Tyre Size:

F: 205/55R16

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / HOHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

05/07/18

Survey held at

Modern

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP AXA.

MV: 651K

PV: 51K

Nett: 141K

\$5,250

K(\$5,893.40/53%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos:

Others:

TOTAL

Report Format:

Lump Sum / I.B.I. (\$)

**MODERN AUTOMOTIVE PTE LTD**  
**BLK 3023A UBI ROAD 1 # 01-61**  
**SINGAPORE 408717**

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

AXA Insurance Singapore Pte Ltd  
 8 Shenton Way  
 # 27-01  
 Singapore 068811  
 Tel : 6338 - 7288  
 Fax : 6880 - 4838

*Joy*

**Quotation**  
 DATE : 06.07.018  
 VEH NO : SLV3022J  
 MODEL : Peugeot 308  
 D O A : 05.07.2018  
 YR REF : GZ3141L

(Pls arrange vehicle survey & check liability)

**RE : ESTIMATE FOR ACCIDENT REPAIR SLV3022J (PEUGEOT 308)**

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
<b>NO</b>	<b>LIST ITEMS</b>		
1	Front Bumper <i>Defamed</i>	1	785.00 ✓
2	Front Bumper Clips <i>new</i>	1 set	30.00 ✓
3	Front Bumper Side Holder - LH <i>Damaged</i>	1	54.00 ✓
4	Front Bumper Reinforcement <i>not new</i>	1	585.00 X
5	Front Bumper Side Grille - LH <i>not new</i>	1	135.00 X
6	Front Bumper Side Chrome - LH <i>cut</i>	1	246.00 ✓
7	Front Bumper Side Lamp - LH <i>cut</i>	1	98.00 ✓
8	Headlamp - LH <i>Cracked</i>	1	1,325.00 ✓
9	Bonnet <i>Repair</i>	1	1,115.00 +
10	Bonnet Logo <i>new</i>	1	85.00 ✓
11	Front Fender - LH <i>Buckled</i>	1	362.00 ✓
12	Front Fender Inner Shield - LH <i>Defamed</i>	1	148.00 ✓
13	Front Fender Inner Shield Clips - LH <i>new</i>	1 set	30.00 ✓
14	Front Door - LH <i>Repair</i>	1	985.00 +
15	Front Door Weatherstripe - LH <i>not new</i>	1	198.00 +
16	Front Door Hinge - LH <i>not new</i>	1	75.00 X
17	Front Wheel Rim - LH <i>cut</i>	1	892.00 ✓
18	Front Shock Absorber - LH <i>not new</i>	1	365.00 +
19	Font Knuckle Arm - LH <i>Best</i>	1	565.00 ✓
20	Front Lower Arm - LH <i>Best</i>	1	292.00 ✓
21	Front Wheel Hub c/w Bearing - LH <i>2nd</i>	1	256.00 ✓
			\$ 8,626.00
Less 10%			(862.60)
			\$ 7,763.40
	<b>S/NETT ITEMS</b>		
1	Front Tyre - LH <i>cut</i>	1	280.00 <i>200</i>
Total Parts			\$ 8,043.40

*5168*  
*465120*

RE : ESTIMATE FOR ACCIDENT REPAIR SLV3022J (PEUGEOT 308)

LABOUR CHARGE

1	To knocking & pull out front portion & renew above parts	\$	<del>1,200.00</del> 600
2	To putty & spray up paint works	\$	<del>1,200.00</del> 800
3	To check wiring	\$	<del>50.00</del> 30
4	To underseal	\$	150.00 +
5	To remove front undercarriage	\$	<del>350.00</del> 220
6	To perform wheel alignment	\$	<del>150.00</del> 80
		\$	3,100.00

Grand Total

**\$ 11,143.40**

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

total: 6581.20.

L/S: 5250

06 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:


Date:

## Service Request Details

Claim

S8M00NGC

Reference

None 

Loss Date

July 5, 2018

Request Date

July 5, 2018

Due Date

July 12, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

05072018 C 4.45pm

ms Ho veh in

Estimate done will call Adrian

### Actions

Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

Incident Vehicle Registration #

SLV3022J

Make

TPVD PEUGEOT

Model

308

Service Address

---

...

Primary Contact/Insured

---

W.L(WEI LEE.) PTE. LTD.

42 MACTAGGART ROAD, #02-02 MACTAGGART BUILDING, 368086, Singapore

93825631

ZBOX1688@GMAIL.COM

Claim Handler

---

TAY Ernest

6568804835

ernest.tay@axa.com.sg

Additional Instructions

INSD GIA NOT REPORTED

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

06 July, 2018

**W.L(WEI LEE.) PTE. LTD.**  
42 MACTAGGART ROAD  
#02-02 MACTAGGART BUILDING  
SINGAPORE 368086

Dear Sir,

**OUR REF : CC4/ASM18012321/ua3 / S8M00NGC**

**YOUR REF : GZ 3141L**

**ACCIDENT INVOLVING GZ 3141L & SLV 3022J ON 05.07.2018 ALONG/AT T-JUNCTION MACTAGGART ROAD AND HARRISON ROAD**

We write to inform you that we are the appointed loss adjuster by your motor insurer, AXA insurance Pte Ltd to deal with the third party claim against your motor policy.

We refer to the above subject matter. We have received third party claim(s) against your motor insurance policy.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We highlight that this accident has not been reported to your insurer. Under the Motor Claims Framework (MCF), you are required to report any accident with the accident vehicle (whether damaged or not) within 24 hours or by the next working day after the accident. The primary purpose of this reporting is to provide your version of the accident to AXA. Omission to report the accident will result in a loss of your No Claim Discount (NCD) upon renewal of your policy, and will prejudice any claim(s) by or against you. We would appreciate it if you could urgently file a report at our approved reporting centre.

The report has to be lodged at any of AXA Premium Workshops or reporting centres (subject to your policy). For the list of AXA Premium Workshops conveniently located throughout Singapore, please refer to the back of your Certificate of Insurance or the accompanying folder, or visit <https://www.axa.com.sg/customer-care/personal/motor/owndamageaccidentreporting>.

Your full co-operation is required. Kindly submit the following when lodging the report which list is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)

- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to us immediately. You may email it to [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com) or deliver it by hand to 51 Ubi Avenue 1, #01-25 Paya Ubi Ind. Park S(408933).

You should also IMMEDIATELY forward us by hand any letters or Courts Summons received from the other party involved in the accident. You should not negotiate, admit liability or offer payment to them.

We would like to bring to your attention that under Policy Condition, your insurer shall have full discretion in the process and settlement of the said third party claim subject to the merits of the case and according to the rights afforded under the policy.

Your NCD (No Claim Discount) will be reduced by 30% (20% for motorcycle/commercial vehicles) if a claim is made under your policy.

To enable us to look into the matter immediately, please let us hear from you within seven (7) days from date of this letter. In accordance with the policy conditions, your insurer reserve the right to repudiate the said claim to you should you not give proper notice to us of any occurrence which may give rise to it.

Kindly contact us at 6841 2360 if you have any further enquiries.

Yours sincerely,  
Claim Department

This is a computer generated letter and no signature is required.

CC : AXA INSURANCE PTE LTD  
Motor Claim Department



## MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 #01 - 61

SINGAPORE 408717

GST REG. NO : 200501102H

TEL : 6748-4422 / 6744-4422 FAX : 6-747- 6720

Email: chin@modernautomotive.com.sg

YOUR REF : GZ3141L

OUR REF : SLV3022J

Date : 14.02.2019

The Claims Manager

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01, AXA Tower

Singapore 068811

Tel : 6-880-4833 Fax : 6-880-4838

**RE : ACCIDENT INVOLVING SLV3022J & GZ3141L ON 05.07.2018  
AT T-JUNCTION OF MACTAGGART ROAD AND HARRISON ROAD**

---


We refer to the above matter.

We have been authorized by our client Ms Deng Xia to make claim against your insured vehicle No. GZ3141L in respect of the above accident for the following:

Repair cost	\$	5,617.50	(Incl GST)
Loss of use (7 days x \$100.00)	\$	700.00	
Search fee		2.00	
<b>Total :</b>	<b>\$</b>	<b>6,319.50</b>	

Enclosed herewith a copy each of the supporting documents for your perusal.  
Kindly process the above and remit the payment to us asap

Yours faithfully



Modern Automotive Pte Ltd

# MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1# 01-58/61 SINGAPORE 408717  
TEL : 67474422, 67454422 FAX : 67476720  
GST REG. NO : 200501102H

AXA INSURANCE (SINGAPORE) PTE LTD  
8 Shenton Way #27-01  
Singapore 068811

Attention : Motor Claim Department  
Contact : 6338 - 7288 Fax No. : 6880 - 4838

## Tax Invoice : TP001317

Date : 14/02/2019  
Vehicle Num. : SLV 3022J  
Make/Model : PEUGEOT 308-2015  
Chassis/Eng# :  
Accident Date : 05/07/2018  
Claim No. :  
Reference :  
Policy No. : 5098532832

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR :		
		ACCIDENT REPAIR (LUMPSUM)		5,250.00
		Labour Total S\$ :		5,250.00

Total S\$ :	5,250.00
GST @ 7% S\$ :	367.50
Amount Due S\$ :	5,617.50
	=====



MODERN AUTOMOTIVE PTE LTD



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**  
6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

### Third Party Insurer Enquiry

Our Ref No: GR-18-102620  
Date of Request: 05/07/2018

Your Ref No: Online Purchase

Modern Automotive Pte Ltd  
Blk 3023A Ubi Road 1  
#01-61 & #01-58  
Singapore 408717

Dear Sir/Madam,

Enquiry Date: 05/07/2018  
Enquiry By: Ho Meei Huey  
TP Vehicle No: GZ3141L  
Accident Date: 05/07/2018

#### Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GZ3141L	AXA Insurance Pte Ltd	28/08/2017-09/09/2018	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE  
6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

## TAX INVOICE

Our Ref No: GR-18-102620  
Date of Request: 05/07/2018

Your Ref No: Online Purchase

Modern Automotive Pte Ltd  
Blk 3023A Ubi Road 1  
#01-61 & #01-58  
Singapore 408717

Dear Sir/Madam,

Enquiry Date 05/07/2018  
Enquiry By Ho Meei Huey  
TP Vehicle No. GZ3141L  
Accident Date 05/07/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

---

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

# LETTER OF AUTHORIZATION

Date: 5/7/18

TO WHOM IT MAY CONCERN

Dear Sir,

RE: ACCIDENT INVOLVING VEHICLE

SLV 3022 J & Q23141L


ON 05/7/18 ALONG T-Junction MacTaggart  
Road & Harrison Road

This letter is to authorize **MODERN AUTOMOTIVE PTE LTD** at Block 3023A, Ubi Road 1, #01-61, Singapore 408717 to resolve the above matter.

In respect of this authorization, **MODERN AUTOMOTIVE PTE LTD** has my/our authority to decide on my/our behalf whether to accept any offer of settlement from the third party insurers. I/we also agreed that all payments include Loss of Use to make in favour of **MODERN AUTOMOTIVE PTE LTD**.

**MODERN AUTOMOTIVE PTE LTD** is also authorized to sign all the required documents include Discharge Voucher from the third party insurers on my/our behalf.

Yours Faithfully

  
Signature of Owner

S8264641H  
Name / NRIC

## MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1 # 01 - 61

SINGAPORE 408717

GST REG. NO : 200501102H

TEL : 6748-4422 / 6744-4422 FAX : 6-747- 6720

Email: chin@modernautomotive.com.sg

YOUR REF : GZ3141L

OUR REF : SLV3022J

Date : 14.02.2019

The Claims Manager

AXA Insurance Singapore Pte Ltd

8 Shenton Way

#27-01, AXA Tower

Singapore 068811

Tel : 6-880-4833 Fax : 6-880-4838

**RE : ACCIDENT INVOLVING SLV3022J & GZ3141L ON 05.07.2018  
AT T-JUNCTION OF MACTAGGART ROAD AND HARRISON ROAD**

---


We refer to the above matter.

We have been authorized by our client Ms Deng Xia to make claim against your insured vehicle No. GZ3141L in respect of the above accident for the following:

Repair cost	\$	5,617.50 (Incl GST)
Loss of use (7 days x \$100.00)	\$	700.00
Search fee		2.00
<b>Total :</b>	<b>\$</b>	<b><u>6,319.50</u></b>

Enclosed herewith a copy each of the supporting documents for your perusal.  
Kindly process the above and remit the payment to us asap

Yours faithfully

  
Modern Automotive Pte Ltd

# MODERN AUTOMOTIVE PTE LTD

BLK 3023A UBI ROAD 1# 01-58/61 SINGAPORE 408717  
TEL : 67474422, 67454422 FAX : 67476720  
GST REG. NO : 200501102H

AXA INSURANCE (SINGAPORE) PTE LTD  
8 Shenton Way #27-01  
Singapore 068811

Attention : Motor Claim Department  
Contact : 6338 - 7288 Fax No. : 6880 - 4838

Tax Invoice : TP001317

Date : 14/02/2019  
Vehicle Num. : SLV 3022J  
Make/Model : PEUGEOT 308-2015  
Chassis/Eng# :  
Accident Date : 05/07/2018  
Claim No. :  
Reference :  
Policy No. : 5098532832

S/N	Quantity	Particular	Unit Price	Amount S\$
		LABOUR : ACCIDENT REPAIR (LUMPSUM)		5,250.00
		Labour Total S\$ :		5,250.00



MODERN AUTOMOTIVE PTE LTD

Total S\$ : 5,250.00  
GST @ 7% S\$ : 367.50  
Amount Due S\$ : 5,617.50  
=====

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**Third Party Insurer Enquiry**

Our Ref No: GR-18-102620  
Date of Request: 05/07/2018

Your Ref No: Online Purchase

Modern Automotive Pte Ltd  
Blk 3023A Ubi Road 1  
#01-61 & #01-58  
Singapore 408717

Dear Sir/Madam,

Enquiry Date: 05/07/2018  
Enquiry By: Ho Meei Huey  
TP Vehicle No: GZ3141L  
Accident Date: 05/07/2018

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GZ3141L	AXA Insurance Pte Ltd	28/08/2017-09/09/2018	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

**TAX INVOICE**

Our Ref No: GR-18-102620  
Date of Request: 05/07/2018

Your Ref No: Online Purchase

Modern Automotive Pte Ltd  
Blk 3023A Ubi Road 1  
#01-61 & #01-58  
Singapore 408717

Dear Sir/Madam,

Enquiry Date 05/07/2018  
Enquiry By Ho Meei Huey  
TP Vehicle No. GZ3141L  
Accident Date 05/07/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

---

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

# LETTER OF AUTHORIZATION

Date: 5/7/18

TO WHOM IT MAY CONCERN

Dear Sir,

RE: ACCIDENT INVOLVING VEHICLE

SLV 3022 J & Q23141 L

ON 05/7/18 ALONG T-Junction MacTaggart


Road & Harrison Road

This letter is to authorize **MODERN AUTOMOTIVE PTE LTD** at Block 3023A, Ubi Road 1, #01-61, Singapore 408717 to resolve the above matter.

In respect of this authorization, **MODERN AUTOMOTIVE PTE LTD** has my/our authority to decide on my/our behalf whether to accept any offer of settlement from the third party insurers. I/we also agreed that all payments include Loss of Use to make in favour of **MODERN AUTOMOTIVE PTE LTD**.

**MODERN AUTOMOTIVE PTE LTD** is also authorized to sign all the required documents include Discharge Voucher from the third party insurers on my/our behalf.

Yours Faithfully

  
Signature of Owner

S8264641 H  
Name / NRIC

## Joy Irene (LKKAUTO)

---

**From:** Chin <chin@modernautomotive.com.sg>  
**Sent:** Thursday, 14 February 2019 3:08 PM  
**To:** Joy Irene (LKKAUTO)  
**Cc:** Hsiao Tong (LKKAUTO)  
**Subject:** Re: TP Claim SLV3022J (AXA)  
**Attachments:** 20190214151610.pdf

Dear Joy

We refer to the above matter.

Kindly confirm settlement as follows:

Repair Cost: \$5,617.50 (Incl GST)  
LOU (7days x \$100): \$700.00  
Search fee: \$2.00  
Total: \$6,319.50

We enclosed herewith our LOD for your perusal.

Thank you

Regards,  
Grace Chin  
Modern Automotive Pte Ltd  
Blk 3023-A, Ubi Road 1 #01-61  
Singapore 408717

Tel: 6748 4422  
Fax: 6747 6720

## Joy Irene (LKKAuto)

---

**From:** Joy Irene (LKKAuto)  
**Sent:** Friday, 28 June 2019 3:41 PM  
**To:** weileesg@gmail.com  
**Cc:** Admin A  
**Subject:** GZ 3141L ON 05/07/18  
**Attachments:** LETTER TO INSURED.pdf; OI GIA REPORT -.PDF

**Importance:** High

Dear Madam Chan,

We refer to our telephone conversation earlier and our whatsapp message. Please refer to the attached letter.

As spoken, kindly send us the following:

- 1) a letter of authority that your driver LOW CHIN FOO was authorized to drive at the time of accident;
- 2) copy of his driving license and work pass/employment cert.

We would appreciate to receive your prompt response.

Thank you.

Best Regards,

Joy Irene | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2409 | email: [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com) | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.



## Re:REQUEST TO DENY LIABILITY

Type

🔔 Question

Message

PLS PROCEED TO REJECT TP CLAIM

Reply



## REQUEST TO DENY LIABILITY

Type

🔗 Question

Message

Dear Sirs, Video uploaded showed that our insured made the necessary right turn signal when hit by the speeding third-party vehicle. Furthermore, it was in junction whereby vehicle travelling behind should anticipate that vehicles traveling in-front may initiate a turn. We would like to have your view/opinion/instruction whether or not we may proceed to deny liability. On the other hand, we are still pending for insured to furnish us the request LOA nad DL. Thank you. -Joy LKK

Reply

## Joy Irene (LKKAUTO)

---

**From:** Joy Irene (LKKAUTO)  
**Sent:** Thursday, 11 July 2019 11:47 AM  
**To:** Chin  
**Cc:** Hsiao Tong (LKKAUTO)  
**Subject:** RE: TP Claim SLV3022J AND (AXA GZ 3141L ON 5.7.18)

WITHOUT PREJUDICE

Dear Grace,

We refer to the subject.

We have reviewed the matter and basing on your video, our insured made and gave the necessary right turn signal when hit by your speeding client which was travelling from behind. Furthermore, the location was approaching in a junction/ in a junction whereby vehicles travelling behind should anticipate that vehicles travelling in-front may initiate a u turn.

In view of the above, we regret to inform you that we have our principal's instruction to deny liability.

Best Regards,  
Joy Irene | Case Handler  
LKK Auto Consultants Pte Ltd  
DID: 6841-2409 | email: [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com) | Fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

---

**From:** Chin [mailto:[chin@modernautomotive.com.sg](mailto:chin@modernautomotive.com.sg)]  
**Sent:** Thursday, 14 February 2019 3:08 PM  
**To:** Joy Irene (LKKAUTO) <[JoyIrene@lkkauto.com](mailto:JoyIrene@lkkauto.com)>  
**Cc:** Hsiao Tong (LKKAUTO) <[chewht@lkkauto.com](mailto:chewht@lkkauto.com)>  
**Subject:** Re: TP Claim SLV3022J (AXA)

Dear Joy

We refer to the above matter.

Kindly confirm settlement as follows:

Repair Cost: \$5,617.50 (Incl GST)  
LOU (7days x \$100): \$700.00  
Search fee: \$2.00  
Total: \$6,319.50

We enclosed herewith our LOD for your perusal.

Thank you



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18012321/Aja3s2

8 SHENTON WAY #24-01  
AXA TOWERS SINGAPORE 068811

Date : 16-07-2019



ATTN: ERNEST TAY

Code : ASM

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GZ 3141L	Veh. Inspected	SLV 3022J
Policy No.	GA261453	Coverage (\$)	0.00
Claim No.	S8M00NGC	Excess (\$)	0.00
Assign From	ERNEST TAY	Assign Date	05/07/2018

## 2. Vehicle Particulars & Condition

Make & Model	PEUGEOT 308	c.c	1199
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	VF3LPHNYWES264942	Colour	BRONZE
Odometer	62100	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55R16	MICHELIN	6 mm
L/H Front Tyre	205/55R16	MICHELIN	6 mm
R/H Rear Tyre	205/55R16	MICHELIN	6 mm
L/H Rear Tyre	205/55R16	MICHELIN	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND UNDERCARRIAGE.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	05/07/2018	Inspection Date	05/07/2018
Survey held at	MODERN AUTOMOTIVE PTE LTD BLK 3023A UBI ROAD 1 #01-61 SINGAPORE 408717		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 3022J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER (CONSISTENT)	DEFORMED	785.00	785.00
1	SET FRONT BUMPER CLIPS (CONSISTENT)	NECESSARY	30.00	30.00
1	FRONT BUMPER SIDE HOLDER - LH (CONSISTENT)	DAMAGED	54.00	54.00
1	FRONT BUMPER REINFORCEMENT (CONSISTENT)	NOT NECESSARY	585.00	-
1	FRONT BUMPER SIDE GRILLE - LH (CONSISTENT)	NOT NECESSARY	135.00	-
1	FRONT BUMPER SIDE CHORME - LH (CONSISTENT)	CUT	246.00	246.00
1	FRONT BUMPER SIDE LAMP - LH (CONSISTENT)	CUT	98.00	98.00
1	HEADLAMP - LH (CONSISTENT)	CRACKED	1,325.00	1,325.00
1	BONNET (CONSISTENT)	TO REPAIR SEE LABOUR	1,115.00	-
1	BONNET LOGO (CONSISTENT)	NECESSARY	85.00	85.00
1	FRONT FENDER - LH (CONSISTENT)	BUCKLED	362.00	362.00
1	FRONT FENDER INNER SHIELD - LH (CONSISTENT)	DEFORMED	148.00	148.00
1	SET FRONT FENDER INNER SHIELD CLIPS - LH (CONSISTENT)	NECESSARY	30.00	30.00
1	FRONT DOOR - LH (CONSISTENT)	TO REPAIR SEE LABOUR	985.00	-
1	FRONT DOOR WEATHERSTRIP - LH (CONSISTENT)	NOT NECESSARY	198.00	-
1	FRONT DOOR HINGE - LH (CONSISTENT)	NOT NECESSARY	75.00	-
1	FRONT WHEEL RIM - LH (CONSISTENT)	CUT	892.00	892.00
1	FRONT SHOCK ABSORBER - LH (CONSISTENT)	NOT NECESSARY	365.00	-
1	FRONT KNUCKLE ARM - LH (CONSISTENT)	BENT	565.00	565.00
1	FRONT LOWER ARM - LH (CONSISTENT)	BENT	292.00	292.00
1	FRONT WHEEL HUB C/W BEARING - LH (CONSISTENT)	DAMAGED	256.00	256.00
	LESS 10% DISCOUNT		-862.60	-516.80
			7,763.40	4,651.20
<b>SPECIAL NETT ITEMS</b>				
1	FRONT TYRE - LH (SN) (CONSISTENT)	CUT	280.00	200.00
			280.00	200.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO KNOCKING & PULL OUT FRONT PORTION & RENEW ABOVE PARTS. INCLUSIVE OF THE REPAIR OF BONNET AND FRONT DOOR - LH.		1,200.00	600.00
	TO PUTTY & SPRAY UP PAINT WORKS.		1,200.00	800.00
	TO CHECK WIRING.		50.00	30.00
	TO UNDERSEAL.	NOT NECESSARY	150.00	-
	TO REMOVE FRONT UNDERCARRIAGE.		350.00	220.00
	TO PERFORM WHEEL ALIGNMENT.		150.00	80.00
			3,100.00	1,730.00
	<b>GRAND TOTAL</b>		<b>11,143.40</b>	<b>6,581.20</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>5,250.00</b>

Report Ref No. CC4/ASM18012321/Aja3s2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.