



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18012342/Uea3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 30-06-2020



ATTN: WINNIE HO

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKD 558G	Veh. Inspected	SLU 8645J
Policy No.		Coverage (\$)	0.00
Claim No.	S8M00NJA	Excess (\$)	0.00
Assign From	WINNIE HO	Assign Date	06/07/2018

2. Vehicle Particulars & Condition

Make & Model	MAZDA 5 (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JM6CW1071H0127488	Colour	WHITE
Odometer	7847	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	TOYO	6 mm
L/H Front Tyre	205/55 R16	TOYO	6 mm
R/H Rear Tyre	205/55 R16	TOYO	6 mm
L/H Rear Tyre	205/55 R16	TOYO	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/07/2018	Inspection Date	11/07/2018
Survey held at	PROGRESSIVE AUTOMOTIVE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**