

INSURER

INS. CASE OWNER:

CC³ /AIG1801 2347 A w639

LKK

IDAC

Surveyor:

Adrian

DOI:

ASSIGNMENT

11/1/18

Date / Time:

6/1/18

Registered in Merimen:

6/1/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

DJF 2150L

Name of Insured:

FOM HAR YONG

Insured Tel No.:

HP: 90701100

Excess Sec II :SS

D.O.A: 6/1/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

V33098707856

Policy No.:

700406126-03

Make / Model:

INFINITI

Place of Accident:

PIB

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SLW 533TH



INSRS:

WSP:

Tel:

Liability:

RMKS:

premium



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

10/1/18

inman

11/1/18

to firm accident details. inform TP claim. later find out

RECEIVED 27 NOV 2018

STAGE

DATE / PIC

Non-Reporting 1st (1st):

Non-Reporting 1st (2nd):

Non-Reporting 1st (Final):

Notification 1st (if non-pickup):

Call OI:

After call 1st to OI:

Documentation Check List: Handler Typist

Notification 1st (if non-pickup):

After call 1st to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others: NPIC

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28. Ass. Lia:

Repair Cost:

SS 6319.85

Loss of Rental (LOR):

SS

(days)

Loss of Use (LOU):

SS

180.00 15 60 x 3 days

Loss of Income (LOI):

SS

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

LOR + LOU

GIA/LTA Search

SS

2.00

Medical:

SS

-

Disbursement:

SS

-

Legal Cost:

SS

-

(e.g. Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

6501.85

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

6321.85

Name 1:

Premium Automobiles Pte Ltd

Payee 2: (Strike if N.A.)

SS

180.00

Name 2:

Low Wai Mung

Payee 3: (Strike if N.A.)

SS

ASSIGNMENT REC. BY: Adrian King

REF:

W

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03/18/18 days Res.: Yes or NoLum Sum: 2-B/1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLW5337H Yr Regn: 2018, FebType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi TT C.C. 1798Colour: Red A/C: Insured / Std / NI / NASp. Reading: 6237 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: TRU222FV4J1005345Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 245/40R18R: 245/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Hankook

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 11/07/18Survey held at PremiumDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP ALG

8/10/18 Confirm 2-B > \$5906.40 with 3 working days

(Red - \$3941.10
40%)

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

(112)

Report Format :

Lump Sum / L.B.L. (%)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18012347/wb3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 06-07-2018	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJF 2150L	Veh. Inspected	SLW 5337H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	06/07/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	06/07/2018	Inspection Date	
Survey held at	PREMIUM AUTOMOBILES PTE LTD 55 UBI ROAD 1 . SINGAPORE 408699		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0779/2018/GW
Date	:	07-Jul-18

Vehicle NOT in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Low Wai Mung
Address	:	23 Jalan Rajah #08-02 Singapore 329138
Telephone	:	HP +65 97641499
Type of Claim	:	Third Party Claims
Policy No.	:	1800015962
Vehicle No	:	SLW 5337 H
Model Code	:	Audi T T coupe 1.8 TFSI S
Model / Year	:	Feb-18
Engine No	:	CJS 228096
Chassis No	:	TRUZZZFV4J1005045
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	06-Jul-18
Place of Accident	:	PIE Twds Tuas at Clementi Rd Exit 26 A

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLW 5337 H.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N S 280.00	✓
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	S 900.00 550	
3	To respray rear bumper.	S 900.00 550	
4	To remove and renew rear exhaust silencer. Align to position.	S/N S 480.00	✗
5	To carry out diagnostic checks.	S/N S 192.00	✓
TOTAL LABOUR CHARGES		: <u>\$ 2,752.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLW 5337 H.

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
1	REAR BUMPER <i>Deland</i>	\$	1,907.00 ✓	1525.60
2	REAR BUMPER FIXING PARTS <i>Not new</i>	\$	234.00 x	
3	REAR BUMPER SPOILER <i>Lot</i>	\$	246.00 ✓	196.80
4	REAR BUMPER COVER TRIM-LH/RH <i>Not new</i>	2 \$	44.00 x	
5	REAR BUMPER CLOSING ELEMENT <i>Not new Damaged</i>	\$	124.00 x	99.20
6	REAR BUMPER CENTRE PLATE MOUNT KIT <i>Not new</i>	\$	51.00 x	
7	REAR BUMPER UPPER GUIDE SECTION-LH/RH <i>Not new</i>	2 \$	108.00 x	
8	REAR BUMPER GUIDE SECTION-LH/RH <i>Not new</i>	2 \$	64.00 x	
9	REAR BUMPER LOW GUIDE SECTION-LH/RH <i>Not new</i>	2 \$	96.00 x	
10	REAR BUMPER SIDE REINFORCEMENT-LH/RH <i>Not new</i>	2 \$	786.00 ✓	628.40
11	REAR BUMPER HOLDING STRAP-LH/RH <i>Not new</i>	2 \$	108.00 x	
12	REAR SENSOR <i>Not new</i>	2 \$	421.00 x	
13	REAR SENSOR SEAL RING <i>Not new</i>	4 \$	14.00 x	
14	TAIL LIGHT-LH <i>Lot</i>	\$	1,293.00 ✓	1034.40
15	TAIL LIGHT TRIM-LH <i>Not new</i>	\$	26.00 x	
16	REAR SILENCER <i>Not new</i>	\$	982.00 x	
17	REAR SILENCER DUAL CLIP <i>Not new</i>	\$	50.00 x	
18	REAR SILENCER TRIM-LH <i>Not new</i>	\$	117.00 x	
19	SUNDRIES <i>Not new</i>	\$	400.00 x	
20	REAR CAR PLATE NO. <i>Not new</i>	S/N \$	25.00 x	
TOTAL SPARE PARTS CHARGES		:	\$ 7,096.00	
TOTAL LABOUR CHARGES			\$ 2,752.00	
GRAND TOTAL			\$ 9,848.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315	Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0779/2018/GW 25-Jul-18 jb one SLW5337H TT COUPE 1.8TFSI
--	---	--

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
		\$ -	
<u>LABORS</u>			
1	To repair and respray rear panel	\$ 1,200.00	\$ 900.00 ✓
TOTAL		\$ 1,200.00	\$ 900.00

For Premium Automobiles Pte Ltd

Adrian Ling


Authorised Signature



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

:

Adrian King

Surveyed Date

:

11/07/18

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

Not Authorised, 03 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

:

This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0779/2018/GW
Date : 7-Jul-18

Vehicle NOT in workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

3 days - ok - jb - 17 Sep 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Low Wai Mung
Address : 23 Jalan Rajah
#08-02
Singapore 329138
Telephone : HP +65 97641499
Type of Claim : Third Party Claims
Policy No. : 1800015962
Vehicle No : **SLW 5337 H**
Model Code : Audi T T coupe 1.8 TFSI S
Model / Year : Feb-18
Engine No : CJS 228096
Chassis No : TRUZZZFV4J1005045
Mileage :
Date In :
Liability :
Excess Cost :
Estimated By : Johnny Boo / Allan Wu
Accident Date : 6-Jul-18
Place of Accident : PIE Twds Tuas at Clementi Rd Exit 26 A

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLW 5337 H.

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N	\$ 280.00	\$ 280.00 ✓
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.		\$ 900.00	\$ 500.00 ✓
3	To respray rear bumper.		\$ 900.00	\$ 550.00 ✓
4	To remove and renew rear exhaust silencer. Align to position.	S/N	\$ 480.00	
4a	To repair and respray rear end panelling		\$ 1,200.00	\$ 900.00
5	To carry out diagnostic checks.	S/N	\$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 3,952.00</u>	<u>\$ 2,422.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SLW 5337 H.**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	REAR BUMPER	\$ 1,907.00	\$ 1,525.60
2	REAR BUMPER FIXING PARTS	\$ 234.00	
3	REAR BUMPER SPOILER	\$ 246.00	\$ 196.80
4	REAR BUMPER COVER TRIM-LH/RH	2 \$ 44.00	
5	REAR BUMPER CLOSING ELEMENT	\$ 124.00	\$ 99.20
6	REAR BUMPER CENTRE PLATE MOUNT KIT	\$ 51.00	
7	REAR BUMPER UPPER GUIDE SECTION-LH/RH	2 \$ 108.00	
8	REAR BUMPER GUIDE SECTION-LH/RH	2 \$ 64.00	
9	REAR BUMPER LOW GUIDE SECTION-LH/RH	2 \$ 96.00	
10	REAR BUMPER SIDE REINFORCEMENT-LH/RH	2 \$ 786.00	\$ 628.40
11	REAR BUMPER HOLDING STRAP-LH/RH	2 \$ 108.00	
12	REAR SENSOR	2 \$ 421.00	
13	REAR SENSOR SEAL RING	4 \$ 14.00	
14	TAIL LIGHT-LH	\$ 1,293.00	\$ 1,034.40
15	TAIL LIGHT TRIM-LH	\$ 26.00	
16	REAR SILENCER	\$ 982.00	
17	REAR SILENCER DUAL CLIP	\$ 50.00	
18	REAR SILENCER TRIM-LH	\$ 117.00	
19	SUNDRIES	\$ 400.00	
20	REAR CAR PLATE NO.	S/N \$ 25.00	
TOTAL SPARE PARTS CHARGES		\$ 7,096.00	\$ 3,484.40
TOTAL LABOUR CHARGES		\$ 3,952.00	\$ 2,422.00
GRAND TOTAL		\$ 11,048.00	\$ 5,906.40

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : LOW WAI MUNG
Period of Insurance : 20 Feb 2018 To 19 Feb 2019
Engine No. : CJS228096
Chassis No. : TRUZZZFV4J1005045

Vehicle No. : SLW5337H
Policy No. : 1800015962
Endorsement No. :
Issued Date : 20 Feb 2018

ABOUT THE COVER

Make/Model : AUDI TTC 1.8 TFSI
Engine Capacity/Tonnage : 1,798.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2018
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$1200 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

LOW WAI MUNG - \$1200 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408689 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189) Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125223

PREMIUM LEASING - SH
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.



Manik

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

BREAKDOWN OF PAYMENT

Vehicle No: SLW5337H

Accident on 06/07/2018 at PIE TWDS TUAS AT CLEMENTI RD EXIT 26A

Involving vehicle/s SJF2150L

1) Repair cost \$ 61319.85 Payable to: Premium Automobiles Pte Ltd

2) GIA/LTA search fee \$ 2.00 Payable to: Premium Automobiles Pte Ltd

3) Loss of Use or Rental Car \$ 180.00 Payable to: LOW WAI MUNG

4) Medical fees \$ _____ Payable to: _____

5) Others \$ _____ Payable to: _____

Premium Automobiles



AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: CC3/AIG18012347/wb3

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/TP/0779/2018/MAS

17 Nov 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

total pages

RE: INSURANCE CLAIM FOR SLW 5337 H, Audi TT Coupe 1.8 TFSI S-Tro

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SLW 5337 H**, claimant, **Mr. Low Wai Mung**, please find the related document as per attached.

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

1. A copy of the Original invoice no. 85013094 – S\$6,319.85
2. A copy of Authorization to Act duly signed by client
3. A copy of the Release Voucher attached
4. A copy of Breakdown of Payment attached
5. Loss of Use – S\$180.00 (S\$60.00 x 3 working days)
6. GIA Search Fee – S\$2.00

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLW 5337 H



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18012347/wb3

12 July 2018

Koh Har Yong
5A Kovan Road
#15-24
Singapore 544895

Dear Sir/Madam,

ACCIDENT INVOLVING SJF 2150L AND SLW 5337H ON 06/07/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd. to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

Vivian Lau
Case Handler
DID: 6841 8625
FAX: 6741 4108
EMAIL: Vivianlau@lkkauto.com

c.c. AIG Asia Pacific Insurance Pte Ltd
(Motor Claims Dept)

AUTHORISATION TO ACT
(AIG Express Third Party Claim)

I, LOW WAI MUNG (the third party claimant) of 23 JALAN RAJAH
#08-02, SINGAPORE 329138 (address), owner of SLW5337H (vehicle no.)
hereby authorize PREMIUM AUTOMOBILES PTE LTD ("the workshop") to act for me
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle
no. SLW5337H that was damaged pursuant to the accident which occurred on 06/07/2018
(date) along PIE TWDS TUAS AT CLEMENTI RD EXIT 26A (location) involving vehicle no/s
SJF2150L ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 30 (day) of JULY (month) 2018 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Express Third Party Claim)

"We/I, PREMIUM AUTOMOBILES PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$ 6319.85 (Repair Cost), S\$ 180.00 (Loss of rental use), S\$ 2.00 (Disbursement), for vehicle no. SLW5337H that was damaged pursuant to the accident which occurred on 06/07/2018 (date) along PIE TWDS TUAS AT CLEMENTI RD EXIT 26A (location) involving vehicle no/s SJF2150L. This is pursuant to the inspection conducted on 17/18 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner LOW WAI MUNG ("the third party claimant") of vehicle no. SLW5337H make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLW5337H (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 26 (day) of 11 (month) 2018 (year)

Lwf


Signed by appointed surveyor



Signed by "the workshop" (with chop)



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119908
Main Telephone: 6886 2223
Main Telefax: 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 119908
Telephone: 6886 2223
Telefax: 6471 3733

UBI Service Centre
55 Ubi Road 1
Singapore 408823
Telephone: 6342 1111
Telefax: 6342 1111

Customer Service
Service Appointment
24-hour Breakdown Service
Email: customer.care@premiumauto.com.sg
6346 1313
6828 1313

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

Page 1 11:05

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013094 Date : 08/11/2018 Order : SLW5337H Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLW5337H (V 35709) Regn Date: 20/02/2018 Mileage: 6857 WIP No.: 16465

Model: TT COUPE 1.8 TFSI S tronic FV3 Chassis: TRUZZZFV4J1005045 Engine: CJS 228096 Dept: U

VSB No.:

You have been assisted by :- UB-Carrine (43)

		Details	Qty	Unit Price	Amount
S	BODYWORK	N: TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION.	280.00	1.00	280.00
S	BODYWORK	N: TO DISMANTLE AND REPAIR REAR BUMPER. RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	500.00	1.00	500.00
S	BODYWORK	N: TO RESPRAY REAR BUMPER.	550.00	1.00	550.00
S	BODYWORK	N: TO CARRY OUT DIAGNOSTIC CHECKS.	192.00	1.00	192.00
S	BODYWORK	N: TO REPAIR AND RESPRAY REAR PANEL.	900.00	1.00	900.00
X	ABS0945095	TAILLIGHT (SK) (A) Less 020%	1.00	1293.00	1,034.40
X	ABS0807521	SPOILER Less 020%	1.00	246.00	196.80
X	ABS0807385	PLATE Less 020%	1.00	124.00	99.20
X	ABS0807309	BEAM Less 020%	1.00	785.50	628.40
X	ABS0807067A GRU	COVER (SK) (A) Less 020%	1.00	1907.00	1,525.60

Parts 3,484.40
Labour 0.00
Sublet 2,422.00
Menus 0.00
Lubricant 0.00

Sub-Total 3,906.40

7% GST 413.45

Grand Total 6,319.85



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-103114

Date of Request: 06/07/2018

Your Ref No:

Online Purchase

Premium Automobiles Pte Ltd
55 Ubi Road 1
Singapore 408699

Dear Sir/Madam,

Enquiry Date 06/07/2018
Enquiry By Tony Foong Chin Fong
TP Vehicle No. SJF2150L
Accident Date 06/07/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJF2150L	AIG Asia Pacific Insurance Pte. Ltd.	17/03/2018-16/03/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-103114

Date of Request: 06/07/2018

Your Ref No:

Online Purchase

Premium Automobiles Pte Ltd
55 Ubi Road 1
Singapore 408699

Dear Sir/Madam,

Enquiry Date 06/07/2018
Enquiry By Tony Foong Chin Fong
TP Vehicle No. SJF2150L
Accident Date 06/07/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ [X] GIRO ☐ [] Cash ☐ [] Cheque

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S6926397F



LOW WAI MUNG

刘伟文

CHINESE
Date of Birth: 31-07-1969
Country of Birth: SINGAPORE
Sex: M

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number S7323445Z

LEE CHAI YEN
(LI CAIYAN)

Birth Date: 03 Jul 1973
Issue Date: 25 Jan 2005



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7323445Z



LEE CHAI YEN
(LI CAIYAN)

李彩燕

CHINESE
Date of Birth: 03-07-1973
Country of Birth: SINGAPORE
Sex: F

2408172

NRIC No: S6926397F

Blood Group: A+ Date of issue: 21-09-1994

23 JALAN RAJAH #08-02
SINGAPORE 329138

NRIC No: S6926397F Date: 16/08/2012 No: 7108147

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3A Motor cars without clutch pedals <= 3000kg with <= 7 passengers, exclusive of the driver, and motor tractors/vehicles without clutch pedals <= 2500 kg

PASS DATE
25 Jan 2005



NP 428A

1436374

NRIC No: S7323445Z

Blood Group: A+ Date of issue: 16-11-1993

23 JALAN RAJAH #08-02
SINGAPORE 329138

NRIC No: S7323445Z Date: 16/08/2012 No: 7108148

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Jul 2018 Edit Reg		11 Jul 2018 00:00 Edit Adj Rpt	S\$5,906.40 Edit Estimates	S\$5,906.40 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	KOH HAR YONG , ID: 57415940J								
Main Claimant:	LOW WAI MUNG , ID: S6926397F								
Vehicle Reg. No.:	SLW5337H	Date of Loss:	06/07/2018 06:00 - :59 [4 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 2330989078SG	Policy/Cover Note No.:	2100406136 (Comprehensive) Coverage: 17/03/2018 - 16/03/2019						
Vehicle Reg. No. (Insured):	SJF2150L	Policy No. (Claimant):	1800015962						
		Excess:							
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 17/07/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLW5337H (2330989078SG)
[SJF2150L]
TP
LOW WAI MUNG
Jul 6 2018 6:00AM
[KOH HAR YONG]
Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page v ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		
1	(Draft)	Third Party Express Settlement - Payment Breakdown	1	Thumbnail Print
Photos/Images			3 per page v ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
1	27/09/18 19:16	General View	1	Load JPG ☒
2	27/09/18 19:16	General View	1	Load JPG ☒
3	27/09/18 19:16	General View	1	Load JPG ☒
4	27/09/18 19:16	General View	1	Load JPG ☒
5	27/09/18 19:16	General View	1	Load JPG ☒
6	27/09/18 19:16	General View	1	Load JPG ☒
7	27/09/18 19:16	General View	1	Load JPG ☒
8	27/09/18 19:16	General View	1	Load JPG ☒
9	27/09/18 19:16	General View	1	Load JPG ☒
10	27/09/18 19:16	General View	1	Load JPG ☒
11	27/09/18 19:16	General View	1	Load JPG ☒
12	27/09/18 19:16	General View	1	Load JPG ☒
13	27/09/18 19:16	General View	1	Load JPG ☒
14	27/09/18 19:16	Reinspection Photo	1	Load JPG ☒
15	27/09/18 19:16	Reinspection Photo	1	Load JPG ☒
16	27/09/18 19:16	Reinspection Photo	1	Load JPG ☒
17	27/09/18 19:16	Reinspection Photo	1	Load JPG ☒
18	27/09/18 19:16	Reinspection Photo	1	Load JPG ☒
19	27/09/18 19:16	Reinspection Photo	1	Load JPG ☒
20	27/09/18 19:16	Reinspection Photo	1	Load JPG ☒
21	27/09/18 19:16	Reinspection Photo	1	Load JPG ☒
22	27/09/18 19:16	Reinspection Photo	1	Load JPG ☒
23	27/09/18 19:16	Reinspection Photo	1	Load JPG ☒
24	27/09/18 19:16	Reinspection Photo	1	Load JPG ☒
25	27/09/18 19:16	Reinspection Photo	1	Load JPG ☒
26	27/09/18 19:16	Reinspection Photo	1	Load JPG ☒
27	27/09/18 19:16	Reinspection Photo	1	Load JPG ☒
28	27/09/18 19:16	Reinspection Photo	1	Load JPG ☒
29	27/09/18 19:16	Reinspection Photo	1	Load JPG ☒
30	27/09/18 19:16	Reinspection Photo	1	Load JPG ☒
31	27/09/18 19:16	Reinspection Photo	1	Load JPG ☒
32	27/09/18 19:16	Reinspection Photo	1	Load JPG ☒
33	27/09/18 19:16	Reinspection Photo	1	Load JPG ☒
34	27/09/18 19:16	Reinspection Photo	1	Load JPG ☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/07/18 16:03	TP GIA REPORT	 Load PDF	
2	12/07/18 17:34	TP ESTIMATE- MARKED	 Load PDF	
3	28/11/18 09:50	WORKSHOP INVOICE	 Load PDF	
4	28/11/18 09:50	AUTHORISATION TO ACT FORM	 Load PDF	
5	28/11/18 09:50	Release Voucher	 Load PDF	
6	28/11/18 09:50	GIA SEARCH	 Load PDF	
7	28/11/18 09:50	IC	 Load PDF	
8	28/11/18 09:50	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	09/07/18 11:05	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

TEAM _____

Vehicle No:	SJF2150L (Insd veh)	Model:	AUDI TT COUPE 1.8T (A)
	SLW5337H (TP veh)		
Date of Accident:	06/07/2018		

Global Sum Settlement	:	☐ Yes	☒ No	
Repair Estimate	:	\$	11,821.36	
Final Repair Cost	:	\$	6,319.85	
Loss of Use	:	\$	180.00	3.00 days at \$60.00 per day
Rental (if any)	:	\$	0.00	days
LTA / GIA Search Fee	:	\$	2.00	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	6,501.85	

A) For <u>Non GIA Registered Workshop:</u>	Agreed Liability _____ (%)
B) For <u>GIA Registered Workshop:</u>	BOLA Applicable: Yes/ No —BOLA Scenario No: _____27_____
BOLA Liability: _____100_____ (%)	Assessed Liability (*): _____ (%)
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.	

Remarks	

1)	Premium Automobiles Pte Ltd	: \$	6,321.85
2)	Low Wai Mung	: \$	180.00
3)		: \$	

28 Nov
2018

Date _____

https://singapore.merimen.com/claims/index.cfm?fusebox=SVCdoc&fuseaction=dsp_doc... 28/11/2018

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18012347/AWB3Q2

Date: 28/11/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100406136
Claimant Vehicle No : SLW5337H **Insured Vehicle No :** SJF2150L
 Date of Loss: 06/07/2018 Nature of Claim: TP Claim No: 2330989078SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLW5337H**
 Make & Model: AUDI TT, COUPE 1.8T (A) Engine No: CJS228096
 Reg. Date: 20/02/2018 (Man. Year: 2017) Chassis No: TRUZZZFV4J1005045
 Colour: Red Odometer: 6237 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18 Rear Tyre Size: 245/40 R18
 Front Left Side: Hankook 6 mm Rear Left Side: Hankook 6 mm
 Front Right Side: Hankook 6 mm Rear Right Side: Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,096.00	3,484.40	3,611.60	50.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,952.00	2,422.00	1,530.00	38.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,048.00	5,906.40	5,141.60	46.54
+ GST 7.00/7.00% (S\$)	773.36	413.45	359.91	46.54
Nett Amount (S\$)	11,821.36	6,319.85	5,501.51	46.54
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,501.85		

INSPECTION

Date of Assignment: 11/07/2018
 Date Inspected: 11/07/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
 55 Ubi Road 1
 Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING**Manager:** VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,907.00 FS	*1,525.60 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	234.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Cut	246.00 FS	*196.80 FS
4	2		*REAR BUMPER COVER TRIM -LH/RH	Not Necessary	44.00 FS	*- FS
5	1		*REAR BUMPER CLOSING ELEMENT	Damaged	124.00 FS	*99.20 FS
6	1		*REAR BUMPER CENTRE PLATE MOUNT KIT	Not Necessary	51.00 FS	*- FS
7	2		*REAR BUMPER UPPER GUIDE SECTION -LH/RH	Not Necessary	108.00 FS	*- FS
8	2		*REAR BUMPER GUIDE SECTION -LH/RH	Not Necessary	64.00 FS	*- FS
9	2		*REAR BUMPER LOW GUIDE SECTION -LH/RH	Not Necessary	96.00 FS	*- FS
10	2		*REAR BUMPER SIDE REINFORCEMENT -LH/RH	Bent	786.00 FS	*628.40 FS
11	2		*REAR BUMPER HOLDING STRAP -LH/RH	Not Necessary	108.00 FS	*- FS
12	2		*REAR SENSOR	Not Necessary	421.00 FS	*- FS
13	4		*REAR SENSOR SEAL RING	Not Necessary	14.00 FS	*- FS
14	1		*TAIL LIGHT-LH	Cut	1,293.00 FS	*1,034.40 FS
15	1		*TAIL LIGHT TRIM -LH	Not Necessary	26.00 FS	*- FS
16	1		*REAR SILENCER	Not Necessary	982.00 FS	*- FS
17	1		*REAR SILENCER DUAL CLIP	Not Necessary	50.00 FS	*- FS
18	1		*REAR SILENCER TRIM -LH	Not Necessary	117.00 FS	*- FS
19	1		*SUNDRIES	Not Necessary	400.00 FS	*- FS
20	1		*REAR CAR .PLATE NO	Not Necessary	25.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **7,096.00** **3,484.40**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID,CHECL FUNCTION	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER .RE-ORGANISE REAR CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	900.00	500.00
3	TO RESPRAY REAR BUMPER	New	900.00	550.00
4	TO REMOVE AND RENEW REAR EXHAUST SILENCER .ALIGN TO POSITION	New	480.00	0.00
5	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
6	TO REPAIR AND RESPRAY REAR PANEL	New	1,200.00	900.00
Gross Labour Cost (\$\$)			3,952.00	2,422.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >