

REF: CC31 AG 18012362 / Ag 1312

ISS. REC. BY: Adrian Ling

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

13 days

days

Res.: Yes or No

Lump Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLZ6276C Yr Regn: 2018 May

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

Audi Q3

C.C 1395

Colour: _____

Blue

A/C: Insured / Std / NI / NA

Sp. Reading: _____

3722

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

WAUZZZ8U4JR004880

Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F: _____

235/55R17

R: _____

235/55R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

Front

Rear

R/Bal. _____

06

mm

R/Bal. _____

06

mm

L/Bal. _____

06

mm

L/Bal. _____

06

mm

D.O.A. _____

D.O.I. _____

05/07/18

Survey held at _____

Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

ODALG.

No policy number - cannot open merimen.

Revert via merimen

25/11/18 @ 10:12am Victor informed C/A via Merimen.

25/11/18 @ 1:03pm Informed Puna C/A by exs to 15th by email.

12/11/18 @ 10:31am Confirmed with Carine final fig \$15300.64, 13 days -
 (Fed \$8569.76, 36%)

RECEIVED 27 NOV 2018

Date/Time, File Pass to?



: Preli. Report

1) 27/11/18



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 13

Resurvey No. of Trip: _____

Add Fee: ☐

Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Weekend (\$)

Report Format: _____

over 100

Lump Sum / I.B.I. (\$)

15300.64

Survey Fee: _____

Transportation: _____

G + RS. SI

Photos

Others

TOTAL

200

10

210

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Kesaval, Jaclyn-M

Date: 10 Jul 2018

Preliminary Advice

Vehicle No	: SLZ6276C	Accident Date	: 30/06/2018
Make	: AUDI Q3	Policy No.	:
Assignment Date	: 10/07/2018	Excess	: S\$0.00
Date of Inspection	: 05/07/2018	Est. Duration of Repair	: 13.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	23,690.00
Revised Amount	:S\$	15,940.00
Check Items (Estimated)	:S\$	1,199.00
Total	:S\$	17,139.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	160,000.00
COE / PARF Rebate	:S\$	65,694.00
Salvage Value	:S\$	
Margin for Repair	:S\$	94,306.00.

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 13 November 2018 10:31 AM
To: 'Carrine Leong'; SUR
Cc: 'Boo seng yak'; jiayee.yap@premiumauto.com.sg; 'Chang Chee Sing'
Subject: RE: FINAL REVISION - SLZ6276C - OD AIG - SURVEYED - 6 JUL 18

Dear Carrine,

WITHOUT PREJUDICE

Confirm final fig \$15,300.64 before excess \$1,500.00 & GST and 13 repair days.

Kindly expedite the discharge voucher and tax invoice to us for close case.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Carrine Leong <carrine.leong@premiumauto.com.sg>
Sent: Monday, 12 November 2018 10:06 AM
To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Boo seng yak' <boojohnny@gmail.com>; jiayee.yap@premiumauto.com.sg; 'Chang Chee Sing' <claims@premiumauto.com.sg>
Subject: RE: FINAL REVISION - SLZ6276C - OD AIG - SURVEYED - 6 JUL 18
Importance: High

Dear Adrian and all,

Reminder

We have yet receive your confirmation of repair cost and days of repair for above vehicle.

Revised estimate was mailed to you on 08 Oct 2018.

We sincerely appreciate your early closure.

Kindly assist to finalize the repair cost on urgent basis.

Thanks & Best Regard
Carrine Leong
Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9925 f. +65 6841 1183
e. carrine.leong@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 25 July 2018 1:03 PM
To: 'Claims Dept'; SUR
Subject: RE: RE : OD claim for SLZ 6276 C

Dear Phua,

As instructed by our client, please proceed to repair the insured vehicle **SLZ 6276C (Excess \$1,500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept <claims@premiumauto.com.sg>
Sent: Wednesday, 4 July 2018 11:48 AM
To: SUR <sur@lkkauto.com>
Cc: 'Claims Dept' <claims@premiumauto.com.sg>
Subject: RE : OD claim for SLZ 6276 C

Good morning all ,

Here are the attachment of GIA and estimate for your kind reference . Kindly assist for the claim .

Thank you .

Best Regards,

Phua

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 **d.** +65 6768 9911 **f.** +65 6841 1183

e. claims@premiumauto.com.sg **w.** www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 **p.** +65 6836 2223

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	02 Jul 2018 19:08	Clim Veh Model Changed		[] Merimen Administrator
2	02 Jul 2018 19:08	Clim Created	Reg No: SLZ6276C, Acct Date: 2018/06/30, Claim Type: SC, Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification, Created from SAS:MPA118085374	[I] Merimen Administrator
3	10 Jul 2018 09:34	Clim Registration Modified	Setl.Type:3->0, Claim Type:SC->OD.	[] CATHERINE CHONG KAI LING
4	10 Jul 2018 09:34	Adj Clim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] CATHERINE CHONG KAI LING
5	10 Jul 2018 09:34	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] CATHERINE CHONG KAI LING
6	10 Jul 2018 09:34	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/07/19	[A] CATHERINE CHONG KAI LING
7	10 Jul 2018 09:34	Adj Mandate Set	Approved:8000.00,Reinsp:Adj decides.	[A] CATHERINE CHONG KAI LING
8	10 Jul 2018 09:34	Clim Registration Modified	Rep:1137->200611.	[A] CATHERINE CHONG KAI LING
9	10 Jul 2018 09:34	Clim Veh Model Changed	(203438) AUDI Q3 1.4 TFSI (A).	[A] CATHERINE CHONG KAI LING
10	10 Jul 2018 09:34	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] CATHERINE CHONG KAI LING
11	10 Jul 2018 12:19	Adj Rpt Initiated		[A] DENISE TAY KWEE CHENG
12	10 Jul 2018 12:19	Clim Dtl Modified	JPJ Reg. Date: -> 2018/05/11.	[A] DENISE TAY KWEE CHENG
13	10 Jul 2018 12:19	Clim Details Notified		[A] DENISE TAY KWEE CHENG
14	10 Jul 2018 15:49	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/07/19	[A] DENISE TAY KWEE CHENG
15	10 Jul 2018 15:50	Adj Mandate Request	Cur.Req:17139.00:DAMAGE CONSISTENT REPAIR COST ECONOMICAL	[A] DENISE TAY KWEE CHENG
16	10 Jul 2018 16:30	Clim Registration Modified	Init.Est.:>5,000 - 6,000.	[I] Tr, Tinesh
17	24 Jul 2018 15:53	Clim Registration Modified	Excess: -> 1500.00, 2F Remarks: -> Not Applicable, GST: -> 7.00.	[I] Tr, Tinesh
18	24 Jul 2018 15:53	Label Added	(20226):Coverage Confirmed.	[A] Merimen Administrator
19	25 Jul 2018 10:12	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/07/19, Mandate Remarks: Re-inspection to be done for damage check and supplementary items / labour.	[I] Koh, Victor-CK
20	25 Jul 2018 10:12	Adj Mandate Set	Approved:15940.00:Re-inspection to be done for damage check and supplementary items / labour.Reinsp:Yes.	[I] Koh, Victor-CK

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1855414	10/07/2018 12:19	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SLZ6276C		10.70

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2271W
Vehicle Details	
Vehicle No.:	SLZ6276C
Vehicle to be Exported:	No
Intended De-registration Date:	10 Jul 2018
Vehicle Make:	AUDI
Vehicle Model:	Q3 1.4 TFSI S TRONIC (NAV)
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	CZD814493
Chassis No.:	WAUZZZ8U4JR004880
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$32,224.00
Original Registration Date:	11 May 2018
First Registration Date:	11 May 2018
Transfer Count:	0
Actual ARF Paid:	\$37,114.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 May 2028
PARF Rebate Amount:	\$27,835.00
Intended COE Rebate Details	
COE Expiry Date:	10 May 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$38,600.00
COE Rebate Amount:	\$37,859.00
Total Rebate Amount:	\$65,694.00

The information contained herein is correct as at 10 Jul 2018

OK

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **G0672245N**
 Name: **LI PENGZHOU**

Birth Date: **16 Jan 1985**
 Issue Date: **21 Feb 2017**
 Valid Till: **25/03/2022**



002658910A




EMPLOYMENT PASS
 Employment of Foreign Manpower Act (Chapter 91A)
 Republic of Singapore

Employer:
LAU (INTERNATIONAL) DISTRIBUTION PTE. LTD.

Name:
LI PENGZHOU
 FIN:
G0672245N

K0512340



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class	Description	Effective Date
Class 3	Motor cars with unladen weight $\leq 3000\text{kg}$ with ≤ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight $\leq 2500\text{kg}$	26 Mar 2012

NP 428A

Licence No: G0672245N



VISIT PASS
 Immigration Regulations

22-06-2018

Name:
LI PENGZHOU

FIN:
G0672245N

Date of Birth: **16-01-1985** Sex: **M**

Nationality:
CHINESE

MULTIPLE JOURNEY VISA ISSUED

Download SGWorkPass App to check status




YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.





HOTLINE TEL: (65) 6416-3000
FAX: (65) 6415-3721

COVER NOTE

Cover Note No. 100862460		Date 3 Jul 2018	
The following risk described in the Schedule is hereby HELD COVERED in the terms of the applicable Company's policy issued to the Policyholder.			
SCHEDULE			
Policyholder	Premium Automobiles Pte Ltd		
Age Condition	N/A	Registration No	SLZ6276C
Policy Type	COMPREHENSIVE COMMERCIAL MOTOR	Make/Model	Audi Q3 1.4 TFSI
Effective Date	11 May 2018	CC/Tonnage	1,395.00
Expiry Date	25 Dec 2018	Engine No	CZD814493
Hire Purchase Company	NA	Chassis No	WAUZZZ8U4JR004680
		Year of Registration	2018
			
<p>This policy is subject to driver's age condition. The policy will indemnify the insured or any authorised driver only if he/she meets the age condition. Please refer to policy terms and conditions.</p> <p>Usage of vehicle only for the following purposes:</p> <ol style="list-style-type: none">1. Use only for social, domestic and pleasure purposes and for the Policyholder's business.2. Use in connection with the Policyholder's business. Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business and use for social, domestic or pleasure purposes. <p>Please note that acceptance of the risk is subject to our final acceptance and terms and conditions applicable to the policy. Should you require any change to the insurance, please contact us immediately. Otherwise, any change will not be covered under the policy.</p> <p>The Company may cancel this cover by notice in writing and the insurance will be terminated and a proportionate part of the annual premium for the insurance will be charged for the time the Company has been on risk.</p>			
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189) MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA) MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)			
CERTIFICATE OF INSURANCE			
I/We hereby certify that this cover note is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)			

Issued at SINGAPORE

AIG ASIA PACIFIC INSURANCE PTE. LTD.

IMPORTANT NOTICE
THIS COVER NOTE IS VALID FOR
60 DAYS FROM THE FIRST DAY OF
THE POLICY PERIOD.



Authorised Representative

SS/PYTP



HOTLINE TEL.: (65) 6419-3000
FAX: (65) 6415-3723

COVER NOTE

Cover Note No. 100862460		Date 3 Jul 2018	
The following risk described in the Schedule is hereby HELD COVERED in the terms of the applicable Company's policy issued to the Policyholder.			
SCHEDULE			
Policyholder	Premium Automobiles Pte Ltd		
Age Condition	N/A	Registration No	SLZ6276C
Policy Type	COMPREHENSIVE COMMERCIAL MOTOR	Make/Model	Audi Q3 1.4 TFSI
Effective Date	11 May 2018	CC/Tonnage	1,395.00
Expiry Date	25 Dec 2018	Engine No	CZD814493
Hire Purchase Company	NA	Chassis No	WAUZZZ8U4JR004880
		Year of Registration	2018
			
<p>This policy is subject to driver's age condition. The policy will indemnify the insured or any authorised driver only if he/she meets the age condition. Please refer to policy terms and conditions.</p> <p>Usage of vehicle only for the following purposes:</p> <ol style="list-style-type: none">1. Use only for social, domestic and pleasure purposes and for the Policyholder's business.2. Use in connection with the Policyholder's business. Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business and use for social, domestic or pleasure purposes. <p>Please note that acceptance of the risk is subject to our final acceptance and terms and conditions applicable to the policy. Should you require any change to the insurance, please contact us immediately. Otherwise, any change will not be covered under the policy.</p> <p>The Company may cancel this cover by notice in writing and the insurance will be terminated and a proportionate part of the annual premium for the insurance will be charged for the time the Company has been on risk.</p>			
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189) MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA) MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)			
CERTIFICATE OF INSURANCE			
I/We hereby certify that this cover note is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)			

Issued at SINGAPORE

AIG ASIA PACIFIC INSURANCE PTE. LTD.

IMPORTANT NOTICE
THIS COVER NOTE IS VALID FOR
60 DAYS FROM THE FIRST DAY OF
THE POLICY PERIOD.



Authorised Representative

SSPYTP

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0750/2018/KS
Date : 3-Jul-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : PREMIUM AUTOMOBILES PTE LTD
Address : 55 UBI ROAD 1

Singapore 408699
Telephone : HP +65 6366 2323
Type of Claim : OWN DAMAGE CLAIM
Policy No. :
Vehicle No : **SLZ 6276 C**
Model Code : Audi Q3 Sedan 1.4 TFSI
Model / Year : May-18
Engine No : CZD 814493
Chassis No : WAUZZZ8U4JR004880
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 30-Jun-18
Place of Accident : LIANG COURT CARPARK

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLZ 6276 C.

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00 ✓
2	To remove and transfer lhs rear door's multi lock-system and power window devices	S/N \$ 280.00 ✓
3	To remove and reinstall rear seats, back rest, ABCD pillar trims, roof liner, hat trays, carpets, curtain air bag and sill trims.	S/N \$ 1,400.00 ✓
4	To remove and renew lhs quarter glass and rear windscreen for fender renewal	S/N \$ 600.00 ²⁰⁰ 150. ✓
5	To remove and reinstall rear wire harness for tail light, fuse units, battery manager, fuse and relays tray, and electrical components	S/N \$ 1,400.00 ✓
6	To dismantle rear bumper, lhs rear door and both wheel arch cover. Cut out and reweld lhs rear fender. Renew lhs rear door. Transfer old fittings and align to position	\$ 6,000.00 ³⁵⁰⁰ ✓
7	To respray lhs rear fender, lhs rear doors, door entrances, and roof channels. To carry out joint sealer works and stone chip treatments.	\$ 2,500.00 ¹⁶⁵⁰ ✓
8	To carry out diagnostic check.	S/N \$ 192.00 ✓
TOTAL LABOUR CHARGES		<u>\$ 12,652.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLZ 6276 C

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR FENDER - LH <i>Dented</i>	\$ 3,310.00	✓ 2648
2	WHEEL HOUSING LINER - LH <i>new</i>	\$ 215.00	✓
3	WHEEL HOUSING ATTACHMENT <i>Not New.</i>	\$ 132.00	? X
4	WHEEL COVER REAR LH / RH <i>new</i>	2 \$ 454.00	✓ 363.70
5	REAR DOOR LH <i>Dented</i>	\$ 2,294.00	✓ 1835.70
6	DOOR SEAL - OUTER <i>new</i>	\$ 150.00	✓ 119.60
7	DOOR SEAL BRACKET <i>new</i>	\$ 16.00	? 12.40 ✓
8	DOOR ATTACHMENTS <i>Not New.</i>	\$ 187.00	? X
9	DOOR CATCH <i>new</i>	\$ 105.00	X
10	DOOR CATCH COVER <i>new</i>	\$ 14.00	✓
11	DOOR HANDLE, EXTERIOR <i>Repair</i>	\$ 131.00	X
12	MOUNTING BAR <i>Not New</i>	\$ 106.00	X
14	POWER WINDOW REGULATOR <i>new</i>	\$ 242.00	✓
15	REAR WINDOW <i>Not New</i>	\$ 818.00	X
16	QUARTER GLASS <i>new</i>	\$ 299.00	? 239.20 ✓
17	QUARTER GLASS CHROME TRIMS <i>Not New.</i>	\$ 265.00	? X
18	REAR WINDSCREEN SEALANT <i>Not New</i>	S/N \$ 200.00	✓
19	1/4 GLASS SEALANT <i>new</i>	S/N \$ 100.00	✓
20	ARCYLIC SEALANT <i>new</i>	S/N \$ 180.00	✓
SUB-TOTAL SPARE PARTS		\$ 9,218.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLZ 6276 C

S/N	Parts Description	Damage Pa S/NETT
21	CAVITY WAX	S/N \$ 140.00 ✓
22	STONE CHIP TREATMENT	S/N \$ 180.00 ✓
23	METAL FILLER POWDER	S/N \$ 280.00 ✓
24	SUNDRIES	\$ 300.00 ? 20.64 ✓
TOTAL SPARE PARTS		: \$ 10,118.00
TOTAL LABOUR CHARGES		: \$ 13,572.00 12652
GRAND TOTAL		: \$ 23,690.00 22790

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

22950.40

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adnan Ling
Surveyed Date : 05/07/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 13 Aug

LKK Auto Consultants hence notify the Repairer of the following:

- To be resurveyed after repair painting
- To be resurveyed after repair painting resurvey
- To be resurveyed after repair painting resurvey
- Third party survey on "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0750/2018/KS
Date : 3-Jul-18

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

13 days - ok - jb - 8 Oct 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

FOR URGENT CLOSURE

Owner's Name : PREMIUM AUTOMOBILES PTE LTD
Address : 55 UBI ROAD 1

Singapore 408699

Telephone : HP +65 6366 2323
Type of Claim : OWN DAMAGE CLAIM
Policy No. :
Vehicle No : **SLZ 6276 C**
Model Code : Audi Q3 Sedan 1.4 TFSI
Model / Year : May-18
Engine No : CZD 814493
Chassis No : WAUZZZ8U4JR004880
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 30-Jun-18
Place of Accident : LIANG COURT CARPARK

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLZ 6276 C.

S/N	Nature of Jobs	Estimated Charges			
1	To remove and transfer rear parking aid. Check function.	S/N	\$	280.00	\$ 280.00
2	To remove and transfer lhs rear door's multi lock-system and power window devices	S/N	\$	280.00	\$ 280.00
3	To remove and reinstall rear seats, back rest, ABCD pillar trims, roof liner, hat trays, carpets, curtain air bag and sill trims.	S/N	\$	1,400.00	\$ 1,400.00
4	To remove and renew lhs quarter glass and rear windscreen for fender renewal	S/N	\$	600.00	\$ 300.00
5	To remove and reinstall rear wire harness for tail light, fuse units, battery manager, fuse and relays tray, and electrical components	S/N	\$	1,400.00	\$ 1,400.00
6	To dismantle rear bumper, lhs rear door and both wheel arch cover. Cut out and reweld lhs rear fender. Renew lhs rear door. Transfer old fittings and align to position		\$	6,000.00	\$ 3,500.00
7	To respray lhs rear fender, lhs rear doors, door entrances, and roof channels. To carry out joint sealer works and stone chip treatments.		\$	2,500.00	\$ 1,650.00
8	To carry out diagnostic check.	S/N	\$	192.00	\$ 192.00
TOTAL LABOUR CHARGES			\$	12,652.00	\$ 9,002.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLZ 6276 C

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR FENDER - LH	\$ 3,310.00	\$ 2,648.00
2	WHEEL HOUSING LINER - LH	\$ 215.00	
3	WHEEL HOUSING ATTACHMENT	\$ 132.00	
4	WHEEL COVER REAR LH / RH	2 \$ 454.00	\$ 363.20
5	REAR DOOR LH	\$ 2,294.00	\$ 1,835.20
6	DOOR SEAL - OUTER	\$ 150.00	\$ 119.60
7	DOOR SEAL BRACKET	\$ 16.00	\$ 12.40
8	DOOR ATTACHMENTS	\$ 187.00	
9	DOOR CATCH	\$ 105.00	
10	DOOR CATCH COVER	\$ 14.00	
11	DOOR HANDLE, EXTERIOR	\$ 131.00	
12	MOUNTING BAR	\$ 106.00	
14	POWER WINDOW REGULATOR	\$ 242.00	
15	REAR WINDOW	\$ 818.00	
16	QUARTER GLASS	\$ 299.00	\$ 239.20
17	QUARTER GLASS CHROME TRIMS	\$ 265.00	
18	REAR WINDSCREEN SEALANT	S/N \$ 200.00	
19	1/4 GLASS SEALANT	S/N \$ 100.00	\$ 100.00
20	ARCYLIC SEALANT	S/N \$ 180.00	\$ 180.00
SUB-TOTAL SPARE PARTS		\$ 9,218.00	\$ 5,497.60

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLZ 6276 C

S/N	Parts Description	Damage Parts & Prices			
		S/NETT		REMARKS	
		<i>c/f</i>		\$	5,497.60
21	CAVITY WAX	S/N	\$	140.00	\$ 140.00
22	STONE CHIP TREATMENT	S/N	\$	180.00	\$ 180.00
23	METAL FILLER POWDER	S/N	\$	280.00	\$ 280.00
24	Added parts - see attached		\$	225.50	\$ 180.40
25	SUNDRIES		\$	300.00	\$ 20.64
	TOTAL SPARE PARTS	:	\$	10,343.50	\$ 6,298.64
	TOTAL LABOUR CHARGES	:	\$	13,572.00	\$ 9,002.00
	GRAND TOTAL	:	\$	23,915.50	\$ 15,300.64

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/TP/0750/2018/KS
19-Jul-18
JB
ONE
SLZ 6276 C
Q3 SEDAN

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	LHS REAR DOOR COVER (nec) <i>NEC</i>	\$ 225.00	\$ 180.40 <i>OK ✓</i>
		\$ 225.00	\$ 180.40
<u>LABORS</u>			
	TOTAL	\$ 225.00	\$ 180.40

For Premium Automobiles Pte Ltd

Adrian Ling
[Signature]

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SLZ 6276 C

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0750/2018/MAS

23 Nov 2018

Dear Sir,

RE: INSURANCE CLAIM FOR SLZ 6276 C, Audi Q3 1.4 TFSI S-Tro

With reference to the above-mentioned vehicle, no. **SLZ 6276 C** claimant, **Premium Automobiles Pte Ltd**, please find the related document per attached.

1. A copy of the Original invoice no. 85013134 – S\$14,766.68
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLZ 6276 C

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Jul 2018		10 Jul 2018 09:34 Edit Adj Rpt	S\$15,300.64 Edit Estimates	S\$15,300.64 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	PREMIUM AUTOMOBILES PTE LTD, Co. Reg. No.: 199902271W								
Vehicle Reg. No.:	SLZ6276C	Date of Loss:	30/06/2018 21:00 - :59 [1 Months and 19 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 4492935958SG	Policy/Cover Note No.:	(Comprehensive)						
		Excess:	S\$1,500.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Tr, Tinesh] Tinesh.Tr@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 19/07/2018]								
Driver/Custodian:	LI PENG ZHOU (43 / Male), NRIC: G0672245N, Tel: +6597896016								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (25/07/2018): Alert - Adj Mandate Approved (S\$15940.00) - SLZ6276C - Claim Handler: Tr, Tinesh AIG_SG (24/07/2018): SLZ6276C / OD / 30/06/2018 / Coverage & Excess update 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLZ6276C (4492935958SG)
OD
Jun 30 2018 9:00PM
[PREMIUM AUTOMOBILES PTE LTD]
Premium Automobiles Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		Use Viewer		▼
Assessment Reports															1 per page		▼		<input checked="" type="checkbox"/>
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	10/07/18 15:49		Adjuster Immediate Advice														Load HTM		
															3 per page		▼		<input checked="" type="checkbox"/>
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	10/07/18 15:45		General View														Load JPG		<input checked="" type="checkbox"/>
2	10/07/18 15:45		General View														Load JPG		<input checked="" type="checkbox"/>
3	10/07/18 15:45		General View														Load JPG		<input checked="" type="checkbox"/>
4	10/07/18 15:45		General View														Load JPG		<input checked="" type="checkbox"/>
5	10/07/18 15:45		General View														Load JPG		<input checked="" type="checkbox"/>
6	10/07/18 15:45		General View														Load JPG		<input checked="" type="checkbox"/>
7	10/07/18 15:45		General View														Load JPG		<input checked="" type="checkbox"/>
8	10/07/18 15:45		General View														Load JPG		<input checked="" type="checkbox"/>
9	10/07/18 15:45		General View														Load JPG		<input checked="" type="checkbox"/>
10	10/07/18 15:45		General View														Load JPG		<input checked="" type="checkbox"/>
11	10/07/18 15:45		General View														Load JPG		<input checked="" type="checkbox"/>
12	10/07/18 15:45		General View														Load JPG		<input checked="" type="checkbox"/>
13	10/07/18 15:45		General View														Load JPG		<input checked="" type="checkbox"/>
14	10/07/18 15:45		General View														Load JPG		<input checked="" type="checkbox"/>
15	10/07/18 15:45		General View														Load JPG		<input checked="" type="checkbox"/>
16	10/07/18 15:45		General View														Load JPG		<input checked="" type="checkbox"/>
17	10/07/18 15:45		General View														Load JPG		<input checked="" type="checkbox"/>
18	10/07/18 15:45		General View														Load JPG		<input checked="" type="checkbox"/>
19	10/07/18 15:45		General View														Load JPG		<input checked="" type="checkbox"/>
20	10/07/18 15:45		General View														Load JPG		<input checked="" type="checkbox"/>
21	10/07/18 15:45		General View														Load JPG		<input checked="" type="checkbox"/>
22	10/07/18 15:45		General View														Load JPG		<input checked="" type="checkbox"/>
23	10/07/18 15:45		General View														Load JPG		<input checked="" type="checkbox"/>
24	10/07/18 15:45		General View														Load JPG		<input checked="" type="checkbox"/>
															1 per page		▼		<input checked="" type="checkbox"/>
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print		
1	10/07/18 15:40		Certificate of Insurance														Load PDF		
2	10/07/18 15:40		Driving Licence														Load PDF		
3	10/07/18 15:40		estimate														Load PDF		
4	10/07/18 15:40		Singapore Accident Statement														Load PDF		
5	04/12/18 10:26		Supplementary														Load PDF		
6	04/12/18 10:26		WORKSHOP INVOICE														Load PDF		
7	04/12/18 10:26		DISCHARGE VOUCHER														Load PDF		

Linked Accident Report Documents

			View	Use Viewer
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Premium Automobiles Pte Ltd (UBI)	Thumbnail	Print
1	02/07/18 19:08	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>

No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	02/07/18 19:07	Accident Photo		Load JPG	
2	02/07/18 19:07	Accident Photo		Load JPG	
3	02/07/18 19:07	Accident Photo		Load JPG	
4	02/07/18 19:07	Accident Photo		Load JPG	
5	02/07/18 19:07	Accident Photo		Load JPG	
6	02/07/18 19:07	Accident Photo		Load JPG	
7	02/07/18 19:07	Accident Photo		Load JPG	
8	02/07/18 19:07	Accident Photo		Load JPG	
9	02/07/18 19:07	Accident Photo		Load JPG	
10	02/07/18 19:07	Accident Photo		Load JPG	
11	02/07/18 19:07	Accident Photo		Load JPG	
12	02/07/18 19:07	Accident Photo		Load JPG	
Documentation			1 per page		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	02/07/18 19:07	Sketch Plan		Load JPG	
2	02/07/18 19:07	Sketch Plan #2		Load JPG	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid #ccc; height: 150px; margin-top: 5px;"></div>			
<p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18012362/AQD3N2

Date: 04/12/2018

REFERENCE

Insured/Claimant: PREMIUM AUTOMOBILES PTE LTD
Date of Loss: 30/06/2018

Policy No:
Nature of Claim: OD Claim No: 4492935958SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ6276C	Engine No:	CZD814493
Make & Model:	AUDI Q3, 1.4 TFSI (A)	Chassis No:	WAUZZZ8U4JR004880
Reg. Date:	11/05/2018 (Man. Year: 2017)	Odometer:	3722 km
Colour:	Blue		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$160,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R17	Rear Tyre Size:	235/55 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,298.40	6,298.64	3,999.76	38.84
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,652.00	9,002.00	3,650.00	28.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,950.40	15,300.64	7,649.76	33.33
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
(S\$)	21,450.40	13,800.64	7,649.76	35.66
+ GST 7.00/7.00% (S\$)	1,501.53	966.04	535.49	35.66
Nett Amount (S\$)	22,951.93	14,766.68	8,185.25	35.66

INSPECTION

Date of Assignment: 10/07/2018
Date Inspected: 05/07/2018 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 13.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR FENDER - LH	Dented	3,310.00 F	*2,648.00 F
2	1		*WHEEL HOUSING LINER - LH	Not Necessary	215.00 F	*- F
3	1		*WHEEL HOUSING ATTACHMENT	Not Necessary	132.00 F	*- F
4	2		*WHEEL COVER REAR LH/RH	Necessary	454.00 F	*363.20 F
5	1		*REAR DOOR LH	Dented	2,294.00 F	*1,835.20 F
6	1		*DOOR SEAL - OUTER	Necessary	150.00 F	*119.60 F
7	1		*DOOR SEAL BRACKET	Necessary	16.00 F	*12.40 F
8	1		*DOOR ATTACHMENTS	Not Necessary	187.00 F	*- F
9	1		*DOOR CATCH	Not Necessary	105.00 F	*- F
10	1		*DOOR CATCH COVER	Not Necessary	14.00 F	*- F
11	1		*DOOR HANDLE, EXTERIOR	Repair	131.00 F	*- F
12	1		*MOUNTING BAR	Not Necessary	106.00 F	*- F
13	1		*POWER WINDOW REGULATOR	Not Necessary	242.00 F	*- F
14	1		*REAR WINDOW	Not Necessary	818.00 F	*- F
15	1		*QUARTER GLASS	Necessary	299.00 F	*239.20 F
16	1		*QUARTER GLASS CHROME TRIMS	Not Necessary	265.00 F	*- F
17	1		*REAR WINDSCREEN SEALANT	Not Necessary	200.00 F	*- F
18	1		*1/4 GLASS SEALANT	Necessary	100.00 F	*100.00 F
19	1		*ARCYLIC SEALANT	Necessary	180.00 F	*180.00 F
20	1		*CAVITY WAX	Necessary	140.00 F	*140.00 F
21	1		*STONE CLIP TREATMENT	Necessary	180.00 F	*180.00 F
22	1		*METAL FILLER POWDER	Necessary	280.00 F	*280.00 F
23	1		*SUNDRIES	Necessary	300.00 F	*20.64 F
24	1		*LHS REAR DOOR COVER	Necessary	180.40 F	*180.40 F

F=Franchise part.

Total Parts (S\$)	10,298.40	6,298.64
-------------------	-----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION.	New	280.00	280.00
2	TO REMOVE AND TRANSFER LHS REAR DOORS MULTI LOCK-SYSTEM AND POWER WINDOW DEVICES.	New	280.00	280.00
3	TO REMOVE AND REINSTALL REAR SEATS, BACK REST, ABCD PILLAR TRIMS, ROOF LINER, HAT TRAYS, CARPETS, CURTAIN AIR BAG AND SILL TRIMS.	New	1,400.00	1,400.00
4	TO REMOVE AND RENEW LHS QUARTER GLASS AND REAR WINDSCREEN FOR FENDER RENEWAL.	New	600.00	300.00
5	TO REMOVE AND REINSTALL REAR WIRE HARNESS FOR TAIL LIGHT, FUSE UNITS, BATTERY MANAGER, FUSE AND RELAYS TRAY, AND ELECTRICAL COMPONENTS.	New	1,400.00	1,400.00
6	TO DISMANTLE REAR BUMPER, LHS REAR DOOR AND BOTH WHEEL ARCH COVER. CUT OUT AND REWELD LHS REAR FENDER. RENEW LHS REAR DOOR. TRANSFER OLD FITTINGS AND ALIGN TO POSITION.	New	6,000.00	3,500.00
7	TO RESPRAY LHS REAR FENDER, LHS REAR DOORS, DOOR ENTRANCES, AND ROOF CHANNELS. TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENTS.	New	2,500.00	1,650.00
8	TO CARRY OUT DIAGNOSTIC CHECK.	New	192.00	192.00
Gross Labour Cost (\$\$)			12,652.00	9,002.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >