

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

INDIA

Vehicle No : FS 1533 B

Vehicle Model : Yamaha FZ16

Estimated Repair Costs

Qty	Description <u>List Items</u>	Amount S(\$)
1	Front fender	\$ one 70.00 ✓
2	Fork inner tubes	\$ two 440.00 ✓
2	Fork outer tubes	\$ two 460.00 x
1	Fork under bracket	\$ one 245.00 ✓
1	Front sport rim	\$ one 450.00 x
1	Front brake disc	\$ one 155.00 x
1	Front rim shaft	\$ one 45.00 x
1	Front rim bearing	\$ one 38.00 x
1	Meter assy	\$ 320 420.00 ✓
2	Side mirrors	\$ two 120.00 ✓
1	Headlamp	\$ 320 380.00 ✓
1	Lampstay	\$ one 80.00 ✓
1	Handle bar	\$ one 135.00 ✓
1	Handle bar balancer	\$ one 28.00 ✓
1	Hand grip (1 set)	\$ 7.00 50.00 ✓
1	Clutch lever	\$ one 22.00 x
1	Brake lever	\$ one 22.00 ✓
1	Brake master pump	\$ one 185.00 ✓
2	Front signals	\$ 0.50 100.00 pc
2	Fuel tank side covers	\$ 0.50 430.00 pc
1	Fuel tank centre cover	\$ one 195.00 ✓
1	Windshield	\$ 320 220.00 ✓
1	Top fairing -Black	\$ 320 210.00 ✓
1	Top fairing daylight lamp	\$ 320 180.00 ✓
2	Side fairings -Silver	\$ 0.50 330.00 pc
1	Side stand	\$ one 75.00 ✓
1	Main stand	\$ one 105.00 x
2	Front footrests	\$ one 76.00 ✓
2	Front footrest brackets	\$ one 180.00 pc
1	Brake pedal	\$ one 45.00 x
2	Rear footrests	\$ one 84.00 ✓
1	Rear tailboard	\$ one 125.00 x
		\$ 5,700.00

rear swing arm diff. ✓

rear rim 2x

Rear rim centre stuff 1x

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

Vehicle No : FS 1533 B

Vehicle Model : Yamaha FZ16

Estimated Repair Costs

c/f: \$ 5,700.00

List Items

2	Rear signals	\$ <i>AW</i> 100.00 ✓
1	Exhaust assy	\$ <i>n</i> 450.00 ✗
1	Exhaust end cap	\$ <i>cu</i> 48.00 //
1	Exhaust protector	\$ <i>cu</i> 65.00 //
1	Rear fender	\$ <i>cu</i> 85.00 //
1	Ignition key set	\$ <i>cu</i> 180.00 //
		\$ 6,628.00
Less 10%		\$ 662.80
		\$ 5,965.20

Special Nett Items

1	Number plate (1 set)	\$ <i>sm</i> 28.00 /0
2	Fork oils	\$ <i>mu</i> 30.00 //
2	Fork oil seals	\$ <i>mu</i> 56.00 //
1	Coolant	\$ <i>nn</i> 15.00 ✗
1	ERP IU	\$ <i>dic</i> 170.00 ✗
		\$ 299.00

S/No. Labour

1	To provide towing service.	\$ <i>35</i> 50.00
2	To check wiring and reset headlamp focusing.	\$ <i>nn</i> ✗ 80.00
3	To provide labour.	\$ <i>350</i> 380.00
4	To repair body frame.	\$ <i>280</i> 350.00
		\$ 860.00

Grand Total

\$ 7,124.20

Dollars: Seven Thousand One Hundred Twenty-Four And Twenty Cents Only



EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: