		1212/1	
(stema)	CC) /AIG1801 WAY	/ Wash LKK	
INS. CASE OWNER		03	and the same
	SATHUMA ASSIGNMENT	5	Y (18
Surveyor		Dute/Time:	118
December / CCI	/FTF	Registered in Merimen:	11/60
Pre-assign / CCU	SLZ 6022	\$0654815	an Un
Insured Vehicle N	O. Claim No	30000019	(0.50)
Name of Insured	SIM SOLE NOTE Policy No	700486	881-01
insured Tel No.	HP OF MY 8 hin Make / M	lodel PENANT	
Excess Sec II :SS	2011	1.5	
Service Service and		secident	
Is driver the owner			
If NO. Driver Na		EPORT: YES / NO : TP GIA REF	
Driver Tel		lability: % Final?	Les / No
54 1774	<u></u>		
INSRS: WSP:	T - INSRS: INSRS: WSP: WSP:	IN WS	SRS:
Tei: GMV	Tel: Tel:	P A Tel	
Liability:	Liability: Liability	107 101	bility:
RMKS:	RMKS: RMKS:	RN	1KS
Date/Time			
1 10	Movey - A STEPHING	STAGE	DATE/PIC
1/2/18		Non-Reporting lir (1st): Non-Reporting lir (2nd):	
VIVINA		Nun-Reporting ltr (Final):	
A1/V1.		Nonfication ltr (if non-pickup):	IC SHAN N WAI) CLEAR
250/10			He -moil avid
13 11119	File pass tot pe report.	Documentation Check List: 1	111111111111111111111111111111111111111
Kharehua	Los bester the fact.	Notification ltr (if non-pickup)	
		After call lir to OI:	
13/1/3020	File pass to mk to close	Authorisation To Act	
Egasquar		Release Voucher:	
		Final Repair Bill: Car Rental Invoice:	
		Towing Invoice	
		LTA/GIA:	V
		Medical Bill:	
		PIR:	
		Mandate/Nejest Instruction:	
		LOD	
DELININA DEL ADVICA	P. D. P. P. D.	Payment Breakdown Form:	
RELIMINARY ADVICE	E. Date/Time: Sent By:	Post-Repair Photos: Others:	
INALIZATION	Date/Time: Confirm with:	Confirm by:	
epair Cost: 1/1		Email	Cult
INAL SETTLEMENT	Date/Time: 13 1 1000 Confirm with KO CEA	Email Cal	
inal Liability:	(Agreed / Assessed) BOLA S/N No.: -27	If NO or B 28, Ass. I in	
epair Cost:	55 12, 207.58	101 BEAR S	
oss of Rental (LOR):	SS 12450 (52450 x 5 days)	FOI CHA: MUA	will tark?
oss of Income (LOI):	SS V2-50 (5 2-50 x 5 days) SS - (5 - x - days)	COMPAN OF	ervica -
OR only LOU only		11 (0111 11 %)	11-11-11
IIA/LTA Search	ss 7.00	14/1/2	
fedical:	55 ~	1) Claim status: Norm //Reje	
hisbursement:	SS - (e.g. Tow/ Independent.)	2) Report Format:	322
egal Cost otal:	88 \3,466.58 Global Sum SS:	3) Survey fee:	320
INAL PAYMENT	Date/Time: Confirm with:	Email Cal	
ayee 1:	SS 13,466-58 Name 1: SMPLT BUSES		
ayee 2: (Strike if N.A.)	SS Name 2:	0.15	
ayee 3: (Strike if N.A.)	SS Name 3:		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

			rnationale Des Experts En Auto					
AIG	ASIA PACIFIC INS	SURANCE PTE LTD	Ref : CC3/AIG1801	2434/Vwb3				
CHA	SHENTON WAY #0 ARTIS BUILDING GAPORE 079120	8-16	Date: 09-07-2018					
1.		Policy Particu	lars :- THIRD PARTY CLA	AIM				
	Insured Veh.	SLZ 6022T	Veh. Inspected	SG 1225A				
	Policy No.		Coverage (\$)	0.00				
	Claim No.		Excess (\$)	0.00				
	Assign From		Assign Date	09/07/2018				
2.		Vehicle I	Particulars & Condition					
	Make & Model		c.c	0				
	Engine No.	HIDDEN	Year of Reg.					
	Chassis No.		Colour					
	Odometer	9	Steering					
	Brakes		Modification					
	General							
3.		Co	nditions of Tyres					
		Size	Make	Balance				
	R/H Front Tyre			mm				
	L/H Front Tyre			mm				
	R/H Rear Tyre			mm				
0.	L/H Rear Tyre			mm				
4.		Desc	ription of Damages					
5.		Ge	neral Information					
	Accident Date	30/06/2018	Inspection Date	05/07/2018				
	Survey held at	SMRT AUTOMOTIVE SER	VICES PTE LTD					
		60 WOODLANDS INDUST	RIAL PARK E4 SINGAPORE	757705				
5a.			Remarks					



60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No

SG1225A

Ref. No.

BUS/06/18/5054

Reg. Date

03/07/2018

Vehicle Type

BUS -12M

Make

MB CITARO MERCEDES

Model

MB CITARO 0530

Name of Driver

MID OFFICE COST

20 204 20 2

Sun Yanchun

Type of Accident

HEAD TO REAR

Date / Time of Accident

30/06/2018 05:15:00 PM

Accident Reported Date / Time :

02/07/2018 12:00:00 AM

Surveyor is Required?

Yes

Survey by

AIG

Vehicle is Towed Back?

No

Towed Back Date/Time

Replacement Vehicle issued? :

No

Accident Repair Job Card No :

Special Instruction to ARC, if any :

SG1225A - REAR PORTION

SLZ6022T (TP) - FRONT PORTION

Prepared Date

03/07/2018 09:43:54 AM



- Part by Part

- Photo before paint

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- . Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis.
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Admovledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No :

Mileage

0

Work Shop 1:

Repair Completed Date / Time :

01/01/2000

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labout Charges

3.180.00

0.00

Total Spray Painting Charges

616.00

0.00

Total Material Charges

9,589.58

13,385.58

9,589.58

Other Charges

0.00

0.00

TOTAL

Lum Sum Total

0.00

:

0.00

No. of Repair Days

7.00

0.00 0.00

Prepared / Adjusted By

Arc / Surveyor Sing Off Date

: 04/07/2018 05:44:25 PM

01/01/1900 12:00:00 AM

Prepared / Adjusted Date

Remarks

Prepared Date : 04/07/2018 03:48:20 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No

Invoice No

Quotation Date

Invoice Date

Invoice Amount :

Prepared Date:

Section D - Details of Repair Estimates

'art 1 - Labour Works

otal Labour	3,180.00	0.00
O REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	3,180.00	0.00 2120
ob Scope	Quotation from ARC	Adjusted by Surveyor, if applicable

'art 2 - Spray Painting & Panel Beating Related Works

lob Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	616.00	200 500
Total Spray Painting & Panel Beating	616.00	0.00

'art 3 - Other Costs - Accident and Accident Repair Related Expenses

lob Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
otal Other Costs		

US/06/18/5054

Part 4 - Spare Parts / Material Usage

Part : Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen d	Surveyor Approved	Photos Attached
/A62864)2114	·		CROSS BAR REAR BUMPER (SBS VERSION)	1	2,700.00	10.00	2,430.00	Replace	Replace	No
	REAR	6009907	REAR BUMPER CENTER DMG	1	1,791,33	10.00	1,612.20	Replace	Replace	No
	REAR	6009909	REAR BUMPER RH	r 1	837.84	10.00	754.06	Replace	Replace	No
//A62868 34508			COVER UNDER RH (SBS VERSION) / LAT		1,750.00	10.00	1,575.00	Replace	Replace	No
//Q62850)348901			PIPE COPPER (SBS VERSION) / 0T		850.00	10.00	765,00	Replace	Replace	No
2875029 '4	REAR	6010113	FLAP ENGINE :FOR MB CITARO 0530 R	1	5,573.10	100.00	0.00	Repair	Repair	No
8204056		6010008	LAMP, LICENSE PLATE: FOR MB CITARO 0530	2	97.68	10.00	175.82	Replace	Replace	No
32888500 35	REAR	6009908	REAR BUMPER LH	1	837.84	10.00	0.00	Repair	Replace	No
			COOLANT:ANTIFREE	1	524.00	10.00	471.60	Replace	Replace	No
1000683 2308			COVER UNDER LH (SBS VERSION) VLM		1,931.00	10.00	1,737.90	Replace	Replace	No
2	REAR		NUMBER PLATE OT	1	68.00	0.00	68.00	Replace	Replace	No
		1	TOTAL MATERIALS					9,589.58	9,589.58	
		TOTAL	MATERIALS(Discour	ited)				9,589.58	9,589.58	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
	TOTAL SUPPLEMENTARY MATERIALS								10



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd 60 Woodlands Industrial Park E4, Singapore 757705 FAX Number : 63685582 Estimator Talaphone Number : 68662623 Accident Reporting Number : 68662672

Date Generated : 12/12/2018
User ID : CatherineLee

	Section A - Acc	cident Details			
Registration Number	SG1225A			_	
Case Reference Number	BUS/06/18/5054				
Registration Date	27/12/2017			- The same of the	-
Company Type	SMRT Buses Ltd				7
Make	MERCEDES.				
Model	MB CITARO 0530				
Name of Driver	Sun Yanchun				
Type of Accident	HEAD TO REAR			100	
Accident Cate and Time	30/06/2018 5:15 PM				1
Accident Reported Date and Time	02/07/2018 4:23 PM				
s Surveyor Required?	Yes				
lurvey by	AIG				
/ehicle is Towed Back?	No:				
lowed Back Date and Time				(0)	
Replacement Vehicle issued?	No			16	Les Control
lob Card Number	000024096872				
Special Instruction to ARC, if any	SG1225A - REAR PORTI SLZ0022T (TP) - FRONT	ON PORTION		Sum T	— bus
Prepared Date and Time	03/07/2018 9:43 AM			1 1	11 19
Chasais Number	WEB82808323130968				(i)
Aimage					II O
Mark Shop					_
Repair Completion Date and Time	211				
	Section B - Summary	of Repair Estimates		The second second	
Summary of Repair Estimates					
	Quotation from ARC	Adju	sted by Surveyor, if applicable		_ (
Total Labour Cost:	\$3,180.00	52.1	20.00		
fotal Spray Cost	\$616.00	\$500			
Fotal Spare Part Cost	\$9,589.58	\$9.5	69.56		
oral Other Cost	\$0.00	\$0.0	0		
OTAL COST	\$13,385.58	\$12	209-58		
ump Sum Total	\$0.00	\$0.0			
lumber of Repair Days	7.0	5.0			
repared / Adjusted By	Bus Estimator Team	Sath	ys.		
RC / Surveyor Sign Off Date	04/07/2018 S:44 PM	05/0	7/2018 2:06 PM		
Signature	-	T	M		
Remarks					
	Section C - Quotation and		talis		
Zuotation Number		nvoice Number			
Suptation Date		rivolice Data		- 17	
nvoice Amount	The state of the s	Prepared Date			



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685992

Estimator Telephone Number: 66662623

Accident Reporting Number : 68662672

Date Generated : 12/12/2018

User ID | CatherineLee

	10.00		Sect	on D - Det	alls of Repair E	stimates	Sec.	100		
Part 1 - Labo	ur Works							100		
Job Stope	all a	- 0.000		Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS. DAMAGED AFFECTED AREAS.				\$3,180.00				\$2,120.00		
Total Labour				\$3,180.00				\$2,120.00		
Part 2 - Spra	y Painting & i	Panel Beating Reta	sted Works							
Јов Беори				Quotation f	rom ARC	100		Adjusted by Survey	or, if applicable	
PROVIDE LAB	OUR AND MAT	TERIAL TO PUTTY A	ND RESPRAY ABOVE	3616.00				\$500.00		
Total Spray P	einting & Panel	Besting		\$616.00				\$500.00		
Part 3 - Other	Costs - Acci	ident and Accident	Repair Related Expen							
Job Scope		X 31 -		Quetation f	rom ARC			Adjusted by Survey	or, if applicable	
Total Other Co	osts									
Part 4 - Span	Parts / Mute	rial Usage					721,00			
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		MAR286402114	CROSS BAR REAR BUMPER (SBS VERSION)	1,00	\$2,790.00	10.00	\$2,430.00	Replace	Replace /5D	
8009907	MEAR		REAR BUMPER CENTER	1.00	\$1,791.33	10:00	\$1,612.20	Rapiace	Replace / CEK	
5009909	REAR		REAR BUMPER RH	1.00	\$837.84	10.00	\$754.06	Replace	Replace / CEV	
		MA6296834508	COVER UNDER RH (SBS VERSION)	1.00	\$1,750.00	10.00	\$1,575.00	Replace	Regisce /Kur	
		MQ6285003489 01	PIPE COPPER (SBS VERSION)	1.00	\$850.00	10.00	\$765.00	Replace	Reptace DD	
8010113	REAR	6287502974	FLAP ENGINE FOR MB CITARO 0530	1.00	\$5,573.10	100.00	\$0.00	Repair	Repair X R	
801000a		3820405B	LAMP.LICENSE PLATE:FOR MB CITARO 0530	2.00	197.66	10.00	\$175.82	Replace	Replace / CEIC	
8009906	HEAR	6298850005	REAR BUMPER LH	1.00	\$837.84	100.00	80.00	Repair	Repair 74 R	
			COOLANT ANTIFREEZE	1.00	\$524.00	10.00	\$471.60	Replace	Replace /NEC	
		A0006832308	COVER UNDER LH (SBS VERSION)	1.00	\$1,931.00	10.00	\$1,737.90	Replace	Replace / CLIT	
	HEAH		NUMBER PLATE	1.00	\$68.00	0.00	\$68.00	Replace	Repiace / DD	
Total					\$16,960.79		\$9,589.58			
Added Spare	Parts / Mator	ial Usage After Su	rveyar Signed aff			-74				
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	
Total	1						manufacture 2/12		100000000000000000000000000000000000000	
						_	_			

PARTS \$ 9,589.58

LABOUR \$ 2,120.00

SPRAY \$ 500

TOTAL \$ 12,209.58

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details	
Vehicle No.:	SG1225A
Vehicle Type:	H20 - Public Transport Bus/Coach/Minibus
Vehicle Attachment 1:	Air-Conditioned
Vehicle Scheme:	OmniBus (LTA-ARF exempted)
Vehicle Make:	MERCEDES BENZ
Vehicle Model :	CITARO O530 6.4L AT TURBO ABS
Chassis No. :	WEB62808323130959
Propellant:	Diesel
Engine No.:	902926C1112186
Engine Capacity:	6374 cc
Maximum Power Output:	Na contract of the contract of
Maximum Laden Weight:	17900 kg
Unladen Weight:	11020 kg
Year Of Manufacture :	2016
Original Registration Date:	27 Dec 2017
Lifespan Expiry Date :	26 Dec 2034
Road Tax Expiry Date:	26 Dec 2018
Inspection Due Date :	26 Dec 2018
Intended Transfer Date:	09 Jul 2018
CO2 Emission :	i e
CO Emission :	•
HC Emission :	
NOx Emission :	4
PM Emission:	4
Late renewal fee(s) will be impos	ed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.
Road tax, including Over Paymer Amount Payable	nt (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Transfer Fee: 25.00 Total Amount Payable:
You may print this page for reference.

Amount Before GST

OK Print

(5\$)

GST Amount

(5\$)

Amount After GST

(55)

25.00

25.00

Vivian Lau (LKKAuto)

From:

Wui, Shawnkaijye <Shawnkaijye.Wui@aig.com>

Sent:

Tuesday, 10 July, 2018 2:27 PM

To:

Vivian Lau (LKKAuto)

Subject:

FW: Case Assignment TP - SG1225A - 30/06/2018 - 5065281590SG

Dear Vivian,

Please be informed that I have called insured driver to verify on how the accident happened.

OID shared that he went to pick up some gym equipment from his friend and heading to pump petrol. While changing lane from the 1st lane to 3rd lane, the front bus slowed down. Hence, he is unable to stop in time and hit onto TP bus.

Reason to change lane is because OID want to exit at Upper Thomson Exit at the left side.

Traffic Police attended to scene, traffic police did not issue any notice of intended prosecution to OID.

Not drink driving case.

Thanks and Regards, Shawn Wul AIG Complex Claims Examiner Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way, #08-16, Singapore 079120

Tel +(65) 6419 1959 | Fax +(65) 6835 7416

Shawnkaijye.Wui@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use

From: Do-Not-Reply [mailto:do-not-reply@merimen.com]

Sent: Tuesday, July 10, 2018 12:20 PM

To: Wui, Shawnkaijye

Subject: Case Assignment TP - SG1225A - 30/06/2018 - 5065281590SG

This mail is associated with:
*SG1225A (5065281590SG)
[SLZ6022T]
TP
SMRT BUSES LTD
Jun 30 2018 5:00PM

[SIM SOCK NGEE] SMRT Automotive Services Pte Ltd

. Dear Wui, Shawn-KJ,

Please note that a claim has been assigned to you for handling in Merimen. For your action and follow up please.

This is an auto-generated email. Do not reply to this email.

Sent by : Wui, Shawn-KJ (AIG Asia Pacific Insurance Pte. Ltd.)

RE-ASSIGN TO JOY		
Remarks		
Kemarks		
Add		
New remarks Added Remarks 1	By	On
SG 1225A : SLZ 6022T	LSP	9/7/2018 3:15:57 PM
EST :\$ SUR : SATHYA WKSP : SMRT AUTOMOTIVE SERVICES PTE LTD	LSP	9/7/2018 3:16:08 PM
Dear Vivian, Please be informed that I have called insured driver to verify on how the accident happened. OID shared that he went to pick up some gym equipment from his friend and heading to pump petrol. While changing lane from the 1st lane to 3rd lane, the front bus slowed down. Hence, he is unable to stop in time and hit onto TP bus. Reason to change lane is because OID want to exit at Upper Thomson Exit at the left side. Traffic Police attended to scene, traffic police did not	LPF	10/7/2018 2:28:51 PM
Traffic Police attended to scene, traffic police did not issue any notice of intended prosecution to OID. Not drink driving case. Thanks and Regards, Shawn Wui	LPF	10/7/2018 2:29:05 PM
FILE PASS TO VIVIAN	LSP	11/7/2018 8:36:29 AM
	LSP	22/2/2019

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)

Sent: Monday, 23 December 2019 10:00 AM

To: Tan Wei Teck (Auto Svcs/Claims & IA/Claims & IA/Buses

Cc: Karen Chan Siau Chin (Auto Svcs/Claims & IA/Claims & IA/Buses; Admin A

Subject: OFFER - ACCIDENT INVOLVING SG1225A AND SLZ6022T [AIG] ON 30/06/2018 SLE

TOWARDS BKE UPPER THOMSON ROAD EXIT

Without Prejudice (save as to costs)

Dear Sirs/Mdm.

We refer to the above matter.

We propose settlement as follows: -

TOTAL	<u>\$ 13,216.58</u>
3. LTA Search fee	\$ 7.00
2. Loss of Use (5 days x \$200)	\$ 1,000,00
1. Cost of Repair	\$ 12.209.58

Please confirm acceptance.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,

Khanchna Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** email: <u>Khanchna@lkkauto.com</u> Fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[&]quot;Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

Claim Audit

ψo.	On	Audit	Remarks	By		
1	09 Jul 2018 15:27	Clm Veh Model Changed	(2024B1) MERCEDES-BENZ CITARO OS30 6.4 D (A).	[A] Lau Shu Pei		
2	09 Jul 2018 15:27	Clm Created	Reg No: SG1225A. Acct Date: 2018/06/30. Claim Type: TP. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG), TP Insurer: MS First Capital Insurance Ltd (HQ), Workshop: SMRT Automotive Services Pte Ltd (Woodlands)			
3	09 Jul 2018 15:27	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Shu Pei		
4	09 Jul 2018 15:27	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/07/18	[A] Lau Shu Pei		
5	09 Jul 2018 15:27	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.			
6	09 Jul 2018 15:27	Clm Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Express)	[1] Merimen Administrator		
7	09 Jul 2018 15:28	Label Added	(23):Express.			
8	09 Jul 2018 15:28	Adj Adjuster Assigned	[None] -> Sathya Sai Kathirrasen	[A] Lau Shu Pei		
9	21 Nov 2019 17:26	Adj Rpt Initiated		[A] JOANNE LEE KHANG MIN		
10	21 Nov 2019 17:26	Clm Dtl Modified	JPJ Reg. Date: -> 2017/12/27.	[A] JOANNE LEE KHANG MIN		
11	21 Nov 2019 17:26	Clm Details Notified		[A] JOANNE LEE KHANG MIN		
12	22 Nov 2019 17:10	Adj Mandate Request	Cur.Req: 13216.58: Liability down against Insured. Insured vehicle front to rear end TP vehicle. (BOLA 27).** 5 days recommendation for repair	[A] Khanchna Pothura]		

ACTIVITY No record

Merimen Billing for this case - Transaction History								
BILL REF 1961	BIII DAN	BHLTV661	Act Type	MX Rambi	(3ranati)	SREET	Bet 2	Missont
2353065	21 Nov 2019 17:26:01	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SG1225A	SLZ6022T	11,77

Print Received Message

This mail is associated with:

*SG1225A (5065281590SG) [SLZ6022T]

SMRT BUSES LTD Jun 30 2018 5:00PM [SIM SOCK NGEE] SMRT Automotive Services Pte Ltd

From

AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 20/12/2019 14:32 PM.

To

Subject Alert - Adj Mandate Approved (S\$13216.58) - SG1225A - Claim Handler: Chan, Kian-Meng

Approved:13216.58.		

Claim Audit

	20	te From	■ Date To ■ Audit Type None ▼	Go
16	30 Dec 2019 16:29	Adj Mandate Request	Cur.Req:13466.58:Third party wants LOU for \$250 per day - single deck bus	[A] Khanchr Pothuraj
15	30 Dec 2019 16:08	Adjuster Assigned	Sathya Sai Kathirrasen -> QI SUN PIN	[A] Lau Sh Pei
14	2019 14:32	Mandate Set	Approved:13216.58.	[T] Lan, Chee-Hen
13	20 Dec 2019 14:32 20 Dec	Adj Next Rpt Changed Adi	Next Rpt:Final Rpt.Due Date:2018/07/18	[1] Loh, Chee-Hen
12	22 Nov 2019 17:10	Adj Mandate Request	Cur.Req:13216.58:Liability down against Insured. Insured vehicle front to rear end TP vehicle. (BOLA 2 7).** 5 days recommendation for repair	[A] Khanch Pothuraj
11	21 Nov 2019 17:26	Clm Details Notified		[A] JOANN LEE KHAN MIN
10	21 Nov 2019 17:26	Clm Dtl Modified	JPJ Reg. Date: -> 2017/12/27,	[A] JOANN LEE KHAN MIN
9	21 Nov 2019 17:26	Adj Rpt Initiated		[A] JOANN LEE KHAN MIN
8	09 Jul 2018 15:28	Adjuster Assigned	[None] -> Sathya Sai Kathirrasen	[A] Lau Sh Pei
7	09 Jul 2018 15:28	Label Added	(23):Express.	[A] Lau Sh Pei
6	09 Jul 2018 15:27	Clm Ins Co Changed	[200005] AIG Asia Pacific Insurance Pte. Ltd. (SG) -> [203630] AIG Asia Pacific Insurance Pte. Ltd. (Ex press)	[I] Merime Administrat
5	09 Jul 2018 15:27	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] Lau Sh Pel
4	09 Jul 2018 15:27	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/07/18	[A] Lau 5h Pei
3	09 Jul 2018 15:27	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Lau Sh Pei
2	09 Jul 2018 15:27	Clm Created	Reg No: SG1225A. Acct Date: 2018/06/30. Claim Type: TP. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). TP Insurer: MS First Capital Insurance Ltd (MQ). Workshop: SMRT Automotive Services Pte Ltd (Woodlands)	[A] Lau Sh Pei
1	09 Jul 2018 15:27	Clm Veh Model Changed	(202481) MERCEDES-BENZ CITARO O530 6.4 D (A).	[A] Lau Sh Pei
AG.	On	Audit	Atemarks	By

ACTIVITY No record

ferimen Billing for this case - Transaction History								
58 Ref No	SIR Thatis	B# Type	Act Type	Acc hieron	Car Name (Scance)	Ref I	0407	America
2353065	21 Nov 2019 17:26:01	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKX Auto Consultants Pte Ltd (HQ)	SG1225A	SLZ6022T	11.77

Khanchna (LKK Auto)

From: Karen Chan Siau Chin (Auto Svcs/Claims & IA/Claims & IA/Buses)

<ChanSiauChin@smrt.com.sg>

Sent:

Monday, 13 January 2020 11:10 AM

To:

Khanchna (LKK Auto); Tan Wei Teck (Auto Svcs/Claims & IA/Claims & IA/Buses)

Cc:

Admin A

Subject:

RE: OFFER - ACCIDENT INVOLVING SG1225A AND SLZ6022T [AIG] ON 30/06/2018 SLE

TOWARDS BKE UPPER THOMSON ROAD EXIT (BUS/06/18/5054/PT)

Attachments:

img-113110356-0001.pdf

Importance:

High

Without Prejudice

Dear Khanchna.

Thank you for the offer.

The original duly signed DV will be forwarding to your office shortly.

Payment by cheque shall be crossed and made payable to SMRT Buses Ltd.

Thanks & REagrds,

Karen Chan

Claims Department

Tel: 6556 3523

From: Khanchna (LKK Auto) [mailto:khanchna@lkkauto.com]

Sent: Monday, January 13, 2020 9:03 AM

To: Tan Wei Teck (Auto Svcs/Claims & IA/Claims & IA/Buses)

Ce: Karen Chan Siau Chin (Auto Svcs/Claims & IA/Claims & IA/Buses); Admin A

Subject: RE: OFFER - ACCIDENT INVOLVING SG1225A AND SLZ6022T [AIG] ON 30/06/2018 SLE

TOWARDS BKE UPPER THOMSON ROAD EXIT

Without Prejudice (save as to costs)

Dear Sirs/Mdm.

We refer to the above matter.

We confirm settlement as per your e-mail dated 23/12/2019 for \$ 13,466.58(all in).

We attach herewith a copy of the DV and Authorisation Letter for your further action.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

" Wishing you a Happy and Prosperous Lunar New Year"



Best Regards,

Khanchna Case Handler

LKK Auto Consultants Pte Ltd

DID: **6841 2360** email: Khanchna@lkkauto.com|Fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan Wei Teck (Auto Sves/Claims & IA/Claims & IA/Buses) < Tan Wei Teck@smrt.com.sg>

Sent: Monday, 23 December 2019 11:51 AM

To: Khanchna (LKK Auto) <khanchna@lkkauto.com>

Cc: Karen Chan Siau Chin (Auto Svcs/Claims & IA/Claims & IA/Buses) < ChanSiauChin@smrt.com.sg>;

Admin A <admin-a@lkkauto.com>

Subject: RE: OFFER - ACCIDENT INVOLVING SG1225A AND SLZ6022T [AIG] ON 30/06/2018 SLE

TOWARDS BKE UPPER THOMSON ROAD EXIT

WITHOUT PREJUDICE

Dear Khanchna,

We thank you for your offer but regret that we are unable to accept your offer on LOU as it was lower than the benchmark rates for a single deck bus.

Purely for a quick and amicable settlement, we are prepared to accept as follows:-

TOTAL	\$ 13,466.58	
3. LTA Search fee	\$ 7.00	
2. Loss of Use (5 days x \$250)	\$ 1.250.00	
1. Cost of Repair	\$ 12,209.58 (agreed)	

Kindly let us hear from you soon, thanks.

Regards.

Patrick Tan

Claims and Insurance Agency Direct line +65 6556 3522 tanweiteck@smrt.com.sg 6 Ang Mo Kio Street 62 Singapore 569140 From: Khanchna (LKK Auto) [mailto:khanchna@lkkauto.com]

Sent: 23/12/2019 10:00

To: Tan Wei Teck (Auto Svcs/Claims & IA/Claims & IA/Buses)

Cc: Karen Chan Siau Chin (Auto Svcs/Claims & IA/Claims & IA/Buses); Admin A

Subject: OFFER - ACCIDENT INVOLVING SG1225A AND SLZ6022T [AIG] ON 30/06/2018 SLE TOWARDS BKE UPPER.

THOMSON ROAD EXIT

Without Prejudice (save as to costs)

Dear Sirs/Mdm.

We refer to the above matter.

We propose settlement as follows: -

TOTA	\$ 13,216.58
3. LTA Search fee	\$ 7.00
2. Loss of Use (5 days x \$200)	\$ 1.000.00
1. Cost of Repair	\$ 12.209.58

Please confirm acceptance.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

"Best Wishes for Merry Christmas & Happy New Year 2020"

Best Regards,

Khanchna Case Handler


LKK Auto Consultants Pte Ltd

DID: **6841 2360** email: Khanchna@lkkauto.com Fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

[&]quot;Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.







Print Received Message

This mail is associated with:

*SG1225A (5065281590SG) [SLZ6022T]

TP SMRT BUSES LTD Jun 30 2018 5:00PM [SIM SOCK NGEE] SMRT Automotive Services Pte Ltd

From

AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 02/01/2020 13:49 PM.

Subject

Alert - Adj Mandate Approved (S\$13466.58) - SG1225A - Claim Handler: Chan, Kian-Meng

Approved: 13466.58.

...CLAIM SUBFOLDER...(Pending for Survey Report) Express

Case Notified Est Submitted Adj Assigned Adj Rpt Adj		Submitted	Ins Auth'ed	Statu	15					
Main	08 Jul 2018 Edit Reg		05 Jul 2018 00:00 Edit Adj Rpt	S\$12,209.58 Edit Estimate	1119 1111	2,209.58 ew Rpt		Pending for Survey Report Cancel Case		lurvey
	Main	R	eference	Clain	Details		Document	*	٦.	Show All
CLAIM SU	BFOLDER D	ETAILS				[Created	by adjuster]			
insured:	SIM SOC	K NGEE, ID: S11	85532F							
Main Claimant:	SMRT BU	SES LTD, Co. R	eg. No.: 198202292	D						
Vehicle Res	SG122	5A		Da	e of Loss:		2018 17:00 - :59 ths and 3 Days From LTA Reg Date (Man Yr))			
Claim Type	TP / 50	55281590SG			cy/Cover e No.:	21004868	2100486881 (Comprehensive)			
Vehicle Re No. (Insured):		SLZ6022T				D-180902	D-18090224MFBP			
				1 4011	ess:		II - Walter W. H. Walter T. Child	1		
Repairer:			s Pte Ltd (Woodla						6866262	18:
Handling Insurer:		Pacific Insurance Chan1@aig.com	e Pte. Ltd. (Expre	ss) - Tel: 65-64	19-3000	[Handled	by Chan, Kian-Me	ingj		
Claimant's Insurer:	MS First	ALTERNATION STORY	e Ltd (HQ) - Tel: 6							
Adjuster:	18/07/2		Ltd (HQ) - Tel: 62	56-3561 [Ha	ndled by !	Sathya Sar	Kathirrasen] [Final R	lpt due	
ASSOCIATED MAIL RECEIVED							Vie	ew All	Compos	e Casa Mai
 AIG_SG AIG_SG 	_EXPRESS (0) _EXPRESS (2)	2/01/2020): Alert 0/12/2019): Alert	- Adj Mandate Ap; - Adj Mandate Ap;	proved (5\$134 proved (5\$132	66.58) - 16.58) -	SG1225A - SG1225A -	Claim Handler: Claim Handler: C	Chan, Ki Chan, Ki	an an	
ALL ASS	CIATED TA	sks ^E				View All	Search Tasks	Create Ne	w Task	Complet
Due Dat	te Priority	Type Task	Group Subject	t Handler		ned By	Completed On		eated On	Don

Claim Documents

*SG1225A (5065281590SG) [SLZ6022T]
TP
SMRT BUSES LTD Jun 30 2018 5:00PM [SIM SOCK NGEE] SMRT Automotive Services Pte Ltd

Lett	ters/Corresponden	ices	1 per	page 🔻	82
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnall	Prin
1	(Draft)	Third Party Express Settlement - Payment Breakdown	0	Edit	
Ass	essment Reports		1 per	page [V]	V
No.	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnall	
1	10/07/18 11:56	Accident Statement	0	Load HTM	
		From:SC - Reg. Nv: St,Z6022T, Claimant: SIM SOCK NGEE			-
Pho	itos/Images		3 per	page 🔻	100
No:	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	1
1	10/07/18 09:39	General View	0	Load JPG	N
2:	10/07/18 09:39	General View	0	Load JPG	80
3	10/07/18 09:39	General View	0	Load JPG	Ø
4	10/07/18 09:39	General View	0	Load JPG	V
5	10/07/18 09:39	General View	0	Load JPG	Z
6	10/07/18 09:39	General View	0	Load JPG	80
7	10/07/18 09:39	General View	0	Load JPG	Ø
В	10/07/18 09:39	General View	0	Load JPG	Ø
9	10/07/18 09:39	General View	0	Load JPG	Ø
10	10/07/18 09:39	General View	0	Load 3PG	82
11	10/07/18 09:39	General View	0	Load JPG	82
12	10/07/18 09:39	General View	0	Load JPG	V
_		General View	0	Load JPG	12
13	10/07/18 09:39		0	Load 3PG	2
14	10/07/18 09:39	General View			-
15	10/07/18 09:39	General View	- 0	Load JPG	8
16	10/07/18 09:39	General View	0	Load JPG	8
17	10/07/18 09:39	General View	0	Load JPG	82
18	10/07/18 09:39	General View		Load 3PG	V
19	10/07/18 09:39	General View	0	Load JPG	N
20	10/07/18 09:39	General View	0	Load JPG	2
21	10/07/18 09:39	General View	0	Load JPG	82
22	10/07/18 09:39	General View	0	Load JPG	8
23	10/07/18 09:39	General View	0	Load JPG	V
24	10/07/18 09:39	Chassis Number	0	Load JPG	V
25	10/07/18 09:39	Odometer Reading	0	Load JPG	2
26	10/07/18 09:39	General View	0	Load JPG	2
27	10/07/18 09:39	General View	0	Load JPG	M
28	10/07/18 09:39	General View	0	Load JPG	N
29	28/02/19 18:26	Replacement Part Photo	0	Load JPG	R
-		Replacement Part Photo	0	Load JPG	120
30	28/02/19 18:26	Replacement Part Photo	0	Load JPG	100
31	28/02/19 18:26	y engles and an analysis of the control of the cont			1 EZ
32	28/02/19 18:26	Replacement Part Photo	0	Load JPG	_
33	28/02/19 18:26	Replacement Part Photo	0	Load JPG	82
34	28/02/19 18:26	Replacement Part Photo	0	Load JPG	82
35	28/02/19 18:26	Replacement Part Photo	0	Load JPG	8

Lett	ters/Corresponder	ces	1 per s	sage 🔻	1000
Nα	Finalized On	zed On LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	
industriants.		10.75			82
Doc	cumentation		1 per s	age V	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	09/07/18 17:09	TP ESTIMATE- MARKED	0	Load PDF	
2	09/07/18 17:09	TP GIA REPORT	0	Load PDF	
3	28/08/19 17:11	EMAIL TO OI	0	Load PDF	
4	02/09/19 11:07	OI GIA REPORT	0	Load PDF	
5	22/11/19 08:11	LTA SEARCH	0	Load PDF	
6	22/11/19 17:09	LOD FINAL TAX INVOICE LTA SEARCH	0	Load PDF	
7	15/01/20 10:23	WORKSHOP INVOICE	0	Load PDF	
8	15/01/20 10:23	AUTHORISATION TO ACT FORM	0	Load PDF	
9	15/01/20 10:23	Release Voucher	0	Load PDF	
10	15/01/20 10:23	LOD	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	^
	~
Show Remarks To: Handling Insurer flute: Remarks are private unless you show it to other parties.	

NOTE: TO BE COMP	LETED	BY	SURVEYOR
------------------	-------	----	----------

TEAM		
1 6-2111		

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLZ60	SLZ6022T (Insd veh)		Model:	MERCEDES-BEN	MERCEDES-BENZ CITARO	
	SG1225A (TP veh) : 30/06/2018			O530 6.4 D (A)			
Date of Accident							
Global Sum Settle	ment :	[] Yes		[X] No			
Repair Estimate			; \$	20,854,47			
Final Repair Cost			\$	12,209.5	8		
Loss of Use			: \$	1,250.0	0 5.00 days at \$250	.00 per day	
Rental (if any)			: \$	0.0	0 days		
LTA / GIA Search	Fee		: \$	7.0	0		
Others:			: \$	0.0	0		
			: \$				
Final Settlement S	Sum		: \$	13,466.5	8		
A) For Non GIA	Register	ed Worksho	p:	Agreed Liabi	ity100(%) able: Yes/ No BOLA Scr	anario No	
B) For GIA Regi	stered W	orkshop:		BOLA Applic	able: Yes/ No BOLA So	anano ivo:	
BOLA Liability	,-	(%)		Assessed Lis	bility (*):(%	63	
			for chai		for cases where BOLA do		
Remarks			N. C.				
						_	
Payment Instruc	tion: Pay	ee's Breakd	own				
1) SMRT Buses	Ltd			: \$		13,466.5	
2)				: \$			
3)				: \$			
JOANNE	LEE KHA	ANG MIN		15 Jan 2020			
LKK Auto	Consultar	nts Pte Ltd		Date			

Please attach all the supporting documents to the form. (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any)

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18012434/VKA3Q2

Date:

15/01/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

2100486881

Claimant Vehicle No:

SG1225A

Insured Vehicle No: SLZ6022T

Date of Loss:

30/06/2018

Nature of Claim:

TP

Claim No: 5065281590SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SG1225A

Make & Model:

MERCEDES-BENZ CITARO 0530, 6.4 D (A)

Engine No:

902926C1112186

Reg. Date: Colour:

27/12/2017 (Man. Year: 2016) Multi-colour

Chassis No: Odometer:

WEB62808323130959 6398 km

Engine Capacity:

6374 cc

Market Value/New Car

N/A

Price:

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Sum Insured (S\$):

Steering (Serviceable):

Yes Engine Modification:

Yes Footbrake (Serviceable): No Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES Front Tyre Size:

275/70 R22.5

Rear Tyre Size:

275/70 R22.5

Front Left Side:

Bridgestone 6 mm

Rear Left Side:

Bridgestone 6 mm

Front Right Side:

Bridgestone 6 mm

Rear Right Side:

Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		17,058.47	9,589.58	7,468.89	43.78
Miscellaneous Items		0.00	0.00	0.00	
Labour		3,796.00	2,620.00	1,176.00	30.98
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Nett Amount (S\$)	20,854.47	12,209.58	8,644.89	41.45
	+ Loss of Use (5.0 x S	\$250.00/day) (S\$)	1,250.00		
	+ Do	c/Search Fee (S\$)	7.00		
		Nett Liability (S\$)	13,466.58		

INSPECTION

Date of Assignment:

05/07/2018

Date Inspected:

05/07/2018 Inspected At:

SMRT Automotive Services Pte Ltd

(Woodlands)

60 Woodlands Industrial Park E4

Singapore 757705

Estimated Period of Repair:

5.0 days

Adjuster: Sathya Sar Kathirrasen

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*CROSS BAR REAR BUMPER (SBS VERSION)	Dented	2,700.00 F	*2,700.00 FL
1		*REAR BUMPER CENTER	Damaged	1,791.33F	*1,791.33 FL
1		*REAR BUMPER RH	Cut	837.84 F	*837.84 FL
1		*COVER UNDER RH (SBS VERSION)	Cut	1,750.00 F	*1,750.00 FL
1		*PIPE COPPER (SBS VERSION)	Dented	850.00 F	*850.00 FL
2		*LAMP ,LICENSE PLATE FOR MB CITARO 0530	Cracked	195.36 F	*195.36 FL
1		*COOLANT :ANTIFREEZE	Necessary	524.00 F	*524.00 FL
1		*COVER UNDER LH (SBS VERSION)	Cut	1,931.00 F	*1,931.00 FL
1		*FLAP ENGINE:FOR MB CITARO 0530	Repair	5,573.10F	*-FL
1		*REAR BUMPER LH	Repair	837.84 F	*-FL
1		*NUMBER PLATE	Dented	68.00 FS	*68.00 FS
chise	part S=Spc	Nett. L=ListitemDisc.	Sub Total (S\$)	17,058.47	10,647.53
		0.00	1,057.95		
		in the second se	Total Parts (S\$)	17,058.47	9,589.58
** * * * * * * * * * * * * * * * * * * *	1 1 1 1 1 1 1 1 1	1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	*CROSS BAR REAR BUMPER (SBS VERSION) *REAR BUMPER CENTER *REAR BUMPER RH *COVER UNDER RH (SBS VERSION) *PIPE COPPER (SBS VERSION) *LAMP ,LICENSE PLATE FOR MB CITARO 0530 *COOLANT :ANTIFREEZE *COVER UNDER LH (SBS VERSION) *FLAP ENGINE:FOR MB CITARO 0530 *REAR BUMPER LH *NUMBER PLATE chise part. S=SpcNett. L=ListHemDisc. - List Item Discount on L Items 0.	*CROSS BAR REAR BUMPER (SBS VERSION) *REAR BUMPER CENTER *REAR BUMPER RH *COVER UNDER RH (SBS VERSION) *PIPE COPPER (SBS VERSION) *LAMP ,LICENSE PLATE FOR MB CITARO 0530 *COOLANT :ANTIFREEZE *COVER UNDER LH (SBS VERSION) *FLAP ENGINE:FOR MB CITARO 0530 *FLAP ENGINE:FOR MB CITARO 0530 *REAR BUMPER LH *NUMBER PLATE Chise part. S=SpcNeft. L=ListItemDisc. *Sub Total (S\$) *List Item Discount on L Items 0.00/10.00% (S\$)	*CROSS BAR REAR BUMPER (SBS VERSION) Dented 2,700.00 F *REAR BUMPER CENTER Damaged 1,791.33 F *REAR BUMPER RH Cut 837.84 F *COVER UNDER RH (SBS VERSION) Cut 1,750.00 F *PIPE COPPER (SBS VERSION) Dented 850.00 F *LAMP ,LICENSE PLATE FOR MB CITARO 0530 Cracked 195.36 F *COOLANT :ANTIFREEZE Necessary 524.00 F *COVER UNDER LH (SBS VERSION) Cut 1,931.00 F *FLAP ENGINE:FOR MB CITARO 0530 Repair 5,573.10 F *REAR BUMPER LH Repair 837.84 F *NUMBER PLATE Dented 68.00 FS chise part. S=SpcNett. L=ListItemDisc. *Sub Total (S\$) 17,058.47 - List Item Discount on L Items 0.00/10.00% (S\$) 0.00

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	3,180.00	2,120.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	New	616.00	500.00
	Gross Labou	r Cost (S\$)	3,796.00	2,620.00
	Report was unsubmitted durin	g this print-out.		

< END OF ESTIMATES >