

22/03/2018

ASS. REC. BY:

REF: CS/AWA18012443/Asd3n2

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Tang Ben

of

AWAC

Date/Time: 9/07/2018 @ 2:54pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGJ 1965Z

Insured:

SJU 1742G

at Workshop m/s

New Hook Teck

Tel:

6747 9241

of 1 kaki Bukit Ave 6 Blk C # 01-43 Autobay

Policy No:

AVPPSB0550871700

Claim No:

Sum Insured

Excess:

Make of Veh:

(Client's Record)

D.O.A. 06/07/2018

CA / REV / REP. / REV 24 HRS

kup

H.O.D. Endorsement:

Date/Time:

3:05pm @ 9/7/18

Person Contacted:

Reena

Vehicle: IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SGJ 1965Z - X
	SJU 1742G - X
	(\$ 22,375.90 Red - 63%)

REF:

ASS. REC. BY: Adrian King

ASSIGNMENT

2010 March

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SG1965Z Yr Regn: 1
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Honda Accord c.c. 1997
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 120219 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MRHC2163097020032
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 225/50 R17
 R: 225/50 R17

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 09/07/18
 Survey held at NHT

Bal. or Market Value: _____
 IDAG Accident Rport: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP AWA.
	MV: 34.5K
	PV: 21.4K
	Nett: 13.1K
RECEIVED 17 AUG 2018	

Date/Time, File Pass to? 17/08/18
 1) Typist
 Date/Time, File Return to? _____
 2) _____
 Report Format: _____
 Lump Sum / L.B.I. (\$) 13,000.00 HS

Days Of Repair: 12
 Resurvey No. of Trip: 1
 Add Fee: Site Insp (\$))
 Interview (\$))
 Tech. Invs (\$))
 Weekend (\$))
 Survey Fee: _____
 Transportation: _____ \$ + RS, SI
 Photos _____
 Others _____
 TOTAL 350

Nivitha (LKK Auto)

From: Tang, Ben <Ben.Tang@awac.com>
Sent: Monday, 9 July 2018 2:54 PM
To: LKK (assignments@lkkauto.com)
Cc: reena@nhtmotor.com; SUR (sur@lkkauto.com) (sur@lkkauto.com)
Subject: TP Survey assignment for SGJ1965Z DOA:06/07/2018 Our ref: SJU 1742G

The above captioned accident refers.

Pursuant to the Practice Directions Amendment No. 1 of 2016 which was effective on 1 April 2016, we like to advise that the third party claimant and us do have consensus in the appointment of **Mr Chua Weijie** as the Single Joint Expert to conduct the pre-repair survey of the third party claimant's vehicle.

Please conduct "THIRD PARTY" survey on without prejudice basis. The information as are follows:

3 rd Party Vehicle	:	SGJ 1965Z
Insured Vehicle	:	SJU 1742G
Policy Number	:	AVPPSB0550871700
Name of Workshop	:	New Hock Teck Motor Pte Ltd
Contact Number	:	6747 9241
Person to Contact	:	Reena
Estimated Cost of repairs	:	\$NA

Regards,
Claims Division

Copy to New Hock Teck Motor Pte Ltd (Your Ref:SGJ1965Z) via Email

Note -

- (x)
1. This is to keep you informed that we have appointed surveyors to conduct inspection to your client's damaged vehicle on a without prejudice basis.
 2. **Please keep our motor surveyor and us informed so as to enable the surveyor to conduct a post repair inspection once your client's vehicle has been repaired and before returning the repaired vehicle to your customer.**
 3. Please quantify your client's claim with all relevant supporting documents once your client's vehicle has been repaired.
 4. Please do not construe this appointment of surveyor and our above request as an admission of liability.

Regards
Motor Claims
Claims Group
Global Market

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, GmbH or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
 Owner ID: 5634F

Vehicle Details

Vehicle No.: SGJ1965Z
 Vehicle to be Exported: Yes
 Intended De-registration Date: 06 Jul 2018
 Vehicle Make: HONDA
 Vehicle Model: ACCORD 2.0L
 Primary Colour: White
 Manufacturing Year: 2009
 Engine No.: R20A32800183
 Chassis No.: MRHCP16309P020232
 Maximum Power Output: 115.0 kW (154 bhp)
 Open Market Value: \$30,624.00
 Original Registration Date: 29 Mar 2010
 First Registration Date: 29 Mar 2010
 Transfer Count: 0
 Actual ARF Paid: \$30,624.00

Intended PARF Rebate Details

PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 28 Mar 2020
 PARF Rebate Amount: \$16,843.00

Intended COE Rebate Details

COE Expiry Date: 28 Mar 2020
 COE Category: B - Car (1601cc & above)
 COE Period(Years): 10
 QP Paid: \$26,389.00
 COE Rebate Amount: \$4,554.00
Total Rebate Amount: \$21,397.00

The information contained herein is correct as at 06 Jul 2018

OK

MSME18087593 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 07/07/2018 13:21
 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the judgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/07/2018 13:21
Date Of Accident	06/07/2018 17:30
Exact Location Of Accident	TPE (SLE) AFTER EXIT 5
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGJ1965Z
Insured/Policyholder	
Name Of Registered Owner	SIEW KOK WAH RAYMOND
NRIC No	S1385634F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98621001
Alternative Phone No	OFFICE-98621001
Vehicle Particulars	
Manufacturer	HONDA
Model	ACCORD
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D27480187QMY
Cover Note Number	
Driver	
Name of Driver	SIEW KOK WAH RAYMOND
NRIC No	S1385634F
Date Of Birth	25/03/1959
Occupation	INDOOR
Date Of Driving Pass	11/06/1979
Driving Experience	39 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98621001
Fax Number	
Contact Number	OFFICE-98621001
E-Mail Address	NOEMAIL

07/07 2018 SAT 13:53 FAX

Address BLK 122 PUNGGOL WALK #07-45
 Postcode 828771
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

MY VEHICLE WAS STATIONARY ON THE EXTREME RIGHT LANE ALONG TPE (SLE) AFTER EXIT 5. SUDDENLY, I HEARD A LOUD BANG AND FELT A HUGE IMPACT. VEHICLE B HIT ON THE REAR PORTION OF MY VEHICLE AND CAUSED DAMAGES. DUE TO THE HUGE IMPACT, MY VEHICLE SURGED FORWARD AND HIT ONTO VEHICLE D. I ALIGHTED AND REALISED THERE WERE A TOTAL OF 4 VEHICLES INVOLVED.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJU1742G
 Vehicle Make/Model/Colour
 Details Of Properties VEHICLE B
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SKW3598X
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE C
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SJX5556K
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE D
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:
7/18

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

STAMP HERE (If applicable)

NEW HOCK TOOK

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My vehicle was stationary on the extreme right lane along TPE (SLE). After Exh 5.

Suddenly, I heard a loud bang and felt a huge impact. Vehicle B hit on the rear portion of my vehicle and caused damage.

Due to the huge impact, my vehicle surged forward and hit onto vehicle D.

I alighted and realized there were a total of 4 vehicles involved.

DECLARATION

(We declare the foregoing particulars are true in every respect.

[Signature]
 Policyholder's Signature
 Date & Time:

[Signature]
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

my vehicle was stationary on the extreme right lane along TPE (SLE). After EXT B.

Suddenly, I heard a loud bang and felt a huge impact. vehicle B hit on the rear portion of my vehicle and caused damages.

Due to the huge impact, my vehicle surged forward and hit onto vehicle D.

I alighted and realized there were a total of 4 vehicles involved.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SELL YOUR CAR BY BIDDING

HIGHEST SELLING PRICE GUARANTEED!

OR GET \$100 CASH!

FOR SALE BY OWNER

Post an Advertisement
Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

[Post an Ad](#) | [Advertiser Login](#) | [Ways of Selling](#)

Reg.Date: 27-May-2010, Mercedes-Benz 300, 2997cc.

High OMV \$91,289.00 / COE \$38,000.00, PARF Car. Direct Owner StarAd

ABWIN **ONE-STOP** AUTOMOTIVE SOLUTIONS

VIEW OUR PROFILE

[Browse by Category](#) | [Save Search](#) | [Print](#) | Sort by Date Posted | 20 results/page

8 vehicles | **Search** Honda Accord

Advanced Search | |

Make | Model | Price | Depreciation | Reg Date | Eng Cap | Mileage | Veh Type | Status

Search Selection	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
	Honda	Accord	Any	Any	2010	Any	Any	Any	Available

Honda Accord 2.0A | \$32,300 | \$10,710 /yr | 10-Feb-2010 | 1,997 cc | - | Luxury | Available

Lowest Price Luxury Accord In The Mkt! New 2018 License Plate Number! Low Mileage, Up To 90% Loan Available. No Repair Needed! Potential For COE Renewal! Flexible Auto Loans & Trade In Welcome. Buy Wi...

★ Posted: 23-Jul-2018 | Tags: 2010 Honda Accord, Honda Accord, Honda, Accord, Used Honda

Honda Accord 2.0A | \$33,800 | \$10,970 /yr | 17-Mar-2010 | 1,997 cc | - | Luxury | Available

Popular Mid Size Sedan, Honda Accord At Its Best! Well Taken Care By Owner, Daily Driven For Work. Looking To Upgrade Hence Selling The Vehicle. Impressive Fuel Consumption For An Accord, View To Appr...

★ Posted: 15-May-2018 | Tags: 2010 Honda Accord, Honda Accord, Honda, Accord, Used Honda

Honda Accord 2.4A | \$33,800 | \$9,510 /yr | 29-Mar-2010 | 2,354 cc | 135,482 km | Luxury | Available

1 Owner Only! Beautiful Black On Black Honda Accord! Stylish, Spacious And Comfortable Executive Sedan! High Parf Value Of \$17472! Call Us Today!

★ Posted: 16-Jun-2018 | Tags: 2010 Honda Accord, Honda Accord, Honda, Accord, Used Honda

Honda Accord Euro S | \$40,800 | \$13,370 /yr | 14-Jun-2010 | 2,354 cc | 160,000 km | Luxury | Available

Very Well Maintained Euro-S, Belongs To A Ex Retired Military Officer That Changed A New Car, Totally Can't Bear To Part With This Ex-lover. Can't Bear To See This Car Being Single In A Car Mart Parki...

Car Times Automobile Pte Ltd

★ Posted: 28-Jun-2018 | Tags: 2010 Honda Accord, Honda Accord, Honda, Accord, Used Honda

[Car Buying](#) | [Car Selling](#) | [Car Ownership](#) | [Car Aftermarket](#) | [On The Move](#) | [Lifestyle](#)

Buying a pre-owned car, but Unsure of its Condition? Get STA Car Evaluation

Honda Accord 2.4A | \$41,800 | \$11,850 /yr | 10-Aug-2010 | 2,354 cc | - | Luxury | Available

Well Maintained, Beautiful Interior And Exterior, Only \$4,180 Down Payment. Up To 90% Flexible Loan. We Provide Lowest Interest Rate. Flexible Loan And High Trade In Are Available. Package With Unriva...

Classic Credit Pte Ltd

★ Posted: 20-Jun-2018 | Tags: 2010 Honda Accord, Honda Accord, Honda, Accord, Used Honda

Honda Accord 2.4A | \$40,800 | \$11,370 /yr | 10-Aug-2010 | 2,354 cc | - | Luxury | Available

Flexible Loan. We Provide Lowest Interest Rate. Flexible Loan And High Trade In Are Available. Package With Unrivalled Warranty Complete With Certificate And Test Report. Check Out Our New Offer Now. M...

Classic Credit Pte Ltd

★ Posted: 23-May-2018 | Tags: 2010 Honda Accord, Honda Accord, Honda, Accord, Used Honda

Honda Accord 2.0A | \$42,800 | \$11,810 /yr | 02-Nov-2010 | 1,997 cc | 107,000 km | Luxury | Available

Well Maintained By 1 Owner With Low Mileage Done. Spacious And Luxury Drive For You And Your Family. Flexible Loan Scheme With In House Loan Available. Please Call Or Visit Us Now For Further Details.

★ Posted: 04-Jul-2018 | Tags: 2010 Honda Accord, Honda Accord, Honda, Accord, Used Honda

| **Honda Accord 2.0A** | \$44,888 | \$12,510 /yr | 10-Nov-2010 | 1,997 cc | - | Luxury | Available **(GREAT OFFER)**



Adrian Lee AWA
 新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883
 Email: admin@nhtmotor.com Website: www.nhtmotor.com
 Tel: 6747 9241 Fax: 6741 7276
 UEN: 201718370K

RAYMOND SIEW KOK WAH
 Blk 1 Kaki Bukit Ave 6
 # 01-43
 Singapore 417883

09/07/2018

TPAWA
 Shirley
 MRHCP16309P020232

Accident date: 06/07/2018

Estimated repair cost for vehicle no: SGJ1965Z HONDA ACCORD 2.0 A '10

CHASSIS: MRHCP16309P020232

S/n	Qty	Items	U/price	Amount
1	1	Front Bonnet <i>Distorted</i>		\$899.50 ✓
2	2	Front Bonnet Hinge <i>2 new</i>	\$43.50	\$87.00 ✗
3	2	Front Bonnet Shock Absorber <i>new</i>	\$165.00	\$330.00 ✗
4	1	Front Bonnet Lock <i>Damaged</i>		\$102.50 ✓
5	1	Front Bonnet Insulator <i>Cracked</i>		\$119.50 ✓
6	9	Front Bonnet Insulator Clip <i>new</i>	\$6.50	\$58.50 ³⁰
7	1	Front Bonnet Inner Rubber <i>2 new</i>		\$68.10 ✗
8	9	Front Bonnet Inner Rubber Clip <i>new</i>	\$3.50	\$31.50 ✗
9	2	Front Head Lamp <i>cracked</i>	\$621.70	\$1,243.40 ✓
10	2	Front Head Lamp Lower Bracket <i>cracked</i>	\$88.50	\$177.00 ✓
11	1	Front Bumper <i>Deformed</i>		\$620.50 ✓
12	8	Front Bumper Clip <i>new</i>	\$6.50	\$52.00 ³⁰
13	2	Front Bumper Side Retainer <i>new</i>	\$25.00	\$50.00 ✓
14	1	Front Bumper Number Plate <i>Bent</i>		\$50.00 ✓
15	1	Front Bumper Number Plate Garnish <i>Deformed</i>		\$75.40 ✓
17	1	Front Bumper Reinforcement <i>Bent</i>		\$353.90 ✓
19	2	Front Bumper Fog Lamp <i>new</i>	\$397.40	\$794.80 ✗
21	1	Front Bumper Lower Spoiler (Special Nett) <i>Cracked</i>		\$1,800.00 ^{490/sw}
22	2	Front Bumper Sensor <i>Damaged 1 piece</i>	\$226.40	\$452.80 ^{226.40}
23	2	Front Bumper Sensor Holder Bracket <i>2 new</i>	\$48.40	\$96.80 ✗
24	2	Front Bumper Sensor Rubber Seal <i>new</i>	\$12.50	\$25.00 ✗
25	1	Front Grille (Special Nett) <i>Cracked</i>		\$1,200.00 ^{450/sw}
27	1	Front Grille Emblem Logo <i>new</i>		\$27.20 ✓
28	2	Front Fender <i>Repair</i>	\$607.70	\$1,215.40 ✗
29	2	Front Fender Cowling	\$116.60	\$233.20 ✗
30	16	Front Fender Cowling Clip <i>new</i>	\$6.50	\$104.00 ✗
31	2	Front Fender Inner Cover <i>new</i>	\$105.00	\$210.00 ✗
32	6	Front Fender Inner Cover Clip	\$6.50	\$39.00 ✗

33	1	Front Support Panel	Buckled		\$600.40	✓
34	1	Front Support Panel Lock Cover	Crushed		\$65.10	✓
36	1	Front Support Panel Top Cover	Repaired		\$128.00	x
37	8	Front Support Panel Top Cover Clip	new	\$6.50	\$52.00	20 ✓
38	2	Front Support Panel Lower Side Air Duct Cover	new	\$61.90	\$123.80	x
39	1	Front Air-Con Condenser	Bent		\$623.10	✓
40	1	Front Air-Con Section Pipe	2nd		\$196.70	x
41	1	Front Air-Con Discharge Pipe	new		\$196.60	x
42	1	Front Air-Con Fan Motor Assy	new		\$396.70	x
43	1	Front Radiator	Bent		\$1,354.50	1283 ✓
44	1	Front Radiator Top Hose	new		\$34.40	x
45	1	Front Radiator Fan Motor Assy	new		\$302.80	x
46	1	Front L/H Side Air Duct Cover	new		\$55.00	x
47	1	Rear Boot Lid	Buckled		\$878.40	✓
48	2	Rear Boot Lid Hinge	new	\$44.20	\$88.40	x
49	1	Rear Boot Lid Emblem Logo	?		\$27.10	✓
50	1	Rear Boot Lid Accord Logo	new		\$24.20	✓
51	1	Rear Boot Lid I-Vtec Logo			\$32.20	✓
52	1	Rear Boot Lid Number Plate	new		\$50.00	x
53	1	Rear Boot Lid Number Plate Garnish	behind		\$432.80	✓
54	2	Rear Boot Lid Side Reflector	new	\$292.40	\$584.80	x
55	1	Rear Boot Lid Top Spoiler (Special Nett)	new		\$680.00	x
56	1	Rear Boot Lid Inner Lock	dent		\$210.90	✓
57	1	Rear Boot Lid Inner Rubber	lt		\$185.00	✓
58	1	Rear Boot Lid Inner Trim Board	2nd		\$264.80	x
59	8	Rear Boot Lid Inner Trim Board Clip	new	\$6.50	\$52.00	x
60	2	Rear Tail Lamp	crushed	\$336.70	\$673.40	✓
61	4	Rear Tail Lamp Clip	new	\$8.00	\$32.00	✓
62	2	Rear Tail Lamp Panel	Repair	\$189.20	\$378.40	x
63	1	Rear Bumper	Deformed		\$630.50	✓
64	8	Rear Bumper Clip	new	\$6.50	\$52.00	30 ✓
65	2	Rear Bumper Side Retainer	new	\$47.50	\$95.00	✓
66	1	Rear Bumper Reinforcement	Bent		\$295.60	✓
68	2	Rear Bumper Mud Shield	2nd	\$93.80	\$187.60	x
69	8	Rear Bumper Mud Shield Clip	new	\$6.50	\$52.00	x
70	1	Rear Bumper Lower Spoiler (Special Nett)	behind		\$1,800.00	95d(w) ✓
72	4	Rear Bumper Reverse Sensor	Dent (2 pieces)	\$226.40	\$905.60	452.80 ✓
73	4	Rear Bumper Reverse Sensor Holder Bracket	2nd	\$48.10	\$192.40	x
74	4	Rear Bumper Reverse Sensor Rubber Seal	new	\$12.50	\$50.00	x
75	1	Rear End Panel	Dented		\$287.40	✓
76	1	Rear End Panel Top Garnish	Deformed		\$197.70	✓
77	2	Rear Fender Inner Trim Board	2nd	\$163.50	\$327.00	x
78	16	Rear Fender Inner Trim Board Clip	new	\$6.50	\$104.00	x

79	1	Rear Spare Tyre Panel	Repair		\$837.50	+
80	1	Rear Spare Tyre Panel Top Cover	top		\$233.40	✓
81	2	Rear Spare Tyre Panel Top Side Sponge	new	\$145.00	\$290.00	+
82	1	Rear Spare Tyre Panel & End Panel Sealant	new		\$450.00	(dsw)
83	1	Rear Exhaust	Beut		\$1,241.30	1005-60
85	1	Rear Exhaust Chrome Pipe	Beut		\$126.00	✓
86	2	Rear Exhaust Mounting	AMP	\$25.70	\$51.40	+
87	1	Rear Exhaust Aluminium Cover	new		\$159.00	+

11168.50
8934.80

Subtotal :- \$27,805.90
S N 2250

Labour charges

To remove & refit front & rear bumper lower spoiler & boot lid spoiler		\$380.00	200
To remove & refit front sensor & reverse sensor		\$200.00	120
To remove & refit cushion		\$280.00	80
To remove & refit rear & center exhaust		\$380.00	80
To remove & refit air-con condenser, radiator, fan motor & top up gas		\$380.00	120
To check wiring		\$100.00	60
Tuff kote		\$150.00	50
Towing Fees		\$100.00	60
Panel beating		\$3,000.00	2100
Spray painting		\$2,600.00	2100

total 16264.89
h/s: 13K
12 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Subtotal :- \$7,570.00
Total:- \$35,375.90



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA18012443/Asd3n2

(SINGAPORE BRANCH)
60 ANSON ROAD #08-01 (8th FLOOR)
MAPLETREE ANSON
SINGAPORE 079914

Date : 20-08-2018



Code : AWA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJU 1742G	Veh. Inspected	SGJ 1965Z
Policy No.	AVPPSB0550871700	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	TANG BEN	Assign Date	09/07/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA ACCORD	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	MRHCP16309P020232	Colour	WHITE
Odometer	120219	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/50 R17	PIRELLI	6 mm
L/H Front Tyre	225/50 R17	PIRELLI	6 mm
R/H Rear Tyre	225/50 R17	PIRELLI	6 mm
L/H Rear Tyre	225/50 R17	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/07/2018	Inspection Date	09/07/2018
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
-------------------------------------	------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGJ 1965Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BONNET	DISTORTED	899.50	899.50
2	FRONT BONNET HINGE @\$43.50	NOT NECESSARY	87.00	-
2	FRONT BONNET SHOCK ABSORBER @\$165.00	NOT NECESSARY	330.00	-
1	FRONT BONNET LOCK	DAMAGED	102.50	102.50
1	FRONT BONNET INSULATOR	CRUMPLED	119.50	119.50
9	FRONT BONNET INSULATOR CLIP @\$6.50	NECESSARY	58.50	30.00
1	FRONT BONNET INNER RUBBER	NOT NECESSARY	68.10	-
9	FRONT BONNET INNER RUBBER CLIP @\$3.50	NOT NECESSARY	31.50	-
2	FRONT HEAD LAMP @\$621.70	CRACKED	1,243.40	1,243.40
2	FRONT HEAD LAMP LOWER BRACKET @\$88.50	CRACKED	177.00	177.00
1	FRONT BUMPER	DEFORMED	620.50	620.50
8	FRONT BUMPER CLIP @\$6.50	NECESSARY	52.00	30.00
2	FRONT BUMPER SIDE RETAINER @\$25.00	NECESSARY	50.00	50.00
1	FRONT BUMPER NUMBER PLATE	BENT	50.00	50.00
1	FRONT BUMPER NUMBER PLATE GARNISH	DEFORMED	75.40	75.40
1	FRONT BUMPER REINFORCEMENT	BENT	353.90	353.90
2	FRONT BUMPER FOG LAMP @\$397.40	NOT NECESSARY	794.80	-
2	FRONT BUMPER SENSOR @\$226.40	DAMAGED (1 PC ONLY)	452.80	226.40
2	FRONT BUMPER SENSOR HOLDER BRACKET @\$48.40	NOT NECESSARY	96.80	-
2	FRONT BUMPER SENSOR RUBBER SEAL @\$12.50	NOT NECESSARY	25.00	-
1	FRONT GRILLE EMBLEM LOGO	NECESSARY	27.20	27.20
2	FRONT FENDER @\$607.70	TO REPAIR SEE LABOUR	1,215.40	-
2	FRONT FENDER COWLING @\$116.60	NOT NECESSARY	233.20	-
16	FRONT FENDER COWLING CLIP @\$6.50	NOT NECESSARY	104.00	-
2	FRONT FENDER INNER COVER @\$105.00	NOT NECESSARY	210.00	-
6	FRONT FENDER INNER COVER CLIP @\$6.50	NOT NECESSARY	39.00	-
1	FRONT SUPPORT PANEL	BUCKLED	600.40	600.40
1	FRONT SUPPORT PANEL LOCK COVER	CRACKED	65.10	65.10
1	FRONT SUPPORT PANEL TOP COVER	REPEATED	128.00	-

Report Ref No. CS/AWA18012443/Asd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
8	FRONT SUPPORT PANEL TOP COVER CLIP @\$6.50	NECESSARY	52.00	20.00
2	FRONT SUPPORT PANEL LOWER SIDE AIR DUCT COVER @\$61.90	NOT NECESSARY	123.80	-
1	FRONT AIR-CON CONDENSER	BENT	623.10	623.10
1	FRONT AIR-CON SECTION PIPE	NOT NECESSARY	196.70	-
1	FRONT AIR-CON DISCHARGE PIPE	NOT NECESSARY	196.60	-
1	FRONT AIR-CON FAN MOTOR ASSY	NOT NECESSARY	396.70	-
1	FRONT RADIATOR	BENT	1,354.50	1,283.00
1	FRONT RADIATOR TOP HOSE	NOT NECESSARY	34.40	-
1	FRONT RADIATOR FAN MOTOR ASSY	NOT NECESSARY	302.80	-
1	FRONT L/H SIDE AIR DUCT COVER	NOT NECESSARY	55.00	-
1	REAR BOOT LID	BUCKLED	878.40	878.40
2	REAR BOOT LID HINGE @\$44.20	NOT NECESSARY	88.40	-
1	REAR BOOT LID EMBLEM LOGO	NECESSARY	27.10	27.10
1	REAR BOOT LID ACCORD LOGO	NECESSARY	24.20	24.20
1	REAR BOOT LID I-VTEC LOGO	NECESSARY	32.20	32.20
1	REAR BOOT LID NUMBER PLATE	NOT NECESSARY	50.00	-
1	REAR BOOT LID NUMBER PLATE GARNISH	DEFORMED	432.80	432.80
2	REAR BOOT LID SIDE REFLECTOR @\$292.40	NOT NECESSARY	584.80	-
1	REAR BOOT LID INNER LOCK	DAMAGED	210.90	210.90
1	REAR BOOT LID INNER RUBBER	CUT	185.00	185.00
1	REAR BOOT LID INNER TRIM BOARD	NOT NECESSARY	264.80	-
8	CLIP @\$6.50	NOT NECESSARY	52.00	-
2	REAR TAIL LAMP @\$336.70	CRACKED	673.40	673.40
4	REAR TAIL LAMP CLIP @\$8.00	NECESSARY	32.00	32.00
2	REAR TAIL LAMP PANEL @\$189.20	TO REPAIR SEE LABOUR	378.40	-
1	REAR BUMPER	DEFORMED	630.50	630.50
8	REAR BUMPER CLIP @\$6.50	NECESSARY	52.00	30.00
2	REAR BUMPER SIDE RETAINER @\$47.50	NECESSARY	95.00	95.00
1	REAR BUMPER REINFORCEMENT	BENT	295.60	295.60
2	REAR BUMPER MUD SHIELD @\$93.80	NOT NECESSARY	187.60	-
8	REAR BUMPER MUD SHIELD CLIP @\$6.50	NOT NECESSARY	52.00	-

Report Ref No. CS/AWA18012443/Asd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REFIT AIR-CON CONDENSER,RADIATOR,FAN MOTOR & TOP UP GAS.		380.00	120.00
	TO CHECK WIRING.		100.00	60.00
	TUFF KOTE.		150.00	60.00
	TOWING FEES.		100.00	60.00
	PANEL BEATING INCLUSIVE OF THE REPAIR OF FRONT FENDER,REAR TAIL LAMP PANEL AND REAR SPARE TRYE PANEL.		3,000.00	2,100.00
	SPRAY PAINTING.		2,600.00	2,100.00
			7,570.00	4,980.00
	GRAND TOTAL		35,375.90	17,347.52
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			13,000.00

Report Ref No. CS/AWA18012443/Asd3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.