

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbroy@gmail.com

Invoice/Ref No: GZ3253Y180706

Estimate

Customer

Name: AXA Insurance Singapore Pte Ltd

Address Motor Claims Department

8 Shenton Way #27-01

AXA Tower

Singapore 068811

Date: 06-07-18

Vehicle No: GZ3253Y

Model/Make: Toyota Dyna 150D

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Windscreen Glass 1340.70	\$ 1,573.50	
2	Windscreen Glass Weather Strip	\$ 303.60	
3	Corner Panel	\$ 376.50	
4	Corner Panel Garnish	\$ 199.75	
5	Mirror Arm	\$ 410.80	
6	Side Mirror "Round"	\$ 110.50	
7	Side Mirror "Square"	\$ 185.30	
8	Side Mirror Outer Garnish	\$ 165.20	
9	Door 1775.10	\$ 1,568.30	
10	Door Hinges 02 pcs (@ S\$118.20)	\$ 236.40	
11	Door Inner Board	\$ 781.20	
12	Door Weather Strip	\$ 294.00	
13	Door Glass Run Channel 02 pcs (@ S\$265.80)	\$ 531.60	
14	Door Glass	\$ 498.00	
15	Door Glass Front Garnish	\$ 280.40	
16	Door Glass Moulding	\$ 126.30	
17	Door Pillar	\$ 947.00	
18	Door Pillar Garnish	\$ 297.00	
19	Roof Top Lining	\$ 980.00	
20	Rear Cargo Box Pillar front	\$ 600.00	
21	Cargo Box Inner Panel	\$ 400.00	
22	Cargo Box Outer Panel	\$ 400.00	
23	Cargo Box Sliding Door	\$ 1,200.00	
24	Cargo Box Sliding Door Lower Member	\$ 900.00	
	Remove & reinstall dashboard, meter instruments, disconnect wiring & Etc...	\$ 300.00	
	Remove and refix rear Cargo Back Door components and etc..	\$ 1,600.00	
	Remove & reinstall Windscreen Glass to facilitate repairs & perform water test	\$ 120.00	
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,800.00	
	To putty & spray painting & including touch up paint on accident affected area	\$ 1,400.00	
	To apply Rust Proofing , reseal tuff-coating treatment on accident area	\$ 80.00	

Total Parts & Labour of estimate for damaged vehicle

S 18,665.35

Total amount in Lump Sum Basis for repaired vehicle

SDLS:

We, the undersigned, hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



M/s Liu's Brother Auto Engrg Wks

Not Affected

2/5 #7100/- ?
9/7/18
J. H.

P- 5736.30

257

4302.22

S.N-219880

C/L- 2600

9101.02