KIM CHWEE AUTO PTE LTD 1 Kaki Bukit Ave 6 #01-46,48,50 Autobay SINGAPORE 417883 2/5# 1100/ 2/5# 2 dy.

VEHICLE NO:SGM 6835S

QTY	PARTICULAR	/
1 PCS	REAR BUMPER \$99.0/ ≠	1,072.60 J
1 PCS	REAR BUMPER SIDE HOLDER O/S	\$66.50
1 SET	REAR BUMPER CLIPS	un \$50.00
1 PCS	REAR BUMPER LOWER SKIRTING O/S	↑ \$342.10 X
1 PCS	REAR BUMPER REFLECTOR O/S	11 \$66.80 X
1 PCS	REAR END PANEL	11 \$452.00 €
1 SET	REAR REVERSE SENSOR	1 1 \$250.00 ×
		\$2,300.00
	LABOUR CHARGES:	
	TO CHECK WIRING	1 × \$50.00 ×
	TO DISMENTLE & REFIX REVERSE SENSOR	\$80.00 50
	TO DISMENTLE & REFIX SEAT, CUSHION UPHOLSTREY	17 \$120.00 X
	TO SPRAY RUST PROOFING	17 \$80.00 ×
	LABOUR FOR PANEL BEATING & REPLACING PARTS	\$500.00200
	TO PUTTY & SPRAY PAINTING	\$600.00720
	TOTA	L \$3,730.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1-1015:57 202 B12.40 1382.40 105.52