	ASS, REC. BY	Rith 6	s/ct118012470/RI	vd3 Period hornerion.	
4	Merinen		CHECKENIALENTI (C)(C)		
the .	From (Person)  Estimated Cost	Elaine cheorg	of C71	Desc/Tune 1	7/180 S.04pm
	OI)/TP/WS	TP RES / OD RES / EVA	/ INV / MV 7 CS		
	To Inspect Vel at Workshop in	nicle No.	LN 14382	Insured 0196 6	100
	of	rye k	& Camarage Ind. & punden forp	Tel 4180 3	5109
	Policy No. DN	16c2 N 303 Q 3318	Claim No:	3NM18 DO 33	48001/8
	Sum Insured_		Excess:	\$ 500.00	101 2010
	Make of Veh (Client's Record	)		10/07/2018	04/2012
		REP. / REV 24 HRS	V.1.	H.O.D. Endorsen	S.N.S.
	Date/Time; _5	5-16pm@9/7/18 Pars	on Contacted.	Vehicle(IN).OU	ľ
	Date/Time	Action/Instruction (	) Estimate	No. A	-[2]
		35141438 Z-(81	C7118012458/9d3	D0 F1	:57 2018
	11/18	Revert via meri	men		
	12/7/18	Pace approved of	iom Susan via		
	12/7/18	Informed mr Yik	cla ex \$500	by email	
	25 A 18	Final dig \$ 4	328.82 Confirmed	by email (Red	2827-63, 3990

# ASSIGNMENT

From: Date:	Veh No:	SLN 14362	Yr Regn. 2017	
Estimated Cost:		-	Lorry / Taxi / Prime Move	r/
OB TP //WS / TP RES / OD RES / EVA / INV / MY	100000	k / Trailer or	¥	-600
To Inspect Vehicle No: 5LN 14 382	Make:	WERCEURS Grow		595
at Workshop m/s C&C	Colour	BLUE	A/C: Insured / St	d/NI/NA
of Pansan Love	Sp.Reading	12648	T/Radio: Insured / S	td / NI / NA
Insured: CT1	Eng/No:		5000 <b>.</b>	
Policy No.	C/No.	WDD176043	327496964	
Claims No.		Good Far / Poor / Bu		
Sum Insured: Excess: 5	Steering: (	norder / Jammed / Leak	ed / Burnt or	
(Client's Record)	Brake:	norder / Jammed / Leak	ed / Burnt or	
Make of Veh:	Modi: N	il / S/R/m / STD A/Rim	50000 UM 10000000000000000000000000000000	
# 15 C F F F F F F F F F F F F F F F F F F	Tyre Size:	F: 3	25/45R17	
(Policy Condition)		R:	n -	
Remark: The veh had commenced its	N/S O/S BS)/ DUN	EXNOVA / GY / FS / LI	ZA / MIC / OHTSU / PIR / S	SUMI /
repair at the time of inspection.	TOYOTY	OKO or		
Bal. or Market Value:	Front	,	Rear	
IDAC Accident Rport: Consistent? : Yes or	No R/Bal.	<b>⊘</b> mm	R/Bal.	mm
GIA / PR Seen: Consistent?: Yes or	r No L/Bal.	, mm	L/Bal. 6	mm
Est Repairs: days Res.: Yes o	r No D.O.A.	65 01 V8	D.O.I. (00	1/18
Lum Sum: % 3 Val.: Yes o	r No Survey he	ld at C	ec CAL) '	
CA I REVII REP. / 24 HRS	Des. of Da	amages Fr Rear / C	D/S / N/S / U/C / Roofto	p or
	ehicle: IN / OUT	_		
Date: Person Contacted:	The U	C / Chassis frame / E	Body Structure affected do	ue to collision.
Date / Time Action / Instruction  RECEIVED 2 5 JUL 20	118			
Date/Time, File Pass to?  : Preli. Report : Final Report	Days Of Resurve	Repair: 3	Survey Fee	
Date/Time, File Return to?	93		Transportation	
21 25/7 - typut	Add Fee: S	ite Insp (\$	)S+RS,SI	
. 0	: In	terview (\$	) Photos	
Report Format: Merimen	: T	ech Invs (\$	) Others	
Lump Sum / I.B.I: (\$ \\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	) : V	/eekend (\$	)	
2 230000			TOTAL	550

# ...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Sub	mitted	Ins Auth'ed	Status		
Main	09 Jul 2018		09 Jul 2018 17:42 Assign					New Assignment Cancel Case	nt	
	Main	Re	ference		Claim Details		Document	s	Show All	
CLAIM S	UBFOLDER D	ETAILS	NAME OF TAXABLE PARTY.			[Created	by insurer]		Maria de California de Califor	
Insured:	PENNY C	HIA LI JIA, ID:	58430558H, To	el: +659655	6046, Email: N	OEMAIL				
Vehicle Re No.:	g. SLN143	SLN1438Z				s: 05/07/2018 21:00 - :59				
Claim Type	pe: <b>OD</b> / SNM18D03348C01				Policy/Cover Note No.:	DMPCSN3020231800 (Comprehensive)				
					Excess:	S\$500.00				
Repairer:	Cycle & C	arriage Industri	es Pte Ltd (Pan	idan Loop)	188 Pandan Loop	p, 128378 V	Vest Coast - Tel: 9	91865300		
Handling Insurer:	China Ta	iping Insurance (	Singapore) Pto	e. Ltd. (HQ	) - Tel: 6389 611	1 [Handl	ed by Elaine Che	eong]		
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	[Final Rpt	due 18/0	7/2018]			
Driver/Cus dian:	PENNY CH	IA LI JIA (33 / Fen	nale), NRIC: S	8430558H,	Tel: +6596556	046				
ASSOCIA	TED MAIL RE	CEIVED					Ţ,	/iew All   Compose	c Case Mail	
There are	no mail for this	case.					-			
ALL ASS	OCIATED TAS	SKS <sup>=</sup>				View All	Search Tasks	Create New Task	Complete	
Due Da		Type Task	Group Sub)	ject Han	dler Assign	ned By	Completed On	Created On	Done	

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

From: LKK Auto Consultants Pte Ltd China Taiping Insurance (Singapore) Pte. Ltd. To: 51 Ubi Ave 1 #01-25 3 Anson Road Paya Ubi Industrial Park #16-00 Springleaf Tower Singapore 408933 Singapore 079909 11 Jul 2018 Date: Elaine Cheong Attn: Preliminary Advice : 05/07/2018 Accident Date : SLN1438Z Vehicle No Policy No. : MERCEDES-BENZ A200 Make DMPCSN3020231800 : \$\$500.00

Excess

: 3.00

Est. Duration of Repair : 10/07/2018 : CYCLE & CARRIAGE INDUSTRIES PTE LTD (PANDAN LOOP) 188 PANDAN LOOP SINGAPORE 128378

## Point of Impact / General Description of Damages

: 09/07/2018

Assignment Date

Date of Inspection

Inspection At

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,036.26	
Revised Amount	:S\$	4,208.63	
Check Items (Estimated)	:S\$	2,438.63	
Total	:S\$	6,647.26	
Lump Sum Repair	:S\$		
Total Loss Consideration			
New for Old Value	:S\$		
Pre-Accident Value	:S\$	116,000.00	
COE / PARF Rebate	:S\$	63,761.00	
Salvage Value	:S\$		
Margin for Repair	:S\$	52,239.00	

: In Order Brake System Steering System : In Order Tyre Condition (Front) : 6/6 mm Tyre Conditiion (Rear) : 6/6 mm

Remarks (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation. The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck. Other comments:

## Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Wednesday, 25 July 2018 9:51 AM

To:

'Dennis Yap Kian Meng'; Yik Chan Hoe; Rasul (LKKAuto)

Cc:

SUR; Tony Lim Hock Seng

Subject:

RE: SLN1438Z final bill

Dear Mr Yik,

Confirmed amount \$4328.82 before excess \$500 and GST

No of days:3 days

Best Regards,

Veron Chen | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

----Original Message-----

From: Dennis Yap Kian Meng <dennis.yap@cyclecarriage.com.sg>

Sent: Tuesday, 24 July 2018 6:52 AM

To: Yik Chan Hoe <chanhoe.yik@cyclecarriage.com.sg>; Rasul (LKKAuto) <Rasul@lkkauto.com>

Cc: SUR <sur@lkkauto.com>; Tony Lim Hock Seng <tony.lim@cyclecarriage.com.sg>

Subject: RE: SLN1438Z final bill

HI Yik,

As requested.

With thanks & best regards
Dennis Yap
Technical Executive
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
188 Pandan Loop Service Center

TEL: 67778388 | DID 67714434 | HP 94506582

Wedsite: www.mercedes-benz.com.sg

----Original Message-----

From: Yik Chan Hoe

Sent: Monday, 23 July, 2018 7:45 PM

To: Rasul@lkkauto.com; Dennis Yap Kian Meng Cc: 'sur@lkkauto.com'; Tony Lim Hock Seng

Subject: SLN1438Z final bill

Hi Rasul,

Fyna.

Hi Dennis,

Please forward the photos to Rasul.

Thanks & Regards,

Yik Chan Hoe Mercedes-Benz Body Care & Repair Center Cycle & Carriage Industries Pte Ltd Pandan Loop Service Center

Mobile: 9186 5109 | DID: 6771 4353 | Fax: 6872 1272

Website: www.mercedes-benz.com.sg

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

### Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Thursday, 12 July 2018 10:19 AM

To:

'Yik Chan Hoe'; SUR

Subject:

RE: SLN1438Z-DOA: 5/7/2018 (CHINA TAIPING OD)

Dear Mr Yik,

As instructed by our client, please proceed to repair the insured vehicle SLN 1438Z (Excess \$500/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)

Sent: Thursday, 12 July 2018 9:09 AM

To: 'Yik Chan Hoe' <chanhoe.yik@cyclecarriage.com.sg>; SUR <sur@lkkauto.com>; 'Elaine Cheong'

<elaine.cheong@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: RE: SLN1438Z-YOUR REF: SNM18D03348C01

Dear Mr Yik,

We are pending approval from insurance.

Dear Elaine,

Please kindly assist for approval.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Yik Chan Hoe [mailto:chanhoe.yik@cyclecarriage.com.sg]

Sent: Thursday, 12 July 2018 8:52 AM

To: SUR < sur@lkkauto.com >

Subject: SLN1438Z

Dear OIC,

Kindly advise on the authorisation of this vehicle.

Thanks & Regards,

#### Yik Chan Hoe

Mercedes-Benz Body Care & Repair Center Cycle & Carriage Industries Pte Ltd Pandan Loop Service Center Mobile: 9186 5109 | DID: 6771 4353 | Fax: 6872 1272

Website: www.mercedes-benz.com.sg

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

## View Received Message

This mail is associated with:

#### \*SLN1438Z (SNM18D03348C01)

OD
Jul 5 2018 9:00PM
[PENNY CHIA LI JIA]
Cycle & Carriage Industries Pte Ltd

Reply	Reply All Mark as Unread Print Message Delete Message Forward
керіу	
From	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 12/07/2018 09:27 AM.
To Subject	LKK_HQ Alert - Adj Mandate Approved (S\$6647.26) - SLN1438Z - Claim Handler: Elaine Cheong
Approved	1:6647.26.
DOCUM	ENTS SUMMARY

There are no documents.

#### Nivitha (LKK Auto)

From:

Elaine Cheong <elaine.cheong@sg.cntaiping.com>

Sent:

Monday, 9 July 2018 5:04 PM

To:

assignments@lkkauto.com

Subject:

FW: SLN1438Z OD Claim (SNM18D03348C01/8)

Attachments:

Scan Data from FX-C5A1F4 (789 KB); OD REPAIR ESTIMATE - SLN1438Z.pdf

Dear All,

#### OWN DAMAGE CLAIM

Policy Number: DMPCSN3020231800

Policy excess: \$500.00

The email below with attachments has reference.

Please proceed to survey our insured's vehicle as soon as possible.

Please check consistency of damages & revert.

Thank you.

Regards,

Elaine Cheong

Executive (Motor Claims) Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909 Co. Reg. No. 200208384E

DID: 6389 6530 Fax: 6225 5879

Email: elaine.cheong@sg.cntaiping.com

Website: www.sg.cntaiping.com



From: Yik Chan Hoe [mailto:chanhoe.yik@cyclecarriage.com.sg]

Sent: Monday, 9 July, 2018 4:50 PM

To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: FW: SLN1438Z OD Claim (SNM18D03348C01/8)

Dear Elaine,

Kindly arrange survey asap.

Thanks & Regards,

#### Yik Chan Hoe

Mercedes-Benz Body Care & Repair Center Cycle & Carriage Industries Pte Ltd Pandan Loop Service Center

Mobile: 9186 5109 | DID: 6771 4353 | Fax: 6872 1272

Website: www.mercedes-benz.com.sg

From: Yik Chan Hoe

Sent: Monday, 9 July, 2018 11:04 AM To: 'claimsdept@sg.cntaiping.com'

Subject: FW: SLN1438Z OD Claim (SNM18D03348C01/8)

Dear Elaine,

Kindly refer to the amended GIA repoprt.

Thanks & Regards,

#### Yik Chan Hoe

Mercedes-Benz Body Care & Repair Center Cycle & Carriage Industries Pte Ltd Pandan Loop Service Center

Mobile: 9186 5109 | DID: 6771 4353 | Fax: 6872 1272

Website: www.mercedes-benz.com.sg

From: Elaine Cheong [mailto:elaine.cheong@sg.cntaiping.com]

Sent: Monday, 9 July, 2018 10:28 AM

To: Yik Chan Hoe

Cc: Alfred Toh; Chee So Chow

Subject: FW: SLN1438Z OD Claim (SNM18D03348C01/8)

Dear Mr Yik,

Our telephone conversation a moment ago has reference.

As spoken, please amend the date of accident on the SAS report. We will assign surveyor upon receipt of your amended report.

Thank you.

Regards,

Elaine Cheong Executive (Motor Claims) Claims Department China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

Co. Reg. No. 200208384E

DID: 6389 6530 Fax: 6225 5879

Email: elaine.cheong@sg.cntaiping.com

Website: www.sg.cntaiping.com



-----Original Message-----From: Claims Dept of CTI

Sent: Monday, 9 July, 2018 10:12 AM

To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>

Cc: Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>

Subject: SLN1438Z OD Claim

Elaine

Please assist to look into the matter.

Best Regards

Alfred Toh Senior Executive Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909

DID: +65 6389 6183

FAX: +65 6224 7478/6224 7175 Email: claimsdept@sg.cntaiping.com alfred.toh@sg.cntaiping.com www.sg.cntaiping.com

#### Disclaimer:

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

----Original Message-----

From: Yik Chan Hoe [mailto:chanhoe.yik@cyclecarriage.com.sg]

Sent: Monday, July 09, 2018 9:27 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: SLN1438Z OD Claim

Dear Sir/Mdm,

Kindly arrange survey asap, vehicle is in.

Thanks & Regards,

Yik Chan Hoe Mercedes-Benz Body Care & Repair Center Cycle & Carriage Industries Pte Ltd Pandan Loop Service Center

Mobile: 9186 5109 | DID: 6771 4353 | Fax: 6872 1272

Website: www.mercedes-benz.com.sg

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit http://www.symanteccloud.com

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

This email has been scanned by the Symantec Email Security.cloud service. For more information please visit <a href="http://www.symanteccloud.com">http://www.symanteccloud.com</a>

## > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	0558H
Vehicle No.:	SLN1438Z
Vehicle to be Exported:	No
Intended De-registration Date:	11 Jul 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	A200 FL STYLE (R17 HLG)
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	27091031036868
Chassis No.:	WDD1760432J496964
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$25,411.00
Original Registration Date:	25 Apr 2017
First Registration Date:	25 Apr 2017
Transfer Count:	1
Actual ARF Paid: Intended PARF Rebate Details	\$22,576.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Apr 2027
PARF Rebate Amount: Intended COE Rebate Details	\$16,932.00
COE Expiry Date:	24 Apr 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,300.00
COE Rebate Amount:	\$46,829.00
Total Rebate Amount:	\$63,761.00

The information contained herein is correct as at 11 Jul 2018

OK

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

aforesaid.	ACCIDENT STATEMENT	
Date Of Report	06/07/2018 11:01	
Date Of Accident	05/07/2018 21:00	
Exact Location Of Accident	PADANG JERINGAU	
Country/State of Loss	SINGAPORE	
	DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLN1438Z	
Insured/Policyholder		
Name Of Registered Owner	PENNY CHIA LI JIA	
NRIC No	S8430558H	
Email Address	NOEMAIL	
Mobile Phone No	(LOCAL) +65-96556046	

OFFICE-96556046

#### Alternative Phone No Vehicle Particulars

MERCEDES-BENZ Manufacturer

A180 Model

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

If No. Please state action to be taken

PRIVATE CAR Vehicle Category

#### Insurance Company

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD. Name of Insurance Company

COMPREHENSIVE Type Of Coverage

NO Fleet Policy

DMPCSN3020231800 Policy Number

Cover Note Number

#### Driver

PENNY CHIA LI JIA Name of Driver

S8430558H NRIC No 25/09/1984 Date Of Birth INDOOR Occupation 06/06/2006 Date Of Driving Pass

12 YEARS AND 0 MONTHS Driving Experience

FEMALE Gender

(LOCAL) +65-96556046 Mobile Number

Fax Number

OFFICE-96556046 Contact Number

NOEMAIL EMail Address

Address

BLK 167 HOUGANG AVE 1 #11-1550

Postcode

530167

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

COVIAC

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

2

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

NO

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

#### Circumstances of Accident

I ASSUMED THAT CAR B (GZ8196X, VAN) HAD MOVED OFF. I TURNED TO CHECK FOR TRAFFIC AND LET GO OF THE BRAKES NOT KNOWING THAT CAR B WAS STILL INFRONT OF MY CAR AND KNOCKED INTO THE BACK OF CAR B.

#### Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

#### **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

GZ8196X

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

WANG SHUOGANG

NRIC/Passport Number

G2476912M

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### SKETCH PLAN

#### IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, (b) disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including (c) their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or Vik Chan Hoe

    Vik Chan Hoe

    Pie Lid

    Cycle & Carriage Industries Pie Lid

    Cycle & Carriage Remain Content

(ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time

Driver's Signature

(If driver is not the policyholder)

Date & Time

Cycle & Carriage Industries Pie Ltd

Cycle & Carriage Industries Pie Ltd

Cycle & Carriage Repair Conter

Body Care & Repair Fax: 5872 1272


HP: 9186 5109 Fax: 5872 1272

DID: 6771 4353 HP: 9186 5109

Email Lebanhoe vikalevelecarriage.com.se 5: 6771 4353 HP: 9186 5109 Fax: 6872 127 Email: chauhoeyik@cyclecarriage.com.sg

Name:

NRIC/FIN No .:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I assumed that (as B (van) had moved off, I turned to check for traffic and let so of the brakes not knowing that cor B was still infourt of my car and knocked into the bade of car B.

DECLARATION

I/We declare the foregoing particulars are true invevery respect.

Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.

(Please contact your insurance company for any further details)

Policyholder's Signature

Date & Time

Driver's Signature

(If driver is not the policyholder)

Date & Time

Cycle & Carriage Center Set Center Set 110 Fax: 6872 1272

DID: 6771 4353 HY

Email: chanhoe

Reporting Centre Personnel's

Name:

NRIC/FIN No.:



## 中国太平保险(新加坡)有限公司

MX1E N SN AN0006A COMPREHENSIVE

#### CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 Road Transport Act, 1987 (Malaysia) Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE No.

DMPCSN3020231800

Engine No : 27091031036868

Chassis No: WDD1760432J496964

Index Mark and Registration

Number of Vehicle

SLN1438Z

2. Name of Policy Holder

MISS PENNY CHIA LI JIA

Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment 11 MARCH 2018

NAMED DRIVERS EX SECT. I.......S\$500.00

IN ADDITION TO NAMED DRIVERS EX:

EX SECT. I - AGE >= 26......\$\$500.00

4. Date of Expiry of Insurance

24 APRIL 2019

Persons or Classes of Persons entitled to drive \*

. AGE AS AT DATE OF ACCIDENT

(A) THE POLICYHOLDER.

(B) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH HIS PERMISSION.

PROVIDED THAT THE PERSON DRIVING IS PERMITTED IN ACCORDANCE WITH THE LICENSING OR OTHER LAWS OR REGULATIONS TO DRIVE THE MOTOR VEHICLE OR HAS BEEN SO PERMITTED AND IS NOT DISQUALIFIED BY ORDER OF A COURT OF LAW OR BY REASON OF ANY ENACTMENT OR REGULATION IN THAT BEHALF FROM DRIVING THE MOTOR VEHICLE.

#### 6. Limitations as to use: \*

USE FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES AND FOR THE POLICYHOLDER'S BUSINESS. THE POLICY DOES NOT COVER USE FOR HIRE OR REWARD TUITION DRIVING TEST RACING PACE-MAKING, RELIABILITY TRIAL, SPEED-TESTING, THE CARRIAGE OF GOODS OTHER THAN SAMPLES IN CONNECTION WITH ANY TRADE OR BUSINESS OR USE FOR ANY PURPOSE IN CONNECTION WITH THE MOTOR TRADE.

EXCESS WHICHEVER IS APPLICABLE FOR LOSSES OCCURRING OUTSIDE SINGAPORE (CONSTRUCTIVE TOTAL LOSS / THEFT) WILL BE DOUBLED.

ONE TIME WAIVER OF EXCESS FOR THE FIRST S\$1,000 WILL APPLY TO THE INSURED AND NAMED DRIVERS IN THE EVENT OF OWN DAMAGE CLAIM AT OUR AUTHORISED WORKSHOPS FOR EACH POLICY YEAR.

HIRE PURCHASE CO. : STANDARD CHARTERED BANK SINGAPORE LTD AS HP OWNER

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia). Please see reverse

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Countersigned By:

Authorised Officer

Authorised Signatory

## REPUBLIC OF SINGAPORE IDENTITY CARD NO. \$8430558H



PENNY CHIA LI JIA



Race CHINESE

Date of birth 25-09-1984 Country/Place of birth

SINGAPORE

REPUBLIC OF SINGAPORE, DRIVING LICENCE



Licence Number: S8430558H

PENNY CHIA LI JIA

Birth Date: 25 Sep 1984 Issue Date: 06 Jun 2006

FOR CACUSE ONLY

5295965



19-04-2014

APT BLK 349 HOUGANG AVENUE 7 #06-621 SINGAPORE 530349

ACUSE ONLY

PASS DATE

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars=< 3000kg with =</p>
7 passengers, exclusive 06 Jun 2006 of the driver; and other motor vehicles =< 2500kg</p>

字



## **ESTIMATE FOR SLN1438Z\*RA**

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

CHINA TAIPING INSURANCE (S) PTE

LTD

ATTN: MOTOR CLAIM DEPARTMENT

3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909

62222366

Vehicle & Document Information

WIP No 25012

Reg No/Reg Date

SLN1438Z\*RA / 25/04/2017

Date In/Mileage Chassis No

/ 0 WDD1760432J496964

Engine No

27091031036868

Make/Model

MB/MB A 200 (W176) "STYLE"

Colour/Trim

021 162 south sea b/ 044 471 ARTICO/Fabr

Account No	Terms	Date/Time Printed	CSE	Opera					
WC000668	Credit	09/07/2018/ 09:09	YK	395 /	Yik Chan Hoe	nis hence	notify		
		Description of Goods	/ Services		To resurvey before/at	otyving:	Unit Price	Disc%	Amount
M BPNSUN POLICY N DRIVE IN BY/AUTHR S BPNSUB 1 PC FRO A BPILAB PANEL BE BODY PAN A BPIRES RESPRAY A BPILAB USING XE STANDARD A BPILAB CHECK HE M FRONT CR M FRONT CR M RADIATOR M FRONT LI M FRONT BU M FRONT BU	DATE SURVE IZED ON NT REG. PL ATING TO R ELS WITH R FRONT BUMP NTRY SYSTE SETTINGS. ADLAMP WIT OSS MEMBER A RADAR SE GRILLE ME GRILLE ME GRILLE OR	: 09/07/2018 // TBA Y: : ATE  EPAIR AFFECTED AREAS, EFINISH.  OR TH FOCUS ADJUSTMENT: NE ENSOR ERCEDES STAR B STAR HOLDER ENAMENTAL TRIM  TE MOLDING E	REMOVE AN	D REPLAGE MEMORY T	RASUL Hp 90010 3 clays olo7/18 @1230 Excess: Sou Reveri very 64 part Fix: 6872 1272	ct to confunts in a Without (s) is allowed ) must to res oval from this (er:	310.54 1157.08 130.65 72.06 116.50 58.68 120.86 1146.15	0.10 00.00 00.00 00.00 00.00 00.00 00.00 00.00 00.00	960 1200.00 600 750.00 380.00 120.00 \$157.00 \$157.00 \$157.00 \$2.00 \$4.55 \$4.564.5 \$4.564.5 \$4.564.5 \$4.564.5 \$4.564.5 \$4.564.5 \$4.564.5
Confirmed 8	accepted by							Nett	7,036.26
						7% G	ST on 7	036.26	

Validity of this estimate is 14 days from date of quote. This is a computer generated document, mo signature is required.


Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring

the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel. 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg



# ESTIMATE FOR BLN1438Z

CHINA TAIPING INSURANCE (S) PTE

ATTN: MOTOR CLAIM DEPARTMENT

● (\*\*) かられる。
・ (\*\*) かられる。

3 ANSON ROAD #16-00

SPRINGLEAF TOWER

SINGAPORE 079909

LTD

62222366

## Finalization

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

Vehicle & Document Information

WIP No

25012

Reg No/Reg Date

25/04/2017

Date In/Mileage Chassis No.

12107/2018/ 12648 WDD1760432J496964

**Engine No** 

27091031036868

Qty

Make/Model

MB/MB A 200 (W176) "STYLE"

Colour/Trim

021 162 south sea b/ 044 471 ARTICO/Fabr

Unit Price Disc%

CSE Operator Date/Time Printed Terms Account No 395 / Yik Chan Hoe 23/07/2018/ 19:13 Credit WC000668 Description of Goods / Services

Z REQUEST Custoger M BPNSUN

POLICY NO/ACC DATE : DMPCSN3020231800 // 05/06/2018 : 09/07/2018 // \$500.00 DRIVE IN/EXCESS DATE IN/DATE SURVEY: 10/07/2018 @ 1230 // RASUL LKK BY/AUTHRIZED ON : 12/07/2018 @ 1015 // VERON LKK

S BPNSUB SUPPLY 1 PC NO PLATE Working Days

A BPILAB PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE BODY PANELS WITH REFINISH.

A BPIRES

RESPRAY FRONT BUMPER A BPILAB USING XENTRY SYSTEM TO CHECK STANDARD SETTINGS.

MEMORY TO

A BPILAB CHECK HEADLAMP WITH FOCUS ADOUSTMENT

X BPNEXC INSURANCE EXCESS

RADIATOR GRILLE MERCEDES STAR RADIATOR GRILLE MB STAR HOLDER RADIATOR GRILLE ORNAMENTAL TRIM RADIATOR GRILLE X FRONT LICENSE PLATE MOLDING X

FRONT BUMPER FRONT IMPACT ABSORBER

130.65 00.00 1.00

72.06 00.00 1.00 1.00 116.50 00.00 564.59 00.00 1.00 1.00

1.00

1.00

58.68 00.00 1146.15 00.00 120.19 00.00

0.10

564.59 58.68 1146.15 120.19 (A)

Amount

60.00

960.00

600.00

380.00

120.00

-500.00

130.65

72.06

116.50

Yik Chan Hoe

Cycle & Carriage Industries Pte Ltd Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272 Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

3828.82 7% GST on

3,828.82 268.02

Total Payable

Nett

4.096.84

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, so signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg





Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

ESTIMATE FOR BLN 1438Z

CHINA TAIPING INSURANCE (S) PTE

ATTN: MOTOR CLAIM DEPARTMENT

SUPPLEMENTARY

25012

Reg No/Reg Date

25/04/2017

Date In/Mileage Chassis No.

12/07/2018/ 12648 W001760482J496964

Engine No.

WIP No

27091031036868

Make/Model

MB/MB A 200 (W176) "STYLE"

Vehicle & Document Information

Colour/Trim

021 162 south sea b/ 044 471 ARTICO/Fabr

Account No WC000668

LTD

62222366

Terms Credit

3 ANSON ROAD #16-00

SPRINGLEAF TOWER

SINGAPORE 079909

Date/Time Printed

CSE

Operator

23/07/2018/ 19:13

395 / Yik Chan Hoe

Description of Goods / Services

Unit Price Disc%

Amount

Z REQUES Ma BRNSUN

POLICY NO/ACC DATE : DMPCSN3020231800 // 05/06/2018

DRIVE IN/EXCESS : 09/07/2018 // \$500.00

DATE IN/DATE SURVEY: 10/07/2018 @ 1230 // RASUL LKK
BY/AUTHRIZED ON : 12/07/2018 @ 1015 // VERON LKK

STIMA

X FRONT IMPACT ABSORBER

120.19 CRA



Cycle & Carriage Industries Pte Ltd Body Care & Repair Center DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272 Binails shanhosiyik@systeenrisgesomisg

Confirmed & accepted by

Nett

120.19

7% GST on

120.19

8.41

Total Payable

128.60

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg



## LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road, #16-00 Springleaf Tower

Singapore 079909

Our File No:

CS/CTI18012470/R1VD3N2

Date:

02/08/2018

REFERENCE

Insured/Claimant: Date of Loss:

PENNY CHIA LI JIA

Policy No:

DMPCSN3020231800

Nature of Claim:

Claim No: SNM18D03348C01

12648 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

05/07/2018

Reg No:

**SLN1438Z** 

Make & Model:

MERCEDES-BENZ A200, 1.6 W176 (A) 25/04/2017 (Man. Year: 2016)

Engine No: Chassis No:

Odometer:

27091031036868

WDD1760432J496964

Reg. Date: Colour:

1595 cc

Engine Capacity:

Market Value/New Car Price:

S\$116,000.00

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

225/45R17

Rear Tyre Size:

225/45R17

Front Left Side:

Bridgestone 6 mm Bridgestone 6 mm Rear Left Side: Rear Right Side: Bridgestone 6 mm Bridgestone 6 mm

Front Right Side: The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts Miscellaneous Items	<b>Repairer's</b> 4,706.45 0.00	Adjuster's 2,268.82 0.00	2,437.63 0.00	<b>Diff</b> % 51.79
Labour	2,450.00	2,060.00	390.00	15.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,156.45	4,328.82	2,827.63	39.51
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	6,656.45	3,828.82	2,827.63	42.48
+ GST 7.00/7.00% (S\$)		268.02	197.93	42.48
Nett Amount (S\$)	7,122.40	4,096.84	3,025.56	42.48

INSPECTION

Date of Assignment:

09/07/2018

Date Inspected:

10/07/2018 Inspected At:

Cycle & Carriage Industries Pte Ltd

(Pandan Loop) 188 Pandan Loop Singapore 128378

Estimated Period of Repair:

3.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Aug 2018)

Parts: 144 MERCEDES-BENZ A200 1.6 W176 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLN1438Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

Recom	men	hah	Parts
Recom	men	ueu	rails

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*FRONT CROSS MEMBER	Serviceable	310.54 FS	*-FS
1		, 프로젝터 (F) 프로젝터 (B) (100명은 경기를 하고 P) (P) (B) (B) (B) (B) (B) (B) (B) (B) (B) (B	Serviceable	1,157.08 FS	*-FS
1		*RADIATOR GRILLE MERCEDES STAR	Necessary Necessary	130.65 FS 72.06 FS	*130.65 FS *72.06 FS
1		*RADIATOR GRILLE ORNAMENTAL TRIM *RADIATOR GRILLE	Cracked Scratched	116.50 FS 564.59 FS	*116.50 FS *564.59 FS
1		*FRONT LICENSE PLATE MOULDING *FRONT BUMPER GRILLE	Deformed Serviceable	58.68 FS 120.86 FS	*58.68 FS *- FS
1		*FRONT BUMPER	Deformed Serviceable	1,146.15 FS 849.15 FS	*1,146.15 FS *- FS
1		*FRONT IMPACT ABSORBER	Cracked	120.19FS	*120.19 FS
1		*FRONT REG PLATE	Bent	60.0015	60.00F3
anchise	part. S=SpcN	Jett.	Total Parts (S\$)	4,706.45	2,268.82
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 1 1 1 1 1 1 1 1 1 1	*FRONT CROSS MEMBER  *FRONT CPA RADAR SENSOR  *RADIATOR GRILLE MERCEDES STAR  *RADIATOR GRILLE BM STAR HOLDER  *RADIATOR GRILLE ORNAMENTAL TRIM  *RADIATOR GRILLE  *FRONT LICENSE PLATE MOULDING  *FRONT BUMPER GRILLE  *FRONT BUMPER  *RIGHT HEADLAMP UNIT	1 *FRONT CROSS MEMBER Serviceable 1 *FRONT CPA RADAR SENSOR Serviceable 1 *RADIATOR GRILLE MERCEDES STAR Necessary 1 *RADIATOR GRILLE BM STAR HOLDER Necessary 1 *RADIATOR GRILLE ORNAMENTAL TRIM Cracked 1 *RADIATOR GRILLE SCRAMENTAL TRIM SCRACKED 1 *FRONT LICENSE PLATE MOULDING Deformed 1 *FRONT BUMPER GRILLE Serviceable 1 *FRONT BUMPER Deformed 1 *FRONT BUMPER CRILLE Serviceable 1 *FRONT BUMPER DEFORMED 1 *FRONT IMPACT ABSORBER Cracked 1 *FRONT REG PLATE Bent	1         *FRONT CROSS MEMBER         Serviceable         310.54 FS           1         *FRONT CPA RADAR SENSOR         Serviceable         1,157.08 FS           1         *RADIATOR GRILLE MERCEDES STAR         Necessary         130.65 FS           1         *RADIATOR GRILLE BM STAR HOLDER         Necessary         72.06 FS           1         *RADIATOR GRILLE ORNAMENTAL TRIM         Cracked         116.50 FS           1         *RADIATOR GRILLE         Scratched         564.59 FS           1         *FRONT LICENSE PLATE MOULDING         Deformed         58.68 FS           1         *FRONT BUMPER GRILLE         Serviceable         120.86 FS           1         *FRONT BUMPER         Deformed         1,146.15 FS           1         *RIGHT HEADLAMP UNIT         Serviceable         849.15 FS           1         *FRONT IMPACT ABSORBER         Cracked         120.19 FS           2         *FRONT REG PLATE         Bent         60.00 FS

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING TO REPAIR AFFECTED AREAS.REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH	New	1,200.00	960.00
2	RESPRAY FRONT BUMPER	New	750.00	600.00
3	USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO STANDARD SETTINGS	New	380.00	380.00
4	CHECK HEADLAMP WITH FOCUS ADJUSTMENT	New	120.00	120.00
	Gross Lab	oour Cost (S\$)	2,450.00	2,060.00
	Report was unsubmitted d	uring this print-out.	100 100	

< END OF ESTIMATES >